Building Condition Assessment Survey 2023-2024

Asset:		IATTAN, 32 WEST 92		AII, III, 10025			
Inspectior					Time		Last Edited
	155 ELECTRICAL				2023-	-10-13 07:53AN	4 2023-11-06 06:19PM
sset Data							
Question				Answer			
Have any	Systems/Major Building	Components been upgrade	ed?	Systems:		V System, LAN	
				Years:	2023	G : 1	
				Systems:	Partial Service	e Switch	
				Years: Systems:	2020, 2009 Partial Malda	d Casa Circuit E	Breaker Panel Board
				Years:	2020, 2008, 1		bicakei Fallei Boalu
				Systems:	Partial Switch		
				Years:	2020	loouru	
				Systems:	Lighting - Sec	curity	
				Years:	2019, 2000	5	
				Systems:		rm System (Pani	c Switch)
				Years:	2017	•	,
				Systems:	Telephone Sy	stem	
				Years:	2015		
				Systems:	Auditorium (Theater Lighting	System)
				Years:	2014		
				Systems:			ence Lab Rooms 228,
							LED Lighting), Most
				Years:	Exit Lights (E 2013	sattery Pack)	
				Systems:		Room 228. Fire	Alarm System, Public
				5			System, Auxiliary
					Signal/Bell Sy	ystem	
				Years:	2012		
				Systems:			m), Intrusion Alarm
				Years:	2009	ral Control Pane	1)
				Systems:	Science Lab F	Room 328	
				Years:	2008		
				Systems:		ight/Exit Light F	Panel
				Years:	2000		
Type of S	ervice			Below Gro			
	active Whiteboard (IWB) Exist?		Yes			
Water Pen	etration In Electrical Roo	om?		No			
	TED INTERCOMS	IN FIRE RESCUE AR	EAS				
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and					Response		
your bu	ilding?	ance Areas, Fire Rescue Ai	reas, and/or Holding Roon	ns in N	lo		
riority Co			~	•	n ()	.	
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System -	N/A	Fire Alarm	Main Entrance	Eugenio	Custodian	No Photo Taken
	Not Connected to		System -	Lobby	Rodriguez		
	Central Station		Digital	-	-		
			Communicator				

Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		MU8
uestion	Response	
AUDITORIUM		
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting	1	
Instance on 1st Floor - Staff	Inspected	
	*	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection		IVIUC
lestion	Response	
CAFETERIA		
Lighting		
Instance on 1st Floor - Students	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Pendant Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Surface Mounted		
Instance on 1st Floor - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Local Sound System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Response
Does not exist
Inspected
Inspected
No
Inspected
Inspected
1
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
Inspected
De constante
Does not exist
Does not exist
Does not exist
Inspected
Inspected
3- Fair
LIGHTING FIXTURE NOT OPERATIONAL
10
EACH
REPAIR DECODITY 2
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist

Building Condition Assessment Survey 2023-2024

1	Λ./	٢A	o	1
	V	U	a	4

trical Inspection		M084
Question	Response	
GYMNASIUM		
Local Sound System		
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	A	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 210	Inspected	
Lighting		
Instance on Room 210	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 210	Inspected	
Pendant Mounted		
Instance on Room 210	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 210	Does not exist	
Recessed Mounted		
Instance on Room 210	Does not exist	
Lighting Fixture - HID		
Instance on Room 210	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 210	Does not exist	
Lighting Fixture - LED		
Instance on Room 210	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room 210	Does not exist	
	2 Seb Hot entity	

Building Condition Assessment Survey 2023-2024

lestion	Response	
JBRARY		
Projection System		
Instance on Room 210	Does not exist	
LOCKER ROOM	Inspected	
Instance on 2nd Floor	Inaccessible	
AULTIPURPOSE ROOM	Does not exist	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 228	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 328	Inspected	
Power Panel?		
Alternative Use	Yes	
	Yes	
Lighting Instance on Room 228	Inspected	
Instance on Room 328	Inspected	
Lighting Fixture - Fluorescent	hispected	
Instance on Room 228	Inspected	
Instance on Room 328	Inspected	
Pendant Mounted	hisperied	
Instance on Room 228	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 328	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficición recorded	
Instance on Room 228	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 328	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 228	Does not exist	
Instance on Room 328	Does not exist	
Lighting Fixture - HID		
Instance on Room 228	Does not exist	
Instance on Room 328	Inspected	
Pendant Mounted	inspected	
Instance on Room 328	Does not exist	
Surface Mounted		
Instance on Room 328	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 328	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 228	Does not exist	
Instance on Room 328	Does not exist	
Lighting Fixture - LED		
Instance on Room 228	Does not exist	
Instance on Room 328	Does not exist	
Emergency Gas Shut-Off Valve		

Building Condition Assessment Survey 2023-2024

ллоо	1
VIUð	4

uestion	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Room 228	Does not exist	
Instance on Room 328	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 228	Does not exist	
Instance on Room 328	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 228	Does not exist	
Instance on Room 328	Inspected	
Instructor Unit	X	
Instance on Room 328	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 328	Does not exist	
Student Unit		
Instance on Room 328	Does not exist	
Projection System		
Instance on Room 228	Does not exist	
Instance on Room 328	Does not exist	
SCIENCE PREP ROOM	Does not exist	
	Does not exist	
SWIMMING POOL		
FOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	

Building Condition Assessment Survey 2023-2024

•	IVIUO
uestion	Response
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Staircases D/1, D/2, Near Rooms 128, 130, 136, 234
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35672726Z
Non Battery Pack	Inspected 3- Fair
Condition	-
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1 EACH
Quantity Uom Potential Action	
Urgency of Action	INSTALL COVER PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

M084

cai inspection	N108
estion	Response
IRE ALARM SYSTEM	
Heat Detector	
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ademco
EquipmentId	Digital Communicator
Installation Year	2012
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

uestion	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room 301
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance Deficiency Quantity	Boiler Room 2
Quantity Uom	2 EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion	Response
ANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Rooms 310, 328, 340
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 140
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2009
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

M084	L
IVIU04	ŀ

lestion	Response
BECURITY	
Intrusion Alarm System	
Remote Annunciator	
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Near Main Entrnce
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
ERVICE SWITCH	Inspected
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B7
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Computer Service Switch
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Heating Equipt Service SW

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

iteur inspection	11
uestion	Response
SERVICE SWITCH	
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Electrical Room B7
Instance	
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Main Switch
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
WITCHBOARD	Inspected
Number of Spares	2
	Inspected
Fused Disconnect Switch Type Instance	Electrical Room B7
	1- Good
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	AC-DP 800 MSW
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Royal Switchboard Co.
Manufacturer	Main Distr Center
EquipmentId	
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1962
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist