Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset: P.S. 87 - MANHATTAN, 160 WEST 78 STREET, MANHATTAN, NY, 10024				
Inspection Id	Inspection Type		Time In	Last Edited
4889	MECHANICAL		2024-04-22 06:46AM	2024-06-20 12:13PM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Water Service	
		Years:	2024	
		Systems:	Terminal Unit Thermostatic Trap	s; F&T/Steam Drip
			Traps; Radiators/Convectors (~8	0%)
		Years:	2021	
		Systems:	Electric Domestic Water Heater	
		Years:	2020	
		Systems:	MDF Room - Dedicated A/C Equ	upment (DX Split

	System)
	Years: 2018
	Systems: Fixtures - Toilets
	Years: 2015
Are there fuel tanks?	No
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Sub-Basement MER, MER 320
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Room B7 (painted, 5)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No condi	tion recorded							

Inspection

iestion	Response	
echanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	3- Fair	
Deficiency	UP TO 5 TONS:DEFECTIVE	
Deficiency Location/Instance	Room above Lunch Room (2. of 3)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Dry Cooler	Does not exist	
Packaged / Rooftop Unit	Does not exist	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	14100
uestion	Response
AIR CONDITIONING	
Refrigerant Piping	
Condition	2- Between Good and Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Lower Roof above Cafeteria
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Under construction
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Under construction
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Sub-Basement Crawlspace - North Side; Basement Electrical
	Room - Gas/Sprinkler Room
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Under construction
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Under construction
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Sub-Basement MER (2 of 2)
Deficiency Quantity	2

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

1		100
iestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sump Pump		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Lavatory/Sink	-	
Condition	3- Fair	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF	
	VALVE,ETC.)	
Deficiency Location/Instance Deficiency Quantity	Staff Toilet Room 215	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Room 311B	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Student	Inspected	_
Drinking Fountain	Inspected	
Condition	3- Fair	-
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	_
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Toilet Room 126	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF	
	VALVE,ETC.)	
Deficiency Location/Instance	Toilet Room 126, Boy's Toilet Room 111B	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

intent inspection	11
iestion	Response
FIXTURES	
Student	
Lavatory/Sink	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on 2nd Floor - Boy's	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Denetency	VALVE,ETC.)
Deficiency Location/Instance	Room 105, 203, 124
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
	Under construction
GAS SERVICE	
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Under construction
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Under construction
Steam Piping	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Deficiency Terminal Unit Thermostatic Trap	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	Response	
Тгар		
*	No deficiencies recorded	
urces	Does not exist	
	Under construction	
	Inspected	
nent	Under construction	
	Inspected	
1, 213, 313	-	
1, 210, 515		
1, 213, 313	Inspected	
., 210, 010		
Instance		
	PRIORITY 3	
	LEVEL 2	
	No violations recorded	
	Inspected	
	inspected	
	Not required	
	Notrequired	
	Does not exist	
	Does not exist	
	Inspected	
	No deficiencies recorded	
	Turner de d	
	-	
	No deficiencies recorded	
	-	
	No deficiencies recorded	
	Inspected	
	3- Fair	
	No deficiencies recorded	
I. Contraction of the second se		
	Does not exist	
er		
	Does not exist	
	Inspected	
	3- Fair	
	No deficiencies recorded	
	Inspected	
	mopeeted	
	Trap nent 1, 213, 313 1, 213, 313 /Instance	Trap No deficiencies recorded urces Does not exist Under construction Inspected inspected int i, 213, 313 Inspected Inspected I, 213, 313 Inspected Inspected I, 213, 313 Inspected Inspected I, 213, 314 Inspected Inspected I, 213, 214, 214, 214, 214, 214, 214, 214, 214

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

uestion	Response	
MDF Room		
Dedicated A/C Equipment		
Instance on Room 115	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
·	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB		
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Room B7 (painted, 5)	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	