Building Condition Assessment Survey 2023-2024

Asset:	P.S. 92 - MANHATTAN, 222 WEST 134 STREET, M.	ANHATTAN, NY, 100	30	
Inspection Id	Inspection Type		Time In	Last Edited
1115	ELECTRICAL		2023-11-17 09:12AM	2024-04-30 12:52PI
sset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	LED Lighting (Auditorium, Gyn	nnasium)
		Years:	2023	
		Systems:	Transformer, Partial Service Swi	tch
		Years:	2022	
		Systems:	Partial Molded Case Circuit Brea	aker Panel Board
		Years:	2020, 2019, 2013, 2007, 2000, 1	990
		Systems:	Security Lights	
		Years:	2020, 2009	
		Systems:	Intercom System (Holding Room	ns)
		Years:	2020	
		Systems:	Computer Lab (Raceway With R Auditorium (Projection System,	-
		Years:	Lighting) 2016	
		Systems:	Lightning Protection, Exit Lights	s (Battery Pack)
		Years:	2015	(Dunely Tuen)
		Systems:	Intrusion Alarm System (Remote Switch)	Annunciator, Panic
		Years:	2014	
		Systems:	Interior Lighting (Except Library Switchboard, Partial Fused Disco	
			Panel Board, Intercom System (I	
			Emergency Lighting (Battery Pa (Tamper Flow Switch/Chain, Sp.	
		Years:	Pressure Switch) 2013	
		Systems:	IPDVS/CCTV System	
		Years:	2012	
		Systems:	Telephone System, LAN	
		Years:	2011	
		Systems:	Science Lab Room 322	
		Years:	2009	
		Systems:	Intrusion Alarm System (Remote Switch)	Annunciator, Panic
		Years:	2004	
		Systems:	Fire Alarm System (Electronic S	ub-Panel)
		Years:	2003, 1997	
		Systems:	Public Address System (Amplifi (Elevator Recall)	er), Fire Alarm System
		Years:	2003	
		Systems:	Library	
		Years:	1999	
		Systems:	Fire Alarm System (Fan Shutdov Smoke Detector, Strobe)	vn Control, Duct
		Years:	1997	1
		Systems:	Emergency Light/Exit Light Pan	el
m 2~ :		Years:	1995	
Type of Service		Below Gr	round	
	e Whiteboard (IWB) Exist?	Yes		
water Penetration	on In Electrical Room?	No		

Electrical .								M092
		N FIRE RESCUE AREAS						
		ance Areas, Fire Rescue Areas, a	nd/or Holding Room		Response No			
Priority Co								
Exist	Priority	Condition	Commonant	Location	Dougon(s)	Dawson(s)	Photo	
Last Year?	Category	Description	Component Affected	Description Description	Person(s) Notified	Person(s) Title	Image	
Yes	Fire Alarm System - Defective	One Circuit is Not Operational and this is causing improper Bell functionality	Fire Alarm System	Boiler Room	Jeff Sutton	Fireman	No Photo Taken	
Yes	Fire Alarm System - Defective	Smoke Detection Sub Panel has a short circuit	Fire Alarm System - Sub Panel	Boiler Room	Jeff Sutton	Fireman	No Photo Taken	
Yes	Fire Alarm System - Components Not Operational	Visual Fire Signal Indicator Cabinet Panel is Not Operational	Fire Alarm System - Sub Panel	Boiler Room	Jeff Sutton	Fireman	No Photo Taken	
Inspection	r							
Question	1			Response				
Electrica	al							
ATHL	ETIC FIELD			Does not	exist			
AUDI	ГORIUM			Inspected				
	Instance on 1st Floor			Inspected				
Hous	se Lighting							
	Instance on 1st Floor			Inspected				
	Does a Chandelier Ex			No				
Lig	ghting Fixture - Fluoresce	ent						
_	Instance on 1st Floor			Inspected				
P	endant Mounted			D	:-4			
_	Instance on 1st Floor			Does not	exist			
S	Instance on 1st Floor			Inspected				
	Instance Condition				en Good and Fa	ir		
	Deficiency				encies recorded			
_ D	Recessed Mounted			TVO defici	cheres recorded			
r	Instance on 1st Floor			Does not	evist			
Lic	ghting Fixture - HID			Does not	CAIST			
2.16	Instance on 1st Floor			Does not	exist			
Lig	ghting Fixture - Incandes	cent						
	Instance on 1st Floor			Does not	exist			
Lig	ghting Fixture - LED							
	Instance on 1st Floor			Inspected				
P	endant Mounted							
	Instance on 1st Floor			Does not	exist			
$\overline{\mathbf{s}}$	urface Mounted							
	Instance on 1st Floor			Inspected				
	Instance Condition			1- Good				
_	Deficiency			No defici	encies recorded			
F	Recessed Mounted							
	Instance on 1st Floor			Does not	exist			
Loca	l Sound System							
	Instance on 1st Floor			Inspected				
	Instance Condition			5- Poor				
	Installation Year	Voor		1966	tod			
	Source of Installation Deficiency	1001		Documen AMPLIE	IER NOT OPER	PATIONAI		
	Deficiency			AMPLIF	IER NOT OPER	CALIONAL		

Building Condition Assessment Survey 2023-2024

	1/10/2
Response	
1	
EACH	
REPLACE SYSTEM	
PRIORITY 2	
LEVEL 2	
No violations recorded	
Inspected	
2- Between Good and Fair	
Ceiling	
No deficiencies recorded	
Inspected	
Does not exist	
Inspected	
3- Fair	
LIGHTING FIXTURE BEYOND USEFUL LIFE	
74	
EACH	
REPLACE-UPGRADE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
Inspected	
Does not exist	
Inspected	
The deficiences recorded	
Does not exist	
DOES NOT CARS.	
Does not exist	
Increated	
шърсеси	
Dogs not avist	
DOES HOT CYIST	
Does not exist	
2- Between Good and Fair	
	1 EACH REPLACE SYSTEM PRIORITY 2 LEVEL 2 No violations recorded Inspected 2- Between Good and Fair Ceiling No deficiencies recorded Inspected Inspected Inspected LINSPECTED LIGHTING FIXTURE BEYOND USEFUL LIFE 74 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2

Electrical Inspection	MO	M092	
0 "	n.		

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1966
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 222	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 222	Inspected

Building Condition Assessment Survey 2023-2024

Electrical InspectionM092QuestionResponse

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 222	Inspected
Pendant Mounted	
Instance on Room 222	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 222	Does not exist
Recessed Mounted	
Instance on Room 222	Does not exist
Lighting Fixture - HID	
Instance on Room 222	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 222	Does not exist
Lighting Fixture - LED	
Instance on Room 222	Does not exist
Raceway With Receptacles	
Instance on Room 222	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	
	Inspected
Lighting Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	nispected
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	DOCS HOT CAIST
Instance on 1st Floor	Does not exist
	Does not exist
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Increased
	Inspected
Pendant Mounted	Does not exist
Instance on 1st Floor Surface Mounted	Does not exist
Instance on 1st Floor	Township
	Inspected 1- Good
Instance Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year Source of Installation Year	1966 Documented
Deficiency Deficiency Quantity	AMPLIFIER NOT OPERATIONAL 1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

Electrical Inspection	M092
Question	Response

neu Inspection		1/10/2
Question	Response	
GYMNASIUM		
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	-	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 202/204	Inspected	
Lighting		
Instance on Room 202/204	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 202/204	Inspected	
Pendant Mounted		
Instance on Room 202/204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 202/204	Does not exist	
Recessed Mounted		
Instance on Room 202/204	Does not exist	
Lighting Fixture - HID		
Instance on Room 202/204	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 202/204	Does not exist	
Lighting Fixture - LED		
Instance on Room 202/204	Does not exist	
Raceway With Receptacles		
Instance on Room 202/204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 202/204	Does not exist	
LOCKER ROOM	Does not exist	

Electrical Inspection	M092
Question	Response

uestion	Response
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 322	Inspected
Power Panel?	
Alternative Use	Yes
	No
Lighting	Inspected
	inspected
Lighting Fixture - Fluorescent Instance on Room 322	Inspected
	nispected
Pendant Mounted Instance on Room 322	
	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 322	Does not exist
Recessed Mounted	
Instance on Room 322	Does not exist
Lighting Fixture - HID	
Instance on Room 322	Inspected
Pendant Mounted	
Instance on Room 322	Does not exist
Surface Mounted	
Instance on Room 322	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 322	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 322	Does not exist
Lighting Fixture - LED	
Instance on Room 322	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 322	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 322	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 322	Inspected
Instructor Unit	
Instance on Room 322	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 322	Does not exist
Student Unit	
Instance on Room 322	Does not exist
Projection System	
Instance on Room 322	Inspected
Instance Condition	3- Fair

M09
Response
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
3- Fair
LESS THAN 20% SPARE CIRCUIT BREAKERS
Electrical Meter Room B15
I EACH
INSTALL NEW PANEL BOARD
PRIORITY 5
LEVEL 2
No violations recorded
PANEL BOARD DOOR LOCK IS MISSING
Electrical Meter Room B15
1
EACH MAINTENANCE
MAINTENANCE
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
Inspected

Building Condition Assessment Survey 2023-2024

cui Inspection		
estion	Response	
MERGENCY LIGHTING		
Battery Pack		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
TIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency		
Strobe	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency		
Manual Pull Station	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency		
Area Smoke Detector	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist Inspected	
Elevator Recall Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Magnetic Door Holder/Contactor Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fire Alarm Digital Communicator Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Fire Alarm Control Panel (Standard)		
Instance	Boiler Room 4- Between Fair and Poor	
Instance Condition		
Instance Quantity	1	

uestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Manufacturer	Edwards
EquipmentId	Fire Alarm Control Panel
Installation Year	1966
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	99,000
Quantity Uom	S.F.
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
*	
Deficiency Location/Instance Deficiency Quantity	Boiler Room
	99,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	N/A
Model	N/A
EquipmentId	Visual Fire Indicator Cabinet
Installation Year	1997
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1 EAGN
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Elevator Smoke Detection
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Condition	

Building Condition Assessment Survey 2023-2024

icui Inspection		14107
uestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity Uom	EACH	
Manufacturer	Pyrotronics	
Model	System 3	
EquipmentId	Smoke Detection Panel	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	Sprinkler Alarm Control Board	
Installation Year	1966	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	99,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected Does not exist	
Display Monitor		
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Holding Area	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

icui Inspection	141072
uestion	Response
INTERCOM SYSTEM	
Holding Area	
Deficiency	No deficiencies recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<u>-</u>	
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Rooms 219, 133, 109
Deficiency Quantity	3
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room, Corridor near Room B9
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 106
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Model	N/A
Installation Year	1966
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 106
Deficiency Quantity	99,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
	Inspected
IPDVS/CCTV System	2- Between Good and Fair
Condition Installation Year	2012
Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2004
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO EMERGENCY POWER
•	SOURCE
Deficiency Quantity	1
Quantity Uom	EACH

Electrical Inspection		M1092
Question	Response	

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room B15
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room B15
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Photovoltaic System Disconnect Switch '89-L'
- *	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SERVICE SWITCH		
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Meter Room B15	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan Electric	
	Main SWBD	
EquipmentId Capacity/Size Quantity	1000	
Capacity/Size Quantity Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	Amps rotal	
	Section(s)	
Capacity/Size 2 UOM	. ,	
Source of Capacity/Size	Nameplate 1966	
Installation Year Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Meter Room B15	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Meter Room B15	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	MDP-2	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Switchboard Mains Size	
Installation Year	2013	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
	Inspected	
TELEPHONE SYSTEM		
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response
TRANSFORMER	
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	Solar Transformer
Capacity/Size Quantity	150
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded