Asset:	P.S./I.S. 210 - M	ANHATTAN, 501-503 WES	T 152 STREET	, MANHATTAN	NY, 10031		
Inspection				,	Time	In	Last Edited
	2765 ELECTRICAL				2024-	01-26 09:11AM	2024-06-17 11:17A
set Data							
Question				Answer			
Have any	Systems/Major Building (Components been upgraded?		Systems:	Retrofitted LI	ED Interior Lighti	ng
				Years:	2022		
				Systems:	Security Ligh	ting	
				Years:	2018, 2007		
				Systems:	Telephone Sy	stem	
				Years:	2018		
				Systems:		enerator Set Batte	ery Charger
				Years:	2014	-41 C4	1 C
				Systems: Years:	2007	ctrical Systems ar	ia Components
Type of S	ervice			Below Gr			
• •	ervice ractive Whiteboard (IWB)	Exist?		Yes			
	netration In Electrical Room			Yes			
DEDICA	ATED INTERCOMS I	N FIRE RESCUE AREAS					
Question					Response		
		nce Areas, Fire Rescue Areas, ar	nd/or Holding Roo	ms in	es es		
your bu		ble in all of these spaces for use of	luring a fire?		Yes		
	all dedicated intercoms op		iuring a fire?		es es		
		crationar.			.03		
<i>iority Co</i> xist		Condition	C	T4:	D(-)	D(-)	DL -4-
ast Year?	Priority Category	Description Description	Component Affected	Location Description	Person(s) Notified	()	Photo Image
o	Emergency Generator Components - Not Operational	Defective Fuel/Supply Delivery System	Emergency Generator	Roof - Emergency Generator Enclosure	Sylvester Wright	Fireman	
o	Water Penetration in	N/A	Electrical	Electrical	Sylvester	Fireman	
	Electrical Room		Equipment	Room B13	Wright		
o o	Lightning Protection - Defective	Lightning Protection Conductor Clamps are not properly attached in four areas throughout the roof.	Lightning Protection	Roof - Building Perimeter	Sylvester Wright	Fireman	
/es	Fire Alarm System - Components Not Operational	Not Operational	Fire Alarm System - Elevator Recall	Roof Elevator Machine Room	Sylvester Wright	Fireman	No Photo Taken
nspection	!						
Question				Response			
Electrica	1						
ATHLI	ETIC FIELD			Does not o	exist		
AUDITORIUM				Does not	exist		

Building Condition Assessment Survey 2023-2024

neu Inspection		14107
uestion	Response	
CAFETERIA		
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 2nd Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 2nd Floor	Inspected	
	2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Theater Lighting System	D	
Instance on 2nd Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?		
Lighting Fixture - Fluorescent	No	
	No Does not exist	
Lighting Fixture - HID	No Does not exist Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	No Does not exist Does not exist Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED	No Does not exist Does not exist Does not exist Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted	No Does not exist Does not exist Does not exist Inspected Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition	No Does not exist Does not exist Does not exist Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted	No Does not exist Does not exist Does not exist Inspected Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency COMPUTER LAB	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency Recessed Mounted Condition Deficiency COMPUTER LAB GYMNASIUM	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Does not exist Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency Recessed Mounted Condition Deficiency COMPUTER LAB GYMNASIUM Instance on Basement	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency Recessed Mounted Condition Deficiency COMPUTER LAB GYMNASIUM Instance on Basement Lighting	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Does not exist Inspected Inspected Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency Recessed Mounted Condition Deficiency Lighting Instance on Basement	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Does not exist Inspected	
Lighting Fixture - HID Lighting Fixture - Incandescent Lighting Fixture - LED Pendant Mounted Condition Deficiency Surface Mounted Condition Deficiency Recessed Mounted Condition Deficiency Recessed Mounted Condition Deficiency COMPUTER LAB GYMNASIUM Instance on Basement Lighting	No Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Does not exist Inspected Inspected Inspected	

Electrical Inspection	M093
Question	Response

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard	D	
Instance on Basement	Does not exist	
Theater Lighting System	Turnostod	
Instance on Basement	Inspected	
Dimming System	Y 4.1	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	

Electrical Inspection	M093

tem mapeenen		
uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 501	Inspected	
Lighting		
Instance on Room 501	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 501	Does not exist	
Lighting Fixture - HID		
Instance on Room 501	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 501	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 501	Inspected	
Pendant Mounted	Inspected	
Instance on Room 501	Does not exist	
Surface Mounted	Does not exist	
Instance on Room 501	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 501	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Raceway With Receptacles Instance on Room 501	Inspected	
Instance Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Projection System Instance on Room 501	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 510	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 510	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 510	Does not exist	
Lighting Fixture - HID		
Instance on Room 510	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 510	Does not exist	
Lighting Fixture - LED		

Electrical Inspection	M093
Question	Response

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - LED	
Instance on Room 510	Inspected
Pendant Mounted	
Instance on Room 510	Does not exist
Surface Mounted	
Instance on Room 510	Does not exist
Recessed Mounted	
Instance on Room 510	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 510	Does not exist
Projection System Instance on Room 510	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 510A Power Panel?	Inspected
	No .
Alternative Use	No
Lighting Instance on Room 510A	Inspected
Lighting Fixture - Fluorescent	inspected
Instance on Room 510A	Does not exist
Lighting Fixture - HID	DOCS HOT CAIST
Instance on Room 510A	Does not exist
Lighting Fixture - Incandescent	Does not east
Instance on Room 510A	Does not exist
Lighting Fixture - LED	2000 1100 4.1100
Instance on Room 510A	Inspected
Pendant Mounted	
Instance on Room 510A	Does not exist
Surface Mounted	
Instance on Room 510A	Does not exist
Recessed Mounted	
Instance on Room 510A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Room 510A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 510A	Does not exist
Power Supply	
Instance on Room 510A	Does not exist

Building Condition Assessment Survey 2023-2024

M093

Electrical Inspection

EquipmentId

Capacity/Size Quantity

Source of Capacity/Size

Capacity/Size UOM

Installation Year Source of Installation Year

Deficiency

Instance

Question	Response
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected

Beliefeliey	1 to deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Room B10	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metron Inc	
EquipmentId	Fire Pump Automatic Transfer Switch	
Capacity/Size Quantity	1500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Room R02	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	

70

Amps

Nameplate 2007

Documented

Room R02

No deficiencies recorded

Fire Alarm Automatic Transfer Switch

Building Condition Assessment Survey 2023-2024

em inspection	1120
estion	Response
MERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS 1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Room R03
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	
Manufacturer	EACH
	EACH Square D
EquipmentId	Square D N/A
Capacity/Size Quantity	Square D N/A 800
Capacity/Size Quantity Capacity/Size UOM	Square D N/A 800 Amps Total
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity	Square D N/A 800 Amps Total 1
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM	Square D N/A 800 Amps Total 1 Section(s)
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size	Square D N/A 800 Amps Total 1 Section(s) Nameplate
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year	Square D N/A 800 Amps Total I Section(s) Nameplate 2007 Documented
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Instance	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Condition	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Quantity	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Condition	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor 1 EACH
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Quantity	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor 1 EACH Caterpillar
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor 1 EACH Caterpillar Emergency Generator
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Instance Quantity Instance Quantity Uom Manufacturer EquipmentId Capacity/Size Quantity	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor 1 EACH Caterpillar Emergency Generator 312
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Source of Capacity/Size Installation Year Source of Installation Year Deficiency Molded Case Circuit Breaker Type Diesel Instance Instance Condition Instance Quantity Instance Quantity Uom Manufacturer EquipmentId	Square D N/A 800 Amps Total 1 Section(s) Nameplate 2007 Documented No deficiencies recorded Does not exist Inspected Roof - Emergency Generator Enclosure 4- Between Fair and Poor 1 EACH Caterpillar Emergency Generator

Building Condition Assessment Survey 2023-2024

ricui Inspection	1/103
euestion	Response
EMERGENCY GENERATOR SET	
Diesel	
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	866
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	DEFECTIVE FUEL SUPPLY/DELIVERY SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
•	
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

icui mspection		1/10/5
estion	Response	
FIRE ALARM SYSTEM		
Elevator Recall	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	DETECTOR NOT OPERATIONAL	
Deficiency Location/Instance	Roof - Elevator Machine Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Fire Pump Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Fire Alarm Communicator	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year Source of Installation Year	2007	
	Documented No deficiencies recorded	
Deficiency	Does not exist	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Printer Condition	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	

Building Condition Assessment Survey 2023-2024

icui inspection	1410/5
Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
	3- Fair
Condition	
Deficiency	LIGHTNING PROTECTION CONDUCTOR CLAMPS NOT PROPERLY ATTACHED
Deficiency Location/Instance	Roof - Building Perimeter
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 307
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
	Telecor II
Model	
Model Installation Year Source of Installation Year	2007 Documented

Building Condition Assessment Survey 2023-2024

uestion	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Location/Instance	Library, Science Prep Room 510A, by Rooms (306, 404)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	By Exit 2, Exterior Wall by Main Entrance
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B13
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MSB Main Brkr
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B13
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded