Building Condition Assessment Survey 2023-2024

EAST SIDE MIDDLE SCHOOL - MANHATTAN, 331 EAST 91 STREET, MANHATTAN, NY, 10128

Electrical Inspection

Asset:

Inspection	on Id Inspection Type				Time	In	Last Edited
	853 ELECTRICAL				2023-	11-09 08:59A	M 2023-11-09 02:04PM
lsset Data	a						
Questio	n			Answer			
Have an	y Systems/Major Buildin	g Components been upgrade	:d?	Systems:			LED Lighting),
				Years:	2021	ighting (Retrofi	(Itted)
				Systems:	All Other Ele	ctrical Systems	and Components
				Years:	2010	·	•
Type of	Service			Below Gr	ound		
	teractive Whiteboard (IW	B) Exist?		Yes			
Water Pe	enetration In Electrical Ro	oom?		No			
DEDIC	CATED INTERCOMS	S IN FIRE RESCUE AR	EAS				
Questio					Response		
		stance Areas, Fire Rescue Ar	eas, and/or Holding Roor	ns in	Yes		
	ouilding?	1 1 1 1 0 1 0	1				
	re all dedicated intercoms avai	lable in all of these spaces for	or use during a fire?		Yes Yes		
		operational?			ies		
Priority C							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
	lition recorded						
Inspectio	n						
Questio	n			Response	;		
Electric	cal						
ATHI	LETIC FIELD			Does not	exist		
	TORIUM			Does not	exist		
	ETERIA			Inspected			
CAFE	Instance on Baseme	nt		Inspected			
Liał	hting	IIt		mspected			
Ligi	Instance on Baseme	nt		Inspected			
Li	ghting Fixture - Fluores						
	Instance on Baseme			Does not	exist		
Li	ghting Fixture - HID						
	Instance on Baseme	nt		Does not	exist		
Li	ghting Fixture - Incande						
	Instance on Baseme			Does not	exist		
Li	ghting Fixture - LED						
	Instance on Baseme	nt		Inspected			
-	Pendant Mounted						
	Instance on Baseme	nt		Does not	exist		
5	Surface Mounted						
	Instance on Baseme	nt		Does not	exist		
]	Recessed Mounted						
	Instance on Baseme	nt		Inspected			
	Instance Condition			-	en Good and Fai	r	
	Deficiency			No deficio	encies recorded		
Loc	al Sound System						
	Instance on Baseme	nt		Inspected			
	Instance Condition			3- Fair			
	Instance Condition						
	Installation Year			2010			
		n Year			ted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
CAFETERIA	Response	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting	inspected	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		N1114
Question	Response	
GYMNASIUM		
Local Sound System		
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
	Inspected	
Instance on 3rd Floor - Girls, 3rd Floor - Boys		
Alternative Use	No	
	Turner et al	
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Does not exist	
Lighting Fixture - LED	· · ·	
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Inspected	
Pendant Mounted		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Does not exist	
Surface Mounted		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Does not exist	
Recessed Mounted		
Instance on 3rd Floor - Girls, 3rd Floor - Boys	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Dechenge	
uestion	Response	
Lighting		
Lighting Fixture - LED Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 421, 423	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms 421, 423	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 421, 423	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 421, 423	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 421, 423	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 421, 423	Inspected	
Pendant Mounted		
Instance on Rooms 421, 423	Does not exist	
Surface Mounted		
Instance on Rooms 421, 423	Does not exist	
Recessed Mounted		
Instance on Rooms 421, 423	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Rooms 421, 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 421, 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms 421, 423	Inspected	
Instructor Unit		
Instance on Rooms 421, 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 421, 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 421, 423	Does not exist	
Projection System		
Instance on Rooms 421, 423	Does not exist	
SCIENCE PREP ROOM	Inspected	

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Electrical Inspection

rical Inspection	D	M114
uestion	Response	
SCIENCE PREP ROOM		
Instance on Room 422	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 422	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 422	Does not exist	
Lighting Fixture - HID		
Instance on Room 422	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 422	Does not exist	
Lighting Fixture - LED		
Instance on Room 422	Inspected	
Pendant Mounted		
Instance on Room 422	Does not exist	
Surface Mounted		
Instance on Room 422	Does not exist	
Recessed Mounted		
Instance on Room 422	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Room 422	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 422	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 422	Does not exist	
SWIMMING POOL	Does not exist	
FOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection M114 Ouestion Response **TOILET ROOM - STUDENT** Lighting **Lighting Fixture - LED Recessed Mounted** Deficiency No deficiencies recorded Inspected AUXILIARY SIGNAL/BELL SYSTEM 3- Fair Condition Deficiency No deficiencies recorded Does not exist EMERGENCY DC STANDBY BATTERY POWER Inspected EMERGENCY GENERATOR SET Inspected Automatic Transfer Switch (ATS) ATS Room B05A Instance Instance Condition 2- Between Good and Fair Instance Quantity 1 EACH Instance Quantity Uom Kohler Power Systems Manufacturer Transfer Switch EquipmentId Capacity/Size Quantity 30 Capacity/Size UOM Amps Source of Capacity/Size Nameplate 2010 Installation Year Source of Installation Year Documented No deficiencies recorded Deficiency Room B13 Instance 2- Between Good and Fair Instance Condition Instance Quantity 1 Instance Quantity Uom EACH Firetrol Manufacturer Fire Pump Power Transfer Switch EquipmentId Capacity/Size Quantity 25 Capacity/Size UOM HP Source of Capacity/Size Nameplate 2010 Installation Year Source of Installation Year Documented Deficiency No deficiencies recorded Instance ATS Room B05A 2- Between Good and Fair Instance Condition Instance Quantity 1 EACH Instance Quantity Uom Kohler Power Systems Manufacturer EquipmentId Transfer Switch Capacity/Size Quantity 600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year 2010 Source of Installation Year Documented Deficiency No deficiencies recorded Inspected **Battery Charger** Room 601 Instance 2- Between Good and Fair Instance Condition Instance Quantity 1 EACH Instance Quantity Uom Kohler Power Systems Manufacturer Battery Charger EquipmentId Capacity/Size Quantity 10

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui In	spection		14111
uestion		Response	
EMERG	ENCY GENERATOR SET		
	Charger		
Buttery	Capacity/Size UOM	AmpsDC	
	Capacity/Size 2 Quantity	26	
	Capacity/Size 2 UOM	VDC	
	Source of Capacity/Size	Nameplate	
	Installation Year	2010	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Emerge	ency Distribution Board	Inspected	
Numb	ber of Spares	4	
Fused	Disconnect Switch Type	Inspected	
	Instance	ATS Room B05A	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	-
	Instance Quantity Uom	EACH	
	Manufacturer	Square D	
	EquipmentId	EMDB	
	Capacity/Size Quantity	600	
	Capacity/Size UOM	Amps Total	
	Capacity/Size 2 Quantity		
	Capacity/Size 2 UOM	Section(s)	
	Source of Capacity/Size	Nameplate	
	Installation Year	2010	-
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	ed Case Circuit Breaker Type	Does not exist	
Diesel		Inspected	
	Instance	Room 601	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Kohler Power Systems	
	EquipmentId	Emergency Generator	
	Capacity/Size Quantity	250	
	Capacity/Size UOM	kVA	
	Capacity/Size 2 Quantity	200	
	Capacity/Size 2 UOM	kW	
	Capacity/Size 3 Quantity	694	
	Capacity/Size 3 UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	2010	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Natura	l Gas	Does not exist	
EMERG	ENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERG	ENCY LIGHTING	Inspected	
Battery	Pack	Does not exist	
	ttery Pack	Inspected	
Condi	tion	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
EXIT LI	GHT	Inspected	
Battery	Pack	Inspected	
Condi		3- Fair	
	Deficiency	No deficiencies recorded	
Non Ro	ttery Pack	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response
EXIT LIGHT	
Non Battery Pack	
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
TIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Custodian's Office - Room B09
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Statewide Fire Corp
EquipmentId	Central Station Fire Alarm
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Vestibule

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui inspection		
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
AN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
IGHTNING PROTECTION	Does not exist	
AOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspection	IVIII.
uestion	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 522
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof
Deficiency Quantity	Roof 2
Quantity Uom	2 EACH
Ullantity Llom	EACH
Potential Action	REPLACE BALLAST

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion		Response
SECURITY		
Lighting - Secu	urity	
Purj	pose of Action	LEVEL 3
Viol	lations	No violations recorded
SERVICE SWIT	ГСН	Inspected
Instan		Electrical Meter Room B05B
	ace Condition	2- Between Good and Fair
	nce Quantity	1
	the Quantity Uom	EACH
	facturer	Square D
	pmentId	Fire Pump Disconnect
	city/Size Quantity	400
	city/Size UOM	Amps
	e of Capacity/Size	Nameplate
	lation Year	2010
Source	e of Installation Year	Documented
Defici	iency	No deficiencies recorded
Instan		Electrical Meter Room B05B
	nce Condition	2- Between Good and Fair
	nce Quantity	1
		EACH
	ace Quantity Uom	
	facturer	Square D
	mentId	N/A 800
	sity/Size Quantity sity/Size UOM	
	e of Capacity/Size	Amps Nameplate
	lation Year	2010
	e of Installation Year	Documented
Defici		No deficiencies recorded
Instan		Electrical Meter Room B05B
	nce Condition	2- Between Good and Fair
	ace Quantity	1 EACH
	ace Quantity Uom	
	facturer	Square D
1 1	mentId	N/A
	city/Size Quantity	1600
	city/Size UOM	Amps
-	e of Capacity/Size lation Year	Nameplate 2010
	ation Year e of Installation Year	Documented
		No deficiencies recorded
Defici		
Instan		Electrical Meter Room B05B
	nce Condition	2- Between Good and Fair
	ace Quantity	1
Instan	ace Quantity Uom	EACH
Manu	facturer	Square D
	omentId	HDB 5th Floor
	city/Size Quantity	4000
	city/Size UOM	Amps
	e of Capacity/Size	Nameplate
	lation Year	2010
	e of Installation Year	Documented
Defici	iency	No deficiencies recorded
SWITCHBOAR	RD	Inspected
Number of Spar	res	10

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	Inspected
Instance	Electrical Meter Room B05B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MDB-1, MDB-2
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room 523
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	HDB
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist

TRANSFORMER