#### **Building Condition Assessment Survey 2023-2024**

	Inspection	TATTAN 207 WEGT 177 G	TOFFT MANUL				Μ
Asset:		HATTAN, 586 WEST 177 S	TREET, MANHA	ATTAN, NY, 100		-	
Inspectio					Time		Last Edited
	2321 ELECTRICAL				2024-	01-10 09:05AM	[ 2024-02-07 01:27P]
sset Data	!						
Question	1			Answer			
Have any	v Systems/Major Building	Components been upgraded?		Systems:	Most Emerger		nce Lab Room 505), on Battery Pack)
				Years:	2016	505 T 1	
				Systems:		coom 505, Telep	hone System, LAN
				Years:	2015 Eused Discom	neet Switch Type	Panel Board
				Systems: Years:	2014, 1998	nect Switch Type	e Panel Board
				Systems:	Partial Moldee	d Case Circuit B	reaker Panel Board
				Years:	2014, 1995, 19	989	
				Systems:	Partial Securit	y Lighting	
				Years:	2013		
				Systems:	IPDVS/CCTV	' System	
				Years:	2010		
				Systems:	Fire Alarm Sy Sound System		dress System, Local
				Years:	2006		
				Systems:		Theater Lighting	)
				Years:	2003		
				Systems:	• •	ght/Exit Light P	anel
				Years:	1989		
Type of S				Below Gro	ound		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Roo	N FIRE RESCUE AREAS		Yes			
Ouestion				F	Response		
	ere any Life Rescue Assista uilding?	nnce Areas, Fire Rescue Areas, a	and/or Holding Roon		lo		
iority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
/es	Fire Alarm System - Not Connected to Central Station	NA	Fire Alarm System - Main Panel	Main Entrance Lobby	Nicolas Sanchez, Jr	Custodian	No Photo Taken
	Water Penetration in Electrical Room	Water dripping off from the above slab and Concrete wall	Electrical Equipment	Electrical Meter Room	Arthur Knight	Fireman	No Photo Taken
<i>les</i>		concrete wan					
	Emergency Lighting - Not Operational	NA	Emergency Lighting	Throughout the Building	Nicolas Sanchez, Jr	Custodian	No Photo Taken
lo	Not Operational			-		Custodian	No Photo Taken
Tes No <b>nspection</b> Question	Not Operational			-	Sanchez, Jr	Custodian	No Photo Taken
to nspection	Not Operational			the Building	Sanchez, Jr	Custodian	No Photo Taken
nspection Question Electrica	Not Operational			the Building	Sanchez, Jr	Custodian	No Photo Taken
o Ispection Question Electrica ATHL	Not Operational			the Building Response	Sanchez, Jr	Custodian	No Photo Taken
o Ispection Question Electrica ATHL	Not Operational n al ETIC FIELD	NA		the Building Response Does not c	Sanchez, Jr	Custodian	No Photo Taken
o Question Electrics ATHL AUDI	Not Operational	NA		the Building Response Does not e Inspected	Sanchez, Jr	Custodian	No Photo Taken
o Question Electrics ATHL AUDI	Not Operational	NA		the Building Response Does not e Inspected	Sanchez, Jr	Custodian	No Photo Taken
o Question Electrics ATHL AUDI	Not Operational	NA Floor Floor		the Building Response Does not e Inspected Inspected	Sanchez, Jr	Custodian	No Photo Taken

Lighting Fixture - HID

Instance on Lower 1st Floor

Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

Response	
Does not exist	
Inspected	
ľ	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
3- Fair	
2006	
Documented	
No deficiencies recorded	
Does not exist	
Inspected	
Does not exist	
Inspected	
Inspected	
Inspected	
Inspected	
Inspected	
Inspected	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
	Inspected Does not exist Inspected Does not exist Inspected Does not exist Does not exist Inspected Does not exist Does not exist Does not exist Does not exist Inspected Does not exist Inspected Does not exist Inspected Inspec

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	IVI1.
iestion	Response
CAFETERIA	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Local Sound System	
Instance on 1st Floor - Large	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Small	Does not exist
Projection System	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Theater Lighting System	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting Does a Chandelier Exist?	Inspected
	Yes
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist Does not exist

## **Building Condition Assessment Survey 2023-2024**

Response Does not exist

#### **Electrical Inspection**

GYMNASIUM

Question

GIMINASIOM	
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 313	Inspected
Lighting	
Instance on Room 313	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 313	Inspected
Pendant Mounted	
Instance on Room 313	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 313	Does not exist
Recessed Mounted	
Instance on Room 313	Does not exist
Lighting Fixture - HID	
Instance on Room 313	
	Does not exist
Lighting Fixture - Incandescent	Does not exist
	Does not exist Does not exist
Lighting Fixture - Incandescent Instance on Room 313	
Lighting Fixture - Incandescent	
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED Instance on Room 313	Does not exist
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED	Does not exist
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED Instance on Room 313 Raceway With Receptacles	Does not exist Does not exist
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED Instance on Room 313 Raceway With Receptacles Instance on Room 313	Does not exist Does not exist
Lighting Fixture - Incandescent         Instance on Room 313         Lighting Fixture - LED         Instance on Room 313         Raceway With Receptacles         Instance on Room 313         Projection System         Instance on Room 313	Does not exist Does not exist Does not exist
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED Instance on Room 313 Raceway With Receptacles Instance on Room 313 Projection System Instance on Room 313 LOCKER ROOM	Does not exist
Lighting Fixture - Incandescent Instance on Room 313 Lighting Fixture - LED Instance on Room 313 Raceway With Receptacles Instance on Room 313 Projection System Instance on Room 313 LOCKER ROOM	Does not exist Inspected
Lighting Fixture - Incandescent         Instance on Room 313         Lighting Fixture - LED         Instance on Room 313         Raceway With Receptacles         Instance on Room 313         Projection System         Instance on Room 313         LOCKER ROOM         MULTIPURPOSE ROOM         Instance on 1st Floor - Small	Does not exist Inspected Inspected Inspected
Lighting Fixture - Incandescent         Instance on Room 313         Lighting Fixture - LED         Instance on Room 313         Raceway With Receptacles         Instance on Room 313         Projection System         Instance on Room 313         LOCKER ROOM         MULTIPURPOSE ROOM         Instance on 1st Floor - Small         Instance on 1st Floor - Large	Does not exist Inspected
Lighting Fixture - Incandescent         Instance on Room 313         Lighting Fixture - LED         Instance on Room 313         Raceway With Receptacles         Instance on Room 313         Projection System         Instance on Room 313         Projection System         Instance on Room 313         LOCKER ROOM         MULTIPURPOSE ROOM         Instance on 1st Floor - Small         Instance on 1st Floor - Large         Lighting	Does not exist Inspected Inspected Inspected Inspected
Lighting Fixture - Incandescent         Instance on Room 313         Lighting Fixture - LED         Instance on Room 313         Raceway With Receptacles         Instance on Room 313         Projection System         Instance on Room 313         LOCKER ROOM         MULTIPURPOSE ROOM         Instance on 1st Floor - Small         Instance on 1st Floor - Large	Does not exist Inspected Inspected Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	IVII
Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Small	Inspected
Instance on 1st Floor - Large	Inspected
Pendant Mounted	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Surface Mounted	
Instance on 1st Floor - Small	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Large	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Local Sound System	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
Theater Lighting System	
Instance on 1st Floor - Small	Does not exist
Instance on 1st Floor - Large	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 505	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 505	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 505	Inspected
Pendant Mounted	
Instance on Room 505	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	IVIII
Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 505	Does not exist
Recessed Mounted	
Instance on Room 505	Does not exist
Lighting Fixture - HID	
Instance on Room 505	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 505	Does not exist
Lighting Fixture - LED	
Instance on Room 505	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 505	Does not exist
Emergency Shut-Off Power	
Instance on Room 505	Does not exist
Power Supply	
Instance on Room 505	Does not exist
Projection System	
Instance on Room 505	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

-	1411.
lestion	Response
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
	Inspected
Non Battery Pack Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Basement Floor Near Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
TRE ALARM SYSTEM	Inspected
	Inspected
Bell/Horn Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

-	14111
iestion	Response
FIRE ALARM SYSTEM	
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2006
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
ROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not exist
AN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
IGHTNING PROTECTION	Does not exist
AOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

<b>M</b> 1	15
1111	10

uestion	Response
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	5th Floor - Near Staircase 5, Room 503, 507, 513B. 4th Floor -
	Near Staircase 5, Room 413B. 3rd Floor - Near Staircase 5, Room
Deficiency Quantity	313, 307, 304, 2nd Floor, Staircase 5, Room 203
• - •	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 210
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	General Office - Room 210
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1990
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 210
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ical Inspection	N11
uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	4- Between Fair and Poor
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Exit - 3, 5, 6, 9, 10 & Main Entrance Lobby
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	Inspected
Lighting - Security	3- Fair
Condition	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Building Perimeter 8
Quantity Uom	o EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Courtyard
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
Manufacturer EquipmentId	Main Switch
Equipmentia Capacity/Size Quantity	1500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1966
Source of Installation Year	Documented

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

uestion	Response
SERVICE SWITCH	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Closet inside Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	N/A
Capacity/Size Quantity	1500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Closet inside Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist