Building Condition Assessment Survey 2023-2024

Electrical Inspection M117

Asset:	J.H.S. 117 - MANHATTAN, 240 EAST 109 STREET, MANHATTAN, NY, 10029		
Inspection Id	Inspection Type	Time In	Last Edited
2907	ELECTRICAL	2024-02-01 09:11AM	2024-06-17 11:27AM

2907 ELECTRICAL	2024-02-01 09:11AM 2024-06-17 11:27
t Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 2023, 2019, 2010, 2005, 1995
	Systems: Most Security Lighting
	Years: 2023, 2015
	Systems: Exit Lights (Battery Pack)
	Years: 2022, 2015
	Systems: Most Emergency Lighting (Battery Pack), Fire Alarm System (CO Detector)
	Years: 2022
	Systems: Intercom System (Holding Area), Variable Frequency Drive
	Years: 2021
	Systems: Emergency Lighting (Non Battery Pack)
	Years: 2020, 2015
	Systems: Gymnasium (LED Lighting), Public Address System (Most Clocks)
	Years: 2020
	Systems: Science Rooms W313, W315
	Years: 2018
	Systems: Interior Lighting Except (Gymnasium, Stairwells, West Side Basement Corridors, Toilet Rooms), LAN
	Years: 2015
	Systems: Telephone System, Intercom System (Elevator)
	Years: 2014
	Systems: Fire Alarm System
	Years: 2011
	Systems: Public Address System (Amplifier), Local Sound System, IPDVS/CCTV System
	Years: 2010
	Systems: Fluorescent Lighting (Stairwells, West Side Basement Corridors), Toilet Rooms
	Years: 2009
	Systems: Intrusion Alarm System, Public Address System, Emergency Light/Exit Light Panel
	Years: 1998
Type of Service	Below Ground

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Yes

No

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Emergency Shut-Off Power - Not Operational	N/A	Emergency Shut-Off Power	Science Lab - Room W315	Benie Singh	Fireman	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

M117

No	Intercom - Not	N/A	Intercom	Elevator -	Benie	Fireman
	Connected to Remote		System -	Device ID:	Singh	
	Monitoring Station		Elevator	1P33028		



•	11.51)	ection

spection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	1
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected

Building Condition Assessment Survey 2023-2024

nestion	Response
AUDITORIUM	
Local Sound System	
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	96
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	•
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	Does not exist
Instance on Basement	Does not exist
Recessed Mounted	DOGS HOT CAIST
Instance on Basement	Inspected
	2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
CAFETERIA		
Local Sound System		
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room W115	Inspected	
Power Panel?	No	
Instance on Room W310	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room W115	Inspected	
Instance on Room W310	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room W115	Inspected	
Instance on Room W310	Inspected	
Pendant Mounted	-	
Instance on Room W115	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room W310	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room W115	Does not exist	
Instance on Room W310	Does not exist	
Recessed Mounted		
Instance on Room W115	Does not exist	
momittee on record III 110	2 000 MOT VAIDE	

Building Condition Assessment Survey 2023-2024

Duestion	Response	
COMPUTER LAB	ксоронос	
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room W310	Does not exist	
Lighting Fixture - HID	2000 1000 0.1100	
Instance on Room W115	Does not exist	
Instance on Room W310	Does not exist	
Lighting Fixture - Incandescent	2000 1000 011100	
Instance on Room W115	Does not exist	
Instance on Room W310	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Room W115	Does not exist	
Instance on Room W310	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room W115	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W310		
Instance Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency		
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	

Deficiency Quantity

Building Condition Assessment Survey 2023-2024

trical Inspection	_	
Question	Response	
GYMNASIUM		
Scoreboard		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	

Does not exist

Inspected

Inspected

Inspected

Inspected

Does not exist

Does not exist

Does not exist

2- Between Good and Fair

No deficiencies recorded

Inspected

Lighting Fixture - LED

LIBRARY

Lighting

Instance on Basement

Instance on Room W204

Instance Condition Deficiency

Lighting Fixture - Fluorescent Instance on Room W204

Pendant Mounted

Surface Mounted

Recessed Mounted

Lighting Fixture - HID

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M117

uestion	Response	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room W301	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room W305	Inspected	-
Power Panel?	No	
Alternative Use	Yes	
Instance on Room W309	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Lighting		
Instance on Room W301	Inspected	
Instance on Room W305	Inspected	
Instance on Room W309	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room W301	Inspected	
Instance on Room W305	Inspected	
Instance on Room W309	Inspected	
Pendant Mounted		
Instance on Room W301	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room W305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room W309	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room W301	Does not exist	
Instance on Room W305	Does not exist	
Instance on Room W309	Does not exist	
Recessed Mounted		
Instance on Room W301	Does not exist	
Instance on Room W305	Does not exist	
Instance on Room W309	Does not exist	
Lighting Fixture - HID		
Instance on Room W301	Does not exist	
Instance on Room W305	Does not exist	
Instance on Room W309	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room W301	Does not exist	
Instance on Room W305	Does not exist	
Instance on Room W309	Does not exist	
Lighting Fixture - LED		
Instance on Room W301	Does not exist	
Instance on Room W305	Does not exist	
Instance on Room W309	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room W301	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

M117

Response	
Does not exist	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
No	
Yes	
Inspected	
Yes	
No	
Inspected	
	Does not exist Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Inspected Inspected No Yes Inspected Yes No

Yes

No

Lighting	
Instance on Room W205	Inspected
Instance on Room W209	Inspected
Instance on Room W315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room W205	Inspected
Instance on Room W200	Inspected

Electrical Inspection

Power Panel?

Alternative Use

Instance on Room W315

Instance Condition

Instance on Room w 209	Inspected
Instance on Room W315	Inspected
Pendant Mounted	

Instance on Room W205	Does not exist
Instance on Room W209	Does not exist
Instance on Room W315	Does not exist

Surface Mounted	
Instance on Room W205	Does not exist
Instance on Room W209	Does not exist
Instance on Room W315	Does not exist

ecessed Mounted	
Instance on Room W205	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room W209	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Inspected

2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M117

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room W205	Does not exist
Instance on Room W209	Does not exist
Instance on Room W315	Does not exist
Lighting Fixture - Incandescent	
Instance on Room W205	Does not exist
Instance on Room W209	Does not exist
Instance on Room W315	Does not exist
Lighting Fixture - LED	
Instance on Room W205	Does not exist
Instance on Room W209	Does not exist
Instance on Room W315	Inspected
Pendant Mounted	
Instance on Room W315	Does not exist
Surface Mounted	
Instance on Room W315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room W315	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room W205	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W209	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W315	Does not exist
Emergency Shut-Off Power	
Instance on Room W205	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W209	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W315	Inspected
Instance Condition	5- Poor
Deficiency Deficiency Quantity	NOT OPERATIONAL
Quantity Uom	1 EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Power Supply	
Instance on Room W205	Inspected
Instance on Room W209	Inspected
Instance on Room W315	Inspected
Instructor Unit	

Building Condition Assessment Survey 2023-2024

Question	Response	
·	response	
SCIENCE LAB		
Power Supply Instructor Unit		
Instructor Unit Instance on Room W205	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W209	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W315	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit	No deficiencies recorded	
Instance on Room W205	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W209	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W315	Does not exist	
Student Unit	Does not exist	
Instance on Room W205	Does not exist	
Instance on Room W209	Does not exist	
Instance on Room W315	Does not exist	
Projection System	Does not come.	
Instance on Room W205	Does not exist	
Instance on Room W209	Does not exist	
Instance on Room W315	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room W207	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room W313	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Room W207	Inspected	
Instance on Room W313	Inspected	
Lighting Fixture - Fluorescent	ı	
Instance on Room W207	Inspected	
Instance on Room W313	Inspected	
Pendant Mounted	1	

Does not exist

Does not exist

Does not exist

Inspected

2- Between Good and Fair

2- Between Good and Fair

No deficiencies recorded

No deficiencies recorded

Inspected

Instance on Room W207

Instance on Room W313

Instance on Room W207

Instance on Room W313

Instance on Room W207

Instance Condition
Deficiency

Instance Condition

Deficiency

Surface Mounted

Recessed Mounted

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M117
•	

iricui Inspection		171117
Question	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room W313	Does not exist	
Lighting Fixture - HID		
Instance on Room W207	Does not exist	
Instance on Room W313	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room W207	Does not exist	
Instance on Room W313	Does not exist	
Lighting Fixture - LED		
Instance on Room W207	Does not exist	
Instance on Room W313	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room W207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W313	Does not exist	
Emergency Shut-Off Power		
Instance on Room W207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room W313	Does not exist	
Power Supply		
Instance on Room W207	Does not exist	
Instance on Room W313	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
TOILET ROOM - STAFF	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist Does not exist	
TOILET ROOM - STUDENT	Inspected Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Pendant Mounted	Inspected	
Surface Mounted Condition	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

near inspection	IVIII
uestion	Response
AUXILIARY SIGNAL/BELL SYSTEM	
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room E-B6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room E-B6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	New Fitness Room (Inside Gymnasium)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected

Building Condition Assessment Survey 2023-2024

		VIII
estion	Response	
TRE ALARM SYSTEM		
Fan Shutdown Control		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	_
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	_
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	_
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	_
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	_
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	_
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	_
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	_
Sprinkler Flow/Air Pressure Switch	Inspected	_
Condition	2- Between Good and Fair	_
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

aricai Inspection	IVIII /
Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
	Inspected
Elevator Condition	2- Between Good and Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device ID: 1P33028
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Variable Frequency Drive Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms (W104, W310)
Deficiency Location/instance Deficiency Quantity	2
Quantity Uom	EACH
Quantity Com Potential Action	
rotential Action	REPLACE PANEL BOARD

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	By Room E-B17, Science Demo - Room W301
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Rooms (W-B5, 2nd Floor), Electrical Room E-B6
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room W108
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	1998
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	By Room E-B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	General Office - Room W108
Deficiency Quantity	1 FACH
Quantity Uom	EACH PERMACE
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

uestion	Response
SECURITY	
IPDVS/CCTV System	
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	1st Floor - Main Entrance (C1/26)
Quantity Uom	1 EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room W102
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security Condition	Inspected 2- Between Good and Fair
	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	Canopy Facing 2nd Avenue
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room E-B6
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pringle
Manufacturer EquipmentId	SERV. A
EquipmentId Capacity/Size Quantity	1600
Capacity/Size Quantity Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1958

Building Condition Assessment Survey 2023-2024

real Inspection		171117
euestion	Response	
SERVICE SWITCH		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room E-B6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room E-B6	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Pringle	
EquipmentId	SERV. B	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room E-B6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Inspected	
Instance	Electrical Room E-B6	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Cole	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency		
Deficiency Location/Instance	BEYOND USEFUL LIFE	
	BEYOND USEFUL LIFE Electrical Room E-B6	
Deficiency Quantity		
	Electrical Room E-B6	
Deficiency Quantity	Electrical Room E-B6	
Deficiency Quantity Quantity Uom Potential Action	Electrical Room E-B6 1 EACH	
Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Electrical Room E-B6 1 EACH REPLACE	
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	Electrical Room E-B6 1 EACH REPLACE PRIORITY 1 LEVEL 2	
Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Electrical Room E-B6 1 EACH REPLACE PRIORITY 1	

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Knife Switch Type	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cole
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room E-B6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist