## **Building Condition Assessment Survey 2023-2024**

	P.S. 38 (OLD M1						
Inspection 1					Time 1		Last Edited
	651 ELECTRICAL				2023-	11-01 09:12A	M 2024-04-15 03:42P
set Data							
Question				Answer	Y 437		
Have any S	Systems/Major Building C	Components been upgraded?		Systems:	LAN		
				Years:	2023	C Ciit D	l. Dl
				Systems: Years:	2020, 2013, 20		Greaker Panel Board
				Systems:	Intrusion Alar		10, 1993
				Years:	2020	iii systeiii	
				Systems:		ng Most Eme	rgency Lighting (Non
				Systems.	_	, Exit Lights (E	
				Years:	2017		
				Systems:			stem, Projection System,
				<b>V</b> 7	Theater Lighti	ing System)	
				Years: Systems:	2015 Fire Alarm Sv	etam Dublic A	ddress System, Local
				Systems:			Fused Disconnect Switch
						oard, Security I	
				Years:	2006	-	
				Systems:	Emergency Li	ght/Exit Light	Panel
				Years:	1995		
Type of Ser				Below Gro	ound		
	active Whiteboard (IWB)			Yes			
Water Penet							
DEDICAT Question		n? N FIRE RESCUE AREAS nce Areas, Fire Rescue Areas, a	nd/or Holding Room		Response		
Question Are there your build	TED INTERCOMS II any Life Rescue Assistations?	N FIRE RESCUE AREAS	nd/or Holding Room	F			
DEDICAT Question Are there your build	rED INTERCOMS II any Life Rescue Assistanting? adition	N FIRE RESCUE AREAS nce Areas, Fire Rescue Areas, and		ms in N	No	Person(s)	Photo
Question Are there your build ciority Conditions:	TED INTERCOMS II any Life Rescue Assistations?	N FIRE RESCUE AREAS	nd/or Holding Roon  Component  Affected	F		Person(s) Title	Photo Image
Question Are there your build ciority Consists ast Year?	reany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition	Component	ms in N	Person(s)	` '	
Question Are there your build ciority Constant Last Year?	reany Life Rescue Assistanding?  addition  Priority  Category	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description	Component Affected Lighting	ms in N  Location Description  Staircase KL -	Person(s) Notified Nathanael	Title	Image
Question Are there your build ciority Conditional Year?	rany Life Rescue Assistanding?  adition  Priority Category  Water Leaks onto Electrical Equipment	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture	Location Description Staircase KL - Bulkhead 1	Person(s) Notified Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build ciority Conditional Year?	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical	Person(s) Notified Nathanael Soto Nathanael	Title Fireman	Image No Photo Taken
Question Are there your build iterity Conditional iterity Conditio	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iterative Constitute Cons	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iterity Constitution in the constitu	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iterity Constitution in the constitu	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build it in it is in it	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iority Conditional Year?  Yes Year?  Yes Year  Yes Year  Asspection Question Electrical ATHLET AUDITO	rany Life Rescue Assistanding?  addition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room  Response	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iority Conditional Year?  Yes Year?  Yes Year  Yes Year  Asspection Question Electrical ATHLET AUDITO	any Life Rescue Assistant ding?  Indition  Priority Category  Water Leaks onto Electrical Equipment  Water Penetration in Electrical Room  FIC FIELD  DRIUM Instance on 1st Floor	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room  Response	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iority Conditional Year?  Yes Year?  Yes Year  Yes Year  Asspection Question Electrical ATHLET AUDITO	any Life Rescue Assistant ding?  Indition  Priority Category  Water Leaks onto Electrical Equipment  Water Penetration in Electrical Room  FIC FIELD  DRIUM  Instance on 1st Floor  Lighting	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition  Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room  Response  Does not e Inspected Inspected	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
Question Are there your build iterity Constitute Consti	any Life Rescue Assistant ding?  Indition  Priority Category Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  ORIUM Instance on 1st Floor  Lighting Instance on 1st Floor	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response  Does not e Inspected Inspected	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition Exist  Asst Year?  The second of the second	rany Life Rescue Assistanding?  Indition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  ORIUM Instance on 1st Floor Lighting Instance on 1st Floor Does a Chandelier Existing Fixture - Fluoresceit Instance on 1st Floor	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response  Does not e Inspected Inspected	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition Exist  Asst Year?  The second of the second	any Life Rescue Assistant ding?  Indition  Priority Category  Water Leaks onto Electrical Equipment  Water Penetration in Electrical Room  FIC FIELD  DRIUM Instance on 1st Floor Lighting Instance on 1st Floor Does a Chandelier Existing Fixture - Fluorescer Instance on 1st Floor Instance on 1st Floor Instance on 1st Floor	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room  Response  Does not e Inspected Inspected No Inspected	Person(s) Notified Nathanael Soto Nathanael Soto	Title Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition Exist  Asst Year?  The second of the second	any Life Rescue Assistanting?  Indition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  ORIUM Instance on 1st Floor Does a Chandelier Existing Fixture - Fluorescer Instance on 1st Floor Indant Mounted Instance on 1st Floor	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room  Response  Does not et al. Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected	Person(s) Notified  Nathanael Soto  Nathanael Soto	Title Fireman Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition Exist  Asst Year?  The second of the second	any Life Rescue Assistanting?  Indition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  ORIUM Instance on 1st Floor Does a Chandelier Existing Fixture - Fluorescer Instance on 1st Floor Instance Onlist Floor Instance Onlist Floor Instance Condition	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response  Does not e Inspected Inspected No Inspected Inspected 2- Betwee	Person(s) Notified Nathanael Soto Nathanael Soto exist	Title Fireman Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition East Year?  The second of the	rany Life Rescue Assistanding?  Idition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  DRIUM Instance on 1st Floor Lighting Instance on 1st Floor Does a Chandelier Existing Fixture - Fluorescert Instance on 1st Floor Instance on 1st Floor Instance On 1st Floor Instance On 1st Floor Instance Condition Deficiency	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response  Does not e Inspected Inspected No Inspected Inspected 2- Betwee	Person(s) Notified  Nathanael Soto  Nathanael Soto	Title Fireman Fireman	Image No Photo Taken
DEDICAT Question Are there your build ciority Condition East Year?  The second of the	any Life Rescue Assistanting?  Indition  Priority Category  Water Leaks onto Electrical Equipment Water Penetration in Electrical Room  FIC FIELD  ORIUM Instance on 1st Floor Does a Chandelier Existing Fixture - Fluorescer Instance on 1st Floor Instance Onlist Floor Instance Onlist Floor Instance Condition	N FIRE RESCUE AREAS  nce Areas, Fire Rescue Areas, and  Condition Description  Roof Leak  N/A	Component Affected Lighting Fixture Electrical	Location Description Staircase KL - Bulkhead 1 Electrical Room Response  Does not e Inspected Inspected No Inspected Inspected 2- Betwee	Person(s) Notified Nathanael Soto Nathanael Soto exist	Title Fireman Fireman	Image No Photo Taken

## **Building Condition Assessment Survey 2023-2024**

ricai Inspection		W1121
Question	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

ancui Inspection		171121
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	W1121

cont inspection		
estion	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
AITCHEN	Inspected	
Instance on 1st Floor	Inspected	
	nispected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	T 1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
JBRARY	Inspected	
Instance on Room 510	Inspected	
	nispected	
Lighting Instance on Room 510	Inspected	
	nispected	
Lighting Fixture - Fluorescent	Y 1	
Instance on Room 510	Inspected	
Pendant Mounted		
Instance on Room 510	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 510	Does not exist	
Recessed Mounted		
Instance on Room 510	Does not exist	
Instance on Room 510 Lighting Fixture - HID	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

incui inspection	141121
Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 510	Does not exist
Lighting Fixture - LED	
Instance on Room 510	Does not exist
Raceway With Receptacles	
Instance on Room 510	Does not exist
Projection System	
Instance on Room 510	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected  Does not exist
Pendant Mounted	Inspected
Surface Mounted	2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist  Does not exist
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

iricai Inspection	1)	V1121
Question	Response	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
•		
EXIT LIGHT	Inspected	
Battery Pack	Inspected  2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Area Smoke Detector Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
CO Detector		
Heat Detector	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency		
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	AFP - 300	

## **Building Condition Assessment Survey 2023-2024**

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)  Condition	Inspected 1- Good
Deficiency	No deficiencies recorded
	Inspected
Main Equipment Rack (MDF)  Condition	1- Good
	No deficiencies recorded
Deficiency	
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen, Basement Mechanical Room
Deficiency Quantity	3 EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
1 Otolital Action	NEI EACE-OI GRADE

## **Building Condition Assessment Survey 2023-2024**

incui Inspection	171121
Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Basement Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Basement Mechanical Room
Deficiency Quantity	Í
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 133
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Model	Dukane 250
Installation Year	2006
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Closet in General Office - Room 133
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2020
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	35654985Y
ERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Standard Switchboard
Manufacturer	Service A
EquipmentId Capacity/Size Quantity	600
Capacity/Size UOM	
Source of Capacity/Size	Amps Nameplate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	Service B
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 1953
Installation Year	
Source of Installation Year	Documented  PEYOND LISEFUL LIFE
Deficiency Location/Instance	BEYOND USEFUL LIFE
Deficiency Quantity	Electrical Room
Deficiency Quantity	1 EACH
Quantity Uom	EACH DEDLAGE
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

1	
uestion	Response
SERVICE SWITCH	
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Switchboard A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Switchboard B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist