### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:		MANHATTAN, 40 DIVIS	ION SIKEEI, N	IANHAI IAN, N	1,10002		
Inspectio	n Id Inspection Type				Time	In	Last Edited
	2402 ELECTRICAL				2024-	-01-11 09:09A	M 2024-01-30 09:56AN
sset Data							
Question	l			Answer			
Have any	Systems/Major Building	Components been upgraded?		Systems:	Telephone Sy	stem	
				Years:	2018		
				Systems:	Recessed Flue and Kitchen)		ior Lighting (Except Floor - Student Cafeteria
				Years:	2016	10 0 10	
				Systems:			Breaker Type Panel Board
				Years:	2014, 2012, 2	.003	
				Systems:	LAN		
				Years:	2012		
				Systems:	Fire Alarm Sy	stem	
				Years: Systems:	2009 Auditorium (1	ocal Sound C-	(stem)
				2		Local Sound Sy	scilly
				Years: Systems:	2007 Public Addres	ss System (Amp	lifier)
				Years:	2005	ss system (Amj	since)
				Systems:	Recessed Flue		ng (Kitchen, Student
				Years:	2002	rtial Security L	
				Systems:	Panel, Partial		ergency Light/Exit Light
				Years:	1994		
Type of S		<b>T</b> 1 10		Below Gr	ound		
	eractive Whiteboard (IWB)			Yes No			
	netration In Electrical Room	N FIRE RESCUE AREAS		INO			
Question		N FIKE RESCUE AREAS			Response		
-		nce Areas, Fire Rescue Areas, a	and/or Holding Room		Yes		
your bu	-	, , ,	8				
		ble in all of these spaces for use	e during a fire?		No		
Wh	ich spaces do not have ded	licated intercoms?		]	Rooms 104, 204	, 304	
riority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	Foundation Wall Leak affecting a Wall Outlet	Wall Outlet	Auditorium - Stage	Arthur Ng	Fireman	
nspection	1						
Question	1			Response			
Electrica	ગ						
ATHL	ETIC FIELD			Does not	exist		
AUDITORIUM			Inspected				
	Instance on 1st Floor			Inspected			
				mspected			

**Lighting Fixture - Fluorescent** 

Instance on 1st Floor

Instance on 1st Floor

Does a Chandelier Exist?

House Lighting

Inspected

Inspected

No



# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

stion	Response
JDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 35
Quantity Uom	EACH
Potential Action	<b>REPLACE-UPGRADE</b>
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AFETERIA	Inspected
Instance on 1st Floor - Student	Inspected
Instance on 1st Floor - Staff	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

AL

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

•	
uestion	Response
CAFETERIA	
Theater Lighting System	
Instance on 1st Floor - Student	Does not exist
Instance on 1st Floor - Staff	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	Inspected Does not exist
Pendant Mounted	
Surface Mounted	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ricai Inspection	MII
uestion	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1976
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
ATCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 214	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

neui Inspeciion		11112
Question	Response	
LIBRARY		
Lighting		
Instance on Room 214	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 214	Inspected	
Pendant Mounted		
Instance on Room 214	Does not exist	
Surface Mounted		
Instance on Room 214	Does not exist	
Recessed Mounted		
Instance on Room 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 214	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 214	Does not exist	
Lighting Fixture - LED		
Instance on Room 214	Does not exist	
Raceway With Receptacles		
Instance on Room 214	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 214	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
	Does not exist	
SWIMMING POOL		
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

nui inspeciion	14112
uestion	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected 3- Fair
Condition	No deficiencies recorded
Deficiency	
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Cafeteria, by Rooms (128, 337)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fan Shutdown Control	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector Condition	Inspected 2- Between Good and Fair

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

*		19112
iestion	Response	
FIRE ALARM SYSTEM		
Heat Detector		
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Faraday	
Model	MPC - 7000	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
VTERCOM SYSTEM	Inspected	
	Inspected	
Elevator Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
AN	Inspected Inspected	
Local Distribution Frame (I/LDF)	Inspected	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

ical Inspection	MII.
uestion	Response
LAN	
Local Distribution Frame (I/LDF)	
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Federal Pacific Electric
EquipmentId	N/A 200
Capacity/Size Quantity Capacity/Size UOM	
Capacity/Size 000M Capacity/Size 2 Quantity	Amps 2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1976
Source of Installation Year	Documented
Deficiency	MCC PUSH BUTTON NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
ANEL BOARD	Inspected
	Inspected
Fused Disconnect Switch Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE Poiler Poom Chiller Poom C20, Poiler Poom Machanical
Deficiency Location/Instance	Boiler Room - Chiller Room C20, Boiler Room, Mechanical Room 208
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

uestion	Response
PANEL BOARD	
Fused Toggle Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchgear Room C5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 251
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchgear Room C5, by Electrical Switchgear Room C5, Cafeteria, by Rooms (104, 107, 128), by Mechanical Room 208, Room 251
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance Deficiency Quantity	By Room 124
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Nurse's Office - Room 100A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
-	
Model	Biamp Advantage 301 1976
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Nurse's Office - Room 100A
Deficiency Quantity	93,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

estion	Response
ECURITY	
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 101B (Inside General Office)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1994
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 101B (Inside General Office)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inaccessible
Lighting - Security	
ERVICE SWITCH	Inspected
Instance	Electrical Switchgear Room C5 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	SWDB #1 Via Transf. #1
Capacity/Size Quantity	1200
Capacity/Size UOM Source of Capacity/Size	Amps
Installation Year	Nameplate 1976
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	Electrical Switchgear Room C5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

uestion	Desponse	
uestion	Response	
SERVICE SWITCH		
Violations	No violations recorded	
Instance	Electrical Switchgear Room C5	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	SWDB #2 Via Transf. #2	
Capacity/Size Quantity Capacity/Size UOM	1600	
Source of Capacity/Size	Amps Nameplate	
Installation Year	1976	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Switchgear Room C5	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Switchgear Room C5	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Disc. Sw. SWBD #1	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	4	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year Source of Installation Year	1976 Documented	
	BEYOND USEFUL LIFE	
Deficiency Deficiency Location/Instance	Electrical Switchgear Room C5	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Switchgear Room C5	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Disc. Sw. SWBD #2	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Installation Year	1976
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchgear Room C5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	Electrical Switchgear Room C5
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Emergency Lighting Transformer
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room C5
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
	Federal Pacific
Manufacturer	N/A
EquipmentId	750
Capacity/Size Quantity Capacity/Size UOM	
Source of Capacity/Size	kVA Nameplate
Installation Year	1976
Source of Installation Year	Documented
	BEYOND USEFUL LIFE
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Electrical Switchgear Room C5
	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded