# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection M131

Asset:	I.S. 131 - MANHATTAN, 100 HESTER STREET, MA	HIIIAI IAII, III, 1000		
Inspection Id	Inspection Type		Time In	Last Edited
	ELECTRICAL		2024-01-17 07:15PM	2024-02-13 07:57A
et Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	CCTV/IPDVS System	
		Years:	2023	
		Systems:	LAN	
		Years:	2022	
		Systems:	Most Exit Lights (Battery Pack)	
		Years:	2021, 2016	
		Systems:	Retrofitted Interior Fluorescent I Auditorium, Locker Rooms, Cor 102), Retrofitted LED Lighting ( Cafeteria), LED Lighting (1st Fl- Emergency Lighting (Battery Pa System (Clocks)	nputer Lab - Room Gymnasium, South oor Lobby), Most
		Years:	2021	
		Systems:	Partial Lighting - Security, North Lighting)	n Cafeteria (LED
		Years:	2020	
		Systems:	Gymnasium (Scoreboard)	
		Years:	2019	
		Systems:	Auditorium (Fluorescent Lightin Lighting), Local Sound System ( Gymnasium)	
		Years:	2016	
		Systems:	Computer Lab - Room 102 (Fluo	prescent Lighting)
		Years:	2015	
		Systems:	Locker Rooms (Fluorescent Ligh	nting)
		Years:	2012	
		Systems:	Fire Alarm System	
		Years:	2009	
		Systems:	Library (Incandescent Lighting)	
		Years:	2005	
		Systems:	Intrusion Alarm System	
		Years:	2003	
		Systems:	Switch Type Panel Board	used Disconnect
		Years:	2000, 1983	
		Systems:	All Other Electrical Systems and	Components
		Years:	1983	
Type of Service		Below Gr	ound	
	e Whiteboard (IWB) Exist?	Yes		
	on In Electrical Room?  D INTERCOMS IN FIRE RESCUE AREAS	No		

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

### **Priority Condition**

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Leaks onto Electrical Equipment	Water Leak from above slab directly upon Lighting Fixtures	Lighting Fixture	Basement Staircase - F, Boys Locker Room, Room 327	Angelo Rodriguez	Fireman	No Photo Taken

## **Building Condition Assessment Survey 2023-2024**

Question	Response
lectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	2000 100 01100
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Local Sound System	ivo deficiencies recorded
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	1983
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
·	
Deficiency Location/Instance Deficiency Quantity	Auditorium-1st Floor 1
Quantity Uom	I EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	

## **Building Condition Assessment Survey 2023-2024**

arica inspection	W113
Question	Response
AUDITORIUM	
Projection System	5 D
Instance Condition	5- Poor Ceiling
Is the projector on a cart or installed on the ceiling?  Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	VIDEO PROJECTOR IS NOT OPERATIONAL  1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	•
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	160
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Lighting	•
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Lighting Fixture - Fluorescent	-
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Lighting Fixture - LED	2000 100 01100
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - North	Inspected
Pendant Mounted	mspeccu
Instance on 1st Floor - North	Inchected
	Inspected 1- Good
Instance Condition	
Deficiency	No deficiencies recorded

### **Building Condition Assessment Survey 2023-2024**

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - North	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Tio delicibiles recorded
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - North  Instance on 1st Floor - South	Does not exist  Does not exist
	Dues not exist
Local Sound System  Instance on 1st Floor - North	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance on 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Theater Lighting System	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected

## **Building Condition Assessment Survey 2023-2024**

stion	Response
_ASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	55 EL GY
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
OMPUTER LAB	Inspected
Instance on Room 102	Inspected
<u> </u>	
Power Panel?	No
Instance on Room 131	Inspected
Power Panel?	No
Lighting	
Instance on Room 102	Inspected
Instance on Room 131	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 102	Inspected
Instance on Room 131	Inspected
Pendant Mounted	
Instance on Room 102	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 131	Does not exist
Surface Mounted	Does not onto
Instance on Room 102	Does not exist
Instance on Room 131	Does not exist
Recessed Mounted	
Instance on Room 102	Does not exist
Instance on Room 131	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 102	Does not exist

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	M131

		14113
uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - HID		
Instance on Room 131	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 102	Does not exist	
Instance on Room 131	Does not exist	
Lighting Fixture - LED		
Instance on Room 102	Does not exist	
Instance on Room 131	Does not exist	
Raceway With Receptacles		
Instance on Room 102	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 131	Does not exist	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on Basement	Does not exist	
Lighting Fixture - HID	DOGS HOT CAIST	
Instance on Basement	Does not exist	
	DOCS HOT CAIST	
Lighting Fixture - Incandescent  Instance on Basement	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on Basement	Inspected	
Pendant Mounted	nispected	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2016	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on Basement	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor - North	Inspected	
Instance on 1st Floor - South	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	M131

icui Inspection		
estion	Response	
KITCHEN		
Lighting		
Instance on 1st Floor - South	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - North	Inspected	
Instance on 1st Floor - South	Inspected	
Pendant Mounted	-	
Instance on 1st Floor - North	Does not exist	
Instance on 1st Floor - South	Does not exist	
Surface Mounted		
Instance on 1st Floor - North	Does not exist	
Instance on 1st Floor - South	Does not exist	
Recessed Mounted		
Instance on 1st Floor - North	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - South	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor - North	Does not exist	
Instance on 1st Floor - South	Does not exist	
	DOCS HOT CAIST	
Lighting Fixture - Incandescent  Instance on 1st Floor - North	Does not exist	
Instance on 1st Floor - North	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on 1st Floor - North	Does not exist	
Instance on 1st Floor - South	Does not exist	
LIBRARY	Inspected	
Instance on Room 224	Inspected	
Lighting		
Instance on Room 224	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 224	Inspected	
Pendant Mounted		
Instance on Room 224	Does not exist	
Surface Mounted		
Instance on Room 224	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 224	Does not exist	
Lighting Fixture - HID		
Instance on Room 224	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 224	Inspected	
Pendant Mounted		
Instance on Room 224	Does not exist	
Surface Mounted		
Instance on Room 224	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		

## **Building Condition Assessment Survey 2023-2024**

<b>F</b>		
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Incandescent		
Recessed Mounted		
Instance on Room 224	Does not exist	
Lighting Fixture - LED		
Instance on Room 224	Does not exist	
Raceway With Receptacles		
Instance on Room 224	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 224	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Surface Mounted		
Instance on Basement - Boys, Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
	Inspected	
SCIENCE LAB Instance on Room 410	Inspected	
Power Panel?		
	Yes	
Alternative Use	Yes	
Instance on Room 408, 414, 429	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 433, 434, 440, 444	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 410	Inspected	
Instance on Room 408, 414, 429	Inspected	
Instance on Room 433, 434, 440, 444	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 410	Inspected	
Instance on Room 408, 414, 429	Inspected	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 433, 434, 440, 444	Inspected	
Pendant Mounted		
Instance on Room 410	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 408, 414, 429	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 433, 434, 440, 444	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 410	Does not exist	
Instance on Room 408, 414, 429	Does not exist	
Instance on Room 433, 434, 440, 444	Does not exist	
Recessed Mounted		
Instance on Room 410	Does not exist	
Instance on Room 408, 414, 429	Does not exist	
Instance on Room 433, 434, 440, 444	Does not exist	
Lighting Fixture - HID		
Instance on Room 410	Does not exist	
Instance on Room 408, 414, 429	Does not exist	
Instance on Room 433, 434, 440, 444	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 410	Does not exist	
Instance on Room 408, 414, 429	Does not exist	
Instance on Room 433, 434, 440, 444	Does not exist	
Lighting Fixture - LED		

Instance on Room 433, 434, 440, 444	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 410	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 408, 414, 429	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 433, 434, 440, 444	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	

Does not exist

Inspected

Instance on Room 410

Instance on Room 410

Instance on Room 410

Instance on Room 410

Power Supply

**Projection System** 

Instance on Room 408, 414, 429

Instance on Room 408, 414, 429

Instance on Room 433, 434, 440, 444

Instance on Room 433, 434, 440, 444

Instance on Room 408, 414, 429

## **Building Condition Assessment Survey 2023-2024**

aricai Inspection		WIISI
Question	Response	
SCIENCE LAB		
Projection System		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 408, 414, 429	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 433, 434, 440, 444	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Inspected	
Power Panel?	No	
Alternative Use		
	No	
Lighting	Inspected	
	nispected	
Lighting Fixture - Fluorescent  Instance on Room 408/410/414A, 429/433A/434, 440/444A	Inspected	
Pendant Mounted	nispected	
	Inchested	
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Inspected  2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted	D	
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Recessed Mounted		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Lighting Fixture - HID		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Lighting Fixture - LED		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Emergency Shut-Off Power		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
Power Supply 400/410/4144 420/4224 440/4444		
Instance on Room 408/410/414A, 429/433A/434, 440/444A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	

## **Building Condition Assessment Survey 2023-2024**

icai inspection		WIIJ
uestion	Response	
FOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		-
Deficiency	No deficiencies recorded	-
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	-
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
FIRE ALARM SYSTEM		
Heat Detector		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected  2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	

## **Building Condition Assessment Survey 2023-2024**

iricai Inspection	MIDI
Question	Response
LAN	
Local Distribution Frame (I/LDF)	
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER  MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Variable Frequency Drive PANEL BOARD	Inspected
	<del>-</del>
Fused Disconnect Switch Type	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C13
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance Instance Condition	Room 237A 3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Model	Rauland Telecenter III
Installation Year	1983
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 237A
Deficiency Quantity	180,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

Question         Response           SECURITY         Inspected           IPDVS/CCTV System         Inspected           Condition         1 - Good           Installation Year         2023           Source of Installation Year         Documented           Deficiency         No deficiencies recorded           Intrusion Alarm System         Inspected           Instance Condition         3 - Fair           Instance Condition         3 - Fair           Instance Quantity         1           Instance Quantity Uom         EACH           Model         Vista - 50P           Installation Year         2003           Source of Installation Year         2003           Source of Installation Year         Condition           Deficiency         No deficiencies recorded           Infract Sessor         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Remote Annunciator         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           SirenSytobe         Inspected           Condition         3 - Fair           Deficiency <th< th=""></th<>
Inspected
Inspected
Condition         1- Good           Installation Year         2023           Source of Installation Year         Documented           Deficiency         No deficiencies recorded           Intrusion Alarm System         Inspected           Central Control Panel         Inspected           Instance         Room C31           Instance Condition         3- Fair           Instance Quantity         1           Instance Quantity Uom         EACH           Model         Vista - 50P           Installation Year         2003           Source of Installation Year         Custodial Staff           Deficiency         No deficiencies recorded           Infrared Sensor         Inspected           Condition         3- Fair           Deficiency         No deficiencies recorded           Panic Switch         Inspected           Condition         3- Fair           Deficiency         No deficiencies recorded           Remote Annunciator         Inspected           Condition         3- Fair           Deficiency         No deficiencies recorded           Siren/Strobe         Inspected           Condition         3- Fair           Deficiency
Source of Installation Year         Documented           Deficiency         No deficiencies recorded           Intrusion Alarm System         Inspected           Central Control Panel         Inspected           Instance         Room C31           Instance Quantity         1           Instance Quantity Uom         EACH           Model         Vista - 50P           Installation Year         2003           Source of Installation Year         Custodial Staff           Deficiency         No deficiencies recorded           Infrared Sensor         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Panic Switch         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Remote Annunciator         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Siren/Strobe         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Siern/Strobe         Inspected           Condition         3 - Fair           On defici
Deficiency   No deficiencies recorded
Intrusion Alarm System Central Control Panel Instance Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Um EACH Model Vista - 50P Installation Year Source of Installation Year Deficiency No deficiencies recorded Infrared Sensor Inspected Condition Jeficiency No deficiencies recorded Inspected Siren/Strobe Inspected Condition Jeficiency No deficiencies recorded Inspected Lighting - Security Inspected
Instance   Room C31     Instance Condition   3- Fair     Instance Quantity   1     Instance Quantity Uom   EACH     Model   Vista - 50P     Installation Year   2003     Source of Installation Year   Custodial Staff     Deficiency   No deficiencies recorded     Infrared Sensor   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Panic Switch   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Remote Annunciator   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Remote Annunciator   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Remote Annunciator   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected     Condition   3- Fair     Deficiency   No deficiencies recorded     Siren/Strobe   Inspected
Central Control Panel       Inspected         Instance       Room C31         Instance Quantity       3 - Fair         Instance Quantity       1         Instance Quantity Uom       EACH         Model       Vista - 50P         Installation Year       2003         Source of Installation Year       Custodial Staff         Deficiency       No deficiencies recorded         Infrared Sensor       Inspected         Condition       3 - Fair         Deficiency       No deficiencies recorded         Panic Switch       Inspected         Condition       3 - Fair         Deficiency       No deficiencies recorded         Remote Annunciator       Inspected         Condition       3 - Fair         Deficiency       No deficiencies recorded         Siren/Strobe       Inspected         Condition       3 - Fair         Deficiency       No deficiencies recorded         Siren/Strobe       Inspected         Condition       3 - Fair         Deficiency       No deficiencies recorded         Inspected       No deficiencies recorded         Inspected       No deficiencies recorded
Instance Condition 3- Fair Instance Quantity
Instance Quantity Instance Quantity Uom EACH Model Vista - 50P Installation Year 2003 Source of Installation Year Deficiency No deficiencies recorded Infrared Sensor Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair Deficiency No deficiencies recorded Inspected Condition 3 - Fair No deficiencies recorded
Instance Quantity Uom         EACH           Model         Vista - 50P           Installation Year         2003           Source of Installation Year         Custodial Staff           Deficiency         No deficiencies recorded           Infrared Sensor         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Panic Switch         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Remote Annuciator         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Siren/Strobe         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Lighting - Security         Inspected
Model Vista - 50P Installation Year 2003 Source of Installation Year Custodial Staff Deficiency No deficiencies recorded Infrared Sensor Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Panic Switch Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Remote Annunciator Inspected  Condition 3- Fair  Deficiency No deficiencies recorded  Remote Annunciator Inspected  Siren/Strobe Inspected  Condition 3- Fair  Deficiency No deficiencies recorded  No deficiencies recorded  No deficiencies recorded  No deficiencies recorded  Inspected  No deficiencies recorded  No deficiencies recorded  Inspected  Inspected
Model         Vista - 50P           Installation Year         2003           Source of Installation Year         Custodial Staff           Deficiency         No deficiencies recorded           Infrared Sensor         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Panic Switch         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Remote Annunciator         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Siren/Strobe         Inspected           Condition         3 - Fair           Deficiency         No deficiencies recorded           Lighting - Security         Inspected
Source of Installation Year Deficiency No deficiencies recorded Infrared Sensor Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected Condition 3- Fair Deficiency No deficiencies recorded Remote Annuciator Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected Siren/Strobe Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected Inspected Condition J- Fair Deficiency No deficiencies recorded Inspected
Source of Installation Year Deficiency No deficiencies recorded Infrared Sensor Inspected Condition 3- Fair Deficiency No deficiencies recorded Inspected  Condition 3- Fair  Condition 3- Fair Deficiency No deficiencies recorded Inspected  Condition 3- Fair Deficiency No deficiencies recorded Inspected  Condition 3- Fair Condition 3- Fair Deficiency No deficiencies recorded Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Inspected  Siren/Strobe Inspected  Condition 3- Fair Deficiency No deficiencies recorded Inspected  Inspected  Condition 3- Fair Deficiency Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected
Infrared SensorInspectedCondition3- FairDeficiencyNo deficiencies recordedPanic SwitchInspectedCondition3- FairDeficiencyNo deficiencies recordedRemote AnnunciatorInspectedCondition3- FairDeficiencyNo deficiencies recordedSiren/StrobeInspectedCondition3- FairDeficiencyNo deficiencies recordedLighting - SecurityInspected
Condition 3- Fair Deficiency No deficiencies recorded  Panic Switch Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Remote Annunciator Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Siren/Strobe Inspected  Condition 3- Fair Deficiency No deficiencies recorded  No deficiencies recorded  No deficiencies recorded  Inspected
Condition 3- Fair  Deficiency No deficiencies recorded  Panic Switch Inspected  Condition 3- Fair  Deficiency No deficiencies recorded  Remote Annunciator Inspected  Condition 3- Fair  Deficiency No deficiencies recorded  Siren/Strobe Inspected  Condition 3- Fair  Deficiency No deficiencies recorded  Lighting - Security Inspected
Panic Switch Condition 3- Fair Deficiency No deficiencies recorded Remote Annunciator Inspected Condition 3- Fair Deficiency No deficiencies recorded  Inspected Siren/Strobe Inspected Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected Inspected Inspected
Panic Switch Condition 3- Fair Deficiency No deficiencies recorded Remote Annunciator Inspected Condition 3- Fair Deficiency No deficiencies recorded  Inspected Siren/Strobe Inspected Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected Inspected Inspected
Condition 3- Fair Deficiency No deficiencies recorded  Remote Annuciator Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Siren/Strobe Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected
Deficiency  Remote Annunciator  Inspected  Condition  Deficiency  No deficiencies recorded  No deficiencies recorded  No deficiencies recorded  Inspected  Siren/Strobe  Inspected  Condition  Deficiency  No deficiencies recorded  Inspected  No deficiencies recorded  Inspected  Inspected  Inspected  Inspected
Remote Annunciator     Inspected       Condition     3- Fair       Deficiency     No deficiencies recorded       Siren/Strobe     Inspected       Condition     3- Fair       Deficiency     No deficiencies recorded       Lighting - Security     Inspected
Condition 3- Fair Deficiency No deficiencies recorded  Siren/Strobe Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected
Deficiency No deficiencies recorded  Siren/Strobe Inspected  Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected
Siren/Strobe  Condition  Deficiency  No deficiencies recorded  Lighting - Security  Inspected
Condition 3- Fair Deficiency No deficiencies recorded  Lighting - Security Inspected
Deficiency No deficiencies recorded  Lighting - Security Inspected
Lighting - Security Inspected
<u> </u>
Condition 3- Fair
Deficiency LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance Throughout Building Exterior
Deficiency Quantity 32
Quantity Uom EACH
Potential Action REPLACE-UPGRADE
Urgency of Action PRIORITY 1
Purpose of Action LEVEL 3
Violations No violations recorded
Deficiency TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance Electrical Room
Deficiency Quantity 1
Quantity Uom EACH
Potential Action REPLACE
Urgency of Action PRIORITY 3 Purpose of Action LEVEL 3
Violations No violations recorded
SERVICE SWITCH Inspected
Instance Electrical Room C13
Instance Condition 3- Fair
Instance Quantity 1
Instance Quantity Uom EACH
Manufacturer Gallagher
EquipmentId A.C SERV SW(Chiller No. 1)
Capacity/Size Quantity 400
Capacity/Size UOM Amps

## **Building Condition Assessment Survey 2023-2024**

cui Inspection	1/11.
estion	Response
ERVICE SWITCH	
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
	A.C SERV SW (Chiller No. 2)
EquipmentId Capacity/Size Quantity	400
Capacity/Size Quantity Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	BP-1 Boiler Room (Disconnect Switch)
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	HE Serv SW (H.E. Power Panel)
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Gallagher
EquipmentId	Main SERV. SW. No. 1 (Dist SWBD No. 1)
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1

## **Building Condition Assessment Survey 2023-2024**

иси търесион	14113
nestion	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Main SERV. SW. No. 2 (Dist SWBD No. 2)
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room By C40
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C13
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1983
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FRANSFORMER	Does not exist