Building Condition Assessment Survey 2023-2024

Inspection Id	Inspection Type				Time In	Last Edited
815	ELECTRICAL				2023-11-08 09:104	AM 2023-11-08 11:52A
sset Data						
Question				Answer		
Have any System	ns/Major Building Co	omponents been upgraded	?	Systems:	Partial Molded Case Circui	t Breaker Panel Board
				Years:	2023, 2019, 2010, 2003, 20	000
				Systems:	Lighting - Security, Emerge Pack), Exit/Emergency Lig	
				Years:	2022	
				Systems:	Intrusion Alarm System (Co Inferred Sensor, Most Rem	
				Years:	2021	
				Systems:	Telephone System	
				Years: Systems:	2020 Auditorium (Except House	Lighting), LED Lighting
				Years:	(Cafeteria, Kitchen) 2019	
				Systems:	Emergency Lighting (Non	Battery Pack)
				Years:	2018	
				Systems:	Staff Toilet Rooms (Pendar	nt Fluorescent Lighting)
				Years:	2015	i. Ci4-1.)
				Systems:	Intrusion Alarm System (Pa	anic Switch)
				Years: Systems:	2013 Exit Lights (Battery Pack)	
				Years:	2012	
				Systems:	Library	
				Years:	2010	
				Systems:	Interior Fluorescent Lightin Cafeteria (Local Sound Sys	•
				Years:	2006	
				Systems:	Emergency Light/Exit Light	nt Panel
				Years:	2003	
				Systems:	Service Switch, Switchboar	rd
				Years:	2001	
Type of Service	William Lawren	F. 1.40		Below Gr	ound	
	Whiteboard (IWB) I on In Electrical Room			Yes No		
		FIRE RESCUE ARE	ΔS	NO		
Question	IIVIERCOMS IIV	THE RESCUETINE	110]	Response	
Are there any your building		ice Areas, Fire Rescue Are	as, and/or Holding Roo	oms in	No	
iority Conditi	on					
Exist Prio	•	Condition	Component	Location	Person(s) Person(s)	Photo
No condition red	egory	Description	Affected	Description	Notified Title	Image
nspection	corded					
Question				Response		
Electrical				response	<u>, </u>	
ATHLETIC 1	FIFI D			Does not	exist	
				Inspected		
AUDITORIU	stance on 1st Floor			Inspected		
				mspecied		
House Ligh	stance on 1st Floor			Inspected		
	oes a Chandelier Exist	49		No		
De	ies a Chandener exist	l?		INO		

Building Condition Assessment Survey 2023-2024

		WIIJ
uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	-
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System	•	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting	*	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

ricui inspection		IVIIS
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Installation Year	2006	
Source of Installation Year	Inspector Estimate	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - IED	Under construction	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 5th Floor	Inspected	
Lighting		
Instance on 5th Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 5th Floor	Inspected	
Pendant Mounted		
Instance on 5th Floor	Does not exist	
Surface Mounted		

Building Condition Assessment Survey 2023-2024

ricui Inspection		WII32
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on 5th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 5th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 5th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 5th Floor	Does not exist	
Lighting Fixture - LED		
Instance on 5th Floor	Does not exist	
Local Sound System		
Instance on 5th Floor	Does not exist	
Projection System		
Instance on 5th Floor	Does not exist	
Scoreboard		
Instance on 5th Floor	Does not exist	
Theater Lighting System		
Instance on 5th Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 212/213	Inspected	
Lighting	1	
Instance on Room 212/213	Inspected	
Lighting Fixture - Fluorescent	^	
Instance on Room 212/213	Inspected	
Pendant Mounted	A	
Instance on Room 212/213	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	1.0 deficiencies recorded	

Building Condition Assessment Survey 2023-2024

_		
uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on Room 212/213	Does not exist	
Recessed Mounted		
Instance on Room 212/213	Does not exist	
Lighting Fixture - HID		
Instance on Room 212/213	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 212/213	Does not exist	
Lighting Fixture - LED		
Instance on Room 212/213	Does not exist	
Raceway With Receptacles		
Instance on Room 212/213	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 212/213	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

	141132
Response	
No deficiencies recorded	
-	
Inspected	
No deficiencies recorded	
<u>-</u>	
No deficiencies recorded	
Inspected	
1- Good	
FIXTURE NOT OPERATIONAL	
Auditorium	
1	
EACH	
REPAIR	
PRIORITY 5	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
	No deficiencies recorded Does not exist Does not exist Inspected 3 - Fair No deficiencies recorded Inspected Inspe

Building Condition Assessment Survey 2023-2024

нсш інгресион	IVIII
Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm Control Panel
Installation Year	1960
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	81,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Installation Year	1960
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	81,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected

Building Condition Assessment Survey 2023-2024

ctrical Inspection	M132
Question	Response
LAN	
Local Distribution Frame (I/LDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Under construction
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Mechanical Rooms
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Room 508
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Kitchen, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor near Room 404
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

cirical Inspection	N1132
Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 204
Instance Condition	3- Fair
Instance Quantity	1
<u>-</u>	EACH
Instance Quantity Uom Model	
	Rauland TC2100 2006
Installation Year Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Old Custodian's Office
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2021
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator Condition	Inspected 2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Response	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
3- Fair	
*	
<u> </u>	
*	
``/	
1	
No deficiencies recorded	
1- Good	
No deficiencies recorded	
	No deficiencies recorded Inspected 1- Good No deficiencies recorded Inspected 1st Floor Electrical Meter Room 3- Fair 1 EACH Delta Metal Product Main Service Switch 800 Amps Nameplate 2001 Documented No deficiencies recorded Inspected 1 Inspected Basement Electrical Room 3- Fair 1 EACH Electrotech MDP - Sec 1, 2 800 Amps Total 2 Section(s) Nameplate 2001 Documented No deficiencies recorded Inspected