### **Building Condition Assessment Survey 2023-2024**

•	ection					Μ
Asset:	P.S. 134 - MAN	HATTAN, 293 EAST B	ROADWAY, MANHA	ATTAN, NY, 10	002	
Inspection Id	Inspection Type				Time In	Last Edited
1670	ELECTRICAL				2023-12-14 09:05AN	1 2024-02-06 12:57P
set Data						
Question				Answer		
Have any Syste	ms/Major Building	Components been upgraded	1?	Systems:	Auditorium LED Lighting	
				Years:	2023	
				Systems:	(Clocks)	Public Address System
				Years:	2022	nal Cantural Danial
				Systems:	Intrusion Alarm System (Cent Infrared Sensor, Remote Annu 2021	
				Years:	2021 Security Lighting	
				Systems:	Security Lighting	
				Years:	2018, 2007, 1999 Talanhana System, LAN	
				Systems:	Telephone System, LAN	
				Years:	2017	D (1)
				Systems:	Computer Lab (Raceway With	(Receptacies)
				Years: Systems:	2016 Interior Lighting (Except Libr Science Rooms), Most Emerg	-
				Years:	Battery Pack) 2014	ency Lighting (Non
				Systems:	Partial Molded Case Circuit B	reaker Panel Board
				Years:	2009, 2007, 2002, 2000, 1998	
				Systems:	Auditorium (Theater Lighting Science Rooms, Locker Room (Amplifier, Tuner), Local Sou System (Except Printer), Servi Switchboard	n, Public Address System nd System, Fire Alarm
				Years:	2007	
				Systems:	Intrusion Alarm System (Sirer	n, Panic Switch)
				Years:	2004	
				Systems:	Emergency Light/Exit Light P	anel
				Years:	2002	
Type of Service	2			Below G	ound	
	e Whiteboard (IWB)			Yes		
	on In Electrical Roo			No		
	) INTERCOMS I	N FIRE RESCUE ARE	EAS			
Question	L'CD A		1/ 11.11° D		Response	
your building		nce Areas, Fire Rescue Are	eas, and/or notding Koon	is in	Yes	
Are dedicated intercoms available in all of these spaces for use during a f		r use during a fire?		No		
Which spaces do not have dedicated intercoms?				Rooms 418, 318, 218		
iority Condit	ion					
xist Prio	ority egory	Condition Description	<b>Component</b> Affected	Location Description	Person(s) Person(s) Notified Title	Photo Image
No condition re	<u> </u>	Description	maau	Description		
nspection				-		
Question				Response		
Electrical						
ATHLETIC	FIELD			Does not	exist	
AUDITORIUM			Inspected			

House Lighting

Instance on 1st Floor

Instance on 1st Floor

Inspected

Inspected

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

uestion	Response
AUDITORIUM	
House Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

rical Inspection		M134
Question	Response	
CAFETERIA		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Does not exist	
	Inspected	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting Does a Chandelier Exist?	Inspected No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
•	Inspected	
Surface Mounted	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 430	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 430	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 430	Inspected	
Pendant Mounted		
Instance on Room 430	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

rical Inspection		NI13
uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 430	Does not exist	
Recessed Mounted		
Instance on Room 430	Does not exist	
Lighting Fixture - HID		
Instance on Room 430	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 430	Does not exist	
Lighting Fixture - LED		
Instance on Room 430	Does not exist	
Raceway With Receptacles		
Instance on Room 430	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted	*	
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

rical Inspection	Response	
	Kesponse	
KITCHEN		
Lighting Instance on 1st Floor	Inspected	
	hispetted	
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	
	Inspected	
Pendant Mounted	D	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 202/208	Inspected	
Lighting	mipoted	
Instance on Room 202/208	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on Room 202/208	Inspected	
	nispecteu	
Pendant Mounted	T ( 1	
Instance on Room 202/208	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 202/208	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 202/208	Does not exist	
Lighting Fixture - HID		
Instance on Room 202/208	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 202/208	Does not exist	
Lighting Fixture - LED		
Instance on Room 202/208	Does not exist	
Raceway With Receptacles		
Instance on Room 202/208	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Projection System	Doog not aviat	
Instance on Room 202/208	Does not exist	
LOCKER ROOM	Inspected	
Instance on 2nd Floor	Inspected	
Alternative Use	Yes	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

uestion	Response	
LOCKER ROOM	*	
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 423	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 427	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Lighting	105	
Instance on Room 423	Inspected	
Instance on Room 427	Inspected	
Lighting Fixture - Fluorescent	ľ	
Instance on Room 423	Inspected	
Instance on Room 427	Inspected	
Pendant Mounted	*	
Instance on Room 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 423	Does not exist	
Instance on Room 427	Does not exist	
Recessed Mounted		
Instance on Room 423	Does not exist	
Instance on Room 427	Does not exist	
Lighting Fixture - HID		
Instance on Room 423	Does not exist	
Instance on Room 427	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 423	Does not exist	
Instance on Room 427	Does not exist	
Lighting Fixture - LED		

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

ical Inspection	M
uestion	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - LED	
Instance on Room 427	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 423	Does not exist
Instance on Room 427	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 423	Does not exist
Instance on Room 427	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 423	Does not exist
Instance on Room 427	Does not exist
Projection System	
Instance on Room 423	Does not exist
Instance on Room 427	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 425	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 425	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 425	Inspected
Pendant Mounted	
Instance on Room 425	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 425	Does not exist
Recessed Mounted	
Instance on Room 425	Does not exist
Lighting Fixture - HID	
Instance on Room 425	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 425	Does not exist
Lighting Fixture - LED	
Instance on Room 425	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 425	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 425	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 425	Does not exist
SWIMMING POOL	Does not exist

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

	1411.
Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
	3- Fair
Condition	No deficiencies recorded
Deficiency	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance Deficiency Quantity	Electrical Room B2
Quantity Uom	1 EACH
Potential Action	EACH INSTALL NEW PANEL BOARD
Urgency of Action Purpose of Action	PRIORITY 5 LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
	Inspected
Battery Pack Condition	3- Fair
	No deficiencies recorded
Deficiency	
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

M
Response
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Main Entrance Lobby
2- Between Good and Fair
l EACH
Edwards System Technology
EST 2
Fire Alarm Control Panel
2007
Documented
No deficiencies recorded
Does not exist
Does not exist
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

rical Inspection	MIS
Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
	Inspected
MOTOR CONTROLLER	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
	Does not exist
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
•	
Deficiency Location/Instance Deficiency Quantity	Throughout the Building 11
Quantity Uom	II EACH
Potential Action	EACH REPLACE-UPGRADE
	NLI LACE-UI UNADE

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

iestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms (405, 106), Cafeteria, Mechanical Room B1
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	By Room 405
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	By Rooms (225, 205), Auditorium - Stage
Deficiency Quantity	By Rooms (223, 203), Auditorium - Stage
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 124
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1960
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 124
Deficiency Quantity	87,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 126
	1- Good
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2021

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

iestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	
Deficiency	3- Fair No deficiencies recorded
-	
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room B2
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Precision Switchboard
EquipmentId	Service Switch 1 Existing Switchboard B Disconnect
Capacity/Size Quantity	600
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B2
Instance Condition	2- Between Good and Fair
Instance Quantity	1
· · · · · · · · · · · · · · · · · · ·	EACH
Instance Quantity Uom	Precision Switchboard
Manufacturer	Service Switch 2 Existing Switchboard A Disconnect
EquipmentId Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B2
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Precision Switchboard
EquipmentId	Service Switch 3 New Distribution Panel A-2
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year Deficiency	Documented No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

		/1134
uestion	Response	
SWITCHBOARD		
Number of Spares	1	
Fused Disconnect Switch Type	Inspected	-
Instance	Electrical Room B2	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Precision Switchboard	
EquipmentId	N/A	
Equipmentid Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	Does not exist	
Fused Knife Switch Type		
Molded Case Circuit Breaker Type	Inspected Electrical Room B2	
Instance		
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	AA Switchboard Co.	
EquipmentId	Main SW BD A	
Capacity/Size Quantity	500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B2	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	AA Switchboard Co.	
EquipmentId	Main SW BD B	
Capacity/Size Quantity	500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B2	
Deficiency Quantity	1	
Quantity Uom	EACH	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

uestion	Response	
SWITCHBOARD		
Molded Case Circuit Breaker Type		
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	-
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	

BCAS Partners Version 2.0 (P)