# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:	I.S. 136 - MANH	ATTAN, 6 EDGECO	MBE AVENUE, MANI	HATTAN, NY, 1	0030	
Inspection Id	Inspection Type				Time In	Last Edited
2477	ELECTRICAL				2024-01-18 09:21A	AM 2024-02-13 07:42A
sset Data						
Question				Answer		
Have any Systems/Major Building Components been upg		Components been upgrade	ed?	Systems:	Computer Lab - Room 420 Receptacles), IPDVS/CCTV	
				Years:	2023	
				Systems:	Partial Molded Case Circuit	
				Years: Systems:	2021, 2019, 2014, 2010, 20 Exit Light (Battery Pack), V	
				Years:	Partial Fused Disconnect Sv 2021	
				Systems:	5th Floor Gymnasium (LED	D Lighting)
				Years:	2019	
				Systems:	Science Rooms 301, 303, 30 Fluorescent Lighting), Most Battery Pack), 3rd Floor Gy	t Emergency Lighting (Non
				Years:	2016	
				Systems:	Lighting - Security	
				Years:	2013	
				Systems:	Telephone System	
				Years:	2012	
				Systems: Years:	Auditorium (Pendant Fluore Lighting System) 2010	escent Lighting, Theater
				Systems:	Public Address System, Loc	cal Sound System
				Years:	2009	5
				Systems:	Kitchen, Locker Room Stain	r H/3 (Lighting)
				Years:	2008	
				Systems:	Emergency Light/Exit Light	t Panel
				Years:	2002	
				Systems:	Interior Lighting	
				Years:	2000	
				Systems:	Intrusion Alarm System	
				Years:	1991	
Type of Service		Errict9		Below Gro Yes	ound	
	e Whiteboard (IWB) ion In Electrical Roor			No		
		n FIRE RESCUE AR	EAS	110		
Question				F	Response	
		nce Areas, Fire Rescue A	reas, and/or Holding Room	is in N	lo	
your building						
riority Condit	ion					
	ority	Condition	Component	Location	Person(s) Person(s)	Photo
	egory	Description	Affected	Description	Notified Title	Image
No condition re	ecorded					
Inspection						
Question				Response		
Electrical						
ATHLETIC	FIELD			Does not e	exist	
AUDITORIUM			Inspected			
In	stance on 1st Floor			Inspected		
House Lig	hting					

Instance on 1st Floor Does a Chandelier Exist? Inspected

No

## **Building Condition Assessment Survey 2023-2024**

iestion	Response	
AUDITORIUM	····	
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	<u>^</u>	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting	-	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on 1st Floor - Staff	Inspected	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

cai inspection		MII.
estion	Response	
AFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Students	Inspected	
Pendant Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Surface Mounted		
Instance on 1st Floor - Staff	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
	Does not exist	
Local Sound System Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

-		WIIJU
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 420	Inspected	
Power Panel?	Yes	
Instance on Room 307	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 420	Inspected	
Instance on Room 307	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 420	Inspected	
Instance on Room 307	Inspected	
Pendant Mounted	1	
Instance on Room 420	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on Room 420	Does not exist	
Instance on Room 307	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 420	Does not exist	
Instance on Room 420		
	Does not exist	
Lighting Fixture - HID Instance on Room 420	Description	
	Does not exist	
Instance on Room 307	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 420	Does not exist	
Instance on Room 307	Does not exist	
Lighting Fixture - LED		
Instance on Room 420	Does not exist	
Instance on Room 307	Does not exist	
Raceway With Receptacles	· · · · ·	
Instance on Room 420	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Room 307	Does not exist	
GYMNASIUM	Inspected	
Instance on 5th Floor	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 5th Floor	Inspected	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

estion	Response	
YMNASIUM	response	
Lighting		
Lighting Fixture - HID		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 5th Floor	Inspected	
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 5th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 5th Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DAMAGED	
Deficiency Quantity		
Quantity Uom Potential Action	EACH REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Theater Lighting System		
Instance on 5th Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
ITCHEN	Inspected	
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

		IVI I J
lestion	Response	
KITCHEN		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
JBRARY	Does not exist	
OCKER ROOM	Inspected	
Instance on 3rd Floor - Boys	Inspected	
Alternative Use	No	
Instance on 3rd Floor - Visitors	Inspected	
Alternative Use	Yes	
Instance on Room 560	Inspected	
Alternative Use	Yes	
Instance on Room 561, Stair H/3	Inaccessible	
Lighting		
Instance on 3rd Floor - Boys	Inspected	
Instance on 3rd Floor - Visitors	Inspected	
Instance on Room 560	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor - Boys	Inspected	
Instance on 3rd Floor - Visitors	Inspected	
Instance on Room 560	Inspected	
Pendant Mounted		
Instance on 3rd Floor - Boys	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor - Visitors	Does not exist	
Instance on Room 560	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor - Boys	Does not exist	
Instance on 3rd Floor - Visitors	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 560	Does not exist	
Recessed Mounted		
Instance on 3rd Floor - Boys	Does not exist	
Instance on 3rd Floor - Boys	Does not exist	
	נוסר באוצו	

## **Building Condition Assessment Survey 2023-2024**

Duestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 560	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor - Boys	Does not exist	
Instance on 3rd Floor - Visitors	Does not exist	
Instance on Room 560	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor - Boys	Does not exist	
Instance on 3rd Floor - Visitors	Does not exist	
Instance on Room 560	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor - Boys	Does not exist	
Instance on 3rd Floor - Visitors	Does not exist	
Instance on Room 560	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 309	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Room 309	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 309	Inspected	
Pendant Mounted	1	
Instance on Room 309	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 309	Does not exist	
Recessed Mounted		
Instance on Room 309	Does not exist	
Lighting Fixture - HID		
Instance on Room 309	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 309	Does not exist	
Lighting Fixture - LED		
Instance on Room 309	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 309	Does not exist	
Emergency Shut-Off Power		
Instance on Room 309	Does not exist	
Power Supply		
Instance on Room 309	Does not exist	
Projection System		
Instance on Room 309	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 301, 305	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms 301, 305	Inspected	

## **Building Condition Assessment Survey 2023-2024**

cal Inspection	D	M1.
estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent	Improved	
Instance on Rooms 301, 305	Inspected	
Pendant Mounted	T ( 1	
Instance on Rooms 301, 305	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 301, 305	Does not exist	
Recessed Mounted		
Instance on Rooms 301, 305	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 301, 305	Inspected	
Pendant Mounted		
Instance on Rooms 301, 305	Does not exist	
Surface Mounted		
Instance on Rooms 301, 305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Rooms 301, 305	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 301, 305	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 301, 305	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 301, 305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 301, 305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms 301, 305	Inspected	
Instructor Unit	1	
Instance on Rooms 301, 305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 301, 305	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
-		
Student Unit		
Instance on Rooms 301, 305	Does not exist	
Projection System	Doos not aviat	
Instance on Rooms 301, 305	Does not exist	
CIENCE PREP ROOM	Inspected	
Instance on Room 303	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 303	Inspected	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

irical Inspection		MISC
Question	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 303	Inspected	
Pendant Mounted		
Instance on Room 303	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 303	Does not exist	
Recessed Mounted		
Instance on Room 303	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 303	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 303	Does not exist	
Lighting Fixture - LED		
Instance on Room 303	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 303	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 303	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 303	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED		
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

Response

#### Electrical Inspection

Question

uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Closet Near Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

cui inspection	IVI
estion	Response
RE ALARM SYSTEM	
Fused Cutout Panel	
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm Control Board
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	113,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Register Control Board
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	113,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
	Inspected
Punch Register Condition	Inspected 5- Poor

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

Duestion	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Punch Register	
Deficiency Location/Instance	Room 108
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance Deficiency Quantity	Corridor near Rooms 508, 513, 411, 208, 203
	5
Quantity Uom Potential Action	EACH DEDLACE DANEL DOADD
Urgency of Action	REPLACE PANEL BOARD PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 212
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2009
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 108
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1991
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 108
Deficiency Quantity	
Quantity Uom	EACH

# **Building Condition Assessment Survey 2023-2024**

stion	M Response
	Response
CURITY	
Intrusion Alarm System	
Central Control Panel	
Potential Action Urgency of Action	REPLACE PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
	3- Fair
Condition	
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	4- Between Fair and Poor
Deficiency	ANNUNCIATOR NOT OPERATIONAL
Deficiency Location/Instance	Room 108
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Outside By West 136th St.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
CRVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	American Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1968 Decumented
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PRIORITY 1
Urgency of Action	

# **Building Condition Assessment Survey 2023-2024**

M1	36
TATE	50

ical Inspection	IVI
uestion	Response
SERVICE SWITCH	
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1250
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	- Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1250
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Question

TRANSFORMER

Does not exist

Response