Building Condition Assessment Survey 2023-2024

Mechanical Inspection M137

Asset:	P.S. 137 - MANHATTAN, 327 CHERRY STREET, MANHATTAN, NY, 10002		
Inspection Id	Inspection Type	Time In	Last Edited
1587	MECHANICAL	2023-12-11 08:27AM	2024-01-09 03:25PM

Question	Answer	
Have any Systems/Major Building Components been upgraded?	Systems:	Heat Pump Domestic Water Heaters
	Years:	2023
	Systems:	Sump Pump in MER B6 (1 of 2); Climate Control
		System - BMS (except pneumatic sub-components)
	Years:	2019
	Systems:	MDF Room - Dedicated A/C Equipment (DX Split
		System)
	Years:	2018
	Systems:	Fixtures - Student: Lavatory/Sinks, Toilets (~80%),
		Urinals; Kitchen - Grease Traps
	Years:	2015
	Systems:	F&T/Steam Drip Traps; Terminal Unit Thermostatic
		Traps
	Years:	2014
	Systems:	Kitchen - Gas System: Master Gas Control Valve
	Years:	2013
Are there fuel tanks?	No	
Total # of water main service entries to the asset	2	
MERs/Fan Rooms Locations	MER B6	
Are there any spaces with Missing or Defective CO Detectors?	Yes	
Location(s)	Science Pr	rep Room 425
Are there any Painted/Obstructed Sprinkler Heads?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No compo	onents

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s) Title	Photo
Last Year?	Category	Description	Affected	Description	Notified		Image
No	Other	Missing Handle	Science Prep Room - Emergency Shower	Room 425	MARIAN O RAMIREZ	Custodian	

Inspection

uestion	Response	
lechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Dry Cooler	Does not exist	
Packaged / Rooftop Unit	Does not exist	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	

Mechanical Inspection	W1137

uestion		Response	
AIR CO	NDITIONING		
Refrige	erant Piping	Inspected	
Cond	lition	3- Fair	
	Deficiency	No deficiencies recorded	
Return	ı Fan	Does not exist	
CENTR	ALACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMA	ΓΕ CONTROL SYSTEM	Inspected	
BMS		Inspected	
	Instance	Throughout except Multi-Purpose Room (WPT System)	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	ЕАСН	
	Building Area Covered by Operational System	81-100%	
	Installation Year	2019	
	Source of Installation Year	Custodial Staff	
	Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT	
	Deficiency Location/Instance	Rooms 112, 202, 231	
	Deficiency Quantity	3	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Pneum	natic System	Inspected	
	Instance	Cafeteria	
	Instance Condition	5- Poor	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Building Area Covered by Operational System	0-20%	
	Deficiency	DEFECTIVE AIR COMPRESSOR	
	Deficiency Location/Instance	MER B6	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action Violations	LEVEL 2 No violations recorded	
	Deficiency Deficiency Location/Instance	DEFECTIVE DAMPER ACTUATOR MER B6	
	Deficiency Quantity	2	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
	Deficiency	DEFECTIVE TERMINAL UNIT CONTROLLER	
	Deficiency Location/Instance	MER B6	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
TT 1 .	1 System	Does not exist	

Building Condition Assessment Survey 2023-2024

inicui Inspection	14113
estion	Response
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
	Inspected
Domestic Cold Water System Cravity System	Does not exist
Gravity System	Does not exist Does not exist
Pressure Booster System	
Water Service	Inspected
Instance	Basement - Crawlspace, Gas/Sprinkler Room
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
•	DEVICE
Deficiency Location/Instance	Basement - Crawlspace, Gas/Sprinkler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	5- Poor
Deficiency	DETERIORATED
Deficiency Location/Instance Deficiency Quantity	MER B6
Quantity Uom	EACH
Potential Action	
	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Inspected
Instance	MER B6
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
	N/A
EquipmentId	
Capacity/Size Quantity	6 KW Input
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	119

Mechanical Inspection		W113/
Quantian	Dosnonso	

Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Heat Pump Domestic Water Heater		
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	Room B10	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	A.O. Smith	
EquipmentId	N/A	
Capacity/Size Quantity	4	
Capacity/Size UOM	KW Input	
Capacity/Size 2 Quantity	50	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2023	
Source of Installation Year	Custodial Staff No deficiencies recorded	
Deficiency		
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS	
Deficiency Location/Instance	Rooms B3, B10	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE	
Deficiency Location/Instance Deficiency Quantity	Room 425	
	1 EACH	
Quantity Uom Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Sewage Ejector Pump	Inspected	
Sump Pump Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

chanicai Inspection		VII 3 /
Question	Response	
FIXTURES		
Staff And Other		
Janitor Sink		
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Student Drinking Fountain	Inspected	
Condition	3- Fair	
	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF	
Deficiency	VALVE,ETC.)	
Deficiency Location/Instance	Corridor near Room 414	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·	Does not exist	
Locker Room Shower	Inspected	
Sink And Fountain Combo Unit Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	-
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist	
Try of Office Treating	Does not exist	

Building Condition Assessment Survey 2023-2024

estion	Response
EATING	-
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Room 201
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
team Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
	DAMAGED/MISSING INSULATION
Deficiency	
Deficiency Location/Instance Deficiency Quantity	MER B6
	50
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action Violations	
	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Room B10
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Corridor near Room B9
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Inspected 3- Fair
Condition	
Deficiency Deficiency Location/Instance	DEFECTIVE STEAM CONTROL VALVE MER B6

Building Condition Assessment Survey 2023-2024

nanical inspection	M137
Question	Response
HEATING	
Steam supplied by External Sources	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	Does not exist
Enclosed IDF Room	Inspected
Instance on Rooms 111, 415	Inspected
Dedicated A/C Equipment	
Instance on Rooms 111, 415	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Rooms 111, 415
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
KITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	The provided in the control of the c
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	110 0011110110101010101
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Grease Trap	No deficiencies recorded
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected

меспанісаі Інѕресион	MI3/

estion	Response	
KITCHEN		
Kitchen Sink		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room within Room 201	Inspected	
Dedicated A/C Equipment	1	
Instance on Room within Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 323	Inspected	
Alternative Use	Yes	
Instance on Room 421		
-	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank Instance on Room 323	Inspected	
	3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency Later Part 121		
Instance on Room 421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 323	Not required	
Instance on Room 421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shower		
Instance on Room 323	Does not exist	
Instance on Room 421	Does not exist	
Eye Wash		
Instance on Room 323	Does not exist	
Instance on Room 421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 323	Does not exist	
Instance on Room 421	Does not exist	
Hood Exhaust Fan		
Instance on Room 323	Does not exist	
Instance on Room 421	Does not exist	
Fixed Laboratory Hood		
Instance on Room 323	Does not exist	
Instance on Room 421	Does not exist	
Laboratory Sink		
Instance on Room 323	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 421	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

меспанісаі Інѕресион	MI3/

nestion	Response	
SCIENCE LAB		
Make-up Air Unit		
Instance on Room 323	Does not exist	
Instance on Room 421	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 325	Inspected	
Alternative Use	Yes	
Instance on Room 425	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	NO	
Instance on Room 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 425	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
CO Detector	N	
Instance on Room 325	Not required	
Instance on Room 425	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 425	
Deficiency Quantity	1 Except	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Emergency Shower	D	
Instance on Room 325	Does not exist	
Instance on Room 425	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE SHOWER	
Deficiency Location/Instance	Room 425	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Eye Wash		
Instance on Room 325	Does not exist	
Instance on Room 425	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		-
Instance on Room 325	Does not exist	
Instance on Room 425	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on Room 325	Does not exist	
Instance on Room 425	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

unicui Inspection		141137
Question	Response	
SCIENCE PREP ROOM		
Hood Exhaust Fan		
Deficiency	No deficiencies recorded	
Fixed Laboratory Hood		
Instance on Room 325	Does not exist	
Instance on Room 425	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Laboratory Sink		
Instance on Room 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 425	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	110 401101010101010101010101010101010101	
Instance on Room 325	Does not exist	
Instance on Room 425	Does not exist	
	Inspected	
SPRINKLERS, STANDPIPE, FIRE SYSTEM Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Closet inside Multipurpose Room	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	

Building Condition Assessment Survey 2023-2024

uestion	Response	
VENTILATION		
Metal Ductwork		
Deficiency Location/Instance	Multipurpose Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	