# **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 242	(OLD P144) - MANHATTAN	, 134 WEST 122 STR	EET, MANHAT	TAN, NY, 100	)27	
Inspection	n Id Inspectio	on Type			Time	In	Last Edited
	3113 ELECTR	ICAL			2024-	-02-09 08:40AM	2024-03-04 10:44A
set Data							
Question	l			Answer			
Have any	Systems/Major	Building Components been upgrade	ed?	Systems:	Transformer, Exit Lights, Fire Alarm System (Printer)		
				Years:	2023		
				Systems:		ighting (Student	Toilet Rooms)
				Years:	2022, 2009		
				Systems: Years:		uency Drive, Fuso oard, Lightning P	ed Disconnect Switch rotection
				Systems:		Projection System	, Retrofitted LED
				,		curity Lighting	,
				Years:	2019		
				Systems:	Fire Alarm Sy	stem	
				Years:	2014	_	_
				Systems:	Partial Emerg	ing (Except Toile ency Lighting (N	t Rooms and Stairways), on Battery Pack)
				Years:	2013	atam	
				Systems: Years:	Telephone Sy 2012	SIGIII	
				Systems:		ss System, Local S	Sound System
				Years:	2010	ss bystem, Locar	Jouna System
				Systems:		ighting (Staff Toi	let Rooms, Stairways)
				Years:	2009	8 8 (	, ,
				Systems:		Circuit Breaker F	Panel Board
				Years:	2008, 2007, 2	006, 2000	
				Systems:		h, Switchboard	
				Years:	2008		
				Systems:	Emergency L	ight/Exit Light Pa	nel, Intrusion Alarm
					System		
T 60				Years:	2000		
Type of S		ard (IWB) Exist?		Below Gr Yes	ouna		
	netration In Elec	` /		No			
		COMS IN FIRE RESCUE AR	EAS	110			
Question				I	Response		
	•	ue Assistance Areas, Fire Rescue Ar	eas, and/or Holding Roo	ms in	No		
your bu							
iority Co							
xist ast Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Title	Photo Image
o	Exit Light - No Operational	The fireman's concern that they haven't work as how they are suppo to after the recent upgrade. Floors 2nd, 3 would not show the wout in the case of any emergency.	ed sed rd	Throughout the Building	Peter Perkolaj	Fireman	No Photo Taken
spection	ı						
Question	<u> </u>			Response	<u> </u>		
Electrica	ıl						
ATHLI	ETIC FIELD			Does not	exist		
	TORIUM			Inspected			
	Instance on	1st Floor		Inspected			
	s Version 2.0 (P)			of 11			Print Date: 8/8/202

#### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
AUDITORIUM		
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Local Sound System	The deficiences recorded	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System	•	
Instance on 1st Floor	Does not exist	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	28	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
. 1018910110	Inspected	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	M144
Question	Response

Question	Response
CAFETERIA	<del>-</del>
Instance on 1st Floor	Inspected
Lighting	•
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	r
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	

#### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
GYMNASIUM	•	
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	

Does not exist

Does not exist Inspected

Inspected

Inspected

**Lighting Fixture - Incandescent** 

**Lighting Fixture - LED** 

LIBRARY

Lighting

Instance on 1st Floor

Instance on 1st Floor

Instance on Room 201

Instance on Room 201

# **Building Condition Assessment Survey 2023-2024**

rical Inspection		M114
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 201	Inspected	
Pendant Mounted		
Instance on Room 201	Does not exist	
Surface Mounted		
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 201	Does not exist	
Lighting Fixture - HID		
Instance on Room 201	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 201	Does not exist	
Lighting Fixture - LED		
Instance on Room 201	Does not exist	
Raceway With Receptacles		
Instance on Room 201	Does not exist	
Projection System		
Instance on Room 201	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Inspected	
Alternative Use	Yes	
Lighting	103	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Inspected	
Pendant Mounted	1	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Does not exist	
Surface Mounted		
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	140 deficiences recorded	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - LED	Does not exist	
	D	
Instance on 1st Floor - Boys, 1st Floor Mezzanine - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	

# **Building Condition Assessment Survey 2023-2024**

Response
-
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
4- Between Fair and Poor
FIXTURE LAMP NOT OPERATIONAL
Throughout the Building
15
EACH
MAINTENANCE
PRIORITY 5 LEVEL 6
No violations recorded
Inspected
3- Fair
FIXTURE LAMP NOT OPERATIONAL
LIATUKE LAWIT NUT UTEKAHUNAL
1st Floor by Staircase D/Fyit 5
1st Floor by Staircase D/Exit 5
1st Floor by Staircase D/Exit 5 1 EACH

# **Building Condition Assessment Survey 2023-2024**

estion	Response
XIT LIGHT	
Non Battery Pack	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
XIT/EMERGENCY LIGHT	Does not exist
IRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Main Entrance Lobby
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist

# **Building Condition Assessment Survey 2023-2024**

Question	Response		
FIRE ALARM SYSTEM			
Remote Annunciator	Inspected		
Display Monitor	Does not exist		
Panel	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Printer	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
	Does not exist		
Punch Register  Sprinkler Flow/Air Pressure Switch	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
<u>-</u>	Inspected		
Tamper Flow Switch/Chain Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
GROUNDING SYSTEM	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
INTERCOM SYSTEM	Inspected		
Elevator	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Holding Area	Does not exist		
LAN	Inspected		
Local Distribution Frame (I/LDF)	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Main Equipment Rack (MDF)	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
LIGHTNING PROTECTION	Inspected		
Condition_	1- Good		
Deficiency	No deficiencies recorded		
MOTOR CONTROLLER	Inspected		
MOTOR CONTROL CENTER	Does not exist		
MOTOR STARTER/CONTACTOR	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Variable Frequency Drive	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
PANEL BOARD	Inspected		
Fused Disconnect Switch Type	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not exist		
Fused Toggle Switch Type	Does not exist		
Molded Case Circuit Breaker Type	Inspected		
Condition	2- Between Good and Fair		
Deficiency	NO SPARE		
Deficiency Location/Instance Deficiency Quantity	Electrical Room		
Quantity Uom	EACH		

# **Building Condition Assessment Survey 2023-2024**

uestion	Response
PANEL BOARD	хооронос
Molded Case Circuit Breaker Type	
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	1st Floor by Rooms (105, 120)
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 107
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2100
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2000
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair

# **Building Condition Assessment Survey 2023-2024**

Question	Response	
SECURITY	*	
Intrusion Alarm System		
Siren/Strobe		
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	Siemens	
Manufacturer	Service Disconnect	
EquipmentId Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	4	
	Inspected	
Fused Disconnect Switch Type  Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Siemens	
EquipmentId	Switch A, B, C	
Capacity/Size Quantity	1600	
Capacity/Size UOM Capacity/Size 2 Quantity	Amps Total	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Electrical Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	HPS Sentinel	
EquipmentId	Solar Transformer	
Capacity/Size Quantity	300	
Capacity/Size UOM	kVA	

# **Building Condition Assessment Survey 2023-2024**

Question		Response
TRANSFORMER		
Source of Capa	city/Size	Nameplate
Installation Yea	r	2023
Source of Insta	llation Year	Custodial Staff
Deficiency		No deficiencies recorded