## **Building Condition Assessment Survey 2023-2024**

| Asset:  | P.S. 153 - MANI  | HATTAN, 1750 AMSTERD  | AM AVENUE, M   | IANHATTAN, N  | NY, 10031   |                                   |                                     |
|---|--|---|--|---|---|-----------------------------------|-------------------------------------|
| Inspection  | n Id Inspection Type   |   |  |   | Time  | In                                | Last Edited                         |
|   | 2799 ELECTRICAL  |   |  |   | 2024-   | 01-30 09:31A                      | M 2024-06-17 10:17AN                |
| set Data  |  |   |  |   |   |                                   |                                     |
| Question  | 1  |   |  | Answer  |   |                                   |                                     |
| Have any  | Systems/Major Building (   | Components been upgraded?   |  | Systems:  | Exit/Emergen  | cy Lights                         |                                     |
|   |  |   |  | Years:  | 2022  |                                   |                                     |
|   |  |   |  | Systems:  | Telephone Sy  | stem, LAN                         |                                     |
|   |  |   |  | Years:  | 2019  |                                   |                                     |
|   |  |   |  | Systems:  | Partial Molde   | d Case Circuit                    | Breaker Panel Board                 |
|   |  |   |  | Years:  | 2017, 2003, 1   | 995                               |                                     |
|   |  |   |  | Systems:  | Emergency G   | enerator Set (B                   | attery Charger)                     |
|   |  |   |  | Years:  | 2017  |                                   |                                     |
|   |  |   |  | Systems:  | _   | -                                 | ergency Lighting (Non               |
|   |  |   |  |   | Battery Pack)   |                                   |                                     |
|   |  |   |  | Years:  | 2015  | a .                               |                                     |
|   |  |   |  | Systems:  | Partial Lightin   | ng - Security                     |                                     |
|   |  |   |  | Years:  | 2014, 1995  | 10 10                             |                                     |
|   |  |   |  | Systems:  |   | Local Sound Sy                    | rsiem)                              |
|   |  |   |  | Years:  | 2007  | g ,                               |                                     |
|   |  |   |  | Systems:  | Intrusion Alar  | m System                          |                                     |
|   |  |   |  | Years:  | 2006  |                                   | C ( C D ( 1                         |
|   |  |   |  | Systems:  | -   | stem, Emergen<br>h, Partial Swite | cy Generator Set, Partial           |
|   |  |   |  | Years:  | 1995  | n, i ainai Swin                   | modard                              |
| Type of S   | Service  |   |  | Below Gr  |   |                                   |                                     |
|   | eractive Whiteboard (IWB)  | Exist?  |  | Yes   |   |                                   |                                     |
|   | netration In Electrical Room   |   |  |   |   |                                   |                                     |
| TTUCCI I CI   | netiation in Licenteal 1000  | 1111.   |  | No  |   |                                   |                                     |
|   |  | N FIRE RESCUE AREAS   |  | No  |   |                                   |                                     |
| DEDICA<br>Question  | ATED INTERCOMS I   | N FIRE RESCUE AREAS   |  | I   | Response  |                                   |                                     |
| Question Are the  | ATED INTERCOMS I   |   | nd/or Holding Roon   | I   | Response<br>Yes   |                                   |                                     |
| Question Are the your bu  | ATED INTERCOMS I<br>re any Life Rescue Assista<br>tilding?   | N FIRE RESCUE AREAS<br>ince Areas, Fire Rescue Areas, a   |  | ns in   | Yes   |                                   |                                     |
| Question Are the your bu Are d  | ATED INTERCOMS I<br>are any Life Rescue Assista<br>hilding?<br>ledicated intercoms availab   | N FIRE RESCUE AREAS<br>ince Areas, Fire Rescue Areas, a<br>ole in all of these spaces for use   |  | ns in   | Yes<br>Yes  |                                   |                                     |
| Are the your bu   | ATED INTERCOMS I<br>ere any Life Rescue Assista<br>tilding?<br>ledicated intercoms available<br>all dedicated intercoms op   | N FIRE RESCUE AREAS<br>ince Areas, Fire Rescue Areas, a<br>ole in all of these spaces for use   |  | ns in   | Yes   |                                   |                                     |
| Question Are the your bu Are d Are d  | are any Life Rescue Assistantiding? Idedicated intercoms available all dedicated intercoms operation   | N FIRE RESCUE AREAS  ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?   | during a fire?   | ns in   | Yes<br>Yes<br>Yes   |                                   |                                     |
| Are the your bu   | ATED INTERCOMS I<br>ere any Life Rescue Assista<br>tilding?<br>ledicated intercoms available<br>all dedicated intercoms op   | N FIRE RESCUE AREAS<br>ince Areas, Fire Rescue Areas, a<br>ole in all of these spaces for use   |  | ns in   | Yes<br>Yes  | Person(s)<br>Title                | Photo<br>Image                      |
| Question Are the your bu Are d Are  | re any Life Rescue Assistantiding? dedicated intercoms available all dedicated intercoms opendition  Priority  | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  pole in all of these spaces for use perational?  Condition   | during a fire?  Component  | ns in S   | Yes Yes Person(s)   |                                   |                                     |
| Question Are the your bu Are d Are d iority Co xist ast Year?   | are any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  | during a fire?  Component Affected   | Location Description  | Yes Yes Yes Yes Person(s) Notified  | Title                             | Image                               |
| Question Are the your bu Are d Are d iority Co xist ast Year?   | are any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak                          | during a fire?  Component Affected Lighting  | Location Description Corridor near  | Yes Yes Yes Person(s) Notified Julio Segura                                       | Title                             | Image<br>No Photo Taken             |
| Question Are the your bu Are d Are d iority Co xist ast Year?   | are any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System -   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam                                    | Component Affected Lighting Fixture  | Location Description Corridor near Rooms 261,   | Yes Yes Yes Person(s) Notified Julio Segura Julio                                 | Title                             | Image                               |
| Ouestion Are the your but Are defined from the Are | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak                          | during a fire?  Component Affected Lighting Fixture  Fire Alarm System - Area                    | Location Description Corridor near Rooms 261, B26   | Yes Yes Yes Person(s) Notified Julio Segura                                       | <b>Title</b> Fireman              | Image<br>No Photo Taken             |
| Ouestion Are the your but Are defined from the Are | are any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System -   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak                          | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke                              | Location Description Corridor near Rooms 261, B26   | Yes Yes Yes Person(s) Notified Julio Segura Julio                                 | <b>Title</b> Fireman              | Image<br>No Photo Taken             |
| Question Are the your bu Are d Are d Are d Are downstranger Are siority Co xist ast Year?   | re any Life Rescue Assistantiding? dedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  pole in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A                    | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector                     | Location Description Corridor near Rooms 261, B26 Room B26                                    | Yes Yes Yes Person(s) Notified Julio Segura Julio Segura                          | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Ouestion Are the your but Are defined from the Are | re any Life Rescue Assistantiding? dedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm          | Location Description Corridor near Rooms 261, B26 Room B26                                    | Yes Yes Yes Yes Person(s) Notified Julio Segura Julio Segura Julio                | <b>Title</b> Fireman              | Image<br>No Photo Taken             |
| Question Are the your bu Are d Are d Are d Are downstranger Are siority Co xist ast Year?   | re any Life Rescue Assistantiding? dedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  pole in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A                    | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector                     | Location Description Corridor near Rooms 261, B26 Room B26                                    | Yes Yes Yes Person(s) Notified Julio Segura Julio Segura                          | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Are the your bu Are do | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26                                    | Yes Yes Yes Yes Person(s) Notified Julio Segura Julio Segura Julio                | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Question Are the your bu Are d Are diority Coxist ast Year?   | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26 Throughout the Building            | Yes Yes Yes Yes  Person(s) Notified  Julio Segura  Julio Segura  Julio Segura     | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Are the your bu Are do | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26                                    | Yes Yes Yes Yes  Person(s) Notified  Julio Segura  Julio Segura  Julio Segura     | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| DEDICA Question Are the your but Are do Are | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26 Throughout the Building            | Yes Yes Yes  Person(s) Notified Julio Segura  Julio Segura  Julio Segura          | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Question Are the your bu Are of Are diority Coxist ast Year?  o  es  es  Electrica  ATHLI   | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26  Throughout the Building           | Yes Yes Yes  Person(s) Notified Julio Segura  Julio Segura  Julio Segura          | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| Question Are the your bu Are of Are diority Coxist ast Year?  o  es  es  Electrica  ATHLI   | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26 Throughout the Building  Response  | Yes Yes Yes Yes Yes  Person(s) Notified  Julio Segura  Julio Segura  Julio Segura | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| DEDICA Question Are the your but Are of Are | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational  FIRE Alarm System - Components Not Operational  FIRE Alarm System - Components Not Operational | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26  Throughout the Building  Response | Yes Yes Yes Yes Yes  Person(s) Notified  Julio Segura  Julio Segura  Julio Segura | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |
| DEDICA Question Are the your but Are of Are | re any Life Rescue Assistantilding? Idedicated intercoms available all dedicated intercoms operation  Priority Category  Water Leaks onto Electrical Equipment  Fire Alarm System - Components Not Operational  Fire Alarm System - Components Not Operational   | N FIRE RESCUE AREAS  Ince Areas, Fire Rescue Areas, a  ple in all of these spaces for use perational?  Condition Description  Plaza Deck Leak, Steam Pipe Leak  N/A  25 Strobes are Not | Component Affected Lighting Fixture  Fire Alarm System - Area Smoke Detector Fire Alarm System - | Location Description Corridor near Rooms 261, B26 Room B26  Throughout the Building  Response | Yes Yes Yes Yes  Person(s) Notified Julio Segura  Julio Segura  Julio Segura      | Title Fireman Fireman             | Image No Photo Taken No Photo Taken |

## **Building Condition Assessment Survey 2023-2024**

| estion  | Response                            |   |
|---|-------------------------------------|---|
| AUDITORIUM  |                                     |   |
| House Lighting  |                                     |   |
| Lighting Fixture - Fluorescent                          |                                     |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Pendant Mounted   |                                     |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Surface Mounted   |                                     |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Instance Condition                                      | 2- Between Good and Fair            | - |
| Deficiency  | No deficiencies recorded            |   |
| Recessed Mounted  |                                     |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Lighting Fixture - HID                                  |                                     |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Lighting Fixture - Incandescent                         |                                     |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Lighting Fixture - LED                                  | Does not exist                      |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Pendant Mounted   | nispected                           |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Surface Mounted   | Does not exist                      |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Recessed Mounted  | Does not exist                      |   |
| Instance on 1st Floor                                   | Insuranted                          |   |
| Instance Condition                                      | Inspected  2- Between Good and Fair |   |
|   | No deficiencies recorded            |   |
| Deficiency  | No deficiencies recorded            |   |
| Local Sound System  Instance on 1st Floor               | Inspected                           |   |
| Instance Condition                                      | 3- Fair                             |   |
| Installation Year                                       | 2007                                |   |
| Source of Installation Year                             | Documented                          |   |
| Deficiency  | No deficiencies recorded            |   |
| Projection System                                       | To deficiences recorded             |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Instance Condition                                      | 3- Fair                             |   |
| Is the projector on a cart or installed on the ceiling? | Ceiling                             |   |
| Deficiency  | No deficiencies recorded            |   |
| Theater Lighting System                                 |                                     |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Dimming System  |                                     |   |
| Instance on 1st Floor                                   | Does not exist                      |   |
| Theater Lighting  | 2000 1000 01100                     |   |
| Instance on 1st Floor                                   | Inspected                           |   |
| Instance Condition                                      | 3- Fair                             |   |
| Deficiency  | LIGHTING FIXTURE BEYOND USEFUL LIFE |   |
| Deficiency Quantity                                     | 26                                  |   |
| Quantity Uom  | EACH                                |   |
| Potential Action  | REPLACE-UPGRADE                     |   |
| Urgency of Action                                       | PRIORITY 1                          |   |
| Purpose of Action                                       | LEVEL 2                             |   |
| Violations  | No violations recorded              |   |
|   |                                     |   |
| CAFETERIA   | Inspected                           |   |
| Instance on 1st Floor Lighting                          | Inspected                           |   |

## **Building Condition Assessment Survey 2023-2024**

| Electrical Inspection | M153 |
|-----------------------|------|
|                       |      |

| Question                                | Response                               |
|---|--|
| CAFETERIA                               |  |
| Lighting                                |  |
| Instance on 1st Floor                   | Inspected                              |
| Lighting Fixture - Fluorescent          |  |
| Instance on 1st Floor                   | Inspected                              |
| Pendant Mounted                         |  |
| Instance on 1st Floor                   | Does not exist                         |
| Surface Mounted                         |  |
| Instance on 1st Floor                   | Inspected                              |
| Instance Condition                      | 2- Between Good and Fair               |
| Deficiency                              | No deficiencies recorded               |
| Recessed Mounted                        |  |
| Instance on 1st Floor                   | Inspected                              |
| Instance Condition                      | 2- Between Good and Fair               |
| Deficiency                              | No deficiencies recorded               |
| Lighting Fixture - HID                  |  |
| Instance on 1st Floor                   | Does not exist                         |
| Lighting Fixture - Incandescent         |  |
| Instance on 1st Floor                   | Does not exist                         |
| Lighting Fixture - LED                  |  |
| Instance on 1st Floor                   | Inspected                              |
| Pendant Mounted                         |  |
| Instance on 1st Floor                   | Does not exist                         |
| Surface Mounted                         |  |
| Instance on 1st Floor                   | Does not exist                         |
| Recessed Mounted                        |  |
| Instance on 1st Floor                   | Inspected                              |
| Instance Condition                      | 2- Between Good and Fair               |
| Deficiency                              | No deficiencies recorded               |
| Local Sound System                      |  |
| Instance on 1st Floor                   | Inspected                              |
| Instance Condition                      | 3- Fair                                |
| Installation Year                       | 1995                                   |
| Source of Installation Year             | Documented  PEYOND LICEFUL LIFE        |
| Deficiency Deficiency Location/Instance | BEYOND USEFUL LIFE Cafeteria-1st Floor |
| Deficiency Quantity                     | 1                                      |
| Quantity Uom                            | EACH                                   |
| Potential Action                        | REPLACE                                |
| Urgency of Action                       | PRIORITY 1                             |
| Purpose of Action                       | LEVEL 2                                |
| Violations                              | No violations recorded                 |
| Projection System                       |  |
| Instance on 1st Floor                   | Does not exist                         |
| Theater Lighting System                 |  |
| Instance on 1st Floor                   | Does not exist                         |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected                              |
| Lighting                                | Inspected                              |
| Does a Chandelier Exist?                | No                                     |
| Lighting Fixture - Fluorescent          | Inspected                              |
| Pendant Mounted                         | Inspected                              |
| Condition                               | 2- Between Good and Fair               |
| Deficiency                              | No deficiencies recorded               |
| Surface Mounted                         | Inspected                              |
| Condition                               | 2- Between Good and Fair               |

## **Building Condition Assessment Survey 2023-2024**

| anea inspection                         |                          | 111133 |
|---|--------------------------|--------|
| Question                                | Response                 |        |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE |                          |        |
| Lighting                                |                          |        |
| Lighting Fixture - Fluorescent          |                          |        |
| Surface Mounted                         |                          |        |
| Deficiency                              | No deficiencies recorded |        |
| Recessed Mounted                        | Inspected                |        |
| Condition                               | 2- Between Good and Fair |        |
| Deficiency                              | No deficiencies recorded |        |
| Lighting Fixture - HID                  | Does not exist           |        |
| Lighting Fixture - Incandescent         | Does not exist           |        |
| Lighting Fixture - LED                  | Inspected                |        |
| Pendant Mounted                         | Does not exist           |        |
| Surface Mounted                         | Does not exist           |        |
| Recessed Mounted                        | Inspected                |        |
| Condition                               | 2- Between Good and Fair |        |
| Deficiency                              | No deficiencies recorded |        |
| COMPUTER LAB                            | Inspected                |        |
| Instance on Room 331                    |                          |        |
|   | Inspected                |        |
| Power Panel?                            | Yes                      |        |
| Lighting                                | Y 1                      |        |
| Instance on Room 331                    | Inspected                |        |
| Lighting Fixture - Fluorescent          |                          |        |
| Instance on Room 331                    | Inspected                |        |
| Pendant Mounted                         |                          |        |
| Instance on Room 331                    | Inspected                |        |
| Instance Condition                      | 2- Between Good and Fair |        |
| Deficiency                              | No deficiencies recorded |        |
| Surface Mounted                         |                          |        |
| Instance on Room 331                    | Does not exist           |        |
| Recessed Mounted                        |                          |        |
| Instance on Room 331                    | Does not exist           |        |
| Lighting Fixture - HID                  |                          |        |
| Instance on Room 331                    | Does not exist           |        |
| Lighting Fixture - Incandescent         |                          |        |
| Instance on Room 331                    | Does not exist           |        |
| Lighting Fixture - LED                  |                          |        |
| Instance on Room 331                    | Does not exist           |        |
| Raceway With Receptacles                |                          |        |
| Instance on Room 331                    | Inspected                |        |
| Instance Condition                      | 3- Fair                  |        |
| Deficiency                              | No deficiencies recorded |        |
| GYMNASIUM                               | Inspected                |        |
| Instance on 1st Floor                   | Inspected                |        |
| Lighting                                |                          |        |
| Instance on 1st Floor                   | Inspected                |        |
| Lighting Fixture - Fluorescent          | 1                        |        |
| Instance on 1st Floor                   | Does not exist           |        |
| Lighting Fixture - HID                  |                          |        |
| Instance on 1st Floor                   | Does not exist           |        |
| Lighting Fixture - Incandescent         |                          |        |
| Instance on 1st Floor                   | Does not exist           |        |
| Lighting Fixture - LED                  | 200 Hot Walst            |        |
| Instance on 1st Floor                   | Inspected                |        |
| instance on 15t i 1001                  | mspecieu                 |        |

## **Building Condition Assessment Survey 2023-2024**

| uestion                        | Response                 |  |
|--------------------------------|--------------------------|--|
| GYMNASIUM                      |                          |  |
| Lighting                       |                          |  |
| Lighting Fixture - LED         |                          |  |
| Pendant Mounted                |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 2- Between Good and Fair |  |
| Deficiency                     | No deficiencies recorded |  |
| Surface Mounted                |                          |  |
| Instance on 1st Floor          | Does not exist           |  |
| Recessed Mounted               |                          |  |
| Instance on 1st Floor          | Does not exist           |  |
| Local Sound System             |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 3- Fair                  |  |
| Installation Year              | 1995                     |  |
| Source of Installation Year    | Documented               |  |
| Deficiency                     | BEYOND USEFUL LIFE       |  |
| Deficiency Location/Instance   | Gymnasium-1st Floor      |  |
| Deficiency Quantity            | 1                        |  |
| Quantity Uom                   | EACH                     |  |
| Potential Action               | REPLACE                  |  |
| Urgency of Action              | PRIORITY 1               |  |
| Purpose of Action              | LEVEL 2                  |  |
| Violations                     | No violations recorded   |  |
| Projection System              |                          |  |
| Instance on 1st Floor          | Does not exist           |  |
| Scoreboard                     |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 3- Fair                  |  |
| Deficiency                     | No deficiencies recorded |  |
| Theater Lighting System        |                          |  |
| Instance on 1st Floor          | Does not exist           |  |
| KITCHEN                        | Inspected                |  |
| Instance on 1st Floor          | Inspected                |  |
| Lighting                       |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Lighting Fixture - Fluorescent |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Pendant Mounted                |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 2- Between Good and Fair |  |
| Deficiency                     | No deficiencies recorded |  |
| Surface Mounted                |                          |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 2- Between Good and Fair |  |
| Deficiency                     | No deficiencies recorded |  |
| Recessed Mounted               | 110 40110110101 10001404 |  |
| Instance on 1st Floor          | Inspected                |  |
| Instance Condition             | 2- Between Good and Fair |  |
| -                              |                          |  |
| Deficiency                     | No deficiencies recorded |  |
| Lighting Fixture - HID         |                          |  |
| Instance on 1st Floor          | Does not exist           |  |

## **Building Condition Assessment Survey 2023-2024**

| icui Inspection                 | 141                              |
|---------------------------------|----------------------------------|
| uestion                         | Response                         |
| KITCHEN                         |                                  |
| Lighting                        |                                  |
| Lighting Fixture - LED          |                                  |
| Instance on 1st Floor           | Inspected                        |
| Pendant Mounted                 | <u> </u>                         |
| Instance on 1st Floor           | Does not exist                   |
| Surface Mounted                 |                                  |
| Instance on 1st Floor           | Does not exist                   |
| Recessed Mounted                |                                  |
| Instance on 1st Floor           | Inspected                        |
| Instance Condition              | 3- Fair                          |
| Deficiency                      | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity             | 6                                |
| Quantity Uom                    | EACH                             |
| Potential Action                | REPAIR                           |
| Urgency of Action               | PRIORITY 3                       |
| Purpose of Action               | LEVEL 2                          |
| Violations                      | No violations recorded           |
| LIBRARY                         | Inspected                        |
| Instance on Room 219            | Inspected                        |
| Lighting                        |                                  |
| Instance on Room 219            | Inspected                        |
| Lighting Fixture - Fluorescent  |                                  |
| Instance on Room 219            | Inspected                        |
| Pendant Mounted                 |                                  |
| Instance on Room 219            | Inspected                        |
| Instance Condition              | 2- Between Good and Fair         |
| Deficiency                      | No deficiencies recorded         |
| Surface Mounted                 |                                  |
| Instance on Room 219            | Does not exist                   |
| Recessed Mounted                |                                  |
| Instance on Room 219            | Inspected                        |
| Instance Condition              | 2- Between Good and Fair         |
| Deficiency                      | No deficiencies recorded         |
| Lighting Fixture - HID          |                                  |
| Instance on Room 219            | Does not exist                   |
| Lighting Fixture - Incandescent |                                  |
| Instance on Room 219            | Does not exist                   |
| Lighting Fixture - LED          |                                  |
| Instance on Room 219            | Does not exist                   |
| Raceway With Receptacles        | 2040 Hot 6.11.50                 |
| Instance on Room 219            | Does not exist                   |
| Projection System               |                                  |
| Instance on Room 219            | Does not exist                   |
| LOCKER ROOM                     | Inspected                        |
| Instance on Inside Gymnasium    | Inspected                        |
| Alternative Use                 | Yes                              |
| Lighting                        | 105                              |
| Instance on Inside Gymnasium    | Inspected                        |
| Lighting Fixture - Fluorescent  | шорестей                         |
| Instance on Inside Gymnasium    | Inspected                        |
|                                 | шърсеса                          |
| Pendant Mounted                 | Does not exist                   |
| Instance on Inside Gymnasium    | DOCS HOT CYIST                   |

## **Building Condition Assessment Survey 2023-2024**

| ricai inspection                | IVI136                   |
|---------------------------------|--------------------------|
| Question                        | Response                 |
| LOCKER ROOM                     |                          |
| Lighting                        |                          |
| Lighting Fixture - Fluorescent  |                          |
| Surface Mounted                 |                          |
| Instance on Inside Gymnasium    | Inspected                |
| Instance Condition              | 2- Between Good and Fair |
| Deficiency                      | No deficiencies recorded |
| Recessed Mounted                |                          |
| Instance on Inside Gymnasium    | Does not exist           |
| Lighting Fixture - HID          |                          |
| Instance on Inside Gymnasium    | Does not exist           |
| Lighting Fixture - Incandescent |                          |
| Instance on Inside Gymnasium    | Does not exist           |
| Lighting Fixture - LED          |                          |
| Instance on Inside Gymnasium    | Does not exist           |
| MULTIPURPOSE ROOM               | Does not exist           |
| SCIENCE DEMO ROOM               | Does not exist           |
| SCIENCE LAB                     | Does not exist           |
|                                 |                          |
| SCIENCE PREP ROOM               | Inspected                |
| Instance on Room 315            | Inspected                |
| Power Panel?                    | No                       |
| Alternative Use                 | Yes                      |
| Lighting                        |                          |
| Instance on Room 315            | Inspected                |
| Lighting Fixture - Fluorescent  |                          |
| Instance on Room 315            | Inspected                |
| Pendant Mounted                 |                          |
| Instance on Room 315            | Inspected                |
| Instance Condition              | 2- Between Good and Fair |
| Deficiency                      | No deficiencies recorded |
| Surface Mounted                 |                          |
| Instance on Room 315            | Does not exist           |
| Recessed Mounted                |                          |
| Instance on Room 315            | Does not exist           |
| Lighting Fixture - HID          |                          |
| Instance on Room 315            | Does not exist           |
| Lighting Fixture - Incandescent |                          |
| Instance on Room 315            | Does not exist           |
| Lighting Fixture - LED          |                          |
| Instance on Room 315            | Does not exist           |
| Emergency Gas Shut-Off Valve    |                          |
| Instance on Room 315            | Does not exist           |
| Emergency Shut-Off Power        |                          |
| Instance on Room 315            | Does not exist           |
| Power Supply                    |                          |
| Instance on Room 315            | Does not exist           |
| SWIMMING POOL                   | Does not exist           |
| TOILET ROOM - STAFF             | Inspected                |
| Lighting                        | Inspected                |
| Lighting Fixture - Fluorescent  | Inspected                |
| Pendant Mounted                 | Inspected                |
| Condition                       | 2- Between Good and Fair |
|                                 |                          |

## **Building Condition Assessment Survey 2023-2024**

| Question                           | Response                                   |
|------------------------------------|--|
| TOILET ROOM - STAFF                | · •  |
| Lighting                           |  |
| Lighting Fixture - Fluorescent     |  |
| Surface Mounted                    | Inspected                                  |
| Condition                          | 2- Between Good and Fair                   |
| Deficiency                         | No deficiencies recorded                   |
| Recessed Mounted                   | Does not exist                             |
| Lighting Fixture - HID             | Does not exist                             |
| Lighting Fixture - Incandescent    | Does not exist                             |
| Lighting Fixture - LED             | Does not exist                             |
| TOILET ROOM - STUDENT              | Inspected                                  |
| Lighting                           | Inspected                                  |
| Lighting Fixture - Fluorescent     | Inspected                                  |
| Pendant Mounted                    | Inspected                                  |
| Condition                          | 2- Between Good and Fair                   |
| Deficiency                         | No deficiencies recorded                   |
| Surface Mounted                    | Inspected                                  |
| Condition                          | 2- Between Good and Fair                   |
| Deficiency                         | No deficiencies recorded                   |
| Recessed Mounted                   | Does not exist                             |
| Lighting Fixture - HID             | Does not exist                             |
| Lighting Fixture - Incandescent    | Does not exist                             |
| Lighting Fixture - LED             | Inspected                                  |
| Pendant Mounted                    | Does not exist                             |
| Surface Mounted                    | Does not exist                             |
| Recessed Mounted                   | Inspected                                  |
| Condition                          | 2- Between Good and Fair                   |
| Deficiency                         | No deficiencies recorded                   |
| AUXILIARY SIGNAL/BELL SYSTEM       | Inspected                                  |
| Condition                          | 3- Fair                                    |
| Deficiency                         | No deficiencies recorded                   |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist                             |
| EMERGENCY GENERATOR SET            | Inspected                                  |
| Automatic Transfer Switch (ATS)    | Inspected                                  |
| Instance                           | Electrical Room B1                         |
| Instance Condition                 | 3- Fair                                    |
| Instance Quantity                  | 1  |
| Instance Quantity Uom              | EACH                                       |
| Manufacturer                       | GE Zenith Controls                         |
| EquipmentId                        | Fire Alarm ATS                             |
| Capacity/Size Quantity             | 40   |
| Capacity/Size UOM                  | Amps                                       |
| Source of Capacity/Size            | Nameplate                                  |
| Installation Year                  | 1995                                       |
| Source of Installation Year        | Documented  No deficiencies recorded       |
| Deficiency                         |  |
| Instance Instance Condition        | Room B26 3- Fair                           |
|                                    |  |
| Instance Quantity                  | 1<br>EACH                                  |
| Instance Quantity Uom              | EACH                                       |
| Manufacturer                       | Kohler Power Systems                       |
| EquipmentId Capacity/Size Quantity | A.T.S. Power System Transfer Switch<br>400 |
| Capacity/Size UOM                  | Amps                                       |
|                                    | 1  |

## **Building Condition Assessment Survey 2023-2024**

| Electrical Inspection | 1/11/55 |
|-----------------------|---------|
|                       | onse    |

| Question   | Response                 |
|--|--------------------------|
| EMERGENCY GENERATOR SET                          |                          |
| Automatic Transfer Switch (ATS)                  |                          |
| Source of Capacity/Size                          | Nameplate                |
| Installation Year                                | 1995                     |
| Source of Installation Year                      | Documented               |
| Deficiency                                       | No deficiencies recorded |
| Battery Charger                                  | Inspected                |
| Instance   | Room B26                 |
| Instance Condition                               | 2- Between Good and Fair |
| Instance Quantity                                | 1                        |
| Instance Quantity Uom                            | EACH                     |
| Manufacturer                                     | SENS                     |
| EquipmentId                                      | Battery Charger          |
| Capacity/Size Quantity                           | 10                       |
| Capacity/Size UOM                                | AmpsDC                   |
| Capacity/Size 2 Quantity                         | 12                       |
| Capacity/Size 2 UOM                              | VDC                      |
| Source of Capacity/Size                          | Nameplate                |
| Installation Year                                | 2017                     |
| Source of Installation Year                      | Documented               |
| Deficiency                                       | No deficiencies recorded |
| Emergency Distribution Board                     | Inspected                |
| Number of Spares                                 | 0                        |
| Fused Disconnect Switch Type                     | Inspected                |
| Instance   | Room B26                 |
| Instance Condition                               | 3- Fair                  |
| Instance Quantity                                | 1                        |
| Instance Quantity Uom                            | EACH                     |
| Manufacturer                                     | All City Switchboard     |
| EquipmentId                                      | EDP                      |
| Capacity/Size Quantity                           | 400                      |
| Capacity/Size UOM                                | Amps Total               |
| Capacity/Size 2 Quantity                         | 1                        |
| Capacity/Size 2 UOM                              | Section(s)               |
| Source of Capacity/Size                          | Switchboard Mains Size   |
| Installation Year                                | 1995                     |
| Source of Installation Year                      | Documented               |
| Deficiency                                       | No deficiencies recorded |
| Molded Case Circuit Breaker Type                 | Does not exist           |
| Diesel   | Inspected                |
| Instance   | Room B26                 |
| Instance Condition                               | 3- Fair                  |
| Instance Quantity                                | 1                        |
| Instance Quantity Uom                            | EACH                     |
| Manufacturer                                     | Kohler Power Systems     |
| EquipmentId                                      | Emergency Generator      |
| Capacity/Size Quantity                           | 125                      |
| Capacity/Size UOM                                | kVA                      |
| Capacity/Size 2 Quantity                         | 100                      |
| Capacity/Size 2 UOM                              | kW                       |
| Capacity/Size 3 Quantity                         | 347                      |
| Capacity/Size 3 UOM                              | Amps                     |
| Source of Capacity/Size                          | Nameplate 1995           |
| Installation Year<br>Source of Installation Year | Documented               |
|  |                          |
| Deficiency                                       | No deficiencies recorded |
| Natural Gas                                      | Does not exist           |

## **Building Condition Assessment Survey 2023-2024**

| Question                         | Response                 |  |
|----------------------------------|--------------------------|--|
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not exist           |  |
| EMERGENCY LIGHTING               | Inspected                |  |
| Battery Pack                     | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | BATTERY NOT OPERATIONAL  |  |
| Deficiency Location/Instance     | Exit 7                   |  |
| Deficiency Quantity              | 1                        |  |
| Quantity Uom                     | EACH                     |  |
| Potential Action                 | REPLACE BATTERY          |  |
| Urgency of Action                | PRIORITY 5               |  |
| Purpose of Action                | LEVEL 4                  |  |
| Violations                       | 35498261R                |  |
| Non Battery Pack                 | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| EXIT LIGHT                       | Inspected                |  |
| Battery Pack                     | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| Non Battery Pack                 | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| EXIT/EMERGENCY LIGHT             | Inspected                |  |
| Condition                        | 1- Good                  |  |
| Deficiency                       | No deficiencies recorded |  |
| FIRE ALARM SYSTEM                | Inspected                |  |
| Bell/Horn                        | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| Strobe                           | Inspected                |  |
| Condition                        | 4- Between Fair and Poor |  |
| Deficiency                       | STROBE NOT OPERATIONAL   |  |
| Deficiency Location/Instance     | Throughout the Building  |  |
| Deficiency Quantity              | 25                       |  |
| Quantity Uom                     | EACH                     |  |
| Potential Action                 | REPLACE                  |  |
| Urgency of Action                | PRIORITY 5               |  |
| Purpose of Action                | LEVEL 6                  |  |
| Violations                       | No violations recorded   |  |
| Manual Pull Station              | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| Fan Shutdown Control             | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| Duct Smoke Detector              | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | No deficiencies recorded |  |
| Area Smoke Detector              | Inspected                |  |
| Condition                        | 3- Fair                  |  |
| Deficiency                       | DETECTOR NOT OPERATIONAL |  |
| Deficiency Location/Instance     | Room B26                 |  |
| Deficiency Quantity              | 1                        |  |
| Quantity Uom                     | EACH<br>PEN A CE         |  |
| Potential Action                 | REPLACE                  |  |

## **Building Condition Assessment Survey 2023-2024**

| cui inspection                        | 1911;                              |
|---------------------------------------|------------------------------------|
| estion                                | Response                           |
| IRE ALARM SYSTEM                      |                                    |
| Area Smoke Detector                   |                                    |
| Urgency of Action                     | PRIORITY 5                         |
| Purpose of Action                     | LEVEL 6                            |
| Violations                            | No violations recorded             |
| CO Detector                           | Does not exist                     |
| Heat Detector                         | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Elevator Recall                       | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Magnetic Door Holder/Contactor        | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Fused Cutout Panel                    | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Fire Alarm Digital Communicator       | Does not exist                     |
| Main Panel                            | Inspected                          |
| Bell At Panel                         | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Fire Alarm Control Panel (Electronic) | Inspected                          |
| Instance                              | Boiler Room                        |
| Instance Condition                    | 3- Fair                            |
| Instance Quantity                     | 1                                  |
| Instance Quantity Uom                 | EACH                               |
| Manufacturer                          | Cerberus Pyrotronics               |
| Model                                 | MXL                                |
| EquipmentId                           | Fire Alarm Panel                   |
| Installation Year                     | 1995                               |
| Source of Installation Year           | Documented                         |
| Deficiency                            | No deficiencies recorded           |
| Fire Alarm Control Panel (Standard)   | Does not exist                     |
| Sub-Panel                             | Inspected                          |
| Bell At Panel                         | Inspected                          |
| Condition                             | 3- Fair                            |
| Deficiency                            | No deficiencies recorded           |
| Fire Alarm Control Panel (Electronic) | Inspected                          |
| Instance                              | Building "K" - 1st Floor By Exit 9 |
| Instance Condition                    | 3- Fair                            |
| Instance Quantity                     | 1                                  |
| Instance Quantity Uom                 | EACH                               |
| Manufacturer                          | Cerberus Pyrotronics               |
| Model                                 | CP - 35                            |
| EquipmentId                           | F.A. SUB Panel (Purge Enable)      |
| Installation Year                     | 1995                               |
| Source of Installation Year           | Documented                         |
| Deficiency                            | No deficiencies recorded           |
| Instance                              | Boiler Room                        |
| Instance Condition                    | 3- Fair                            |
| instance Condition                    |                                    |

## **Building Condition Assessment Survey 2023-2024**

| vent inspection                        |   | 1,110 |
|--|---|-------|
| uestion                                | Response                                  |       |
| FIRE ALARM SYSTEM                      |   |       |
| Sub-Panel                              |   |       |
| Fire Alarm Control Panel (Electronic)  |   |       |
| Manufacturer                           | Cerberus Pyrotronics                      |       |
| Model                                  | System 3                                  |       |
| EquipmentId                            | Fire Alarm Panel (Horn and Strobes Panel) |       |
| Installation Year                      | 1995                                      |       |
| Source of Installation Year            | Documented                                |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Instance                               | Boiler Room                               |       |
| Instance Condition                     | 3- Fair                                   |       |
| Instance Quantity                      | 1   |       |
| Instance Quantity Uom                  | EACH                                      |       |
| Manufacturer                           | Pyrotronics                               |       |
| Model                                  | System 3                                  |       |
| EquipmentId                            | Holding Areas                             |       |
| Installation Year                      | 1995                                      |       |
| Source of Installation Year            | Documented                                |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Fire Alarm Control Panel (Standard)    | Does not exist                            |       |
| Remote Annunciator                     | Inspected                                 |       |
| Display Monitor                        | Does not exist                            |       |
| Panel                                  | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Printer                                | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Punch Register                         | Does not exist                            |       |
| Sprinkler Flow/Air Pressure Switch     | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Tamper Flow Switch/Chain               | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| GROUNDING SYSTEM                       | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| INTERCOM SYSTEM                        | Inspected                                 |       |
| Elevator                               | Inspected                                 |       |
| Condition                              | 3- Fair                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Holding Area                           | Does not exist                            |       |
| LAN                                    | Inspected                                 |       |
| Local Distribution Frame (I/LDF)       | Inspected                                 |       |
| Condition                              | 1- Good                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| Main Equipment Rack (MDF)              | Inspected                                 |       |
| Condition                              | 1- Good                                   |       |
| Deficiency                             | No deficiencies recorded                  |       |
| LIGHTNING PROTECTION                   | Does not exist                            |       |
| MOTOR CONTROLLER                       | Inspected                                 |       |
| MOTOR CONTROLLER  MOTOR CONTROL CENTER | Inspected                                 |       |
| MICHAR CONTROL CENTERS                 | mspected                                  |       |

## **Building Condition Assessment Survey 2023-2024**

| uestion                          | Response                              |
|----------------------------------|---------------------------------------|
| MOTOR CONTROLLER                 |                                       |
| MOTOR CONTROL CENTER             |                                       |
| Instance Condition               | 3- Fair                               |
| Instance Quantity                | 1                                     |
| Instance Quantity Uom            | EACH                                  |
| Manufacturer                     | Gallagher                             |
| EquipmentId                      | N/A                                   |
| Capacity/Size Quantity           | 225                                   |
| Capacity/Size UOM                | Amps                                  |
| Capacity/Size 2 Quantity         | 1                                     |
| Capacity/Size 2 UOM              | Section(s)                            |
| Source of Capacity/Size          | Inspector Estimate                    |
| Installation Year                | 1975                                  |
| Source of Installation Year      | Documented                            |
| Deficiency                       | BEYOND USEFUL LIFE                    |
| Deficiency Location/Instance     | Boiler Room                           |
| Deficiency Quantity              | 1                                     |
| Quantity Uom                     | EACH                                  |
| Potential Action                 | REPLACE                               |
| Urgency of Action                | PRIORITY 1                            |
| Purpose of Action                | LEVEL 2                               |
| Violations                       | No violations recorded                |
| MOTOR STARTER/CONTACTOR          | Inspected                             |
| Condition                        | 3- Fair                               |
| Deficiency                       | No deficiencies recorded              |
| Variable Frequency Drive         | Does not exist                        |
| PANEL BOARD                      | Inspected                             |
| Fused Disconnect Switch Type     | Inspected                             |
| Condition                        | 3- Fair                               |
| Deficiency                       | PANEL BOARD BEYOND USEFUL LIFE        |
| Deficiency Location/Instance     | Boiler Room, Basement Mechanical Room |
| Deficiency Quantity              | 3                                     |
| Quantity Uom                     | EACH                                  |
| Potential Action                 | REPLACE-UPGRADE                       |
| Urgency of Action                | PRIORITY 1                            |
| Purpose of Action                | LEVEL 2                               |
| Violations                       | No violations recorded                |
| Fused Knife Switch Type          | Does not exist                        |
| Fused Toggle Switch Type         | Does not exist                        |
| Molded Case Circuit Breaker Type | Inspected                             |
| Condition                        | 3- Fair                               |
| Deficiency                       | PANEL BOARD BEYOND USEFUL LIFE        |
| Deficiency Location/Instance     | Throughout the Building               |
| Deficiency Quantity              | 18                                    |
| Quantity Uom                     | EACH                                  |
| Potential Action                 | REPLACE-UPGRADE                       |
| Urgency of Action                | PRIORITY 1                            |
| Purpose of Action                | LEVEL 2                               |
| Violations                       | No violations recorded                |
| Deficiency                       | PANEL BOARD COVER IS MISSING          |
| Deficiency Location/Instance     | Corridor near Room B8                 |
| Deficiency Quantity              | 1                                     |
| Quantity Uom                     | EACH                                  |
| Potential Action                 | MAINTENANCE                           |
| Urgency of Action                | PRIORITY 2                            |
| Purpose of Action                | LEVEL 2                               |
|                                  | <del></del>                           |

## **Building Condition Assessment Survey 2023-2024**

| estion                           | Response                      |
|----------------------------------|-------------------------------|
| PANEL BOARD                      |                               |
| Molded Case Circuit Breaker Type |                               |
| Violations                       | No violations recorded        |
| PUBLIC ADDRESS SYSTEM            | Inspected                     |
| Instance                         | General Office - Room 115     |
| Instance Condition               | 3- Fair                       |
| Instance Quantity                | 1                             |
| Instance Quantity Uom            | EACH                          |
| Model                            | Rauland Telecenter IV         |
| Installation Year                | 1980                          |
| Source of Installation Year      | Inspector Estimate            |
| Deficiency                       | CLOCK NOT OPERATIONAL         |
| Deficiency Location/Instance     | Classrooms and Corridors      |
| Deficiency Quantity              | 10                            |
| Quantity Uom                     | EACH                          |
| Potential Action                 | REPLACE                       |
| Urgency of Action                | PRIORITY 3                    |
| Purpose of Action                | LEVEL 2                       |
| Violations                       | No violations recorded        |
| Deficiency                       | BEYOND USEFUL LIFE            |
| Deficiency Location/Instance     | General Office - Room 115     |
| Deficiency Quantity              | 135,000                       |
| Quantity Uom                     | S.F.                          |
| Potential Action                 | REPLACE                       |
| Urgency of Action                | PRIORITY 1                    |
| Purpose of Action                | LEVEL 2                       |
| Violations                       | No violations recorded        |
| SECURITY                         | Inspected                     |
| IPDVS/CCTV System                | Does not exist                |
| Intrusion Alarm System           | Inspected                     |
| Central Control Panel            | Inspected                     |
| Instance                         | Custodian's Office - Room 130 |
| Instance Condition               | 3- Fair                       |
| Instance Quantity                | 1                             |
| Instance Quantity Uom            | EACH                          |
| Model                            | Vista - 128B                  |
| Installation Year                | 2006                          |
| Source of Installation Year      | Documented                    |
| Deficiency                       | No deficiencies recorded      |
| Infrared Sensor                  | Inspected                     |
| Condition                        | 3- Fair                       |
| Deficiency                       | No deficiencies recorded      |
|                                  | Inspected                     |
| Panic Switch Condition           |                               |
|                                  | 3- Fair                       |
| Deficiency                       | No deficiencies recorded      |
| Remote Annunciator               | Inspected                     |
| Condition                        | 3- Fair                       |
| Deficiency                       | No deficiencies recorded      |
| Siren/Strobe                     | Inspected                     |
| Condition                        | 3- Fair                       |
| Deficiency                       | No deficiencies recorded      |
|                                  | Inspected                     |
| Lighting - Security              |                               |
| Lighting - Security Condition    | 3- Fair                       |

## **Building Condition Assessment Survey 2023-2024**

| nestion SECURITY             | Response                                 |  |
|------------------------------|--|--|
| SECURITY                     |  |  |
| Lighting - Security          | P. 445 - P. 4                            |  |
| Deficiency Location/Instance | Building Perimeters                      |  |
| Deficiency Quantity          | 40                                       |  |
| Quantity Uom                 | EACH                                     |  |
| Potential Action             | REPLACE-UPGRADE                          |  |
| Urgency of Action            | PRIORITY 1                               |  |
| Purpose of Action            | LEVEL 3                                  |  |
| Violations                   | No violations recorded                   |  |
| Deficiency                   | LIGHTING FIXTURE NOT OPERATIONAL         |  |
| Deficiency Location/Instance | Roof                                     |  |
| Deficiency Quantity          | 4  |  |
| Quantity Uom                 | EACH                                     |  |
| Potential Action             | REPLACE                                  |  |
| Urgency of Action            | PRIORITY 3                               |  |
| Purpose of Action            | LEVEL 3                                  |  |
| Violations                   | No violations recorded                   |  |
| ERVICE SWITCH                | Inspected                                |  |
| Instance                     | Electrical Room B1                       |  |
| Instance Condition           | 3- Fair                                  |  |
| Instance Quantity            | 1  |  |
| ·                            | EACH                                     |  |
| Instance Quantity Uom        | Gallagher                                |  |
| Manufacturer                 |  |  |
| EquipmentId                  | Air Conditioning Equipment Power Service |  |
| Capacity/Size Quantity       | 1200                                     |  |
| Capacity/Size UOM            | Amps                                     |  |
| Source of Capacity/Size      | Nameplate                                |  |
| Installation Year            | 1975                                     |  |
| Source of Installation Year  | Documented                               |  |
| Deficiency                   | BEYOND USEFUL LIFE                       |  |
| Deficiency Location/Instance | Electrical Room B1                       |  |
| Deficiency Quantity          | 1  |  |
| Quantity Uom                 | EACH                                     |  |
| Potential Action             | REPLACE                                  |  |
| Urgency of Action            | PRIORITY 1                               |  |
| Purpose of Action            | LEVEL 2                                  |  |
| Violations                   | No violations recorded                   |  |
| Instance                     | Electrical Room B1                       |  |
| Instance Condition           | 3- Fair                                  |  |
| Instance Quantity            | 1  |  |
| <u></u>                      | EACH                                     |  |
| Instance Quantity Uom        |  |  |
| Manufacturer                 | Gallagher                                |  |
| EquipmentId                  | Main Light and Power                     |  |
| Capacity/Size Quantity       | 2500                                     |  |
| Capacity/Size UOM            | Amps                                     |  |
| Source of Capacity/Size      | Inspector Estimate                       |  |
| Installation Year            | 1995                                     |  |
| Source of Installation Year  | Documented                               |  |
| Deficiency                   | No deficiencies recorded                 |  |
| Instance                     | Electrical Room B1                       |  |
| Instance Condition           | 3- Fair                                  |  |
| Instance Quantity            | 1  |  |
| Instance Quantity Uom        | EACH                                     |  |
| Manufacturer                 | Siemens                                  |  |
| EquipmentId                  | Main (Addition New Wing)                 |  |
| Capacity/Size Quantity       | 800                                      |  |

## **Building Condition Assessment Survey 2023-2024**

| cirical Inspection                                 | 148                                   |
|--|---------------------------------------|
| Question   | Response                              |
| SERVICE SWITCH                                     |                                       |
| Capacity/Size UOM                                  | Amps                                  |
| Source of Capacity/Size                            | Nameplate                             |
| Installation Year                                  | 1995                                  |
| Source of Installation Year                        | Documented                            |
| Deficiency   | No deficiencies recorded              |
|  | Electrical Room B1                    |
| Instance Instance Condition                        | 3- Fair                               |
| Instance Quantity                                  |                                       |
|  | 1<br>EACH                             |
| Instance Quantity Uom                              |                                       |
| Manufacturer                                       | Siemens                               |
| EquipmentId  | Kitchen Power Panel                   |
| Capacity/Size Quantity                             | 400                                   |
| Capacity/Size UOM                                  | Amps                                  |
| Source of Capacity/Size                            | Nameplate                             |
| Installation Year                                  | 1995                                  |
| Source of Installation Year                        | Documented                            |
| Deficiency   | No deficiencies recorded              |
| Instance   | Electrical Room B1                    |
| Instance Condition                                 | 3- Fair                               |
| Instance Quantity                                  | 1                                     |
| Instance Quantity Uom                              | EACH                                  |
|  | Gallagher                             |
| Manufacturer                                       | · · · · · · · · · · · · · · · · · · · |
| EquipmentId  | Heating Equipment Power Service       |
| Capacity/Size Quantity                             | 400                                   |
| Capacity/Size UOM                                  | Amps                                  |
| Source of Capacity/Size                            | Nameplate                             |
| Installation Year                                  | 1975                                  |
| Source of Installation Year                        | Documented                            |
| Deficiency   | BEYOND USEFUL LIFE                    |
| Deficiency Location/Instance                       | Electrical Room B1                    |
| Deficiency Quantity                                | 1                                     |
| Quantity Uom                                       | EACH                                  |
| Potential Action                                   | REPLACE                               |
| Urgency of Action                                  | PRIORITY 1                            |
| Purpose of Action                                  | LEVEL 2                               |
| Violations   | No violations recorded                |
| SWITCHBOARD  | Inspected                             |
| Number of Spares                                   | 1                                     |
| Fused Disconnect Switch Type                       | Inspected                             |
| Instance   | Electrical Room B1                    |
|  | 3- Fair                               |
| Instance Condition                                 |                                       |
| Instance Quantity                                  | 1                                     |
| Instance Quantity Uom                              | EACH                                  |
| Manufacturer                                       | Gallagher Switchboard Co.             |
| EquipmentId  | N/A                                   |
| Capacity/Size Quantity                             | 2500                                  |
| Capacity/Size UOM                                  | Amps Total                            |
| Capacity/Size 2 Quantity                           | 3                                     |
| Capacity/Size 2 UOM                                | Section(s)                            |
| Source of Capacity/Size                            | Inspector Estimate                    |
| Installation Year                                  | 1975                                  |
| Source of Installation Year                        | Documented                            |
| Deficiency   | BEYOND USEFUL LIFE                    |
| Deficiency Location/Instance                       | Electrical Room B1                    |
| Deficiency Quantity                                | 1                                     |
| , <del>\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \</del> | •                                     |
|  |                                       |

# **Building Condition Assessment Survey 2023-2024**

| Question                         | Response                 |
|----------------------------------|--------------------------|
| SWITCHBOARD                      |                          |
| Fused Disconnect Switch Type     |                          |
| Quantity Uom                     | EACH                     |
| Potential Action                 | REPLACE                  |
| Urgency of Action                | PRIORITY 1               |
| Purpose of Action                | LEVEL 2                  |
| Violations                       | No violations recorded   |
| Instance                         | Room B26                 |
| Instance Condition               | 3- Fair                  |
| Instance Quantity                | 1                        |
| Instance Quantity Uom            | EACH                     |
| Manufacturer                     | All City Switchboard     |
| EquipmentId                      | DB-KA                    |
| Capacity/Size Quantity           | 800                      |
| Capacity/Size UOM                | Amps Total               |
| Capacity/Size 2 Quantity         | 1                        |
| Capacity/Size 2 UOM              | Section(s)               |
| Source of Capacity/Size          | Inspector Estimate       |
| Installation Year                | 1995                     |
| Source of Installation Year      | Documented               |
| Deficiency                       | No deficiencies recorded |
| Fused Knife Switch Type          | Does not exist           |
| Molded Case Circuit Breaker Type | Does not exist           |
| TELEPHONE SYSTEM                 | Inspected                |
| PBX/Intercom                     | Inspected                |
| Condition                        | 1- Good                  |
| Deficiency                       | No deficiencies recorded |
| Standard                         | Inspected                |
| Condition                        | 1- Good                  |
| Deficiency                       | No deficiencies recorded |
| TRANSFORMER                      | Does not exist           |
|                                  |                          |