Building Condition Assessment Survey 2023-2024

Electrical Inspection	M154
-----------------------	------

Asset:	P.S. 154 - M.	ANHATTAN, 250 WEST 127	7 STREET, MANH	ATTAN, NY, 10	027		
Inspectio	n Id Inspection Ty	pe			Time	In	Last Edited
	2616 ELECTRICAL	٠			2024-	01-23 09:19A	M 2024-02-13 09:17AN
sset Data							
Question				Answer			
Have any	Systems/Major Build	ing Components been upgraded?		Systems:	LAN, Partial	Security Lighti	ng
•				Years:	2023		
				Systems:	Partial Molde	d Case Circuit	Breaker Panel Boards
				Years:	2019, 2014		
				Systems:			em, Local Sound System, re Alarm System (Sprinkler
				Years:	2017		
				Systems:	Interior Light Battery Pack)		ergency Lighting (Non
				Years:	2014		
				Systems:	Telephone Sy	stem	
				Years:	2012		
				Systems:	Public Addres (Cafeteria, Gy	•	al Sound System
				Years:	2008	iiiiusiuiii)	
				Systems:	Security Ligh	ting	
				Years:	2006	-	
				Systems:	Intrusion Alar	m	
				Years:	2002		
Type of S	ervice			Below Gr	round		
	eractive Whiteboard (I	WB) Exist?		Yes			
Water Per	netration In Electrical	Room?		No			
		IS IN FIRE RESCUE AREA	AS				
Question		sistance Areas, Fire Rescue Area	and/or Holding Poor		Response No		
your bu		sistance Areas, The Rescue Area	s, and/or froiding Koor	ilis ili — 1	NU		
Priority Co							
Exist Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Manual Pull Station	Gymnasium, Basement Near Exit C.	Kenyatta Collins	Fireman	No Photo Taken
Inspection	1						
Question				Response			
Electrica				F	<u> </u>		
	ETIC FIELD			Does not	exist		
	ORIUM			Inspected			
	Instance on 1st Flo	oor		Inspected			
Hous	e Lighting			1			
	Instance on 1st Flo	oor		Inspected			
	Does a Chandelier	Exist?		No			
Lig	hting Fixture - Fluor	escent					
_	Instance on 1st Flo	oor		Inspected			
P	endant Mounted						
	Instance on 1st Flo	oor		Inspected			
	Instance Condition	n		2- Betwee	en Good and Fai	r	
_	Deficiency			No deficie	encies recorded		
S	urface Mounted						
	Instance on 1st Flo	oor		Inspected			

Building Condition Assessment Survey 2023-2024

uestion	Response	·
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	30	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	<u> </u>

Building Condition Assessment Survey 2023-2024

cui Inspection		1711.
estion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System	DOGS HOL CAISE	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	Two deficiences recorded	
Instance on 1st Floor	Does not exist	
	DOGS HOL CAISE	
Theater Lighting System Instance on 1st Floor	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
	Inspected	
Lighting Fixture - Fluorescent Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
-	No deficiencies recorded	
Deficiency		
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
	Υ , 1	
Surface Mounted	Inspected	
Surface Mounted Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

aricai Inspection	171	1154
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 226	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 226	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 226	Inspected	
Pendant Mounted		
Instance on Room 226	Does not exist	
Surface Mounted		
Instance on Room 226	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
Recessed Mounted		
Instance on Room 226	Does not exist	
Lighting Fixture - HID		
Instance on Room 226	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 226	Does not exist	
Lighting Fixture - LED		
Instance on Room 226	Does not exist	
Raceway With Receptacles		
Instance on Room 226	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M154
Question	Response

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 213	Inspected
Instance on Room 330	Inspected
Lighting	
Instance on Room 213	Inspected
Instance on Room 330	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 213	Inspected
Instance on Room 330	Inspected
Pendant Mounted	
Instance on Room 213	Does not exist
Instance on Room 330	Does not exist
Surface Mounted	
Instance on Room 213	Inspected
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

icui Inspection		14113
uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Instance on Room 330	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 213	Does not exist	
Instance on Room 330	Does not exist	
Lighting Fixture - HID		
Instance on Room 213	Does not exist	
Instance on Room 330	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 213	Does not exist	
Instance on Room 330	Does not exist	
Lighting Fixture - LED		
Instance on Room 213	Does not exist	
Instance on Room 330	Does not exist	
Raceway With Receptacles		
Instance on Room 213	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 330	Does not exist	
Projection System		
Instance on Room 213	Does not exist	
Instance on Room 330	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
Alternative Use	Yes	
Instance on 1st Floor - Girls	Inaccessible	
Lighting		
Instance on 1st Floor - Boys	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Boys	Inspected	
Pendant Mounted		
Instance on 1st Floor - Boys	Does not exist	
Surface Mounted		
Instance on 1st Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Boys	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	

Building Condition Assessment Survey 2023-2024

iricui Inspection	
Question	Response
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition Condition	3- Fair
Deficiency	No deficiencies recorded
•	
EMERGENCY LIGHTING	Inspected
Battery Pack Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
<u> </u>	Inspected
Non Battery Pack Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
	Inspected
Non Battery Pack Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Third Floor Staircase C, Outside Room 309
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

	IVIII
estion	Response
XIT/EMERGENCY LIGHT	Does not exist
IRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	PULL STATION NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Basement Near Staircase C
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Main Panel
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Fire Alarm Control Panel (Electronic) Fire Alarm Control Panel (Standard)	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	90,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
	Does not exist
Remote Annunciator	Inspected
Sprinkler Flow/Air Pressure Switch Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
· · · · · · · · · · · · · · · · · · ·	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

uestion	Response
PANEL BOARD	
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 126
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 130
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	-
	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

rical Inspection	M
uestion	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B8
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Generator Disconnect Switch 89L-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B8
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Main Service Switch
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B8
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	Main Switchboard
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3 Section(a)
Capacity/Size 2 UOM Source of Capacity/Size	Service Switch Size

Service Switch Size

BEYOND USEFUL LIFE

1964

Documented

Source of Capacity/Size

Installation Year Source of Installation Year

Deficiency

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Location/Instance	Electrical Room B8	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	