Building Condition Assessment Survey 2023-2024

Asset:	P.S. 175 - MANI	IATTAN, 175 WEST IC	74 STREET, WITH THE	A1 1A11, N1, 10			
Inspection Id	Inspection Type				Time In		Last Edited
	ELECTRICAL				2024-01-25 10:	44AM	2024-02-13 08:49AN
set Data							
Question				Answer			
Have any Syste	ms/Major Building (Components been upgraded	?	Systems:	Auxiliary Signal/Bell Sy Variable Frequency Driv		icator Panel),
				Years:	2023		
				Systems:	Most Exit Lights (Batter	y Pack)	
				Years:	2022		
				Systems:	Partial Molded Case Circ		er Panel Board
				Years:	2021, 2017, 2012, 2000,	1995	
				Systems:	Security Lighting		
				Years:	2021, 2016 (Retrofitted)		
				Systems:	Intrusion Alarm System	(Infrared	Sensor)
				Years:	2021		
				Systems:	Partial Emergency Light	ing (Batte	ry Pack)
				Years:	2018		
				Systems:	Intrusion Alarm System	(Panic Sw	vitch)
				Years:	2015		
				Systems:	Student Toilet Rooms (F	luorescen	t Lighting)
				Years:	2014, 2008		
				Systems:	Interior Lighting, Compu Lighting (Non Battery P		Partial Emergency
				Years:	2014		
				Systems:	Partial Motor Starters		
				Years:	2012		
				Systems:	Library (Raceway With	Receptacl	es)
				Years:	2010		
				Systems:	Fire Alarm System (Exce System, Local Sound Sy	-	
				Years:	2006		
				Systems:	Intrusion Alarm System Sensor), Emergency Lig		
				Years:	2000		
Type of Service				Below Gr	ound		
	e Whiteboard (IWB)			Yes			
	on In Electrical Room		1.0	No			
) INTERCOMS I	N FIRE RESCUE ARE	AS		D		
Are there any your building		nce Areas, Fire Rescue Are	as, and/or Holding Roor		Response No		
iority Condit	ion						
	ority	Condition	Component	Location	Person(s) Person(s	s) Ph	oto
	egory	Description	Affected	Description	Notified Title		age
No condition re							
nspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not	exist		
AUDITORI				Inspected			
_	stance on 1st Floor			Under con			
CAFETERL				Inspected			
-	stance on 1st Floor			Inspected			
Lighting							

Building Condition Assessment Survey 2023-2024

Electrical InspectionM175QuestionResponse

Question	Response
CAFETERIA	<u> </u>
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year Source of Installation Year	2006 Documented
Deficiency	No deficiencies recorded
	No deficiencies recorded
Projection System Instance on 1st Floor	Does not exist
Theater Lighting System	DOCS HOT CAIST
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 216	Inspected
Power Panel?	No
Lighting	
Instance on Room 216	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 216	Inspected
Pendant Mounted	
Instance on Room 216	Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response	
COMPUTER LAB	певропя	
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	To deficiences recorded	
Instance on Room 216	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 216	Does not exist	
	Does not exist	
Lighting Fixture - HID Instance on Room 216	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on Room 216	Does not exist	
Lighting Fixture - LED	Dona and City	
Instance on Room 216	Does not exist	
Raceway With Receptacles	Y 1	
Instance on Room 216	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

Theater Lighting System

KITCHEN

Does not exist

Does not exist Inspected

Inspected

Building Condition Assessment Survey 2023-2024

M175

Question	Response
KITCHEN	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

псан Іпѕресиоп		M17:
uestion	Response	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER		
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Manual I un Station		

Building Condition Assessment Survey 2023-2024

ent inspection		
estion	Response	
IRE ALARM SYSTEM		
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom	LACII	
Manufacturer		
E grainer and I d	ACME	
EquipmentId	ACME Sprinkler Alarm	
Installation Year	ACME Sprinkler Alarm 1958	
Installation Year Source of Installation Year	ACME Sprinkler Alarm 1958 Documented	
Installation Year Source of Installation Year Deficiency	ACME Sprinkler Alarm 1958 Documented BEYOND USEFUL LIFE	
Installation Year Source of Installation Year Deficiency Deficiency Location/Instance	ACME Sprinkler Alarm 1958 Documented BEYOND USEFUL LIFE Boiler Room	
Installation Year Source of Installation Year Deficiency	ACME Sprinkler Alarm 1958 Documented BEYOND USEFUL LIFE	

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected 3- Fair
Condition	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Quantity	Electrical Room B22
Deficiency Quantity	2 FACH
Quantity Uom Potential Action	EACH PEDLACE LIBORADE
Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY I
Purpose of Action	LEVEL 2
Purpose of Action Violations	No violations recorded
VIOIAUOIIS	INO VIOIAUOIIS FECOFICEU

Building Condition Assessment Survey 2023-2024

Question	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING	
Deficiency Location/Instance	Mechanical Room 230, Boiler Room	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL	
Deficiency Location/Instance	1st Floor (Electrical Closet - Room 113, by Exit 8)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE CIRCUIT BREAKER	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	General Office - Room 116	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Dukane 250	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	MASTER CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	General Office - Room 116	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	4- Between Fair and Poor	
Installation Year	2006	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

ricai inspection	N11/5
Question	Response
SECURITY	
IPDVS/CCTV System	
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	MDF Room 316
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 120
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2000
Source of Installation Year	Documented
Deficiency Deficiency Overtity	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	
Quantity Uom	EACH PICTALL CONDUCTION
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B22
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Service Switch A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation Year	Documented
	BEYOND USEFUL LIFE
•	
Deficiency Deficiency Location/Instance	BEYOND USEFUL LIFE Electrical Room B22

Building Condition Assessment Survey 2023-2024

ісаі Іпѕреспоп	MI
uestion	Response
SERVICE SWITCH	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B22
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Service Switch B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B22
Deficiency Quantity	l lectrical Robin B22
	EACH
Quantity Uom	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
WITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room B22
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Main Switchboard Section A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B22
Deficiency Quantity	
	1 Digit
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B22
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Molded Case Circuit Breaker Type		
Manufacturer	Gallagher Switchboard Co.	
EquipmentId	Main Switchboard Section B	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B22	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	