### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	P.S. 175 - MANHATTAN, 175 WEST 134 STREET, MANHATTAN, NY, 10030				
Inspection Id	Inspection Type		Time In	Last Edited	
2672	MECHANICAL		2024-01-25 08:14AM	2024-03-08 11:08PM	
sset Data					
Question		Answer			
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Water Service; Electric Pressure	Booster System	
		Years:	2023		
		Systems:	F&T/Steam Drip Traps		
		Years:	2022		

Systems: Terminal Unit Thermostatic Traps (~80%)

	· · · · · · · · · · · · · · · · · · ·
	Years: 2014
	Systems: Student Fixtures - Toilets (~80%), Urinals; Staff
	Fixtures - Toilets
	Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	20,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Boiler Room Mechanical Area; MER 230; Penthouse Fan Room
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Rooms B7, B21 (painted, 8)
Are there any Emergency Stop Switches with Missing Hammers?	No components

### **Priority Condition**

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Kitchen Gas System	Defective Shut-Off Switch	Gas System	Kitchen	MICHAEL GUSEK	Custodian	

#### Inspection

pecuon	
Question	Response
Mechanical	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Under construction
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pump
EquipmentId	N/A
Capacity/Size Quantity	2

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	10
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room Mechanical Area, Basement - Crawlspace
Instance Condition	1- Good
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	4- Between Fair and Poor
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	TANK RUSTY/LEAKS
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Under construction
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
	Inspected
Interior Storm Piping Condition	3- Fair

# Building Condition Assessment Survey 2023-2024

#### **Mechanical Inspection**

incui inspection	
estion	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Interior Storm Piping	
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Toilet	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Boy's Toilet Room 213
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Boy's Toilet Room 111, Girl's Toilet Room 217
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

estion	Response
IXTURES	
Student	
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AS FIRED FURNACE	Does not exist
AS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
EATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DAMAGED GUARD/SHIELD
Deficiency Location/Instance	Room 223, Corridor near Room 229
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Steam Condensate Return Piping	*
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

ianical Inspection		M17
Question	Response	
HEATING		
Steam Heating		
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Preferred Utilities	
Burner Model	BHE 8 3M4	
Burner Type	Oil	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Does not exist	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE ISOLATION VALVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity		
Quantity Uom Potential Action	EACH	
	MAINTENANCE PRIORITY 3	
Urgency of Action Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

tion	Response	
ATING PLANT		
oiler System		
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,087	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	National U.S. Radiator Corp.	
EquipmentId	47217-1	
Capacity/Size Quantity	70	
Capacity/Size UOM	Burner GPH	
Source of Capacity/Size	Documented	
Installation Year Source of Installation Year	1958 Desumented	
Deficiency	Documented LEAKY/PLUGGED TUBES	
Deficiency Quantity	LEAK I/PLUGGED TUBES	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6.087	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	National U.S. Radiator Corp.	
EquipmentId	47217-2	
Capacity/Size Quantity	70	
Capacity/Size UOM	Burner GPH	
Source of Capacity/Size	Documented	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	LEAKY/PLUGGED TUBES	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2	
Violations	LEVEL 2 No violations recorded	
uel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

estion		Response
IEATIN	G PLANT	
Fuel Sy	stem	
Fuel (	Dil Storage/Supply System	
	Instance on Basement	Inspected
	Instance Condition	3- Fair
	Deficiency	FUEL OIL PIPING:DEFECTIVE/LEAKS
	Deficiency Location/Instance	Basement near Oil Tank Room
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	MAINTENANCE
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Gas T	rains And Vent At The Boiler	
	Instance on Basement	Does not exist
nclosed	IDF Room	Inspected
	Instance on Room 135	Inspected
Dedicat	ed A/C Equipment	<b>.</b>
	Instance on Room 135	Inspected
	Instance Condition	4- Between Fair and Poor
	Deficiency	DOES NOT EXIST
	Deficiency Location/Instance	Room 135
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	INSTALL
	Urgency of Action	PRIORITY 3
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
атсне	N	Inspected
ITCHE	Instance on 1st Floor	Inspected
CO Det		
CO Du	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Cas Sus		
Gas Sys	Instance on 1st Floor	Inspected
	Instance On 1st Floor	4- Between Fair and Poor
	Deficiency	DEFECTIVE SHUT-OFF SWITCH
	Deficiency Location/Instance Deficiency Quantity	Kitchen 1
	Quantity Uom	1 EACH
	Quantity Uom Potential Action	EACH MAINTENANCE
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 6
	Violations	No violations recorded
C		No violations recorded
Grease	Irap Instance on 1st Floor	Does not exist
Hood		
11000	Instance on 1st Floor	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Harle		
Hood E	xhaust Ductwork	Turmontod
	Instance on 1st Floor Instance Condition	Inspected 3- Fair

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response	
ATCHEN		
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen (1 of 2)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
IDF Room	Inspected	
Instance on Room 316	Inspected	
Dedicated A/C Equipment		
Instance on Room 316	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Does not exist	
CIENCE PREP ROOM	Does not exist	
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Rooms B7, B21 (painted, 8)	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	REPLACE PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations		

### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

uestion	Response	
	Kaponat	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	Penthouse Fan Room @ Toilet Exhust #8; MER 230 @	
	Gymnasium Blower #3, Kitchen Exhaust #5	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE MOTOR	
Deficiency Location/Instance	Cafeteria	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	