Building Condition Assessment Survey 2023-2024

Electrical Inspection M180
Liectical Inspection (VIII)

Inspectio	on Id Inspection Type				Time	In	Last Edited
	2272 ELECTRICAL					01-09 09:14AM	
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Gymnasium (LED Lighting)	
	, -,g			Years:	2021	0 0	
				Systems:	IPDVS/CCTV	/ System, Intrusi	on Alarm System
				Years:	2016		·
				Systems:	Telephone Sys Pack)	stem, Partial Em	ergency Lighting (Battery
				Years:	2015		
				Systems:	Science Lab F	Room 430	
				Years:	2014		
				Systems:		escent Lighting, a Battery Pack)	Partial Emergency
				Years:	2012		
				Systems:	Fire Alarm System, Public Address System, Local Sound System, Auditorium (Dimming System, Most		
				37	Theater Light	ing)	
				Years:	2008 Moldad Cosa	Circuit Da1	Donal Doord Emarco
				Systems:	Light/Exit Lig		Panel Board, Emergency
	~ ·			Years:	2007		
Type of S) F : (9		Below Gro	ound		
	eractive Whiteboard (IWB) enetration In Electrical Roo			Yes No			
		IN FIRE RESCUE AREAS		INO			
	ALEDINIERCOMS	IN FIRE RESCUE AREAS					
Question Are the		ance Areas Fire Rescue Areas ar	nd/or Holding Roo		Response		
Are the your be	ere any Life Rescue Assista uilding? ondition	ance Areas, Fire Rescue Areas, ar		ms in N	No To		
Are the	ere any Life Rescue Assista uilding? ondition Priority Category	Condition Description	Component Affected		Person(s) Notified	Person(s) Title	Photo Image
Are the your be riority Co	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment	Condition	Component	ms in N	Person(s)		
Are the your briority Consist Year?	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment	Condition Description	Component Affected Clock and	Location Description	Person(s) Notified Joel	Title	Image
Are the your briority Consist Year?	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment	Condition Description	Component Affected Clock and	Location Description	Person(s) Notified Joel	Title	Image
Are the your by riority Constitution Constit	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment	Condition Description	Component Affected Clock and	Location Description Room 416	Person(s) Notified Joel	Title	Image
Are the your be riority Continued as Year? Zest Year? Zest Year? Zest Year? Zest Year? Question Electrical	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment	Condition Description	Component Affected Clock and	Location Description Room 416	Person(s) Notified Joel Wielingen	Title	Image
Are the your by iority Coxist ast Year? Is a section Question Electrics ATHL	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment n n	Condition Description	Component Affected Clock and	Location Description Room 416 Response	Person(s) Notified Joel Wielingen	Title	Image
Are the your be control of the policy of the	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment n al	Condition Description	Component Affected Clock and	Location Description Room 416 Response	Person(s) Notified Joel Wielingen	Title	Image
Are the your be civilized as Year? Casist Cast Year? Ces Cuestion Question Electric: ATHL AUDI	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In InIIIIIIIIIIIIIIIIIIIII	Condition Description	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your by Cority Co Exist Last Year? Yes Question Electric: ATHL AUDI	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment n al JETIC FIELD TORIUM	Condition Description	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your be riority Co Exist Last Year? Ves Question Electric: ATHL AUDI	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In Instance on 1st Floor se Lighting	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your biciority Continue Continu	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In Instance on 1st Floor Se Lighting Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your binority Continue	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment n al LETIC FIELD TORIUM Instance on 1st Floor See Lighting Instance on 1st Floor Does a Chandelier Ex	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your by iority Coxist ast Year? The session of the properties of the proper	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In Instance on 1st Floor Se Lighting Instance on 1st Floor Does a Chandelier Exighting Entire Fluoresce	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected No	Person(s) Notified Joel Wielingen	Title	Image
Are the your by iority Coxist ast Year? The second of the	ere any Life Rescue Assista uilding? ondition Priority Category Water Leaks onto Electrical Equipment n al ETIC FIELD TORIUM Instance on 1st Floor se Lighting Instance on 1st Floor Does a Chandelier Exi ghting Fixture - Fluoresce Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected No	Person(s) Notified Joel Wielingen	Title	Image
Are the your be iority Coxist ast Year? The ses as a section of the section of t	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In In In Instance on 1st Floor Se Lighting Instance on 1st Floor Does a Chandelier Exi Instance on 1st Floor Priority Instance on 1st Floor Instance on 1st Floor Does a Chandelier Exi Instance on 1st Floor Priority Instance on 1st Floor Priority Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not e Inspected Inspected No Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your be iority Coxist ast Year? The ses as a section of the section of t	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In Instance on 1st Floor Se Lighting Instance on 1st Floor Does a Chandelier Exighting Fixture - Fluoresce Instance on 1st Floor Pendant Mounted Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not e Inspected Inspected No Inspected	Person(s) Notified Joel Wielingen	Title	Image
Are the your by citority Continue Conti	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In Instance on 1st Floor Does a Chandelier Extended Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected No Inspected Does not et Company to the Com	Person(s) Notified Joel Wielingen	Title	Image
Are the your by ciority Continued Exist Last Year? Ges Conspection Question Electrical AUDI House Fig. 1.	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In In Instance on 1st Floor See Lighting Instance on 1st Floor Does a Chandelier Exighting Fixture - Fluoresce Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not et Inspected Inspected Inspected No Inspected Does not et Company to the Com	Person(s) Notified Joel Wielingen	Title	Image
Are the your by ciority Continued Exist Last Year? Ges Conspection Question Electrical AUDI House Fig. 1.	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In In Instance on 1st Floor See Lighting Instance on 1st Floor Does a Chandelier Exi Instance on 1st Floor Pendant Mounted Instance on 1st Floor Curface Mounted Instance on 1st Floor Recessed Mounted	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not e Inspected Inspected No Inspected Does not e Inspected	Person(s) Notified Joel Wielingen	Title Fireman	Image
Are the your by ciority Continued Exist Last Year? Ges Conspection Question Electrical AUDI House Fig. 1.	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In In Instance on 1st Floor See Lighting Instance on 1st Floor Does a Chandelier Exi Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Instance On 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not e Inspected Inspected Inspected Does not e Does not e Location Response	Person(s) Notified Joel Wielingen	Title Fireman	Image
Are the your be riority Co Exist Last Year? Yes Conspection Question Electrics ATHL AUDIT House F	ere any Life Rescue Assista uilding? Ondition Priority Category Water Leaks onto Electrical Equipment In In In In In In In Instance on 1st Floor Se Lighting Instance on 1st Floor Does a Chandelier Exi Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor	Condition Description Roof Leak	Component Affected Clock and	Location Description Room 416 Response Does not e Inspected Inspected Inspected Does not e Does not e Location Response	Person(s) Notified Joel Wielingen exist exist n Good and Fai	Title Fireman	Image

Building Condition Assessment Survey 2023-2024

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	<u> </u>
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	<u> </u>
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
	шърсеси
Lighting Instance on 1st Floor	Inspected

Inspected

Instance on 1st Floor

Building Condition Assessment Survey 2023-2024

Electrical InspectionM180QuestionResponse

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	10 4011010101010101010101010101010101010
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	2000 1101 411111
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Does not exist
Local Sound System	DOCS HOT CAIST
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Rooms 325	Inspected
Power Panel?	Yes
	100
Lighting Instance on Rooms 325	Inspected
Lighting Fixture - Fluorescent	пороски
Instance on Rooms 325	Inspected
	Inspected
Pendant Mounted Instance on Rooms 325	Inspected
IIISTAILCE OII ROUIIIS 323	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response	
	Response	
COMPUTER LAB		
Lighting Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on Rooms 325	Does not exist	
Recessed Mounted	Does not exist	
Instance on Rooms 325	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Rooms 325	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Rooms 325	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms 325	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Rooms 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	nispected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	персого	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	2000 100 0.100	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	n	
Question	Response	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	D	
Instance on 1st Floor	Does not exist	
Recessed Mounted	Y 1	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 224	Inspected	
Lighting		
Instance on Room 224	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 224	Inspected	
Pendant Mounted		
Instance on Room 224	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 224	Does not exist	
Recessed Mounted		
Instance on Room 224	Does not exist	
Lighting Fixture - HID		
Instance on Room 224	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 224	Does not exist	
Lighting Fixture - LED		
Instance on Room 224	Does not exist	
Raceway With Receptacles		
Instance on Room 224	Does not exist	
Projection System		
Instance on Room 224	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
Alternative Use	Yes	
Instance on 1st Floor - Girls	Inaccessible	
Lighting		
Instance on 1st Floor - Boys	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Boys	Inspected	
Pendant Mounted		
Instance on 1st Floor - Boys	Inspected	

Building Condition Assessment Survey 2023-2024

ricui inspection		MITOU
Question	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - Boys	Does not exist	
Recessed Mounted		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Boys	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Boys	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 430	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Room 430	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 430	Inspected	
Pendant Mounted	1	
Instance on Room 430	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 430	Does not exist	
Recessed Mounted		
Instance on Room 430	Does not exist	
Lighting Fixture - HID		
Instance on Room 430	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 430	Inspected	
Pendant Mounted	•	
Instance on Room 430	Does not exist	
Surface Mounted		
Instance on Room 430	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 430	Does not exist	
Lighting Fixture - LED		
Instance on Room 430	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 430	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		

Building Condition Assessment Survey 2023-2024

Response
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
2- Between Good and Fair
LESS THAN 20% SPARE CIRCUIT BREAKERS
Electrical Room B19
2
EACH
INSTALL NEW PANEL BOARD
PRIORITY 5
LEVEL 2

Building Condition Assessment Survey 2023-2024

1		
nestion	Response	
EMERGENCY LIGHTING		
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Auditorium, Gymnasium, Cafeteria	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station Condition	Inspected 2- Between Good and Fair	
,		
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	

Building Condition Assessment Survey 2023-2024

arical inspection		MIIOU
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	

Building Condition Assessment Survey 2023-2024

ricai inspection	1/110/
Question	Response
MOTOR CONTROLLER	
MOTOR STARTER/CONTACTOR	
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B19
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 124
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
	Inspected
IPDVS/CCTV System	2- Between Good and Fair
Condition Installation Year	2- Between Good and Pan 2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Inspected
Intrusion Alarm System Central Control Panel	Inspected
Instance	Custodian's Office - Room 130
-	2- Between Good and Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

<u>^</u>		
Question	Response	
SECURITY		
Intrusion Alarm System		
Remote Annunciator		
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Under construction	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B19	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Empire Switchboard	
EquipmentId	Sect A	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B19	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B19	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Empire Switchboard	
EquipmentId	Sect B	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size Installation Year	Nameplate 1960	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B19	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	2	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Room B19	
Instance Condition	3- Fair	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

Response	
EACH	
Empire Switchboard	
Sw. Board A	
600	
Amps Total	
1	
Section(s)	
Nameplate	
1960	
Documented	
BEYOND USEFUL LIFE	
Electrical Room B19	
1	
EACH	
REPLACE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Electrical Room B19	
3- Fair	
1	
EACH	
Empire Switchboard	
Sw. Board B	
600	
Amps Total	
1	
Section(s)	
Nameplate	
1960	
Documented	
BEYOND USEFUL LIFE	
Electrical Room B19	
1	
EACH	
REPLACE	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
	EACH Empire Switchboard Sw. Board A 600 Amps Total 1 Section(s) Nameplate 1960 Documented BEYOND USEFUL LIFE Electrical Room B19 1 EACH REPLACE PRIORITY 1 LEVEL 2 No violations recorded Electrical Room B19 3 - Fair 1 EACH Empire Switchboard Sw. Board B 600 Amps Total 1 Section(s) Nameplate 1960 Documented BEYOND USEFUL LIFE Electrical Room B19 1 Section(s) Nameplate 1960 Documented BEYOND USEFUL LIFE Electrical Room B19 1 EACH REPLACE PRIORITY 1 LEVEL 2 No violations recorded Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 1nspected 2- Between Good and Fair