#### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection M190

Asset:	P.S. 290 - MANHATTAN, 311 EAST 82 STREET, MANHATTAN, NY, 10028		
Inspection Id	Inspection Type	Time In	Last Edited
1302	2 MECHANICAL	2023-11-29 08:12AM	2023-12-19 10:09AM

# Asset Data Question Have any Systems/Major Building Components been upgraded? Systems: Boiler Feedwater System; Staff Fixture - Toilets (~50%), Lavatory/Sinks (~50%); Student Fixtures - The Drinking Fountains, Toilets (~15%),

Years: 2023 Systems: Gas Pressure Booster Years: 2022

Lavatory/Sinks (~15%),

Years: 2022

Systems: Exhaust Fans (4 of 5)

Years: 2020

2019

Systems: Fixtures - Students: Toilets (~85%), Lavatory/Sinks (~85%)

Systems: MDF Room - Dedicated A/C Equipment (DX Split System)

Years: 2018
Systems: Climate Control System; Steam Condensate Return
Pumping System; Terminal Unit Thermostatic Traps;

F&T/Steam Drip Traps Years: 2017

Systems: Sump Pumps; Boiler Auxiliary Piping: Boiler Blowdown Piping

Years: 2014

Years:

Are there fuel tanks? No
Total # of water main service entries to the asset 2

MERs/Fan Rooms Locations Basement Fan Room

Are there any spaces with Missing or Defective CO Detectors? No
Are there any Painted/Obstructed Sprinkler Heads? No

Are there any Emergency Stop Switches with Missing Hammers?

Component: Boiler Room Entrance
Location: Boiler Emergency Stop Switch

**Priority Condition** 

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Boiler Safety Auxiliary	Water Column's drain valve is leaking	Steam Boiler	Boiler Room	Ronnie Reyes	Fireman	



#### Inspection

Question		Response	Response
Mechanica	al		
AIR CO	NDITIONING	Does not exist	
CENTR.	AL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMA	TE CONTROL SYSTEM	Inspected	
BMS		Inspected	
	Instance	Throughout	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Building Area Covered by Operational System	81-100%	
	Installation Year	2017	·

## **Building Condition Assessment Survey 2023-2024**

IMATE CONTROL SYSTEM	Response
LIMATE CONTROL SYSTEM	
BMS Source of Installation Year	Documented
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Rooms 202A, 208, 304
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist  Does not exist
Electric System	
OMPACTOR	Does not exist
ONVEYING	Does not exist
OMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Near Ash Hoist, Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	2
	EACH
Instance Quantity Uom	
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	RayPak
EquipmentId	N/A
Capacity/Size Quantity	211
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Inspector Estimate
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

unicai Inspection		WHY
Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
- Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist  Inspected	
Student  Deliching Franching	Inspected	
Drinking Fountain Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Inspected	
Instance	Boiler Room - Gas Meter Area	

## **Building Condition Assessment Survey 2023-2024**

nestion	Response	
GAS SERVICE		
Gas Pressure Booster		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Spencer	
EquipmentId	N/A	
Capacity/Size Quantity	3	
Capacity/Size UOM	HP	
Source of Capacity/Size	Documented	
Installation Year	2022	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE	
Deficiency Location/Instance	4th Floor Staff Toilet Room, Stair "E/5"	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Does not exist	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	4th Floor Girl's Toilet Room	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Pumping System	Inspected	
Condition Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 120	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	M190

estion	Response	
EATING		
Unit Heater/Cabinet Heater		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Power Flame	
Burner Model	C4-G0-30	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	MISSING HAMMER	
Deficiency Location/Instance	Boiler Room Entrance	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Boiler Feedwater System	10000000	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)  Instance on Basement	Does not exist	
Boiler Flue Exhaust	Does not exist	
Instance on Basement	Inspected	
	3- Fair	
Instance Condition		
Deficiency	BOILER BREECHING:DEFECTIVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Does not exist	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

estion	Response
EATING PLANT	Teopolise .
Boiler Auxiliaries	
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	No deficiencies recorded
Instance on Basement	Inspected
Coal-fired Boiler	inspected
	D
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	4,076
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	Yes
Manufacturer	H. B. Smith Co., Inc.
EquipmentId	1173-1
Capacity/Size Quantity	4076
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1972
Source of Installation Year	Inspector Estimate
Deficiency	SECTION LEAKS
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	5- Poor
Туре	Fixed Louver
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
HEATING PLANT		
Fuel System		
Boiler Fresh Air Louver/Damper		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Does not exist	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Inspected	
Instance on Closet within Room 306	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Closet within Room 306	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Closet within Room 306	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	•	
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Does not exist	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Question	Response
KITCHEN	
Kitchen Sink	
Instance Condition	3- Fair
Deficiency	MISSING INDIRECT WASTE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4 SF103325
Violations	
Deficiency Deficiency Location/Instance	DEFECTIVE Kitchen (Leaking)
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MDF Room	Inspected
Instance on Multi-Purpose Room - Room within OT/PT Room	Inspected
Dedicated A/C Equipment	III poetto
Instance on Multi-Purpose Room - Room within OT/PT Room	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
	Does not exist
SCIENCE PREP ROOM	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected  Does not exist
Dry Sprinkler Alarm Valve Assembly	Inspected
Wet Sprinkler Alarm Valve Assembly Condition	3- Fair
Deficiency	No deficiencies recorded
· · · · · · · · · · · · · · · · · · ·	Does not exist
Fire Booster Pump Assembly Roof Tank	Does not exist  Does not exist
Siamese Connection	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement Fan Room (bearing)
Deficiency Quantity	1

# **Building Condition Assessment Survey 2023-2024**

nestion	Response	
VENTILATION		
Exhaust Fan		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	Yes	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	Basement Fan Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	