Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset: P.S. 194 - MANHATTAN, 244 WEST 144 STREET, MANHATTAN, NY, 10030				
Inspection Id	Inspection Type		Time In	Last Edited
80	ELECTRICAL		2023-10-10 09:13AM	2023-11-06 06:00PM
sset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Variable Frequency Drive	
		Years:	2022	
		Systems:	Interior Lighting (Retrofitted LE Auditorium, Gymnasium, Multip	0 0 1

Years:

Years:

2021 Systems: Lighting - Security 2019, 2008

	Systems:	Library (Raceway With Receptacles)
	Years:	2018
	Systems:	LED Lighting (Auditorium, Gymnasium, Multipurpose Room) Exit Lights (Battery Pack), Partial Emergency Lighting (Non Battery Pack), IPDVS/CCTV System
	Years:	2016
	Systems:	Fused Disconnect Switch Type Panel Board, Lightning Protection
	Years:	2010
	Systems:	Service Switch, Switchboard, Molded Case Circuit
		Breaker Panel Board, Public Address System, Local
		Sound System
	Years:	2008
	Systems:	Fire Alarm System
	Years:	2002
	Systems:	Emergency Light/Exit Light Panel, Intrusion Alarm System
	Years:	2000
	Systems:	Auditorium (Chandeliers)
	Years:	1999
Type of Service	Below Gro	ound
Does Interactive Whiteboard (IWB) Exist?	Yes	
Water Penetration In Electrical Room?	No	

water	Felletiation in Electri			INO				
DEDI	CATED INTERC	OMS IN FIRE RESCUE AR	EAS					
Quest	ion				Response			
Are	there any Life Rescue	Assistance Areas, Fire Rescue Ar	eas, and/or Holding Roor	ns in	No			
your	· building?							
Priority	Condition							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency Lighting -	25 Fixtures are Not	Emergency	Throughout	Steven	Custodian	No Photo Taken
	Not Operational	Operational	Lighting	the Building	Velez		
Inspection							
Question				Response	;		
Electrica	1						
ATHLE	ETIC FIELD			Does not	exist		
AUDIT	ORIUM			Inspected			
	Instance on 1st Floor			Inspected			
House	e Lighting						
	Instance on 1st Floor			Inspected			
	Does a Chandelier Exis	t?		Yes			
Lig	hting Fixture - Fluorescen	t					
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - HID						

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	MI
uestion	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year Source of Installation Year	2008 Inspector Estimate
Deficiency	No deficiencies recorded
Projection System Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	mspected
Instance on Basement	Does not exist
Lighting Fixture - HID Instance on Basement	Does not exist
Lighting Fixture - Incandescent Instance on Basement	Does not exist
Lighting Fixture - LED	Increated
Pendant Mounted	Inspected
	Increated
Instance on Basement	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricui Inspection		N1195
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted	•	
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 311	Inspected	
Lighting		
Instance on Room 311	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 311	Does not exist	
Lighting Fixture - HID		
Instance on Room 311	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 311	Does not exist	
Lighting Fixture - LED		
Instance on Room 311	Inspected	
Pendant Mounted		
Instance on Room 311	Inspected	
Instance Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

 	D	
Duestion	Response	
Lighting Lighting Fixture - LED		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 311	Does not exist	
Recessed Mounted		
Instance on Room 311	Does not exist	
Raceway With Receptacles		
Instance on Room 311	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 311	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor		
	Inspected	
Lighting Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
Pendant Mounted	inspected	
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	100 deficicities recorded	
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspection	I VI I 7
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
	Inspected
AUXILIARY SIGNAL/BELL SYSTEM Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	5- Poor
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
	25(590(9))
Violations	35658068P
Violations Non Battery Pack	Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

neur Inspection		11174
uestion	Response	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	By Stair E/4	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Duct Smoke Detector Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Area Smoke Detector	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2002	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection	11177
uestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not exist
LAN	Inspected
	Inspected
Local Distribution Frame (I/LDF) Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Main Equipment Rack (MDF) Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Room, Corridor near Rooms 411, 120

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 223
Instance Condition	3- Fair
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Model	Dukane 250
Installation Year	2008
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Room 401, Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 118
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
	2000
	/(##)
Installation Year Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection	1
lestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	SIREN/STROBE NOT ACTIVE
Deficiency Deficiency Location/Instance	Exterior
Deficiency Quantity	Exterior 1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Galaxy Switchgear
Manufacturer	N/A
EquipmentId Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
WITCHBOARD	Inspected
Number of Spares	8
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	Galaxy Switchgear
Manufacturer	Galaxy Switchgear
EquipmentId Capacity/Size Quantity	MDB Section 1, 2, 3 1600

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Doos not avist	

TRANSFORMER

Does not exist