Building Condition Assessment Survey 2023-2024

1 T

| Electrical Insp | ection | | | M197 |
|-----------------|--|-------------------|---|------------------------|
| Asset: | P.S. 197 - MANHATTAN, 2230 5TH AVENUE, MANI | HATTAN, NY, 10037 | | |
| Inspection Id | Inspection Type | | Time In | Last Edited |
| 2517 | ELECTRICAL | | 2024-01-19 09:28AM | 2024-02-13 07:43AM |
| Asset Data | | | | |
| Question | | Answer | | |
| Have any System | ems/Major Building Components been upgraded? | Systems: | Partial Lighting - Security | |
| | | Years: | 2023 | |
| | | Systems: | Emergency Lights (Partial Batter (Most Battery Pack) | y Pack), Exit Lights |
| | | Years: | 2018 | |
| | | Systems: | Molded Case Circuit Breaker Par | nel Boards |
| | | Years: | 2016, 1995 | |
| | | Systems: | Service Switch, Switchboard, Int Library) | erior Lighting (Except |
| | | Years: | 2016 | |
| | | Systems: | Fire Alarm System | |
| | | Years: | 2014 | |
| | | Systems: | Telephone System, LAN | |
| | | Years: | 2011 | |
| | | Systems: | Library | |
| | | Years: | 2009 | |
| | | Systems: | Intrusion Alarm System | |
| | | Years: | 2004 | |
| | | Systems: | Public Address System (Amplifie | er) |
| | | Years: | 2000 | |
| | | Systems: | Emergency Light/Exit Lights Par | nel |
| | | Years: | 1995 | |
| Type of Servic | | Below Gr | ound | |
| | ve Whiteboard (IWB) Exist? | Yes | | |
| Water Penetrat | ion In Electrical Room? | No | | |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?

Priority Condition

| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo |
|------------|--|-------------|---------------------|----------------|------------------|-----------|-------|
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image |
| No | Water Leaks onto Electrical Equipment | N/A | Lighting Fixture | Kitchen Office | Joshua Murcia | Custodian | _ |

Response

No



| pection | | |
|--------------------------------|----------------|--|
| Question | Response | |
| Electrical | | |
| ATHLETIC FIELD | Does not exist | |
| AUDITORIUM | Inspected | |
| Instance on Basement | Inspected | |
| House Lighting | | |
| Instance on Basement | Inspected | |
| Does a Chandelier Exist? | No | |
| Lighting Fixture - Fluorescent | | |
| Instance on Basement | Inspected | |

Building Condition Assessment Survey 2023-2024

| cal Inspection estion | Response |
|--------------------------------------|--|
| | Kesponse |
| UDITORIUM House Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | DOCS HOLEKIST |
| Instance on Basement | Inspected |
| | lispected |
| Pendant Mounted Instance on Basement | Description |
| | Does not exist |
| Surface Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Local Sound System | |
| Instance on Basement | Inspected |
| Instance Condition | 5- Poor |
| Installation Year | 1968 |
| Source of Installation Year | Inspector Estimate AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | AMPLIFIER NOT OPERATIONAL |
| Quantity Uom | EACH |
| Potential Action | REPLACE SYSTEM |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Projection System | |
| Instance on Basement | Does not exist |
| Theater Lighting System | |
| Instance on Basement | Inspected |
| Dimming System | |
| Instance on Basement | Does not exist |
| Theater Lighting | |
| Instance on Basement | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity | 32 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| AFETERIA | Inspected |
| Instance on 1st Floor | Inspected |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| icai Inspection | | M19 |
|---|---------------------------|-----|
| uestion | Response | |
| CAFETERIA | | |
| Lighting | | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| | No deficiencies recorded | |
| Lighting Fixture - HID Instance on 1st Floor | | |
| | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Does not exist | |
| Local Sound System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 5- Poor | |
| Installation Year | 1968 | |
| Source of Installation Year | Inspector Estimate | |
| Deficiency Deficiency Quantity | AMPLIFIER NOT OPERATIONAL | |
| Quantity Uom | 1 EACH | |
| Potential Action | REPLACE SYSTEM | |
| Urgency of Action | PRIORITY 2 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| | No violations recorded | |
| Projection System Instance on 1st Floor | Does not exist | |
| Theater Lighting System | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| | | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected | |
| Lighting Does a Chandelier Exist? | Inspected No | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| | | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Inspected | |
| Pendant Mounted | Inspected | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| Question | Response |
|---|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - LED | |
| Pendant Mounted | |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| COMPUTER LAB | Inspected |
| Instance on Room 219 | Inspected |
| Power Panel? | Yes |
| Lighting | |
| Instance on Room 219 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 219 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 219 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 219 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 219 | Inspected |
| Pendant Mounted | |
| Instance on Room 219 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 219 | Does not exist |
| Recessed Mounted | |
| Instance on Room 219 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 219 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Inspected |
| Instance on Basement | Inspected |
| Lighting | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 2- Between Good and Fair |
| | |

Building Condition Assessment Survey 2023-2024

| estion | Response | |
|---------------------------------|---------------------------------------|--|
| YMNASIUM | Response | |
| Lighting | | |
| Lighting Fixture - LED | | |
| Recessed Mounted | | |
| Deficiency | No deficiencies recorded | |
| Local Sound System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 5- Poor | |
| Installation Year | 1968 | |
| Source of Installation Year | Inspector Estimate | |
| Deficiency | AMPLIFIER NOT OPERATIONAL | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE SYSTEM | |
| Urgency of Action | PRIORITY 2 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Projection System | | |
| Instance on Basement | Does not exist | |
| Scoreboard | | |
| Instance on Basement | Inspected | |
| Instance Condition | 5- Poor | |
| Deficiency | NOT OPERATIONAL | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Theater Lighting System | | |
| Instance on Basement | Does not exist | |
| ITCHEN | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting | | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | inspected | |
| Instance on 1st Floor | Does not exist | |
| | Does not exist | |
| Surface Mounted | Turner de d | |
| Instance on 1st Floor | Inspected 2- Between Good and Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Lightin <u>g</u> Fixture - HID | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Does not exist | |
| IBRARY | Inspected | |
| Instance on Room 209 | Inspected | |
| Lighting | 1 | |
| Instance on Room 209 | Inspected | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| ricai Inspection | WI19 |
|---------------------------------|--------------------------|
| uestion | Response |
| LIBRARY | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Instance on Room 209 | Inspected |
| Pendant Mounted | |
| Instance on Room 209 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 209 | Does not exist |
| Recessed Mounted | |
| Instance on Room 209 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 209 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 209 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 209 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 209 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Room 209 | Does not exist |
| LOCKER ROOM | Inspected |
| Instance on Basement - Boys | Inspected |
| Alternative Use | Yes |
| Lighting | |
| Instance on Basement - Boys | Inspected |
| Lighting Fixture - Fluorescent | * |
| Instance on Basement - Boys | Inspected |
| Pendant Mounted | * |
| Instance on Basement - Boys | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement - Boys | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Basement - Boys | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement - Boys | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement - Boys | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement - Boys | Does not exist |
| MULTIPURPOSE ROOM | Does not exist |
| | |
| SCIENCE DEMO ROOM | Does not exist |
| SCIENCE LAB | Does not exist |
| SCIENCE PREP ROOM | Does not exist |
| SWIMMING POOL | Does not exist |
| TOILET ROOM - STAFF | Inspected |

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | IVI19 |
|--|---|
| Question | Response |
| TOILET ROOM - STAFF | |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| | Does not exist |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Throughout the Building |
| Deficiency Quantity | 9 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | No violations recorded |
| | Inspected |
| Condition | |
| Condition Deficiency | Inspected |
| Deficiency | Inspected 3- Fair No deficiencies recorded |
| Deficiency EXIT LIGHT | Inspected 3- Fair No deficiencies recorded Inspected |
| Deficiency EXIT LIGHT Battery Pack | Inspected 3- Fair No deficiencies recorded |
| Deficiency EXIT LIGHT Battery Pack Condition | Inspected 3- Fair No deficiencies recorded Inspected 2- Between Good and Fair |
| Deficiency EXIT LIGHT Battery Pack | Inspected 3- Fair No deficiencies recorded Inspected Inspected |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| lestion | Response |
|---------------------------------------|--------------------------------------|
| EXIT LIGHT | |
| Battery Pack | |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| XIT/EMERGENCY LIGHT | Does not exist |
| IRE ALARM SYSTEM | Inspected |
| Bell/Horn | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | PULL STATION COVER IS MISSING |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL COVER |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Heat Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Does not exist |
| Magnetic Door Holder/Contactor | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Does not exist |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | 1st Floor Corridor By General Office |
| Instance Condition | 2- Between Good and Fair |
| Instance Condition | 2- Detween Good and Fall |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | IVI J |
|---------------------------------------|-------------------------------|
| uestion | Response |
| FIRE ALARM SYSTEM | |
| Main Panel | |
| Fire Alarm Control Panel (Electronic) | |
| Instance Quantity Uom | EACH |
| Manufacturer | Edwards |
| Model | EST3X |
| EquipmentId | Fire Alarm Control Panel |
| Installation Year | 2014 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Sub-Panel | Does not exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 5- Poor |
| Deficiency | PRINTER NOT OPERATIONAL |
| Deficiency Location/Instance | Custodian's Office - Room 115 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| NTERCOM SYSTEM | Does not exist |
| AN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| LIGHTNING PROTECTION | Does not exist |
| MOTOR CONTROLLER | Inspected |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| Variable Frequency Drive Condition | Inspected 3- Fair |

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

| cal Inspection estion | Response |
|---|---|
| | * |
| ANEL BOARD | Inspected Does not exist |
| Fused Disconnect Switch Type | Does not exist |
| Fused Knife Switch Type Fused Toggle Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| UBLIC ADDRESS SYSTEM | Inspected |
| | General Office - Room 117 |
| | 3- Fair |
| Instance Condition | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Biamp 301 |
| Installation Year | 1968 |
| Source of Installation Year | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Classrooms and Corridors |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | General Office - Room 117 |
| Deficiency Quantity | 85,000 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| ECURITY | Inspected |
| IPDVS/CCTV System | Does not exist |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | Custodian's Office - Room 115 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128BP |
| Installation Year | 2004 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | Inspected |
| Remote Annunciator | |
| Condition | 4- Between Fair and Poor |
| | |
| | |
| | |
| Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom | ANNUNCIATOR NOT OPERATIONAL Custodian's Office - Room 115 1 EACH |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | IVII; |
|--|----------------------------------|
| uestion | Response |
| SECURITY | |
| Intrusion Alarm System | |
| Remote Annunciator | |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Siren/Strobe | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Building Perimeters |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | East Coast |
| | Main Service Switch |
| EquipmentId Capacity/Size Quantity | 1600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2016 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| WITCHBOARD | Inspected |
| Number of Spares | 11 |
| X | Inspected |
| Fused Disconnect Switch Type Instance | Electrical Room |
| Instance Condition | 2- Between Good and Fair |
| | |
| Instance Quantity | 1 EACH |
| Instance Quantity Uom | |
| Manufacturer | East Coast |
| EquipmentId | MDB |
| Capacity/Size Quantity | 1600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity Capacity/Size 2 UOM | 3 Section(s) |
| Source of Capacity/Size | Section(s) Nameplate |
| Installation Year | 2016 |
| Installation Year Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Fused Knife Switch Type Molded Case Circuit Breaker Type | Does not exist |
| FELEPHONE SYSTEM | Inspected |
| | Inspected |
| PBX/Intercom Condition | 3- Fair |

Building Condition Assessment Survey 2023-2024

| rical Inspection | | M197 |
|------------------|--------------------------|------|
| uestion | Response | |
| TELEPHONE SYSTEM | | |
| PBX/Intercom | | |
| Deficiency | No deficiencies recorded | |
| Standard | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| TRANSFORMER | Does not exist | |