Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 234 - MANHATTAN, 292 GREENWICH STREET, MANHATTAN, NY, 10007				
Inspection Id	Inspection Type		Time In	Last Edited	
2734	MECHANICAL		2024-01-26 09:12AM	2024-03-23 10:41AM	
set Data					
Question		Answer			
Have any Systems/Major Building Components been upgraded?		Systems:	Fixtures - Toilets, Urinals; Drink Climate Control System: Termin Kitchen - Grease Trap (1 of 2)	0 , , , , , , , , , , , , , , , , , , ,	
		Years: Systems:	2022 Student Fixtures - Drinking Four	ntain(~70%)	

2021

2020

2019

Systems: Sewage Ejector Pump (1 of 2)

Sewage Ejector Pump (1 of 2)

Systems: Air Cooled Chillers; Air Cooled Condensers; Chilled

Years:

Years: Systems:

Years:

	Water Distribution: Pumps; Chilled Water System -
	Backflow Preventer; Refrigerant Piping Years: 2018
	Systems: F&T/Steam Drip Traps; Terminal Unit Thermostatic
	Traps
	Years: 2017
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MERs B1, 212, 312; Penthouse MER
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Penthouse MER
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

e nor ny ev	numen						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condit	tion recorded						

Inspection

Question	Response	
Aechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Inspected	
Absorption Chiller	Does not exist	
Air Cooled Chiller	Inspected	
Instance	Penthouse MER	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	Chiller-1	
Capacity/Size Quantity	90	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Documented	
Refrigerant Type	R-134A	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nicui Inspeciion		IVIZ
estion	Response	
IR CONDITIONING		
Chilled Water System		
Air Cooled Chiller		
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	1- Good	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	Trane	
EquipmentId	Chiller-2 90	
Capacity/Size Quantity Capacity/Size UOM	90 Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Documented	
Refrigerant Type	R-134A	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	1- Good	
Instance Quantity		
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	Chiller-3	
Capacity/Size Quantity	90	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate 2018	
Installation Year Source of Installation Year	Documented	
Refrigerant Type	R-134A	
	No deficiencies recorded	
Deficiency	Inspected	
Air Cooled Condenser		
Instance	Roof	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	ACC-1	
Capacity/Size Quantity	90	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year Source of Installation Year	2018	
	Documented	
Deficiency	No deficiencies recorded	
Instance	Roof	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	ACC-2	
Capacity/Size Quantity	90	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Roof	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

stion	Response	
R CONDITIONING		
Chilled Water System		
Air Cooled Condenser		
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	ACC-3	
Capacity/Size Quantity	90	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Backflow Preventer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Central Station Air Handler	Inspected	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-1, AH-3	
Capacity/Size Quantity	5	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year Source of Installation Year	1988	
	Documented No deficiencies recorded	
Deficiency		
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-2 20	
Capacity/Size Quantity Capacity/Size UOM	20 Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1988	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-4	
Capacity/Size Quantity	30	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
IR CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse MER	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-5	
Capacity/Size Quantity	8	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1988	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE FAN	
Deficiency Location/Instance	Penthouse MER	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	MER 312	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-6	
Capacity/Size Quantity	8	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1988	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 212	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Trane	
EquipmentId	AH-7	
Capacity/Size Quantity	10	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1988	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fan Coil Unit	Does not exist	
Packaged Air Cooled Chiller	Does not exist	
Water Cooled Chiller	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

WI254

anical Inspection	IVIZ.
uestion	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	MER 312 / RF-6 (bearing)
Deficiency Quantity	1
	EACH
Quantity Uom Potential Action	EACH MAINTENANCE
	PRIORITY 3
Urgency of Action	
Purpose of Action	LEVEL 2
Violations	No violations recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	81-100%
Building Area Covered by Operational System	
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Room 102
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Room 304
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
	Inspected
CONVEYING	
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	4- Between Fair and Poor
Are all the existing elevators operable?	No
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
	Does not exist Does not exist

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	IV125
uestion	Response
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Water Main Room B1A
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
	DEVICE
Deficiency Location/Instance Deficiency Quantity	Basement - Water Main Room B1A 3
Quantity Uom	5 EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER B1
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARIES(RELIEF VALVE, GAUGE,
	TEMPERATURE REGULATOR, ETC)
Deficiency Location/Instance	MER B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage Ejector Pump	
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	MER B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sump Pump	Inspected 3- Fair
Condition	No deficiencies recorded
Deficiency	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
	Inspected
GAS SERVICE	Inspected
Gas Distribution Piping Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Gas Meter Room Exhaust Fan	Does not exist Does not exist
Gas Meter Room Vent	Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

N /	172	1
111	23	94

nical Inspection	IVI23
estion	Response
AS SERVICE	
CO/Gas Leak Detection	Does not exist
EATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MERs B1, 212, 312; Penthouse MER
Deficiency Quantity	140
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	MER B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	MER B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	MER B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Room 108 - Toilet Room

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		11120
iestion	Response	
HEATING		
Steam Heating		
Steam Piping		
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Inspected	
Instance on Room B11	Inspected	
Dedicated A/C Equipment	1	
Instance on Room B11	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
AITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	Inspected	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Gas System Instance on 1st Floor	Inconceted	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Grease Trap Instance on 1st Floor	Inspected	
	2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency Hood Exhaust Ductwork	No deficiencies recorded	
Instance on 1st Floor	Inspected	
	3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	· · · ·	
Instance on 1st Floor		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System	- · ·	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		N1234
Question	Response	
KITCHEN		
Hood Fire Suppression System		
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room inside Room 206C	Inspected	
Dedicated A/C Equipment	1	
Instance on Room inside Room 206C	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
	Does not exist	
SCIENCE PREP ROOM		
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist Does not exist	
Roof Tank Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
•	Does not exist	
Water Gong SWIMMING POOL	Does not exist	
VENTILATION	Inspected V	
Is the building Mechanically ventilated?	Yes Inspected	
Exhaust Fan Condition	3- Fair	
Condition Approximate Total # of Fans	5- Fair 1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response
VENTILATION	
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Room 206C
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Does not exist
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

BCAS Partners Version 2.0 (P)