Building Condition Assessment Survey 2023-2024

Electrical Inspection M263

Asset:	P.S./I.S. 263 - MANHATTAN, 202 SHERMAN AV	ENUE, MANHATTAN, N	Y, 10034	
Inspection Id	Inspection Type		Time In	Last Edited
59	ELECTRICAL		2023-10-06 08:07AM	2024-01-25 01:03PM
sset Data				
Question		Answer		
Have any Syste	ems/Major Building Components been upgraded?	Systems:	Interior LED Lighting (Retrofitte	ed)
		Years:	2022	
		Systems:	IPDVS/CCTV System	
		Years:	2018	
		Systems:	All Other Electrical Systems and	Components
		Years:	2010	
Type of Service		Below Gro	ound	
Does Interactiv	re Whiteboard (IWB) Exist?	Yes		
Water Penetrati	ion In Electrical Room?	Yes		
DEDICATEI	D INTERCOMS IN FIRE RESCUE AREAS			
Question		F	Response	
•	Life Rescue Assistance Areas, Fire Rescue Areas, and/or H	Iolding Rooms in	Yes	
your building				
	ted intercoms available in all of these spaces for use during	a fire?	Yes	
Are all de	edicated intercoms operational?	Y	Yes	
riority Condit	ion			
		mnonent Location	Person(s) Person(s) P	hoto

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Rooms (510 and 516)/Roof Leak and Back Flow Preventer Respectively	Charles Harvey	Custodian	
Yes	Lightning Protection - Defective	N/A	Lightning Protection	Roof (Rod on RTU - Facing Sherman Avenue)	Charles Harvey	Custodian	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room C05	Charles Harvey	Custodian	

Inspection

Response
Does not exist
Does not exist
Inspected
Inspected
Inspected
Does not exist
Does not exist

Building Condition Assessment Survey 2023-2024

Electrical InspectionM263QuestionResponse

4		
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Incandescent		
Instance on Cellar	Does not exist	
Lighting Fixture - LED		
Instance on Cellar	Inspected	
Pendant Mounted		
Instance on Cellar	Does not exist	
Surface Mounted		
Instance on Cellar	Does not exist	
Recessed Mounted		
Instance on Cellar	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Cellar	Does not exist	
Theater Lighting System		
Instance on Cellar	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No Does not exist	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Rooms 420A/B, 524	Inspected	
Power Panel?		
	No	
Lighting Instance on Rooms 420A/B, 524	Inspected	
	търсски	
Lighting Fixture - Fluorescent Instance on Rooms 420A/B, 524	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Rooms 420A/B, 524	Does not exist	
HISTARICA OII ROUTHS 4201/1/D, 324	DOCS HOL CYIST	

Building Condition Assessment Survey 2023-2024

ical Inspection		N126
uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Rooms 420A/B, 524	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 420A/B, 524	Inspected	
Pendant Mounted		
Instance on Rooms 420A/B, 524	Does not exist	
Surface Mounted		
Instance on Rooms 420A/B, 524	Does not exist	
Recessed Mounted		
Instance on Rooms 420A/B, 524	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Rooms 420A/B, 524	Does not exist	
SYMNASIUM	Inspected	
Instance on Cellar	Inspected	
Lighting	1	
Instance on Cellar	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Cellar	Does not exist	
Lighting Fixture - HID		
Instance on Cellar	Does not exist	
Lighting Fixture - Incandescent		
Instance on Cellar	Does not exist	
Lighting Fixture - LED		
Instance on Cellar	Inspected	
Pendant Mounted	1	
Instance on Cellar	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	To deficiences recorded	
Instance on Cellar	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
Instance on Cellar	Does not exist	
	Does not exist	
Local Sound System Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Scoreboard		
Instance on Cellar	Does not exist	
Theater Lighting System		
Instance on Cellar	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response	
GYMNASIUM		
Theater Lighting System		
Dimming System		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on Cellar	Inspected	
Lighting		
Instance on Cellar	Inspected	
Lighting Fixture - Fluorescent		
Instance on Cellar	Does not exist	
Lighting Fixture - HID		
Instance on Cellar	Does not exist	
Lighting Fixture - Incandescent		
Instance on Cellar	Does not exist	
Lighting Fixture - LED		
Instance on Cellar	Inspected	
Pendant Mounted		
Instance on Cellar	Does not exist	
Surface Mounted		
Instance on Cellar	Does not exist	
Recessed Mounted		
Instance on Cellar	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 301		
Lighting	Inspected	
Instance on Room 301	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Room 301	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room 301	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 301	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Room 301	Inspected	
	nispected	
Pendant Mounted Instance on Room 301	Does not exist	
	Does not exist	
Surface Mounted	Towns of d	
Instance on Room 301	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 301	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	1/12/05

icui Inspection		11120
uestion	Response	
LIBRARY		
Projection System		
Instance on Room 301	Does not exist	
LOCKER ROOM	Inspected	
Instance on Room C12 - Girls	Inaccessible	
Instance on Room C14 - Boys	Inspected	
Alternative Use	Yes	
Lighting		
Instance on Room C14 - Boys	Inspected	
Lighting Fixture - Fluorescent	<u> </u>	
Instance on Room C14 - Boys	Does not exist	
Lighting Fixture - HID		
Instance on Room C14 - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room C14 - Boys	Does not exist	
Lighting Fixture - LED		
Instance on Room C14 - Boys	Inspected	
Pendant Mounted		
Instance on Room C14 - Boys	Does not exist	
Surface Mounted		
Instance on Room C14 - Boys	Does not exist	
Recessed Mounted		
Instance on Room C14 - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 502	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 202	Inspected	
Power Panel?	Yes	
Alternative Use		
	Yes	
Lighting Instance on Room 502	Inspected	
Instance on Room 202	Inspected	
Lighting Fixture - Fluorescent	mspected	
Instance on Room 502		
	Does not exist	
Instance on Room 2017	Does not exist	
Instance on Room 202	Does not exist Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - HID Instance on Room 502	Does not exist Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202	Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent	Does not exist Does not exist Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502	Does not exist Does not exist Does not exist Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202	Does not exist Does not exist Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202 Lighting Fixture - LED	Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202 Lighting Fixture - LED Instance on Room 502	Does not exist Inspected	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202 Lighting Fixture - LED Instance on Room 502 Instance on Room 502 Instance on Room 202	Does not exist	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202 Lighting Fixture - LED Instance on Room 502 Instance on Room 502 Pendant Mounted	Does not exist Inspected Inspected	
Lighting Fixture - HID Instance on Room 502 Instance on Room 202 Lighting Fixture - Incandescent Instance on Room 502 Instance on Room 202 Lighting Fixture - LED Instance on Room 502 Instance on Room 502 Instance on Room 202	Does not exist Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M263
Question	Response

incui Inspection		171205
Question	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance on Room 502	Does not exist	
Instance on Room 202	Does not exist	
Recessed Mounted		
Instance on Room 502	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 202	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Room 502	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 202	Does not exist	
Emergency Shut-Off Power		
Instance on Room 502	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 202	Does not exist	
Power Supply		
Instance on Room 502	Inspected	
Instance on Room 202	Does not exist	
Instructor Unit		
Instance on Room 502	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 502	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 502	Does not exist	
Projection System		
Instance on Room 502	Does not exist	
Instance on Room 202	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 502A	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 202A	Inaccessible	
Lighting		
Instance on Room 502A	Inspected	
Lighting Fixture - Fluorescent	A	
Instance on Room 502A	Does not exist	
Lighting Fixture - HID		
Instance on Room 502A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 502A	Does not exist	
Lighting Fixture - LED		
Instance on Room 502A	Inspected	
	*	

Building Condition Assessment Survey 2023-2024

ricui inspection		IV120.
Question	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Instance on Room 502A	Does not exist	
Surface Mounted		
Instance on Room 502A	Does not exist	
Recessed Mounted		
Instance on Room 502A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Room 502A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 502A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 502A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Heandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected Does not exist	
Lighting Fixture - Fluorescent	Does not exist Does not exist	
Lighting Fixture - HID	Does not exist Does not exist	
Lighting Fixture - Incandescent		
Lighting Fixture - LED	Inspected Does not exist	
Pendant Mounted	Does not exist Does not exist	
Surface Mounted		
Recessed Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

rical Inspection	M26
uestion	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Staircases (A and B) - 2nd and 4th Floors Corridors, Staircase A - 1st Floor Corridor, Staircase - 3rd Floor Corridor, Cafeteria By Room C06, By Rooms (C03, 402A)
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	By Telecom Room 406
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	First Floor - Plaza Deck
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35657670N
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

Building Condition Assessment Survey 2023-2024

cut inspection		1,12
estion	Response	
IRE ALARM SYSTEM		
Manual Pull Station		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Telecom Room 206	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Silent Knight	
EquipmentId	DACT Communicator	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
	Inspected	

Building Condition Assessment Survey 2023-2024

нсш інгресион	W1203
uestion	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office - Room 112
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	LIGHTNING AIR TERMINAL (ROD) DEFECTIVE
Deficiency Location/Instance	Roof (Rod on RTU - Facing Sherman Avenue)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
· ····································	=

Building Condition Assessment Survey 2023-2024

ciricai Inspection	WIZO
Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Telecom Room 206
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 112
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
	Electrical Room C05
Instance Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

cirical Inspection	IVIA
Question	Response
SERVICE SWITCH	
Manufacturer	Cutler Hammer
EquipmentId	SSW#1 3000A Service Disconnect
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C05
Instance Condition	2- Between Good and Fair
	2 2300000 2300 0000
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	SSW#1 2000A Service Disconnect
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Cutler Hammer
Manufacturer	
EquipmentId	SSW#3 Fire Pump Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	20
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Cutler Hammer
Manufacturer	
EquipmentId	HDB Section #1, 2, 3
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate 2010
Installation Year	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MDB Section #1, 2
Equipment d	

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist