Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S./I.S. 217 - MA	ANHATTAN, 645 MAIN ST	FREET, MANHA	TTAN, NY, 10	044		
Inspectio	n Id Inspection Type				Time	In	Last Edited
	232 ELECTRICAL				2023-	-10-17 08:42AN	1 2023-12-22 09:58AN
sset Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:	Fire Alarm Sy	ystem (Main Pan	el, Bell/Horn, Strobe)
				Years:	2023		
				Systems:	Lighting (Nor	n Battery Pack -	LED), Emergency Retrofitted), Lighting -
					Lights (Batter	tial New, Most R ry Pack), Fire Al	tetrofitted), Most Exit arm Printer
				Years:	2022	~	
				Systems:	•	tem (Holding Ar	ea)
				Years:	2015		
				Systems:	•		
				Years:	2014	a	
				Systems:		rm System	
				Years:	2010		
				Systems: Years:		• •	rator Set (Partial nd Battery Charger.
				Systems:		Circuit Breaker	Molded Type Panel
				•	Board	Circuit Breaker	worded Type I aller
				Years:	2008, 1992 Emergency G	enerator Set (Ba	ttam, Charger)
				Systems: Years:	2008	ellerator Set (Ba	(tery Charger)
				Systems:		ctrical Systems	and Components
				Years:	1992	etrical Systems a	and components
Type of S	arvica			Below Gr			
	eractive Whiteboard (IWB)	Exist?		Yes	ound		
	netration In Electrical Roor			Yes			
		N FIRE RESCUE AREAS					
Question	l]	Response		
Are the your bu	•	nce Areas, Fire Rescue Areas, ar	nd/or Holding Room	ns in	Yes		
		le in all of these spaces for use of	during a fire?		Yes		
	all dedicated intercoms op	erational?			Yes		
riority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Penetration in	N/A	Electrical	Electrical	Kenny	Fireman	
	Electrical Room		Equipment	Room B14	Nixon		
Yes	Emergency Generator	Defective fuel delivery.	Emergency	Boiler Room	Kenny	Fireman	No Photo Taken
105	Emergency Generator Components - Not Operational	Fuel storage tank does not exist.	Generator	250	Nixon	гнешай	
No	Public Address System	There is only one speaker	Public Address	Library	Kenny	Fireman	No Photo Taken
	- Speakers Not Operational	in the Library and the announcements are not	System	-	Nixon		
		heard through it.					
nspection	1						
Question	l			Response	2		

Electrical

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		1.127
uestion	Response	
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 2nd Floor	Inspected	
House Lighting	1	
Instance on 2nd Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 2nd Floor	Inspected	
Dimming System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	
Instance on Room 159 - Staff	Inspected	
Lighting	1 ~	
Instance on 1st Floor - Students	Inspected	
Instance on Room 159 - Staff	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor - Students		
	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspeciion		IVIZ /
uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - HID		
Instance on 1st Floor - Students	Does not exist	
Instance on Room 159 - Staff	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Students	Does not exist	
Instance on Room 159 - Staff	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Students	Inspected	
Instance on Room 159 - Staff	Inspected	
	Inspected	
Pendant Mounted	Turner et al	
Instance on 1st Floor - Students	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Room 159 - Staff	Does not exist	
Surface Mounted		
Instance on 1st Floor - Students	Does not exist	
Instance on Room 159 - Staff	Does not exist	
Recessed Mounted		
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 159 - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cafeteria-1st Floor - Students	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Room 159 - Staff	Does not exist	
Projection System		
Instance on 1st Floor - Students	Does not exist	
Instance on Room 159 - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Does not exist	
Instance on Room 159 - Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion		
lestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Gymnasium-Basement	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	Dosnansa	
uestion	Response	
Lighting Instance on 1st Floor	Inspected	
	hispected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - HID Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
	Inspected	
Pendant Mounted	Does not exist	
Instance on 1st Floor	Does not exist	
Surface Mounted Instance on 1st Floor	Does not exist	
	Does flot exist	
Recessed Mounted	Ingrastad	
Instance on 1st Floor Instance Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
LIBRARY	Inspected	
Instance on Room 260	Inspected	
Lighting		
Instance on Room 260	Inspected	
Lighting Fixture - Fluorescent	D	
Instance on Room 260	Does not exist	
Lighting Fixture - HID	D	
Instance on Room 260	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on Room 260	Does not exist	
Lighting Fixture - LED		
Instance on Room 260	Inspected	
Pendant Mounted		
Instance on Room 260	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 260	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 260	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 260	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 260	Does not exist	
LOCKER ROOM	Inspected	
Instance on Room B42 - Boys, B44 - Girls	Inspected	
Alternative Use	Yes	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response	
LOCKER ROOM	торонос	
Instance on Room B42 - Boys, B44 - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room B42 - Boys, B44 - Girls	Does not exist	
Lighting Fixture - HID		
Instance on Room B42 - Boys, B44 - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room B42 - Boys, B44 - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Room B42 - Boys, B44 - Girls	Inspected	
Pendant Mounted	1	
Instance on Room B42 - Boys, B44 - Girls	Does not exist	
Surface Mounted		
Instance on Room B42 - Boys, B44 - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room B42 - Boys, B44 - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Inspected	
Instance on Rooms 308, 313	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	- · · ·	
Instance on Rooms 308, 313	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 308, 313	Does not exist	
Lighting Fixture - HID	~ .	
Instance on Rooms 308, 313	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 308, 313	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 308, 313	Inspected	
Pendant Mounted		
Instance on Rooms 308, 313	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 308, 313	Does not exist	
Recessed Mounted		
Instance on Rooms 308, 313	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Rooms 308, 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 308, 313	Does not exist	
Power Supply		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	M
Question	Response
SCIENCE LAB	
Projection System	
Instance on Rooms 308, 313	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 309	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 309	Inspected
Lighting Fixture - Fluorescent	I
Instance on Room 309	Does not exist
Lighting Fixture - HID	
Instance on Room 309	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 309	Does not exist
Lighting Fixture - LED	
Instance on Room 309	Inspected
Pendant Mounted	1
Instance on Room 309	Does not exist
Surface Mounted	
Instance on Room 309	Does not exist
Recessed Mounted	
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Room 309	Does not exist
Emergency Shut-Off Power	
Instance on Room 309	Does not exist
Power Supply	
Instance on Room 309	Does not exist
SWIMMING POOL	Does not exist
FOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FOILET ROOM - STUDENT	Inspected
	Inspected
Lighting Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - Fluorescent Lighting Fixture - HID	Does not exist
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
TOILET ROOM - STUDENT		
Lighting Fixture - LED		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Auditorium Closet	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	N/A	
Capacity/Size Quantity	30	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Auditorium Stage	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Union Connector Co. Inc	
EquipmentId	N/A	
Capacity/Size Quantity	20	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year Source of Installation Year	2009 Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room B14	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	N/A	
Capacity/Size Quantity	30	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room B14	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui Inspection		1112
estion	Response	
MERGENCY GENERATOR SET		
Automatic Transfer Switch (ATS)		
EquipmentId	Transfer Switch #1 EMDP	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Battery Charger	Inspected	
Instance	Boiler Room 250	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	SENS	
	Regulated Battery Charger	
EquipmentId Capacity/Size Quantity	10	
Capacity/Size UOM	AmpsDC	
Capacity/Size 2 Quantity	24	
Capacity/Size 2 UOM	VDC	
Source of Capacity/Size	Nameplate	
Installation Year	2009	
Source of Installation Year	Documented	
	No deficiencies recorded	
Deficiency		
Emergency Distribution Board	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B14	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mac Power	
EquipmentId	N/A	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Molded Case Circuit Breaker Type	Does not exist	
Diesel	Inspected	
Instance	Boiler Room 250	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer		
E-minut II	Cummins Onan	
EquipmentId	Emergency Generator	
Capacity/Size Quantity	Emergency Generator 219	
Capacity/Size Quantity Capacity/Size UOM	Emergency Generator 219 kVA	
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity	Emergency Generator 219 kVA 175	
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM	Emergency Generator 219 kVA 175 kW	
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM Capacity/Size 3 Quantity	Emergency Generator 219 kVA 175 kW 609	
Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM	Emergency Generator 219 kVA 175 kW	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
EMERGENCY GENERATOR SET	
Diesel	
Source of Installation Year	Documented
Deficiency	GENERATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection		11121
uestion	Response	
FIRE ALARM SYSTEM		
Fused Cutout Panel		
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	N/A	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Does not exist	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Boiler Room 250	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

item inspection			1.1
Juestion		Response	
MOTOR CONTROLL	ER		
MOTOR CONTROL	CENTER		
Instance Qua	ntity	1	
Instance Qua	ntity Uom	EACH	
Manufacture		Allen Bradley	
EquipmentId		MCC-1	
Capacity/Size	Quantity	600	
Capacity/Size		Amps	
Capacity/Size	e 2 Quantity	4	
Capacity/Size	e 2 UOM	Section(s)	
Source of Ca	pacity/Size	Nameplate	
Installation Y		1992	
Source of Ins	tallation Year	Documented	
Deficiency		No deficiencies recorded	
Instance		Electrical Closet 410	
Instance Con	dition	3- Fair	
Instance Qua	ntity	1	
Instance Qua	ntity Uom	EACH	
Manufacture	• •	Allen Bradley	
EquipmentId		MCC-2	
Capacity/Siz		690	
Capacity/Size		Amps	
Capacity/Siz		3	
Capacity/Siz	2 UOM	Section(s)	
Source of Ca	pacity/Size	Nameplate	
Installation Y	ear	1992	
Source of Ins	tallation Year	Documented	
Deficiency		No deficiencies recorded	
MOTOR STARTER/	CONTACTOR	Inspected	
Condition		3- Fair	
Deficiency		No deficiencies recorded	
Variable Frequency I	Drive	Does not exist	
PANEL BOARD		Inspected	
Fused Disconnect Sw	itch Type	Inspected	
Condition		3- Fair	
Deficiency		No deficiencies recorded	
Fused Knife Switch T	ALL OF	Does not exist	
Fused Toggle Switch		Does not exist	
Molded Case Circuit		Inspected	
Condition		3- Fair	
Deficiency		No deficiencies recorded	
PUBLIC ADDRESS SY	STEM	Inspected	
Instance		General Office - Room 101	
Instance Con		3- Fair	
Instance Qua	ntity	1	
Instance Qua	ntity Uom	EACH	
Model		Bogen Multicom - 2000	
Installation Y	ear	1992	
Source of Ins	tallation Year	Documented	
Deficiency		CLOCK NOT OPERATIONAL	
	Location/Instance	Throughout the Building	
Deficiency		17	
Quantity U	om	EACH	
Potential A		REPLACE	
Urgency of	Action	PRIORITY 3	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
PUBLIC ADDRESS SYSTEM	
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Library
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 101
Deficiency Quantity	106,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 111
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Panic Switch	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B14
Instance Condition	3- Fair
Instance Quantity	
· ·	1 EACH
Instance Quantity Uom	
Manufacturer	Mac Power
EquipmentId	Main Disconnect
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 1992
Installation Year	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SERVICE SWITCH	
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B14
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mac Power
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1992
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	Boiler Room B250
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GS Hevi Duty Electric
EquipmentId	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1992
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B14
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	N/A
Capacity/Size Quantity	750
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1992
Source of Installation Year	Documented
Deficiency Instance	No deficiencies recorded Electrical Room B14

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response	
TRANSFORMER		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	STB Hevi-Duty Electric	
EquipmentId	N/A	
Capacity/Size Quantity	1000	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	