Building Condition Assessment Survey 2023-2024

Mechanical Inspection M343

	Asset:	THE PECK SLIP SCHOOL - MANHATTAN, 1 PECK SLIP, MANHATTAN, NY, 10038					
	Inspection Id	Inspection Type	Time In	Last Edited			
	3531	MECHANICAL	2024-02-28 08:17AM	2024-03-30 03:14PM			
cc	ssat Data						

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MER 125, Fire Pump Room 104
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No	Defective Kitchen Gas System	Defective (1)	Gas System	kitchen	Alawi Khatari	Fireman		TAS BAST GIT

Inspection

ecuon		
uestion	Response	
echanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Inspected	
Absorption Chiller	Does not exist	
Air Cooled Chiller	Does not exist	
Air Cooled Condenser	Does not exist	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	PUMP:DEFECTIVE	
Deficiency Location/Instance	Boiler Room / P-2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Backflow Preventer	Does not exist	
Central Station Air Handler	Inspected	
Instance	6th Floor Roof	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Annexair	
EquipmentId	RTU-GA	
Capacity/Size Quantity	30	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection		
Ouestion	Response	

estion	Response
IR CONDITIONING	
Chilled Water System	
Central Station Air Handler	
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	6th Floor Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Annexair
EquipmentId	RTU-CR
Capacity/Size Quantity	100
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	MER 125
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Annexair
EquipmentId	AHU-K/C
Capacity/Size Quantity	20
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fan Coil Unit	Does not exist
Packaged Air Cooled Chiller	Inspected
Instance	6th Floor Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Airstack
EquipmentId	CH-1
Capacity/Size Quantity	150
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Refrigerant Type	R-410A
Deficiency	OVER 100 TONS:DEFECTIVE COMPRESSOR
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	6th Floor Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Airstack

Building Condition Assessment Survey 2023-2024

-	_
estion	Response
IR CONDITIONING	
Chilled Water System	
Packaged Air Cooled Chiller	
EquipmentId	CH-2
Capacity/Size Quantity	150
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Refrigerant Type	R-410A
Deficiency	OVER 100 TONS:DEFECTIVE COMPRESSOR
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	6th Floor Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	AAON
EquipmentId	RTU-L
Equipmentid Capacity/Size Quantity	7
Capacity/Size Quantity Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Source of Heating	Hydronic
Refrigerant Type	R-410A
Deficiency	No deficiencies recorded
	Does not exist
Packaged Terminal A/C	Does not exist Does not exist
Refrigerant Leak Detection System	
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

chunicui Inspection		171545
Question	Response	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected 1- Good	
Condition		
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Inspected	
Condition	2- Between Good and Fair	
Are all the existing non-auditorium handicap stair lifts operable?	No	
Deficiency	No deficiencies recorded	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Inspected	
Electric Pressure Booster System	Inspected	
Instance	Water Service Room 106C	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pump	
EquipmentId	N/A	
Capacity/Size Quantity	2	
Capacity/Size UOM	Total # Pumps	
Capacity/Size 2 Quantity	10tai # 1 umps	
Capacity/Size 2 UOM	Total Pumps HP	
Source of Capacity/Size	Documented	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Hydraulic/Pneumatic Booster System	Does not exist	
Water Service	Inspected	
Instance	Water Service Room 106C	
Instance Condition	1- Good	
Instance Quantity	2 EACH	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Instance	Water Service Room 106C	

Building Condition Assessment Survey 2023-2024

uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Cold Water System		
Water Service		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	RPZ:DEFECTIVE	
Deficiency Location/Instance	Water Service Room 106C	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lochinvar	
EquipmentId	N/A	
Capacity/Size Quantity	400	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Sewage Ejector Pump	Inspected	
Sump Pump Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	No deficiencies recorded Does not exist	

Building Condition Assessment Survey 2023-2024

Building Condition Assessment Survey 2023-2024

unicai Inspection		W134
uestion	Response	
HEATING		
Hydronic Heating		
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	FIN TUBE:DAMAGED GUARD/SHIELD	
Deficiency Location/Instance	Corridor near Room 609	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
IEATING PLANT	Inspected	
Instance on Penthouse	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	N/A	
Burner Model	N/A	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on Penthouse	Inspected	
Boiler Auxiliary Piping		
Instance on Penthouse	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Penthouse	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System	- 10 4011011010110101010101	
Instance on Penthouse	Does not exist	
Boiler Feedwater Treatment(Automatic)	Does not exist	
Instance on Penthouse	Does not exist	
	Does not exist	
Boiler Flue Exhaust		
Instance on Penthouse	Does not exist	
Boiler Make-up Water Backflow Preventer		
Instance on Penthouse	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE RPZ	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	M343
Question	Response

2 ,	DIADITY 1
Boiler Make-up Water Backflow Preventer Urgency of Action Pl	DINORITY 4
Urgency of Action Pl	DIADITY 4
	DIODITY 2
	RIORITY 3
Purpose of Action	EVEL 2
Violations	No violations recorded
Boiler Room Steam And Condensate Piping	
Instance on Penthouse D	Ooes not exist
Boiler Safety Valve	
Instance on Penthouse D	Does not exist
Boiler System	
Instance on Penthouse In	nspected
Coal-fired Boiler	
	Does not exist
Hot Water Boiler	
	Does not exist
Modular Boiler	
Instance on Penthouse In	nspected
Instance on Penthouse In	nspected
<u>Instance</u> Be	Boiler Room
Instance Condition 2-	- Between Good and Fair
Instance Quantity 2,	,426
Instance Quantity Uom M	MBH NET
Manufacturer A	ERCO
z-q-ipm-ma-	J/A
1 7 7	790
1 7	MBH Gross
	Occumented 015
	Occumented
	No deficiencies recorded
	Soiler Room
	- Between Good and Fair
	,426
	MBH NET
instance Quantity Com	ERCO
	V/A
Equipmentia	790
	MBH Gross
• •	Occumented
Installation Year 20	015
	Occumented
Deficiency	No deficiencies recorded
<u>Instance</u> Be	Boiler Room
Instance Condition 2-	- Between Good and Fair
Instance Quantity 2,	,426
Instance Quantity Uom M	MBH NET
	AERCO
z-q-ipm-ma-	J/A
	790
1 2	MBH Gross
	Occumented 015
	015 Documented
	No deficiencies recorded
Deficiency	do deficiencies recorded

Building Condition Assessment Survey 2023-2024

инисш твресион	IVIS
Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Instance on Penthouse	Does not exist
Fuel System	
Instance on Penthouse	Does not exist
Enclosed IDF Room	Inspected
Instance on Rooms 303, 403, 503	Inspected
Dedicated A/C Equipment	-
Instance on Rooms 303, 403, 503	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE SHUT-OFF SWITCH
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Мес	chanical Inspection	M343

•		141343
Question	Response	
KITCHEN		
Hood Fire Suppression System		
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 201	Inspected	
Dedicated A/C Equipment		
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 512	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	110	
Instance on Room 512	Does not exist	
CO Detector		
Instance on Room 512	Not required	
Emergency Shower	,	
Instance on Room 512	Does not exist	
Eye Wash		
Instance on Room 512	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 512	Does not exist	
Hood Exhaust Fan		
Instance on Room 512	Does not exist	
Fixed Laboratory Hood		
Instance on Room 512	Does not exist	
Laboratory Sink		
Instance on Room 512	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up_Air Unit		
Instance on Room 512	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 514	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 514	Does not exist	
CO Detector		
Instance on Room 514	Not required	
Emergency Shower		
Instance on Room 514	Does not exist	
Eye Wash		
Instance on Room 514	Does not exist	

Building Condition Assessment Survey 2023-2024

Building Condition Assessment Survey 2023-2024

uestion	Response	
VENTILATION		
Metal Ductwork		
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	