

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390

Asset: P.S. 183 GYM - MANHATTAN, 408 EAST 67 STREET, MANHATTAN, NY, 10065

Inspection Id	Inspection Type	Time In	Last Edited
2310	ARCHITECTURAL - SENIOR	2024-01-10 09:05AM	2024-02-13 05:12PM
2368	ARCHITECTURAL - ASSOCIATE	2024-01-10 08:35AM	2024-01-10 10:30AM

Asset Data

Question	Answer
Was the Building Fully Accessible for Inspection?	Yes
Principal(s) Information	
Principal Name	Martin Woodard
Principal Organization	P.S. 183 - Manhattan
Meeting with Principal?	Yes
Principal Feedback	The Principal had no comments about the condition of the building at this time.
Custodian	John Brennan
Was the Custodian Present?	Yes
Fireman	Marlon Arias
Was the Fireman Present?	Yes
Building Square Footage	5,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	1 (No Basement)
Comments on the Year Built	2007
Student Population	535
Staff Population	1
Comments on the Number of Classrooms	0
Weather	Fair
Facade Photo	



East 67th Street - South View

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390

Main Entrance Photo



Facade C - Playground

Roof Photo



Roof 1 - Northeast View

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Tandem

Leased Space?

No

No Storm Water Management Type Selected

No System Upgraded

No New Construction

No Tandem

No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the Primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	No
Do any of the following spaces exist? Classroom, Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes
For the spaces that do exist, are they ALL accessible?	Yes
Is there at least one Boys and Girls or Unisex toilet accessible In the building?	Yes

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390


Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
PROGRAMMATIC ACCESSIBILITY						
Exterior Routes						
Exterior Entrances & Exits		Yes				
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	No		No			
Interior Routes						
Corridor and Lobby H/C Lifts	No		No			
Interior Corridor Doors And Hardware	No		No			
Interior Corridors & Lobbies		Yes				
Interior Elevators	No					
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	No					
Rooms & Spaces						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms	No					
Computer Rooms	No					
Gymnasium						
1st Floor	Yes	Yes			No	Yes
Library	No					
Main Office	No					
Multi-purpose Room	No					
Nurse's Office	No					
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
1st Floor	Yes	Yes				
Toilet Rooms (girls)						
1st Floor	Yes	Yes				
Toilet Rooms (staff)	No					

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390

Building Template






Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CHIMNEY	Does not exist
COPING	Does not exist
CORNICE	Does not exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DOOR HARDWARE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	6,450
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	6,450
Instance Quantity Uom	S.F.
Deficiency	BRICK:DETERIORATED CONTROL/EXPANSION JOINTS WITH DAMAGED CAULKING

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390

Question	Response
EXTERIOR	
EXTERIOR WALLS	
Roof Plan Reference	
Elevation	
Elevation Reference	Facade D
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
EXTERIOR SOFFITS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOADING DOCK	Does not exist
LOUVER	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PARAPETS	Does not exist
PLAZA DECK	Does not exist
ROOF	Inspected
ROOFING	Inspected
ROOF HATCH/SMOKE HATCH	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Does not exist
ROOF BARRIER/FENCE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ROOF CAGE	Does not exist
ROOFING	Inspected
Replacement Quantity	5,000
Replacement Uom	S.F.
Instance on IRMA:Roof 1	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M390

Question	Response
EXTERIOR	
ROOF	
ROOFING	
ROOFING	
Instance Roof Photo	
	Roof 1
Instance Condition	2- Between Good and Fair
Instance Quantity	5,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this Roof Instance have a Sustainable Roof System?	No
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	No
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
ROOFING DRAINS	Inspected
Condition	4- Between Fair and Poor
Deficiency	DETERIORATED
Deficiency Location/Instance	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SPECIALTIES	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist
WINDOWS	Does not exist
INTERIOR	Inspected
POOLS	Does not exist
STRUCTURAL	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M390

Question	Response
INTERIOR	
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	3- Fair
Deficiency	MASONRY BEARING WALL:CRACKED/SPALLED
Deficiency Location/Instance	Mezzanine
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	RESTITCH
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo 1	
Deficiency Photo 2	Mechanical Equipment Room
Violations	No photo recorded
	No violations recorded
FLOOR STRUCTURE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FOUNDATION WALLS	Inspected
Material Type(s)	Concrete
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ROOF STRUCTURE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
VAULTS-BUNKERS	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Does not exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	Under construction
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Ceiling	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	SHEET VINYL:BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Entrance

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M390

Question	Response
INTERIOR	
GYMNASIUM	
Floor Finish	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Near Entrance
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Seating	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	MOVABLE PANELS:DAMAGED
Deficiency Location/Instance	Center
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Center
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Stage	
Instance on 1st Floor	Does not exist
Walls	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	WALL PADDING:DETERIORATED
Deficiency Location/Instance	Near Entrance, perimeter
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M390

Question	Response
INTERIOR	
GYMNASIUM	
Walls	
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Entrance
Violations	No photo recorded No violations recorded
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Does not exist
INTERIOR DOOR HARDWARE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTI-PURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SHOWER ROOM	Does not exist
STAIRS/RAMPS: INTERIOR	Under construction
TOILET ROOMS - STAFF	Does not exist
TOILET ROOMS - STUDENTS	Inspected
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not exist
STEEL STAIRS	Does not exist
SITE	Not required

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Architectural Inspection

M390

Does the SCA expect asset to have artwork?

No