Building Condition Assessment Survey 2023-2024

Electrical Inspection

| Electrical Inspection M43 | | | | |
|---|---|--------------------|---|-----------------------|
| Asset: | MANHTN CT FOR MATH & SCI. HS - MANHATTA | AN, 260 PLEASANT A | VENUE, MANHATTAN, NY | , 10029 |
| Inspection Id | Inspection Type | | Time In | Last Edited |
| 1559 | ELECTRICAL | | 2023-12-05 08:38AM | 2024-01-09 10:47AM |
| sset Data | | | | |
| Question | | Answer | | |
| Have any Systems/Major Building Components been upgraded? | | Systems: | IPDVS/CCTV System, 1st Floor Emergency Light Battery Pack, I Light Non Battery Pack, LED Su | Retrofitted Emergency |
| | | Years: | 2023 | |
| | | Systems: | Security Lights | |
| | | Years: | 2022, 2005 (Roof) | |
| | | Systems: | LAN, LED Lighting (Main Entra Auditorium, Basement - Gymnas Surface LED Lighting (Corridors | sium), Retrofitted |
| | | Years: | 2022 | |
| | | Systems: | Library (Lighting) | |
| | | Years: | 2019 | |
| | | Systems: | Raceway with Receptacles (Com | nputer Lab Room 362) |

Years:

Years: Systems:

Years:

Years:

Years: Systems:

Years:

Years:

Systems:

Systems: Years:

Systems:

Years:

Years:

Years:

Yes

No

Systems:

Systems:

Systems:

Systems:

2018

System) 2016

2015

2014

2011

2008

2006

2000

1999

Lighting) 2013

Fire Alarm System (Printer)

Systems: Partial Motor Starter, 1st Floor - Gymnasium (LED

Lighting, Scoreboard), Health Center (Fluorescent

Intercom System (Elevator), Interior Fluorescent Lighting (Except Kitchen, Science Prep Rooms, Science Lab Rooms (305, 306, 313, 314), Science Demo Rooms (323, 381)), Most Emergency Lighting

Molded Case Circuit Breaker Type Panel Board

Public Address System, Local Sound System, Auditorium (Theater Lighting System)

Interior Fluorescent Lighting (Kitchen, Science Prep Rooms, Science Lab Rooms (305, 306, 313, 314),

Service Switch, Switchboard, Fused Disconnect Switch

Type Panel Board, Intrusion Alarm System, Emergency

Exit/Emergency Light

(Non Battery Pack)

2010, 2007, 1999, 1998

Fire Alarm System (Except Printer)

Science Demo Rooms (323, 381))

Light/Exit Light Panel

Exit Light (Battery Pack), Auditorium (Projection

| Type of Service |
|--|
| Does Interactive Whiteboard (IWB) Exist? |
| |

Water Penetration In Electrical Room? DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Response No

Below Ground

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?

Priority Condition

Question

Building Condition Assessment Survey 2023-2024

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image | |
|---------------------|---|---|--|---|-------------------------------|--------------------|----------------|--|
| No | Grounding System - | Improper Grounding since | Grounding | Water Meter | Water | Fireman | No Photo Taken | |
| | Defective | the system is not attached to the Water Main | System | Room by Kitchen | Meter Room by | Theman | | |
| Yes | Water Leaks onto Electrical Equipment | Wall Leak affecting a junction box, Roof Leak affecting a Lighting Fixture, Steam Leak | Panel Board, Junction Box, Lighting Fixture | 4th Floor Corridor near Greenhouse, Auditorium, | Kitchen David Maldonado | Fireman | No Photo Taken | |
| | | affecting one Switchboard, Foundation Wall Leak affecting a junction box in Boiler Room by Dampers and a wall outlet in Gymnasium - Mechanical Room | Fixture | Additionally, Basement (Electrical Room B56, Boiler Room by Dampers, Gymnasium - Mechanical Room) | | | | |
| No | Fire Alarm System - Components Not Operational | N/A | Fire Alarm System - Magnetic Door Holder/Contac tor | Corridor by Room B44 | David Maldonado | Fireman | No Photo Taken | |
| Yes | Intercom - Not Connected to Remote Monitoring Station | N/A | Intercom System - Elevator | Elevator Device ID# 1P20883 | David Maldonado | Fireman | No Photo Taken | |
| Yes | Fire Alarm System - Components Missing | N/A | Fire Alarm System - Magnetic Door | By Rooms (B44, 136, 218, 246, 318, 343) | David Maldonado | Fireman | No Photo Taken | |
| nspection | <i>a</i> | | Holder/Contac tor | | | | | |
| Ouestion | | | | Response | | | | |
| Electrica | | | | Response | | | | |
| | ETIC FIELD | | | Does not o | eviet | | | |
| | FORIUM | | | Inspected | | | | |
| AUDI | Instance on 1st Floor | | | Inspected | | | | |
| Hous | se Lighting | | | Inspected | | | | |
| | Instance on 1st Floor | | | Inspected | | | | |
| | Does a Chandelier Exis | st? | | No | | | | |
| Lig | ghting Fixture - Fluorescer | ıt | | | | | | |
| _ | Instance on 1st Floor | | | Inspected | | | | |
| Р | Pendant Mounted | | | | • . | | | |
| | Instance on 1st Floor | | | Does not o | exist | | | |
| S | Instance on 1st Floor | | | Inspected | | | | |
| | Instance Condition | | | Inspected 3- Fair | | | | |
| | Deficiency | | | | encies recorded | | | |
| | Recessed Mounted | | | | | | | |
| K | Instance on 1st Floor | | | Does not o | eviet | | | |
| Lie | shting Fixture - HID | | | DOES HOL | -1131 | | | |
| Lig | Instance on 1st Floor | | | Does not o | exist | | | |
| Lio | chting Fixture - Incandesc | ent | | 2003 101 | | | | |
| | Instance on 1st Floor | | | Inspected | | | | |
| P | endant Mounted | | | ł | | | | |
| | Instance on 1st Floor | | | Does not o | exist | | | |
| | | | | | | | | |

BCAS Partners Version 2.0 (P)

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|---|--------------------------|--|
| AUDITORIUM | | |
| House Lighting | | |
| Lighting Fixture - Incandescent | | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Local Sound System | Does not exist | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Installation Year | 2006 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Is the projector on a cart or installed on the ceiling? | Ceiling | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting System | | |
| Instance on 1st Floor | Inspected | |
| Dimming System | 1 | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| CAFETERIA | Inspected | |
| Instance on Basement | Inspected | |
| Lighting | hispeeed | |
| Instance on Basement | Inspected | |
| Lighting Fixture - Fluorescent | inspected | |
| Instance on Basement | Inspected | |
| Pendant Mounted | Inspecied | |
| | Increated | |
| Instance on Basement | Inspected 3- Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| | · · · | |
| Instance on Basement Instance Condition | Inspected 3- Fair | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| ical Inspection | 14. |
|---|----------------------------------|
| uestion | Response |
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not exist |
| Local Sound System | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Installation Year | 2006 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Basement | Does not exist |
| Theater Lighting System | |
| Instance on Basement | Does not exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Inspected |
| Pendant Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| | |
| COMPUTER LAB | Inspected |
| Instance on Room 362 | Inspected |
| Power Panel? | No |
| Instance on Rooms 350, 360 | Inspected |
| Power Panel? | Yes |

Building Condition Assessment Survey 2023-2024

| Duestion | Response | |
|---|--------------------------|--|
| COMPUTER LAB | | |
| Lighting | | |
| Instance on Room 362 | Inspected | |
| Instance on Rooms 350, 360 | Inspected | |
| Lighting Fixture - Fluorescent | * | |
| Instance on Room 362 | Inspected | |
| Instance on Rooms 350, 360 | Inspected | |
| Pendant Mounted | | |
| Instance on Room 362 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 350, 360 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 362 | Does not exist | |
| Instance on Rooms 350, 360 | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 362 | Does not exist | |
| Instance on Rooms 350, 360 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 362 | Does not exist | |
| Instance on Rooms 350, 360 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 362 | Does not exist | |
| Instance on Rooms 350, 360 | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Room 362 | Does not exist | |
| Instance on Rooms 350, 360 | Does not exist | |
| Raceway With Receptacles | | |
| Instance on Room 362 | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 350, 360 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| GYMNASIUM | Inspected | |
| Instance on Basement | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting | Inspected | |
| Instance on Basement | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | inspected | |
| Instance on 1st Floor | Inspected | |
| Instance on Basement | Does not exist | |
| Pendant Mounted | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| Surface Mounted | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| Recessed Mounted | DOES HOLEXIST | |
| Instance on 1st Floor | Does not exist | |
| | DOUS HOL CAISU | |
| Lighting Fixture - HID Instance on 1st Floor | Does not exist | |
| Instance on 1st Floor | ראואנ | |

Building Condition Assessment Survey 2023-2024

| estion | Response | |
|----------------------------------|------------------------------------|--|
| YMNASIUM | · | |
| Lighting | | |
| Lighting Fixture - HID | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not exist | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor | Inspected | |
| Instance on Basement | Inspected | |
| Pendant Mounted | | |
| Instance on 1st Floor | Does not exist | |
| Instance on Basement | Does not exist | |
| Surface Mounted | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Basement | Inspected | |
| Instance Condition | 1- Good | |
| | No deficiencies recorded | |
| Deficiency | No deliciencies recorded | |
| Recessed Mounted | ¥ . 1 | |
| Instance on 1st Floor | | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE | |
| Deficiency Quantity | 4 | |
| Quantity Uom Potential Action | EACH REPLACE BALLAST | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Instance on Basement | Does not exist | |
| Local Sound System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Installation Year | 2006 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Installation Year | 2006 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on Basement | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| Scoreboard | | |
| Instance on Basement | Does not exist | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting System | | |
| Instance on Basement | Does not exist | |
| Instance on 1st Floor | Does not exist | |
| ITCHEN | Inspected | |

Building Condition Assessment Survey 2023-2024

| iestion | Response |
|---------------------------------|------------------------------------|
| KITCHEN | |
| Instance on Basement | Inspected |
| Lighting | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not exist |
| | Inspected |
| JBRARY | |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

Building Condition Assessment Survey 2023-2024

| lestion | Response | - |
|--|----------------------------------|---|
| JBRARY | | |
| Raceway With Receptacles | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on 1st Floor | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| LOCKER ROOM | Inspected | |
| Instance on 1st Floor - Visitors | Inaccessible | |
| Instance on Basement - Boys, 1st Floor - Girls | Inspected | |
| Alternative Use | | |
| | No | |
| Lighting Instance on Basement - Boys, 1st Floor - Girls | Inspected | |
| | inspected | |
| Lighting Fixture - Fluorescent Instance on Basement - Boys, 1st Floor - Girls | Inspected | |
| Pendant Mounted | inspected | |
| | Does not exist | |
| Instance on Basement - Boys, 1st Floor - Girls | Does not exist | |
| Surface Mounted | Tu an a da d | |
| Instance on Basement - Boys, 1st Floor - Girls | Inspected 3- Fair | |
| Instance Condition | | |
| Deficiency Deficiency Quantity | LIGHTING FIXTURE NOT OPERATIONAL | |
| | | |
| Quantity Uom | EACH | |
| Potential Action | REPAIR PRIORITY 2 | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Recessed Mounted | | |
| Instance on Basement - Boys, 1st Floor - Girls | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Basement - Boys, 1st Floor - Girls | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Basement - Boys, 1st Floor - Girls | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Basement - Boys, 1st Floor - Girls | Does not exist | |
| AULTIPURPOSE ROOM | Does not exist | |
| CIENCE DEMO ROOM | Inspected | |
| Instance on Room 323 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 381 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Inspected | |
| Power Panel? | | |
| Alternative Use | No | |
| | No | |
| Instance on Room 304 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 367 | Inspected | |

Electrical Inspection

| | | IV143 |
|--|--------------------------|-------|
| stion | Response | |
| CIENCE DEMO ROOM | | |
| Alternative Use | No | |
| Lighting | | |
| Instance on Room 323 | Inspected | |
| Instance on Room 381 | Inspected | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Inspected | |
| Instance on Room 304 | Inspected | |
| Instance on Room 367 | Inspected | |
| Lighting Fixture - Fluorescent | 1 | |
| Instance on Room 323 | Inspected | |
| Instance on Room 381 | Inspected | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Inspected | |
| Instance on Room 304 | Inspected | |
| Instance on Room 367 | Inspected | |
| Pendant Mounted | mspecied | |
| Instance on Room 323 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 381 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| | | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Inspected 3- Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 367 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 323 | Does not exist | |
| Instance on Room 381 | Does not exist | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Does not exist | |
| Instance on Room 304 | Does not exist | |
| Instance on Room 367 | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 323 | Does not exist | |
| Instance on Room 381 | Does not exist | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Does not exist | |
| Instance on Room 304 | Does not exist | |
| Instance on Room 367 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 323 | Does not exist | |
| Instance on Room 381 | Does not exist | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Does not exist | |
| Instance on Room 304 | Does not exist | |
| Instance on Room 367 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 323 | Does not exist | |
| Instance on Room 381 | Does not exist | |
| Instance on Room 301, 302, 315, 316, 378, 380 | Does not exist | |
| | | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|--|--------------------------|--|
| SCIENCE DEMO ROOM | - F - w- | |
| Power Supply | | |
| Instructor Unit | | |
| Deficiency | No deficiencies recorded | |
| Meter Demonstration Unit | | |
| Instance on Room 323 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 381 | Does not exist | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Does not exist | |
| Instance on Room 304 | Does not exist | |
| Instance on Room 367 | Does not exist | |
| Projection System | | |
| Instance on Room 323 | Does not exist | |
| Instance on Room 381 | Does not exist | |
| Instance on Rooms 301, 302, 315, 316, 378, 380 | Does not exist | |
| Instance on Room 304 | Does not exist | |
| Instance on Room 367 | Does not exist | |
| SCIENCE LAB | Inspected | |
| Instance on Room 258 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 305 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | No | |
| Instance on Room 306 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 313 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 314 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | | |
| Lighting | No | |
| Instance on Room 258 | Inspected | |
| Instance on Room 305 | Inspected | |
| Instance on Room 306 | Inspected | |
| Instance on Room 313 | Inspected | |
| Instance on Room 314 | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Room 258 | Inspected | |
| Instance on Room 305 | Inspected | |
| Instance on Room 306 | Inspected | |
| Instance on Room 313 | Inspected | |
| Instance on Room 314 | Inspected | |
| Pendant Mounted | r | |
| Instance on Room 258 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 305 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| cai inspection | | 1014 |
|---|--------------------------|------|
| estion | Response | |
| CIENCE LAB | | |
| Lighting | | - |
| Lighting Fixture - Fluorescent | | |
| Pendant Mounted | | |
| Instance on Room 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 313 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 314 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 258 | Does not exist | |
| Instance on Room 305 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 258 | Does not exist | |
| Instance on Room 305 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 258 | Does not exist | |
| Instance on Room 305 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 258 | Does not exist | |
| Instance on Room 305 | Inspected | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| Pendant Mounted | | |
| Instance on Room 305 | Does not exist | |
| Surface Mounted | | |
| Instance on Room 305 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on Room 305 | Does not exist | |
| | Does not exist | |
| Lighting Fixture - LED Instance on Room 258 | Does not exist | |
| Instance on Room 258 Instance on Room 305 | Does not exist | |
| | | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| Emergency Gas Shut-Off Valve Instance on Room 258 | Does not exist | |
| | | |

Electrical Inspection

| Response | |
|--------------------------|---|
| | |
| | |
| * | |
| | |
| | |
| - | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| | |
| Does not exist | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| * | |
| | |
| | |
| | |
| | |
| No deficición recorded | |
| Does not exist | |
| | |
| | |
| | |
| | |
| hispected | |
| Y / 1 | |
| - | |
| | |
| | |
| - | |
| | |
| | |
| | |
| | |
| No deficiencies recorded | |
| | |
| | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| | Inspected 3 - Fair No deficiencies recorded |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | | M43 |
|--------------------------------|--------------------------|-----|
| Question | Response | |
| SCIENCE LAB | | |
| Power Supply | | |
| Meter Demonstration Unit | | |
| Deficiency | No deficiencies recorded | |
| Student Unit | | |
| Instance on Room 305 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 313 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 314 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on Room 258 | Does not exist | |
| Instance on Room 305 | Does not exist | |
| Instance on Room 306 | Does not exist | |
| Instance on Room 313 | Does not exist | |
| Instance on Room 314 | Does not exist | |
| SCIENCE PREP ROOM | Inspected | |
| Instance on Room 258A | - | |
| Power Panel? | Inspected | |
| | No | |
| Alternative Use | No | |
| Instance on Room 307 | Inspected | |
| Power Panel? | No | |
| Alternative Use | Yes | |
| Instance on Room 311 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Instance on Room 312 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Lighting | | |
| Instance on Room 258A | Inspected | |
| Instance on Room 307 | Inspected | |
| Instance on Room 311 | Inspected | |
| Instance on Room 312 | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Room 258A | Inspected | |
| Instance on Room 307 | Inspected | |
| Instance on Room 311 | Inspected | |
| Instance on Room 312 | Inspected | |
| Pendant Mounted | | |
| Instance on Room 258A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 307 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 311 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Denotorey | | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| 1914 |
|-------------------------------------|
| Response |
| |
| |
| |
| |
| Inspected |
| 3- Fair |
| No deficiencies recorded |
| |
| Does not exist |
| Does not exist |
| Does not exist |
| Inspected |
| 3- Fair |
| No deficiencies recorded |
| |
| Does not exist |
| |
| Does not exist |
| Does not exist |
| Does not exist |
| |
| Does not exist |
| |
| Does not exist |
| Does not exist |
| Inspected |
| Does not exist |
| |
| Inspected |
| 3- Fair |
| LIGHTING FIXTURE BEYOND USEFUL LIFE |
| 2 |
| EACH REPLACE-UPGRADE |
| PRIORITY 1 |
| LEVEL 2 |
| No violations recorded |
| |
| Does not exist |
| |
| Does not exist |
| Does not exist |
| Does not exist |
| |
| Does not exist |
| Does not exist |
| Does not exist |
| Inspected |
| Inspected |
| 3- Fair |
| Nie definischer merended |
| No deficiencies recorded Inspected |
| |

Electrical Inspection

| icai Inspection | 5-1VI |
|---------------------------------|-------------------------------------|
| uestion | Response |
| SCIENCE PREP ROOM | |
| Emergency Gas Shut-Off Valve | |
| Deficiency | No deficiencies recorded |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 312 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 258A | Does not exist |
| Instance on Room 307 | Does not exist |
| Instance on Room 311 | Does not exist |
| Instance on Room 312 | Does not exist |
| Power Supply | |
| Instance on Room 258A | Does not exist |
| Instance on Room 307 | Inspected |
| Instance on Room 311 | Inspected |
| Instance on Room 312 | Inspected |
| Instructor Unit | |
| Instactor on Room 307 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 311 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| Instance on Room 312 | Inspected 3- Fair |
| Instance Condition | No deficiencies recorded |
| Deficiency | |
| SWIMMING POOL | Does not exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|---------------------------------------|-------------------------------------|
| TOILET ROOM - STAFF | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Recessed Mounted | Does not exist |
| Lighting Fixture - LED | Does not exist |
| FOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - LED | Does not exist |
| UXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| | |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Throughout the Building |
| Deficiency Quantity | 19 EACH |
| Quantity Uom Potential Action | EACH DEDLACE DATTEDY |
| Potential Action Urgency of Action | REPLACE BATTERY PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | LEVEL 2 No violations recorded |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium - Stage |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|--------------------------------|---------------------------------------|
| EMERGENCY LIGHTING | |
| Battery Pack | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| • | |
| XIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Main Entrance Lobby by Auditorium |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| XIT/EMERGENCY LIGHT | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| IRE ALARM SYSTEM | Inspected |
| | |
| Bell/Horn | Inspected 2- Between Good and Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not exist |
| CO Detector Heat Detector | Inspected |
| Condition | 2- Between Good and Fair |
| | |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Inspected |
| Condition | 4- Between Fair and Poor |
| Deficiency | CONTACTOR MISSING |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| estion | Response | |
|---------------------------------------|---|--|
| IRE ALARM SYSTEM | | |
| Magnetic Door Holder/Contactor | | |
| Deficiency Location/Instance | By Rooms (218, 246, 318, 343) | |
| Deficiency Quantity | 4 | |
| Quantity Uom | EACH | |
| Potential Action | INSTALL CONTACTOR | |
| Urgency of Action | PRIORITY 5 | |
| Purpose of Action | LEVEL 6 | |
| Violations | No violations recorded | |
| Deficiency | CONTACTOR NOT OPERATIONAL | |
| Deficiency Location/Instance | Corridor by Room B44 | |
| Deficiency Quantity | 2 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 5 | |
| Purpose of Action | LEVEL 6 | |
| Violations | No violations recorded | |
| Fused Cutout Panel | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Digital Communicator | Does not exist | |
| Main Panel | Inspected | |
| Bell At Panel | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| | Inspected | |
| Fire Alarm Control Panel (Electronic) | _ | |
| Instance | Main Entrance Lobby 2- Between Good and Fair | |
| Instance Condition | | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Manufacturer | Edwards System Technology | |
| Model | EST 2 | |
| EquipmentId | Fire Alarm Control | |
| Installation Year | 2008 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Control Panel (Standard) | Does not exist | |
| Sub-Panel | Inspected | |
| Bell At Panel | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Control Panel (Electronic) | Inspected | |
| Instance | Main Entrance Lobby | |
| Instance Condition | 2- Between Good and Fair | |
| Instance Quantity | | |
| | 1 EACH | |
| Instance Quantity Uom | | |
| Manufacturer | Edwards System Technology | |
| Model | EST 2 | |
| EquipmentId | Horn/Strobe Control Panel | |
| Installation Year | 2008 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Control Panel (Standard) | Does not exist | |
| | Inspected | |

Electrical Inspection

| rical Inspection | W145 |
|---|--|
| Question | Response |
| FIRE ALARM SYSTEM | |
| Remote Annunciator | |
| Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | IMPROPER GROUNDING |
| Deficiency Location/Instance | Water Meter Room by Kitchen |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| INTERCOM SYSTEM | Inspected |
| Elevator | Inspected |
| Condition | 3- Fair |
| Deficiency | NOT CONNECTED TO REMOTE MONITORING STATION |
| Deficiency Location/Instance | Elevator Device ID - 1P20883 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL CONNECTION |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Holding Area | Does not exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| MOTOR CONTROLLER | Inspected |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected 3- Fair |
| Condition | |
| Deficiency | MOTOR STARTER NOT OPERATIONAL |
| Deficiency Location/Instance Deficiency Quantity | Mechanical Room 353 (House Bl) |
| | |
| Quantity Uom | EACH |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| uestion | Response |
|---|---|
| MOTOR CONTROLLER | • |
| MOTOR STARTER/CONTACTOR | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Variable Frequency Drive | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Mechanical Rooms (Next to Boiler Room, B8), Electrical Room |
| | B56 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | NO SPARE |
| Deficiency Location/Instance Deficiency Quantity | Boiler Room, Cafeteria, By Room 334, Mechanical Room 353 4 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Instance | General Office - Room 149 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Telecor II |
| Installation Year | 2006 |
| Source of Installation Year | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | By Rooms (B33, 306 - Science Lab) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Condition | 1- Good |
| Installation Year | 2023 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |

| iestion | Response |
|--|---|
| SECURITY | |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | Custodian's Office - Room 180 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128B |
| Installation Year | 1999 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3- Fair |
| Deficiency | SIREN/STROBE NOT ACTIVE |
| Deficiency Location/Instance | Main Entrance Lobby, General Office - Room 149, Exterior Wall by Library |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Lighting - Security | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room B56 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | Main Switchboard 1A |
| Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate 1999 |
| Installation Year Source of Installation Year | Documented |
| | No deficiencies recorded |
| Deficiency | Electrical Room B56 |
| Instance Instance Condition | 3- Fair |
| | |
| Instance Quantity | L EACH |
| Instance Quantity Uom | |
| Manufacturer | All City Switchboard |
| EquipmentId | Main Switchboard 1B 1200 |
| Capacity/Size Quantity Capacity/Size UOM | 1200 Amps |

Building Condition Assessment Survey 2023-2024

Response

Electrical Inspection

Question

| zucstion | Kesponse |
|---|----------------------------------|
| SERVICE SWITCH | |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1999 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | Inspected |
| Number of Spares | 50 |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room B56 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| | Sub Distribution Board 2A and 2B |
| EquipmentId Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 4 |
| Capacity/Size 2 UOM | section(s) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1999 |
| Source of Installation Year | Inspector Estimate |
| Deficiency | No deficiencies recorded |
| | |
| Instance | Electrical Room B56 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | SWITCHBOARD 1A, 2A, 3A, 4A |
| Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 4 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1999 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room B56 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| | SWITCHBOARD 1B, 2B, 3B, 4B |
| EquipmentId Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | |
| Capacity/Size 2 Quantity | Amps Total 4 |
| Capacity/Size 2 Quantity Capacity/Size 2 UOM | 4 Section(s) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1999 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| | |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Does not exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

Electrical Inspection M435 Question Response TELEPHONE SYSTEM Inspected Standard Inspected Condition 3- Fair Deficiency No deficiencies recorded TRANSFORMER Does not exist