

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

**Asset: BAYARD RUSTIN EDUCATIONAL COMP-MANHATTAN, 351 WEST 18 STREET, MANHATTAN, NY, 10011**

Inspection Id	Inspection Type	Time In	Last Edited
1637	ELECTRICAL	2023-12-07 09:03AM	2024-01-09 10:51AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	<p>Systems: Partial Molded Case Circuit Breaker Panel Board</p> <p>Years: 2023, 2018, 2014, 2011, 2000</p> <p>Systems: IPDVS/CCTV System</p> <p>Years: 2023</p> <p>Systems: East Gymnasium (Scoreboard), Service Switch, Switchboard, Grounding System</p> <p>Years: 2019</p> <p>Systems: Auditorium (LED Lighting, Fluorescent Lighting, Theater Lighting System, Projection System)</p> <p>Years: 2018</p> <p>Systems: Most Emergency Lighting (Non Battery Pack)</p> <p>Years: 2016, 2012</p> <p>Systems: Science Rooms (334, 336A, 427, 433, 434, 429/435, 436), LED Lighting (Gymnasiums, Swimming Pool, Basement - Boys Locker Room), Public Address System, Local Sound System, Intrusion Alarm System</p> <p>Years: 2016</p> <p>Systems: Partial Motor Starters, Library, 6th Floor Locker Rooms (Except Shower Rooms Fluorescent Lighting), Pendant Mounted Fluorescent Lighting (7th Floor Offices and Classrooms, 6th Floor Offices and Classrooms), Partial Surface Mounted Fluorescent Lighting (7th Floor Corridors), Recessed Mounted Fluorescent Lighting (Toilet Rooms, 7th Floor and 6th Floor Classrooms and Corridors), LED Lighting (Corridors)</p> <p>Years: 2012</p> <p>Systems: Science Demo Room 327 (Except Fluorescent Lighting)</p> <p>Years: 2010</p> <p>Systems: Telephone System, LAN</p> <p>Years: 2009</p> <p>Systems: Fire Alarm System, Lighting - Security</p> <p>Years: 2008</p> <p>Systems: Partial Fused Disconnect Switch Type Panel Board,</p> <p>Years: 2007, 2000</p> <p>Systems: Transformer</p> <p>Years: 2007</p> <p>Systems: Interior Fluorescent Lighting, Emergency Light/Exit Light Panel</p> <p>Years: 2000</p> <p>Below Ground</p>
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms 210, 310, 410, 512, 625, 703

**Priority Condition**


Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	-------------

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Yes	Emergency DC Standby Battery Power - Battery Bank Not Operational	N/A	Emergency DC Standby Battery Power	Electrical Room B20	Billy McCarthy	Fireman
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contact	7th Floor Corridors by Rooms 701, 706	Billy McCarthy	Fireman



**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 6th Floor - Students	Inspected
Instance on Room 533A - Staff	Inspected
<b>Lighting</b>	
Instance on 6th Floor - Students	Inspected
Instance on Room 533A - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 533A - Staff	Inspected
Instance on 6th Floor - Students	Inspected
<b>Pendant Mounted</b>	
Instance on Room 533A - Staff	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 6th Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 533A - Staff	Does not exist
Instance on 6th Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 533A - Staff	Does not exist
Instance on 6th Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room 533A - Staff	Does not exist
Instance on 6th Floor - Students	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 533A - Staff	Does not exist
Instance on 6th Floor - Students	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 533A - Staff	Does not exist
Instance on 6th Floor - Students	Does not exist
<b>Local Sound System</b>	
Instance on 6th Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on Room 533A - Staff	Does not exist
<b>Projection System</b>	
Instance on 6th Floor - Students	Does not exist
Instance on Room 533A - Staff	Does not exist
<b>Theater Lighting System</b>	
Instance on 6th Floor - Students	Does not exist
Instance on Room 533A - Staff	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	
Does a Chandelier Exist?	Yes
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
	Does not exist
<b>Lighting Fixture - Incandescent</b>	
	Inspected
<b>Pendant Mounted</b>	
	Does not exist
<b>Surface Mounted</b>	
	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	85
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not exist
<b>COMPUTER LAB</b>	Inspected
Instance on Rooms 204, 228	Inspected
Power Panel?	No
<b>Lighting</b>	
Instance on Rooms 204, 228	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 204, 228	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 204, 228	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Rooms 204, 228	Does not exist
<b>Recessed Mounted</b>	
Instance on Rooms 204, 228	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 204, 228	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 204, 228	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 204, 228	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Rooms 204, 228	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 7th Floor - West	Inspected
Instance on 7th Floor - East	Inspected
<b>Lighting</b>	
Instance on 7th Floor - West	Inspected
Instance on 7th Floor - East	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 7th Floor - West	Inspected
Instance on 7th Floor - East	Inspected
<b>Pendant Mounted</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>Surface Mounted</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>Recessed Mounted</b>	
Instance on 7th Floor - West	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 7th Floor - East	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 7th Floor - West	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 7th Floor - East	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>Scoreboard</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 7th Floor - West	Does not exist
Instance on 7th Floor - East	Does not exist
<b>KITCHEN</b>	
Instance on 6th Floor	Inspected
<b>Lighting</b>	
Instance on 6th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 6th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 6th Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 6th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 6th Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 6th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 6th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 6th Floor	Does not exist
<b>LIBRARY</b>	Inspected
Instance on 4th Floor	Inspected
<b>Lighting</b>	
Instance on 4th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 4th Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 4th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 4th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 4th Floor	Does not exist
<b>Raceway With Receptacles</b>	
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 4th Floor	Does not exist
<b>LOCKER ROOM</b>	Inspected
Instance on Basement - Boys	Inspected
Alternative Use	Yes
Instance on Basement - Girls	Inspected
Alternative Use	Yes
Instance on Room 606A - Girls	Inspected
Alternative Use	No

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>LOCKER ROOM</b>	
Instance on Room 621 - Boys	Inspected
Alternative Use	No
<b>Lighting</b>	
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Inspected
Instance on Room 606A - Girls	Inspected
Instance on Room 621 - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Inspected
Instance on Room 606A - Girls	Inspected
Instance on Room 621 - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 606A - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 621 - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 606A - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 621 - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Instance on Room 606A - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 621 - Boys	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Instance on Room 606A - Girls	Does not exist
Instance on Room 621 - Boys	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Boys	Does not exist



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Girls	Does not exist
Instance on Room 606A - Girls	Does not exist
Instance on Room 621 - Boys	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Does not exist
Instance on Room 606A - Girls	Does not exist
Instance on Room 621 - Boys	Does not exist
<b>Pendant Mounted</b>	
Instance on Basement - Boys	Does not exist
<b>Surface Mounted</b>	
Instance on Basement - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement - Boys	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 327	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 341	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 442	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 428	Inspected
Power Panel?	No
Alternative Use	No
<b>Lighting</b>	
Instance on Room 327	Inspected
Instance on Room 341	Inspected
Instance on Room 442	Inspected
Instance on Room 428	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 327	Inspected
Instance on Room 341	Inspected
Instance on Room 442	Inspected
Instance on Room 428	Inspected
<b>Pendant Mounted</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 442	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Room 428	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 327	Does not exist
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 327	Does not exist
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 327	Inspected
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Pendant Mounted</b>	
Instance on Room 327	Does not exist
<b>Surface Mounted</b>	
Instance on Room 327	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 327	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 327	Does not exist
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 327	Does not exist
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
Instance on Room 327	Inspected
Instance on Room 341	Inspected
Instance on Room 442	Does not exist
Instance on Room 428	Inspected
<b>Instructor Unit</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 428	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 428	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 327	Does not exist
Instance on Room 341	Does not exist
Instance on Room 442	Does not exist
Instance on Room 428	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 427	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 433	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Rooms 334, 434	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Lighting</b>	
Instance on Room 427	Inspected
Instance on Room 433	Inspected
Instance on Rooms 334, 434	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 427	Inspected
Instance on Room 433	Inspected
Instance on Rooms 334, 434	Inspected
<b>Pendant Mounted</b>	
Instance on Room 427	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 427	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Inspected
Instance on Rooms 334, 434	Inspected
<b>Pendant Mounted</b>	
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Surface Mounted</b>	
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 427	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Inspected
Instance on Rooms 334, 434	Inspected
<b>Instructor Unit</b>	
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 433	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 334, 434	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>Projection System</b>	
Instance on Room 427	Does not exist
Instance on Room 433	Does not exist
Instance on Rooms 334, 434	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 336A	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 343	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 429/435	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Room 436	Inspected
Power Panel?	No

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
Alternative Use	Yes
<b>Lighting</b>	
Instance on Room 336A	Inspected
Instance on Room 343	Inspected
Instance on Room 429/435	Inspected
Instance on Room 436	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 336A	Inspected
Instance on Room 343	Inspected
Instance on Room 429/435	Inspected
Instance on Room 436	Inspected
<b>Pendant Mounted</b>	
Instance on Room 336A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 343	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 429/435	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 436	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 336A	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Deficiency	No deficiencies recorded
Instance on Room 343	Does not exist
Instance on Room 429/435	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 436	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 336A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 343	Does not exist
Instance on Room 429/435	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 436	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 336A	Does not exist
Instance on Room 343	Does not exist
Instance on Room 429/435	Does not exist
Instance on Room 436	Does not exist
<b>SWIMMING POOL</b>	
Instance on Basement	Inspected
<b>Lighting</b>	
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Surface Mounted</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement	Does not exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	
Instance on Basement	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Inspected
Condition	5- Poor
Deficiency	BATTERY BANK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room B20
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Staircases (D/7, E/7, E/4, B/3, F/2, D at Exit 4)
Deficiency Quantity	6
Quantity Uom	EACH



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Non Battery Pack</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Basement - Locker Room Boys
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Non Battery Pack</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Staff Cafeteria Room 533A, 8th Floor - Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	5th Floor by Staircase B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>EXIT/EMERGENCY LIGHT</b>	
Does not exist	
<b>FIRE ALARM SYSTEM</b>	
<b>Bell/Horn</b>	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not exist
<b>Heat Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	7th Floor Corridors by Rooms 701, 706
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	MDF Room 108A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Honeywell
EquipmentId	N/A
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Alarm Control Panel
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Sub-Panel</b>	Does not exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Remote Annunciator</b>	
<b>Panel</b>	
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms (Basement (B10, B25)), 4th Floor, 8th Floor), By Rooms (318, 409A), By Basement - Elevator Equipment Room
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>PANEL BOARD</b>	
<b>Fused Toggle Switch Type</b>	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Molded Case Circuit Breaker Type</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Basement by Elevator Equipment Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (B16, 109, 136, 138, 305, 338A, 416, 712), By Mechanical Room B10, By Electrical Room B20
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridors By Rooms (109, 205)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	
Instance	Inspected
Instance Condition	Room 126B
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Model	EACH
Installation Year	Dukane 250
Source of Installation Year	2016
Deficiency	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Condition	Inspected
Installation Year	1- Good
Source of Installation Year	2023
Deficiency	Custodial Staff
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance	Inspected
Instance Condition	Inspected
Instance	Custodian's Office - Room 132
Instance Condition	2- Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 250BP
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inaccessible
<b>SERVICE SWITCH</b>	
Instance	Electrical Room B20
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Distribution Service Switch
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B20
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Main Service Switch
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	12
<b>Fused Disconnect Switch Type</b>	
Instance	Electrical Room B20
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**M440**

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	7
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	TELEPHONE NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Auditorium - Stage
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Standard</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
Instance	Inspected
Instance	8th Floor North Elevator Machine Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	4
Capacity/Size Quantity	63
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	8th Floor North Machine Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	3
Capacity/Size Quantity	63
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	8th Floor South Elevator Machine Room
Instance Condition	2- Between Good and Fair
Instance Quantity	2

NYC Department of Education  
Building Condition Assessment Survey 2023-2024

*Electrical Inspection*

M440

Question	Response
<b>TRANSFORMER</b>	
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	N/A
Capacity/Size Quantity	63
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded