Building Condition Assessment Survey 2023-2024

Architectural Inspection M444

Asset:	DISTRICT 2 PRE-K CENTER @ 606 WEST 57TH STREET - MANHATTAN, 606 WEST 57TH STREET,
	MANHATTAN NV 10010

Inspection Id	Inspection Type	Time In	Last Edited
743	ARCHITECTURAL - ASSOCIATE	2023-11-06 11:52AM	2023-11-06 02:57PM
780	ARCHITECTURAL - SENIOR	2023-11-06 11:59AM	2024-06-12 10:16AM

Asset Data

Weather

Facade Photo

sci Duiu		
Question		Answer
Was the Building Fully Acces	ssible for Inspection?	Yes
Principal(s) Information		
	Principal Name	Aisha Thurman Cosby
	Principal Organization	District 2 Pre- K Center @ 606 West 57th Street Manhattan
	Meeting with Principal?	Yes
	Principal Feedback	The Principal had no comments about the condition of the
		building at this time.
Custodian		Michael Pagliaro
Was the Custodian Present?		Yes
Fireman		N/A
Was the Fireman Present?		Yes
Building Square Footage		10,000
Comments on the Area (for A	Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Flo	oors) plus Basements	1 (No Basement)
Comments on the Year Built		2019
Student Population		59
Staff Population		15
Comments on the Number of	Classrooms	4



West 57th Street - South View

Fair

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Main Entrance Photo

IT SIGHTS

A SIGHTS

B SO DA

M444

Facade A - West 58th Street

Not taken

No

No Storm Water Management Type Selected

No System Upgraded

No New Construction

No Tandem

Yes

2019

Inspection Type

Year Leased

Leased Space?

Roof Photo

Tandem

Partial Inspection

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image

No condition recorded

Structural Engineer Required

Do Stormwater Management/Green Infrastructure systems exist?

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Type

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image

No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the Primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	No
Do any of the following spaces exist? Classroom, Art Room, Auditorium, Cafeteria,	Yes
Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	
For the spaces that do exist, are they ALL accessible?	Yes
Is there at least one Boys and Girls or Unisex toilet accessible In the building?	Yes

Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
PROGRAMMATIC ACCESSIBILITY						
Exterior Routes						
Exterior Entrances & Exits		Yes				
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	No		No			
Interior Routes						
Corridor and Lobby H/C Lifts	No		No			
Interior Corridor Doors And	Yes	Yes				
Hardware						
Interior Corridors & Lobbies		Yes				

Building Condition Assessment Survey 2023-2024

M444

Architectural Inspection

					Assistive	Fire
ysical Breakdown Structure	Exists	Complies	Required	Deficiency	Listening	Alarn
Interior Elevators	No				System	Strob
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	Yes	Yes				
Rooms & Spaces						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms						
1st Floor	Yes	Yes				
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office						
Room 106	Yes	Yes				
Multi-purpose Room	No					
Nurse's Office						
Room 117	Yes	Yes				
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
Room 117	Yes	Yes				
Toilet Rooms (girls)						
Room 117	Yes	Yes				
Toilet Rooms (staff)						
Room 121	Yes	Yes				

Building Template



Inspection	
Question	Response
Architectural	
EXTERIOR	Inspected

Building Condition Assessment Survey 2023-2024

Architectural Inspection M444

estion	Response
EXTERIOR	
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Does not exist
CHIMNEY	Does not exist
COPING	Does not exist
CORNICE	Does not exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DOOR HARDWARE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	5,700
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	5,700
Instance Quantity Uom	S.F.
Deficiency	METAL/GLASS CURT WALL:BROKEN GLASS

Roof Plan Reference



Elevation



Elevation Reference Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo 1

Facade A 30 S.F. REPLACE PRIORITY 5

LEVEL 2



Building Condition Assessment Survey 2023-2024

Room 112 No photo recorded No violations recorded Does not exist Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Does not exist Inspected Linspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
No photo recorded No violations recorded Does not exist Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Does not exist Inspected Linspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
No photo recorded No violations recorded Does not exist Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Does not exist Inspected Linspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
No violations recorded Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Linspected Li
No violations recorded Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Linspected Li
Does not exist Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Inspected Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Not required Does not exist Not required Does not exist Not required Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Not required Does not exist Not required Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Not required Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Not required Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Does not exist Inspected Does not exist Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Inspected Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded
Inspected 2- Between Good and Fair No deficiencies recorded
2- Between Good and Fair No deficiencies recorded
No deficiencies recorded
Not required
Not required
Does not exist
Does not exist
Does not exist
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Does not exist
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
T 1
Inspected
1- Good
No deficiencies recorded

Building Condition Assessment Survey 2023-2024

uestion	Response	
INTERIOR	•	
KITCHEN		
Door(s)		
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Floor Finish		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Walls		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTI-PURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SHOWER ROOM	Does not exist	
STAIRS/RAMPS: INTERIOR	Does not exist	
TOILET ROOMS - STAFF	Inspected	
Ceiling	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Stalls	Does not exist	
Walls	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOMS - STUDENTS	Inspected	
Ceiling	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Door(s)		
Floor Finish	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Stalls	Does not exist	
Walls	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIFE SAFETY	Inspected	
F.D. HOLDING AREA	Does not exist	
STEEL STAIRS	Does not exist	
SITE	Inspected	
CONTAINERIZATION	Does not exist	
DRAINAGE SYSTEM FOR ASPHALT	Does not exist	

Building Condition Assessment Survey 2023-2024

Architectural Inspection M444

uestion	Response
SITE	
DRAINAGE SYSTEM FOR SOIL	Does not exist
DRINKING FOUNTAINS	Does not exist
FENCES	Does not exist
IRRIGATION SYSTEM	Does not exist
PAVING	Inspected
Student Non-Use	Does not exist
Student Use	Does not exist
Site Sidewalks & Walkways	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Does not exist
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection M444

Does the SCA expect asset to have artwork?

No