Building Condition Assessment Survey 2023-2024

Electrical Ins	spection						M 4
Asset:	DISTRICT 2 P. MANHATTAN	RE-K CENTER @ 606 WES I, NY, 10019	Г 57TH STREE	T - MANHATTA	N, 606 WES	T 57TH STRE	CET,
Inspection I	d Inspection Type				Time	In	Last Edited
7-	40 ELECTRICAL				2023-	11-06 11:58AM	2023-11-28 04:03PM
Asset Data							
Question				Answer			
Have any Sy	stems/Major Building	Components been upgraded?		Systems:	All Electrical	Systems and Cor	mponents
	, ,			Years:	2019		
Type of Serv	vice			Below Gro	und		
	tive Whiteboard (IWE			Yes			
	ration In Electrical Ro			No			
	ED INTERCOMS	IN FIRE RESCUE AREAS					
Question Are there	any Life Rescue Assist	tance Areas, Fire Rescue Areas, an	d/or Holding Root		esponse		
your build		unice rifeus, rife reseue rifeus, un	a of Holding Root	113 111	O		
Priority Cond	lition						
	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
	Category	Description	Affected	Description	Notified	Title	Image
	ire Alarm System - Defective	N/A	Fire Alarm System	Main Entrance Lobby	Yandeen Burghur	Cleaner	No Photo Taken
Inspection			-	-			
Question				Response			
Electrical				*			
ATHLET	IC FIELD			Does not e	xist		
AUDITO				Does not e			
CAFETE			Does not exist				
		DMINIOTD ATIME OD A CE			VIST		
		ADMINISTRATIVE SPACE		Inspected			
Lighting Does a	Chandelier Exist?		Inspected No				
	ng Fixture - Fluoresc	ent	Does not exist				
	ng Fixture - HID			Does not e	xist		
	ng Fixture - Incandes	scent		Does not e	xist		
Lighti	ng Fixture - LED		Inspected				
Pend	lant Mounted		Inspected				
Co	ndition			2- Between	Good and Fai	r	
	Deficiency			No deficie	ncies recorded		
Surf	ace Mounted		Inspected				
Co	ndition		2- Between Good and Fair				
	Deficiency		No deficiencies recorded				
-	essed Mounted		Inspected				
Со	ndition		2- Between Good and Fair				
	Deficiency				ncies recorded		
COMPUT	TER LAB			Does not e	xist		
GYMNASIUM				Does not e	xist		
KITCHEN				Inspected			
	Instance on 1st Floor			Inspected			
Lighting							
	Instance on 1st Floor			Inspected			
Lighti	ng Fixture - Fluoresc				• .		
	Instance on 1st Floor			Does not e	xıst		
Lighti	ng Fixture - HID			D			
***	Instance on 1st Floor			Does not e	xist		
Lighti	ng Fixture - Incandes			Dagened	vict		
	Instance on 1st Floor			Does not e	vist		

Building Condition Assessment Survey 2023-2024

неш інгресион		W144 ²
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
TOILET ROOM - STAFF	Inspected	
Lighting Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Healitescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL		
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected 1- Good	
Condition	No deficiencies recorded	
Deficiency	ino deficiencies recorded	

Building Condition Assessment Survey 2023-2024

uestion	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Honeywell
Model	E3 Series
EquipmentId	Fire Alarm Control Panel with D.A.C.T
Installation Year	2019
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

Building Condition Assessment Survey 2023-2024

icui inspection		
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Does not exist	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Telecom Room 109	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Model		
Model Installation Year	Bogen Multicom - 2000 2019	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M444

election (vestion)	Response	14144
	<u> </u>	
SECURITY	Inspected	
IPDVS/CCTV System Condition	Inspected 2- Between Good and Fair	
Installation Year	2- Between Good and Pan 2019	
Source of Installation Year	Documented Documented	
Deficiency	No deficiencies recorded	
	Inspected	
Intrusion Alarm System Central Control Panel	Inspected	
	Custodian's Office - Room 119	
Instance		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Remote Annunciator		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Does not exist	
SERVICE SWITCH	Inspected	
Instance	Electrical Room 102	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
	MDB	
EquipmentId Capacity/Size Quantity	600	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD Number of Sugges	Inspected 2	
Number of Spares	Inspected	
Fused Disconnect Switch Type		
Instance	Electrical Room 102	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	MDB	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	

Building Condition Assessment Survey 2023-2024

Question	Response	·
SWITCHBOARD		
Fused Disconnect Switch Type		
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	