Building Condition Assessment Survey 2023-2024

| | GEORGE WASI | HINGTON HS AF - MANH | ATTAN, 549 AU | DUBON AVEN | UE, MANHA | TTAN, NY, 1 | 0040 |
|--|--|-------------------------------------|--------------------------|-------------------------------|--|-----------------------------------|-----------------------|
| Inspectio | n Id Inspection Type | | | | Time | In | Last Edited |
| | 1789 ELECTRICAL | | | | 2023- | -12-18 09:27A | M 2023-12-20 11:14AN |
| Asset Data | ! | | | | | | |
| Question | 1 | | | Answer | | | |
| Have any | Systems/Major Building C | Components been upgraded? | | Systems: | Athletic Field | (Exterior Ligh | ting) |
| | | | | Years: | 2023 | | |
| | | | | Systems: | Lighting - Sec | curity | |
| | | | | Years: | 2017 | | |
| | | | | Systems: | | escent Lighting er Panel Board | , Partial Molded Case |
| | | | | Years: | 2016 | | |
| Type of S | Service | | | Below Gr | round | | |
| Does Inte | eractive Whiteboard (IWB) | Exist? | | Yes | | | |
| Water Pe | netration In Electrical Roor | n? | | No | | | |
| DEDIC | ATED INTERCOMS II | N FIRE RESCUE AREAS | | | | | |
| | | nce Areas, Fire Rescue Areas, an | nd/or Holding Roon | | Response No | | |
| riority Co | | | | | | | |
| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
| Yes | Exit/Emergency Light - Not Operational | 5 of 7 units are Not Operational | Exit/Emergenc y Light | Field House | Anthony Ortiz | Custodian | No Photo Taken |
| Inspection | | • | , , | | | | |
| Question | | | | Response | 2 | | |
| Electrica | | | | F | | | |
| | ETIC FIELD | | | Inspected | <u> </u> | | |
| | rior Lighting | | | Inspected | | | |
| | ndition | | | 1- Good | | | |
| | Deficiency | | | No defici | encies recorded | | |
| Loca | l Sound System | | | Inspected | | | |
| | ndition | | | 5- Poor | <u>- </u> | | |
| | Installation Year | | | 1980 | | | |
| Source of Installation Year Deficiency | | | | Inspector | Estimate | | |
| | | | | AMPLIF | IER NOT OPER | RATIONAL | |
| | Deficiency Quantity | | | 1 | | | |
| | Quantity Uom | | | EACH | | | |
| Potential Action | | | REPLACE SYSTEM | | | | |
| | Urgency of Action | | | PRIORIT | | | |
| | Purpose of Action | | | LEVEL 2 | | | |
| | Violations | | | | ions recorded | | |
| | | | | Inspected | | · E | |
| Score | Instance | | | 5- Poor | Main Asset M46 | 13 | |
| Score | Instance Condition | | | | | | |
| Score | Instance Condition | _ | | 1 | | | |
| Score | Instance Quantity | | | EVCH | | | |
| Score | Instance Quantity Instance Quantity Uom | ı | | EACH | ED ATTION : Y | | |
| Score | Instance Quantity Instance Quantity Uom Deficiency | | | NOT OP | ERATIONAL | | |
| Score | Instance Quantity Instance Quantity Uom Deficiency Deficiency Quantity | | | NOT OP | ERATIONAL | | |
| Score | Instance Quantity Instance Quantity Uom Deficiency Deficiency Quantity Quantity Uom | | | NOT OP | | | |
| Score | Instance Quantity Instance Quantity Uom Deficiency Deficiency Quantity Quantity Uom Potential Action | | | NOT OP 1 EACH REPLAC | E | | |
| Score | Instance Quantity Instance Quantity Uom Deficiency Deficiency Quantity Quantity Uom | | | NOT OP | EE Y 3 | | |

Does not exist

AUDITORIUM

Building Condition Assessment Survey 2023-2024

Electrical Inspection M466

| ctrical Inspection | | N1466 |
|---|-------------------------------------|-------|
| Question | Response | |
| CAFETERIA | Does not exist | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected | |
| Lighting | Inspected | |
| Does a Chandelier Exist? | No | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| COMPUTER LAB | Does not exist | |
| GYMNASIUM | Does not exist | |
| KITCHEN | Does not exist | |
| LIBRARY | Does not exist | |
| | | |
| LOCKER ROOM | Inspected | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Inspected | |
| Alternative Use | No | |
| Lighting | Y 1 | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Inspected | |
| Lighting Fixture - Fluorescent | Yourselved | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Inspected | |
| Pendant Mounted | Description of the second | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Does not exist | |
| Surface Mounted | Y 1 | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Inspected 2- Between Good and Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on 1st Floor - Girls, 1st Floor - Boys | Does not exist | |
| MULTIPURPOSE ROOM | Does not exist | |
| SCIENCE DEMO ROOM | Does not exist | |
| SCIENCE LAB | Does not exist | |
| SCIENCE PREP ROOM | Does not exist | |
| SWIMMING POOL | Does not exist | |
| TOILET ROOM - STAFF | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Does not exist | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Condition | | |

Building Condition Assessment Survey 2023-2024

| Question | Response | |
|---|-------------------------------------|--|
| TOILET ROOM - STAFF | * | |
| Lighting | | |
| Lighting Fixture - Fluorescent | | |
| Surface Mounted | | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not exist | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| TOILET ROOM - STUDENT | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Does not exist | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not exist | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| AUXILIARY SIGNAL/BELL SYSTEM | Does not exist | |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist | |
| EMERGENCY GENERATOR SET | Does not exist | |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not exist | |
| EMERGENCY LIGHTING | Does not exist | |
| | Does not exist | |
| EXIT LIGHT | | |
| EXIT/EMERGENCY LIGHT | Inspected 4- Between Fair and Poor | |
| Condition | | |
| Deficiency Deficiency Location/Instance | FIXTURE NOT OPERATIONAL Field House | |
| Deficiency Quantity | 5 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 5 | |
| Purpose of Action | LEVEL 6 | |
| Violations | No violations recorded | |
| FIRE ALARM SYSTEM | Does not exist | |
| GROUNDING SYSTEM | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| INTERCOM SYSTEM | Does not exist | |
| LAN | Does not exist | |
| | | |
| LIGHTNING PROTECTION | Does not exist | |
| MOTOR CONTROLLER | Inspected | |
| MOTOR CONTROL CENTER | Does not exist | |
| MOTOR STARTER/CONTACTOR | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Variable Frequency Drive | Does not exist | |
| PANEL BOARD | Inspected | |
| Fused Disconnect Switch Type | Does not exist | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection M466

| uestion | Response |
|----------------------------------|--------------------------------|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Mechanical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | Under construction |
| SECURITY | Inspected |
| IPDVS/CCTV System | Does not exist |
| Intrusion Alarm System | Does not exist |
| Lighting - Security | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Inspected |
| Instance | Mechanical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Federal Pacific Electric |
| EquipmentId | Service Switch |
| Capacity/Size Quantity | 200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1979 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Mechanical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SWITCHBOARD | Does not exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Does not exist |
| Standard | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not exist |