#### **Building Condition Assessment Survey 2023-2024**

Asset:	PRE-K CEN	TER @ 252 EAST 57 STREET -	MANHATTA	N, 252 EAST 57	STREET, M	ANHATTAN	, NY, 10022
Inspectio	on Id Inspection Typ	pe			Time	In	Last Edited
	697 MECHANICA	L			2023	-11-03 12:45P	M 2023-12-15 02:33PM
Asset Data	ı						
Question	1			Answer			
Have any	y Systems/Major Buildi	ing Components been upgraded?		No Syster	n Upgraded		
Are there	e fuel tanks?			No			
Total # o	of water main service er	ntries to the asset		0			
MERs/Fa	an Rooms Locations			MERs 20	6, 223		
Are there	e any spaces with Missi	ing or Defective CO Detectors?		No			
	e any Painted/Obstructe			Yes			
Location	n(s)			Electrical	Room 200, ME	ER 223 (obstruc	eted, 5)
Are there	e any Emergency Stop S	Switches with Missing Hammers?		No compo	onents		
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	ition recorded						
Inspection	n						
Question				Response	<u> </u>		
Mechani	ical						
AIR C	CONDITIONING			Inspected			
Chill	led Water System			Does not	exist		
		tion: Piping, Pumps and Auxiliaries		Inspected			
	ndition			1- Good			
	Deficiency			No defici	encies recorded		
Cool	ing Coil in Ductwork			Does not	exist		
	ling Tower			Does not	exist		
	Split System			Does not	exist		
	Cooler			Does not	exist		
Pack	aged / Rooftop Unit			Inspected			
	Instance			MER 223	i		
	Instance Condition	1		1- Good			
	Instance Quantity			1			
	Instance Quantity	Uom		EACH			
	Manufacturer			AAON			
	EquipmentId			AC-1			
	Capacity/Size Qua			30			
	Capacity/Size UO			Tons			
	Source of Capacity	y/Size		Documen	ted		
	Installation Year			2018			
	Source of Installat			Documen			
	Source of Heating			Hydronic			
	Refrigerant Type			R-410A			
	Deficiency				encies recorded		
	Instance			MER 206	1		
	T ( C 1'''						

1- Good

EACH

AAON

AC-2

Tons

Documented 2018

Documented

30

Instance Condition

Instance Quantity Uom

Capacity/Size UOM

Installation Year

Source of Capacity/Size

Source of Installation Year

Instance Quantity

Manufacturer

EquipmentId Capacity/Size Quantity

### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	M474
0 4	n.

nestion	Response		
AIR CONDITIONING			
Packaged / Rooftop Unit			
Source of Heating	Hydronic		
Refrigerant Type	R-410A		
Deficiency	No deficiencies recorded		
Instance	First Floor Lobby (Ceiling Mounted)		
Instance Condition	1- Good		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Thermoplus Air		
EquipmentId	AC-3		
Capacity/Size Quantity	3		
Capacity/Size UOM	Tons		
Source of Capacity/Size	Custodial Staff		
Installation Year	2018		
Source of Installation Year	Documented		
Source of Heating	Hydronic		
Refrigerant Type	N/A		
Deficiency	No deficiencies recorded		
Packaged Terminal A/C	Does not exist		
Refrigerant Leak Detection System	Does not exist  Does not exist		
Refrigerant Piping Return Fan	Inspected		
Condition	1- Good		
	No deficiencies recorded		
Deficiency			
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist		
CLIMATE CONTROL SYSTEM	Inspected		
BMS	Inspected		
Instance	Throughout		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Building Area Covered by Operational System	81-100%		
Installation Year	2018		
Source of Installation Year	Documented		
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT		
Deficiency Location/Instance	Rooms 218, 219		
Deficiency Quantity	2		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Pneumatic System	Does not exist		
Hybrid System	Does not exist		
Electric System	Does not exist		
COMPACTOR	Does not exist		
CONVEYING	Inspected		
UNVETING	Does not exist		
Dumbwaiter			
	Inspected		
Dumbwaiter Elevator Condition			
Dumbwaiter Elevator	Inspected		
Dumbwaiter Elevator Condition	Inspected 1- Good		

### **Building Condition Assessment Survey 2023-2024**

1914 /
Response
Does not exist
Does not exist
Does not exist
Inspected
Does not exist
Inspected
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
1- Good
No deficiencies recorded
Inspected
Does not exist
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
1- Good
DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Corridor near Rooms 206, 221
2
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded

### **Building Condition Assessment Survey 2023-2024**

Question	Response	
FIXTURES	response	
Student  Lavatory/Sink		
Deficiency	CLOGGED/LEAKING	
Deficiency Location/Instance	Room 207	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on Room 208	Inspected	
CO Detector		
Instance on Room 208	Not required	
Gas System		
Instance on Room 208	Does not exist	
Grease Trap		
Instance on Room 208	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on Room 208	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 208	Does not exist	
Hood Exhaust Fan		
Instance on Room 208	Does not exist	
Hood Fire Suppression System		

### **Building Condition Assessment Survey 2023-2024**

Question	Response
KITCHEN	response
Hood Fire Suppression System Instance on Room 208	Does not exist
Hot Water Temperature Booster	DOGS HOT CAIST
Instance on Room 208	Does not exist
Kitchen Sink	Does not exist
Instance on Room 208	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
MDF Room	Inspected
	•
Instance on Room 201	Inspected
Dedicated A/C Equipment  Instance on Room 201	Inspected
	3- Fair
Instance Condition	DEFECTIVE
Deficiency Location/Instance	Room 201
Deficiency Location/Instance Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
SCIENCE DEMO ROOM	
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Electrical Room 200, MER 223 (obstructed, 5)
Deficiency Quantity	5
Quantity Uom	EACH DEDLAGE
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 5 LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected 1- Good
Condition	No deficiencies recorded
Deficiency	
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
<u> </u>	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
VENTILATION		
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	