Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	HEALTH PROFESSIONS HS (OL STY) - MANHATTAN, 345 EAST 15 STREET, MANHATTAN, NY, 10003			
Inspection Id	Inspection Type	Time In	Last Edited	
745	ELECTRICAL	2023-11-02 08:54AM	2023-11-22 02:42PM	
sset Data				
Question		Answer		

Answer	
	g
Systems: Computer Lab - Room 418B	
Years: 2019	
(Theater Lighting System, Projection System, Loca Sound System), Exit Lights (Battery Pack)	
Systems: Computer Lab - Room 520A (Raceway With Receptacles)	
Years: 2014	
Systems: Intercom System (Elevator)	
Years: 2012	
Systems: Auditorium (LED Lighting), IPDVS/CCTV System	n
Years: 2010	
Systems: Most Molded Case Circuit Breaker Panel Board	
Years: 2008, 2000, 1990	
Systems: Service Switch, Switchboard, Intrusion Alarm Syst	em
Years: 2008	
Systems: Interior Lighting	
Years: 2004	
Systems: Emergency Light/Exit Light Panel	
Years: 1995	
Below Ground	
Yes	
No	
Response	
	Systems:LAN, Lighting - Security, Retrofitted LED Lightin (Stairways and Hallways)Years:2023Systems:Variable Frequency DriveYears:2021Systems:LED LightingYears:2019, 2015Systems:Computer Lab - Room 418BYears:2019Systems:Basement Gymnasium (LED Lighting), Auditoriur (Theater Lighting System, Projection System, Loca Sound System), Exit Lights (Battery Pack)Years:2015Systems:Computer Lab - Room 520A (Raceway With

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in No your building?

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Leaks onto Electrical Equipment	Steam Piping Leak affecting Motor Starter, Variable Frequency Drive in Girls Locker Room Mechanical Room, a Lighting Fixture in Girls Shower Room, two Motor Starters and a Safety Switch in Steam Vault inside Steam Room)	Motor Starters, Variable Frequency Drive, Lighting Fixture, Safety Switch	Basement (Girls Locker Room Mechanical Room, Girls Shower Room, Steam Vault inside Steam Room)	Jose Taveras	Handyman	
Inspection	ı						
Question	I			Response			
Electrica	1						
ATHL	ETIC FIELD			Does not e	xist		

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Response

Electrical Inspection

Question

it stion	Kesponse
AUDITORIUM	Inspected
Instance on Basement	Inspected
House Lighting	1
Instance on Basement	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	1
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	Does not exist
Instance on Basement	Does not exist
	Does not exist
Lighting Fixture - Incandescent	Does not exist
Instance on Basement	Does not exist
Lighting Fixture - LED	· · · · ·
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 2nd Floor - East Instance on 2nd Floor - West	Inspected

Building Condition Assessment Survey 2023-2024

stion	Response	
AFETERIA		
Lighting		
Instance on 2nd Floor - East	Inspected	
Instance on 2nd Floor - West	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor - East	Inspected	
Instance on 2nd Floor - West	Inspected	
Pendant Mounted		
Instance on 2nd Floor - East	Does not exist	
Instance on 2nd Floor - West	Does not exist	
Surface Mounted		
Instance on 2nd Floor - East	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor - West	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor - East	Does not exist	
Instance on 2nd Floor - West	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor - East	Does not exist	
Instance on 2nd Floor - West	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor - East	Does not exist	
Instance on 2nd Floor - West	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor - East	Does not exist	
Instance on 2nd Floor - West	Does not exist	
Local Sound System		
Instance on 2nd Floor - East	Inspected	
Instance Condition	5- Poor	
Installation Year	1970	
Source of Installation Year	Inspector Estimate	
Deficiency Deficiency Quantity	AMPLIFIER NOT OPERATIONAL 1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on 2nd Floor - West	Inspected	
Instance Condition	5- Poor	
Installation Year	1970	
Source of Installation Year	Inspector Estimate	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 2nd Floor - East	Does not exist	

Building Condition Assessment Survey 2023-2024

uestion	Response
CAFETERIA	
Theater Lighting System	
Instance on 2nd Floor - East	Does not exist
Instance on 2nd Floor - West	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
COMPUTER LAB	Inspected
Instance on Room 305	Inaccessible
Instance on Room 418B	Inspected
Power Panel?	No
Instance on Room 520A	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 418B	Inspected
Instance on Room 520A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 418B	Does not exist
Instance on Room 520A	Inspected
Pendant Mounted	
Instance on Room 520A	Inspected
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	IVI
lestion	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 520A	Does not exist
Recessed Mounted	
Instance on Room 520A	Does not exist
Lighting Fixture - HID	
Instance on Room 418B	Does not exist
Instance on Room 520A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 418B	Does not exist
Instance on Room 520A	Does not exist
Lighting Fixture - LED	
Instance on Room 418B	Inspected
Instance on Room 520A	Does not exist
Pendant Mounted	
Instance on Room 418B	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 418B	Does not exist
Recessed Mounted	
Instance on Room 418B	Does not exist
Raceway With Receptacles	
Instance on Room 418B	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 520A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Instance on Basement	Inspected
Lighting	
Instance on 1st Floor	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Instance on Basement	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Instance on Basement	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	

Building Condition Assessment Survey 2023-2024

estion	Response	
YMNASIUM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on 1st Floor	Does not exist	
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Installation Year	1979	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1 EACH	
Quantity Uom Potential Action	EACH REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Instance on Basement	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
Instance on Basement	Does not exist	
ITCHEN	Inspected	
Instance on 2nd Floor	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
KITCHEN	Корона	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 2nd Floor	Inspected	
Pendant Mounted	inspected	
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recolded	
Instance on 2nd Floor	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent Instance on 2nd Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on 2nd Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 300	Inspected	
Lighting		
Instance on Room 300	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 300	Inspected	
Pendant Mounted		
Instance on Room 300	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 300	Does not exist	
Recessed Mounted		
Instance on Room 300	Does not exist	
Lighting Fixture - HID		
Instance on Room 300	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 300	Does not exist	
Lighting Fixture - LED		
Instance on Room 300	Does not exist	
Raceway With Receptacles		
Instance on Room 300	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 300	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys	Inspected	
Alternative Use	No	
Instance on Basement - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on Basement - Boys	Inspected	
Instance on Basement - Girls	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Inspected
Pendant Mounted	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - HID	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - LED	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
	Does not exist
MULTIPURPOSE ROOM	
SCIENCE DEMO ROOM	Inspected
Instance on Room 207	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 507	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 508	Inspected
Power Panel?	No
Alternative Use	No
Instance on Rooms 213, 214, 314, 407	Inspected
Instance on Rooms 213, 214, 314, 407	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui Inspection	1414
estion	Response
CIENCE DEMO ROOM	
Alternative Use	No
Instance on Rooms 307, 313	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	10
Instance on Room 207	Inspected
Instance on Room 507	Inspected
Instance on Room 508	Inspected
Instance on Rooms 213, 214, 314, 407	Inspected
Instance on Rooms 307, 313	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 207	Inspected
Instance on Room 507	Inspected
Instance on Room 508	Inspected
Instance on Rooms 213, 214, 314, 407	Inspected
Instance on Rooms 213, 214, 514, 407	Inspected
Pendant Mounted	Inspected
Instance on Room 207	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency Instance on Room 507	
	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Instance on Room 508	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 213, 214, 314, 407	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 307, 313	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 207	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 507	Does not exist
Instance on Room 508	Does not exist
Instance on Rooms 213, 214, 314, 407	Does not exist
Instance on Rooms 307, 313	Does not exist
Recessed Mounted	
Instance on Room 207	Does not exist
Instance on Room 507	Does not exist
Instance on Room 508	Does not exist
Instance on Rooms 213, 214, 314, 407	Does not exist
Instance on Rooms 307, 313	Does not exist
Lighting Fixture - HID	
Instance on Room 207	Does not exist
Instance on Room 507	Does not exist
Instance on Room 508	Does not exist
Instance on Room 508	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui Inspection		1717/
estion	Response	
CIENCE DEMO ROOM		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 207	Inspected	
Instance on Room 507	Does not exist	
Instance on Room 508	Does not exist	
Instance on Rooms 213, 214, 314, 407	Inspected	
Instance on Rooms 307, 313	Inspected	
Pendant Mounted		
Instance on Room 207	Does not exist	
Instance on Rooms 213, 214, 314, 407	Does not exist	
Instance on Rooms 307, 313	Does not exist	
Surface Mounted		
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 213, 214, 314, 407	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 307, 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 207	Does not exist	
Instance on Rooms 213, 214, 314, 407	Does not exist	
Instance on Rooms 307, 313	Does not exist	
Lighting Fixture - LED		
Instance on Room 207	Does not exist	
Instance on Room 507	Does not exist	
Instance on Room 508	Does not exist	
Instance on Rooms 213, 214, 314, 407	Does not exist	
Instance on Rooms 307, 313	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 507	Does not exist	
Instance on Room 508	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 213, 214, 314, 407	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 307, 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	-	
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 507	Does not exist	
Instance on Room 508	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Response
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected 3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
Yes
No
Inspected
Yes
No
Inspected Yes

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

cal Inspection	M4
stion	Response
CIENCE LAB	
Instance on Rooms 309, 315	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 110	Inspected
Instance on Room 112	Inspected
Instance on Room 521	Inspected
Instance on Rooms 309, 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 110	Inspected
Instance on Room 112	Inspected
Instance on Room 521	Inspected
Instance on Rooms 309, 315	Inspected
Pendant Mounted	^
Instance on Room 110	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 521	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 309, 315	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 110	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Does not exist
Instance on Room 521	Does not exist
Instance on Rooms 309, 315	Does not exist
Recessed Mounted	
Instance on Room 110	Does not exist
Instance on Room 112	Does not exist
Instance on Room 521	Does not exist
Instance on Rooms 309, 315	Does not exist
Lighting Fixture - HID	
Instance on Room 110	Does not exist
Instance on Room 112	Does not exist
Instance on Room 521	Does not exist
Instance on Rooms 309, 315	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 110	Inspected
Instance on Room 112	Inspected
Instance on Room 521	Does not exist
Instance on Rooms 309, 315	Inspected
Pendant Mounted	
Instance on Room 110	Does not exist
Instance on Room 112	Does not exist
Instance on Rooms 309, 315	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		1914
estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Surface Mounted		
Instance on Room 110	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 110	Does not exist	
Instance on Room 112	Does not exist	
Instance on Rooms 309, 315	Does not exist	
Lighting Fixture - LED		
Instance on Room 110	Does not exist	
Instance on Room 112	Does not exist	
Instance on Room 521	Does not exist	
Instance on Rooms 309, 315	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 110	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 110	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply Instance on Room 110	Inspected	
Instance on Room 112	Inspected	
Instance on Room 521	Inspected	
Instance on Rooms 309, 315	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		1014
estion	Response	
CIENCE LAB		
Power Supply		
Instructor Unit		
Instance on Room 110	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 110	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 110	Does not exist	
Instance on Room 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 309, 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficicités recorded	
Projection System Instance on Room 110	Does not exist	
Instance on Room 112	Does not exist	
Instance on Room 521	Does not exist	
	Does not exist	
Instance on Rooms 309, 315		
CIENCE PREP ROOM	Inspected	
Instance on Room 112A/B	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 213A	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 315B	Inspected	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

ai insp		
stion		Response
CIENCE	PREP ROOM	
	Alternative Use	No
	Instance on Room 521B	Inspected
	Power Panel?	No
-	Alternative Use	No
ighting		
	Instance on Room 112A/B	Inspected
-	Instance on Room 213A	Inspected
	Instance on Room 315B	Inspected
-	Instance on Room 521B	Inspected
Lightin	g Fixture - Fluorescent	A
	Instance on Room 112A/B	Inspected
	Instance on Room 213A	Inspected
	Instance on Room 315B	Inspected
	Instance on Room 521B	Inspected
	ant Mounted	
	Instance on Room 112A/B	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 213A	Does not exist
	Instance on Room 315B	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 521B	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
		No deficiencies recorded
	ce Mounted	Y , 1
	Instance on Room 112A/B	Inspected 3- Fair
	Instance Condition	
	Deficiency	No deficiencies recorded
	Instance on Room 213A	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 315B	Does not exist
	Instance on Room 521B	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	sed Mounted	
	Instance on Room 112A/B	Does not exist
	Instance on Room 213A	Does not exist
	Instance on Room 315B	Does not exist
	Instance on Room 521B	Does not exist
Lightin	g Fixture - HID	
	Instance on Room 112A/B	Does not exist
	Instance on Room 213A	Does not exist
	Instance on Room 315B	Does not exist
	Instance on Room 521B	Does not exist
Lightin	g Fixture - Incandescent	
	Instance on Room 112A/B	Does not exist
	Instance on Room 213A	Does not exist
	Instance on Room 315B	Does not exist
	Instance on Room 521B	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection	1414
uestion	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - LED	
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Does not exist
Instance on Room 315B	Does not exist
Instance on Room 521B	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 112A/B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 213A	Does not exist
Instance on Room 315B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 521B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 112A/B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 213A	Does not exist
Instance on Room 315B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 521B	Does not exist
Power Supply	
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Inspected
Instance on Room 315B	Inspected
Instance on Room 521B	Inspected
Instructor Unit	
Instance on Room 213A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 315B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 521B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
WIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Dosponso
Response
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
3- Fair
BELL NOT OPERATIONAL
Front Door - (Bell)
1
EACH
REPLACE BELL
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
3- Fair
PANEL BOARD DOOR LOCK IS MISSING
Electrical Room (ELP-B)
l
EACH
MAINTENANCE
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
Inspected 3- Fair
FIXTURE NOT OPERATIONAL
Locker Room - Girls
1
EACH
REPAIR PRIORITY 5
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
2 5-1
3- Fair
No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical inspection	M14 /
Question	Response
EXIT LIGHT	
Battery Pack	
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Under construction
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Does not exist
LIGHTNING PROTECTION	
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Basement (Girls Locker Room Mechanical Room, Steam Vault inside Steam Room)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	Variable Frequency Drive Not Operational
Deficiency Location/Instance	Girls Locker Room Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PANEL BOARD	Inspected
	Does not exist
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	NO SPARE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Room 321A, Auditorium - Stage
Deficiency Quantity	3 EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	
Deficiency Quantity	North Basement Workshop 1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Under construction
SECURITY	Inspected
	Inspected
IPDVS/CCTV System Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 108
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SECURITY	
Lighting <u>- Security</u>	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instan	e Roof - Elevator Penthouses' Perimeter, Exterior Wall - Facing 16th Street.
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH Instance	Inspected Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	l EACH
Instance Quantity Uom	
Manufacturer	All City Switchboard
EquipmentId	S.SW. 1
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instan	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	LEVEL 2 No violations recorded
Standard	Inspected
	Inspected

Building Condition Assessment Survey 2023-2024

trical Inspection		M475
Question	Response	
TELEPHONE SYSTEM		
Standard		
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	