#### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	PRE-K CH	ENTER @ 1683 3RD AVENUE - M	IANHATTAN,	1683 3RD AVEN	UE, MANHA	ATTAN, NY, 1	0128
Inspection	n Id Inspection	Гуре		Time In			Last Edited
	2267 MECHANIC	CAL			2024	-01-08 07:38AN	A 2024-02-13 03:53PM
set Data							
Question				Answer			
Have any	Systems/Major Bu	ilding Components been upgraded?		Systems:	Electric Dom	estic Water Heat	ter
5	5 5	6 1 16		Years:	2023		
Are there	fuel tanks?			No			
Total # of	f water main service	e entries to the asset		0			
MERs/Fa	an Rooms Locations	3		MER 120	)		
Are there	any spaces with M	issing or Defective CO Detectors?		No			
		acted Sprinkler Heads?		No			
Are there	any Emergency Sto	op Switches with Missing Hammers?		No comp	onents		
iority Co	ondition						
xist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
No condit	tion recorded						
nspection	1						
Question	l			Response	9		
Mechani	cal						
AIR CO	ONDITIONING			Inspected			
	ed Water System			Does not			
		ibution: Piping, Pumps and Auxiliaries	s	Inspected			
	ndition	r s/ r		1- Good			
	Deficiency			No defici	encies recorded		
Cooli	ing Coil in Ductwo	rk		Does not	exist		
Cooling Tower				Does not	exist		
DX S	plit System			Does not	exist		
Dry (	Cooler			Does not	exist		
Pack	aged / Rooftop Uni	it		Inspected			
	Instance			MER 120	)		
	Instance Condit	tion		1- Good			
	Instance Quanti	ity		1			
	Instance Quanti	ity Uom		EACH			
	Manufacturer		United CoolAir				
	EquipmentId			VAV-AH	U-1		
	Capacity/Size C	-		40			
	Capacity/Size U			Tons			
	Source of Capa	-		Documer	ited		
	Installation Yea Source of Instal			2018 Documer	tad		
	Source of Heati			Hydronic			
	Refrigerant Typ			R-410A			
	Deficiency				encies recorded		
Packs		٩		Inspected			
Packaged Terminal A/C Condition				1- Good			
201	Deficiency				encies recorded		
Refrigerant Leak Detection System				Does not			
Refrigerant Piping				Does not			
Return Fan				Inspected			
Condition				1- Good			
	Deficiency			No defici	encies recorded		
CENTI	-	E NEUTRALIZING TANK		Does not	exist		
	ATE CONTROL S			Inspected			
	HE CONTROLS			mspecied			

BMS

Inspected

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

unicui Inspection		1117/
Juestion	Response	
CLIMATE CONTROL SYSTEM		
BMS		
Instance	Throughout	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Does not exist	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	l- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

anicui Inspeciion		19145
uestion	Response	
FIXTURES		
Student		
Lavatory/Sink		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
	Does not exist	
Enclosed IDF Room		
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap Instance on 1st Floor	Instructural	
	Inspected 2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Hood	Description	
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork Instance on 1st Floor	Does not exist	
Hood Exhaust Fan Instance on 1st Floor	Does not exist	
	רעניג ווטו באוא	
Hood Fire Suppression System Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster Instance on 1st Floor	Does not exist	
Kitchen Sink		

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

uestion	Response	
KITCHEN		
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 121	Inspected	
Dedicated A/C Equipment		
Instance on Room 121	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room 121	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inaccessible	
Exhaust Fan Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there any uninsulated ductwork by design in Meenancar rooms: Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
· ·	Does not exist	
Supply Fan Unit Ventilator	Does not exist	