Building Condition Assessment Survey 2023-2024

Electrical Inspection M495

Asset: PARK EAST HS - MANHATTAN, 230 EAST 105 STREET, MANHATTAN, NY, 10029				
Inspection Id	Inspection Type		Time In	Last Edited
653	ELECTRICAL		2023-11-01 11:55AM	2023-11-22 02:50PM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Staircases (Surface LED Lighting Lighting (Room 311), Partial IPE (Camera - Staircase B)	J / ·
		Years:	2022	
		Systems:	Partial Molded Case Circuit Brea	ker Panel Board
		Years:	2019, 2011, 2006, 1995	
		Systems:	Gymnasium (Scoreboard)	
		Years:	2019	
		Systems:	Security Lighting	
		Years:	2018	
		Systems:	Interior Lighting (Except Science Gymnasium (Local Sound Syster Exit Lights (Battery Pack)	• • • • • • • • • • • • • • • • • • • •
		Years:	2017	
		Systems:	Science Rooms	
		Years:	2013	
		Systems:	Library, Partial Fused Disconnec Board	t Switch Type Panel
		Years:	2012	
		Systems:	Partial Switchboard	
		Years:	2011	
		Systems:	Emergency Lighting (Battery Pac System	ek), IPDVS/CCTV
		Years:	2010	
		Systems:	Fire Alarm System	
		Years:	2009	
		Systems:	Public Address System	
		Years:	2004	
		Systems:	Intrusion Alarm System	
		Years:	2003	
Type of Service		Below Gr	ound	
Does Interactiv	e Whiteboard (IWB) Exist?	Yes		
Water Penetrati	on In Electrical Room?	No		
DEDICATEI) INTERCOMS IN FIRE RESCUE AREAS			
Question			Response	
Are there any your building	Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in ??	1	No	

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Public Address System - Speakers Not Operational	N/A	Public Address System	Gymnasium	Kenneth Thaxton	Fireman	No Photo Taken
Yes	Local Sound System - Not Connected to Public Address System	N/A	Local Sound System	Gymnasium	Kenneth Thaxton	Fireman	No Photo Taken
No	Water Leaks onto Electrical Equipment	Storm Pipe Leak, Roof Leak	Motor Starters, Lighting Fixture	Boiler Room, Corridor near Exit 2	Kenneth Thaxton	Fireman	No Photo Taken

Inspection

Question	Response
Flectrical	

Building Condition Assessment Survey 2023-2024

Electrical Inspection]	M495
0	D	

uestion	Response	
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Inspected	
Instance on 5th Floor	Inspected	
Lighting	пырескей	
Instance on 5th Floor	Inspected	
Lighting Fixture - Fluorescent	пироско	
Instance on 5th Floor	Inspected	
Pendant Mounted	пироско	
Instance on 5th Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 5th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Instance on 5th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 5th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 5th Floor	Does not exist	
Lighting Fixture - LED		
Instance on 5th Floor	Does not exist	
Local Sound System		
Instance on 5th Floor	Does not exist	
Projection System		
Instance on 5th Floor	Does not exist	
Theater Lighting System		
Instance on 5th Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist Does not exist	
COMPUTER LAB		
GYMNASIUM	Inspected	

Building Condition Assessment Survey 2023-2024

14147
Response
Inspected
Inspected
Does not exist
Does not exist
Does not exist
Inspected
This provides
Does not exist
2040 100 0.1101
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
No deficiencies recorded
Inspected
2- Between Good and Fair
2017
Documented
NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
1
EACH
INSTALL CONNECTION
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
2- Between Good and Fair
Ceiling
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Inspected
r
Inspected
Does not exist
^

Building Condition Assessment Survey 2023-2024

incui Inspection		11173
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 5th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 5th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 5th Floor	Does not exist	
Lighting Fixture - LED		
Instance on 5th Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 214	Inspected	
Lighting		
Instance on Room 214	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 214	Inspected	
Pendant Mounted		
Instance on Room 214	Does not exist	
Surface Mounted		
Instance on Room 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 214	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 214	Does not exist	
Lighting Fixture - LED		
Instance on Room 214	Does not exist	
Raceway With Receptacles		
Instance on Room 214	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 214	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inaccessible	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 410/411	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 410/411	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 410/411	Inspected	
	1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M495
Question	Response

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 410/411	Does not exist
Surface Mounted	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 410/411	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 410/411	Does not exist
Lighting Fixture - LED	
Instance on Room 410/411	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 410/411	Inspected
Instructor Unit	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 410/411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 410/411	Does not exist
Projection System	
Instance on Room 410/411	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 410/411A	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 410/411A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 410/411A	Inspected
Pendant Mounted	
Instance on Room 410/411A	Does not exist
Surface Mounted	
Instance on Room 410/411A	Inspected
Instance Condition	2- Between Good and Fair
	D: (D + 0/0/2024

Building Condition Assessment Survey 2023-2024

uestion	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 410/411A	Does not exist	
Lighting Fixture - HID		
Instance on Room 410/411A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 410/411A	Does not exist	
Lighting Fixture - LED		
Instance on Room 410/411A	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 410/411A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 410/411A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply	The deficiencies recorded	
Instance on Room 410/411A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
ENTERGENCI DO SIMIDDI DALLEKI IUWEK	100 0.1100	

Building Condition Assessment Survey 2023-2024

ricui Inspection	W1433
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office - Room B9	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
INTERCOM SYSTEM	Inspected	
Elevator Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Holding Area		
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	

Building Condition Assessment Survey 2023-2024

iricai Inspection	M1473
Question	Response
MOTOR CONTROLLER	
MOTOR STARTER/CONTACTOR	
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout The Building
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Corridor near Room 411
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Room 302
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 104
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2004
Installation Year Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Deficiency Location/Instance	CLOCK NOT OPERATIONAL Classrooms and Corridors
Deficiency Location/instance Deficiency Quantity	Classrooms and Corndors 8

Building Condition Assessment Survey 2023-2024

nestion	Response
PUBLIC ADDRESS SYSTEM	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Exterior
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Basement Custodian's Office - Room B9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	
	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	By Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST

Building Condition Assessment Survey 2023-2024

Question	Response	
SECURITY	T. F. C.	
Lighting - Security		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
	-	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E.	
EquipmentId	See Detail "A"	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1978	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	DP-AC	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E. Imperial Corp.	
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1978	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	