Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Inspectio	n Id Inspection Ty	ре			Time	In	Last Edited
	199 MECHANICA	AL			2023-	-10-16 07:58AM	2023-11-02 10:20AN
sset Data	!						
Question	1			Answer			
Have any	/ Systems/Major Build	ling Components been upgraded?		No Syster	n Upgraded		
Are there	e fuel tanks?			No			
Total # o	f water main service e	entries to the asset		0			
MERs/Fa	an Rooms Locations			None			
Are there	e any spaces with Miss	sing or Defective CO Detectors?		No			
	e any Painted/Obstruct			No			
Are there	e any Emergency Stop	Switches with Missing Hammers?		No compo	onents		
riority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						
nspection	4						
•				Deenenge			
Question				Response			
Mechani				T (1			
	ONDITIONING			Inspected Does not			
	led Water System			Inspected			
	ndition	ution: Piping, Pumps and Auxiliaries		1- Good			
COL	Deficiency				encies recorded		
				Does not			
-	ing Coil in Ductwork ing Tower			Does not			
	-			Does not			
	Split System Cooler			Does not			
	aged / Rooftop Unit			Inspected			
1	Instance				l (above ceiling)	
	Instance Conditio	n		1- Good	. 8	,	
	Instance Quantity			1			
	Instance Quantity			EACH			
	Manufacturer	Com		N/A			
	EquipmentId			AHU-1			
	Capacity/Size Qu	antity		8			
	Capacity/Size UC	-		Tons			
	Source of Capacit			Inspector	Estimate		
	Installation Year	·		2018			
	Source of Installa	tion Year		Inspector	Estimate		
	Source of Heating	5		N/A			
	Refrigerant Type			N/A			
	Deficiency			No defici	encies recorded		
	Instance				7 (above ceiling)	
	Instance Conditio	n		1- Good			
	Instance Quantity	7		1			
	Instance Quantity	v Uom	-	EACH	-		
	Manufacturer			N/A			
	EquipmentId			AHU-2			
	Capacity/Size Qu	antity		10			
	Capacity/Size UC			Tons			
	Source of Capacit			Inspector	Estimate		
	Installation Year			2018			
	Source of Installa	tion Year		Inspector	Estimate		
				N/A			

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		MOU
uestion	Response	
AIR CONDITIONING		
Packaged / Rooftop Unit		
Refrigerant Type	N/A	
Deficiency	No deficiencies recorded	
Instance	Room 109 (above ceiling)	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	N/A	
EquipmentId	AHU-3	
Capacity/Size Quantity	10	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Inspector Estimate	
Source of Heating	N/A	
Refrigerant Type	N/A	
Deficiency	No deficiencies recorded	
Instance	Room 122 (above ceiling)	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	N/A	
EquipmentId	AHU-4	
Capacity/Size Quantity	8	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation Year	Inspector Estimate	
Source of Heating	N/A	
Refrigerant Type	N/A	
Deficiency	No deficiencies recorded	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Does not exist	
Return Fan	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Does not exist	
Escalator	Does not exist	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nunicui Inspeciion		11500
Question	Response	
CONVEYING		
Non-auditorium Handicap Lift - Vertical	Inspected	
Condition	1- Good	
Are all the existing non-auditorium vertical handicap lifts operable?	Yes	
Deficiency	No deficiencies recorded	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Lavatory/Sink		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response	
FIXTURES		
Student		
Toilet		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
IEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries Condition	Inspected	
	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Does not exist	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected 1- Good	
Condition	No deficiencies recorded	
Deficiency		
IEATING PLANT	Inspected	
Instance on 1st Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	N/A	
Burner Model	N/A N/A	
Burner Type Heating Plant Oil Number	N/A N/A	
Boiler Auxiliaries	11/74	
Instance on 1st Floor	Inspected	
	inspected	
Boiler Auxiliary Piping	Insuranted	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 1st Floor	Does not exist	
Boiler Feedwater System		
Instance on 1st Floor	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on 1st Floor	Does not exist	
Boiler Flue Exhaust		
Instance on 1st Floor	Does not exist	
Boiler Make-up Water Backflow Preventer		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on 1st Floor	Does not exist	
Boiler Safety Valve		
Instance on 1st Floor	Does not exist	
Boiler System		
Instance on 1st Floor	Inspected	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

mieui Inspeciion	1415
estion	Response
IEATING PLANT	
Boiler System	
Coal-fired Boiler	
Instance on 1st Floor	Does not exist
Hot Water Boiler	
Instance on 1st Floor	Does not exist
Modular Boiler	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	73
Instance Quantity Uom	MBH NET
Manufacturer	Rheem
EquipmentId	N/A
Capacity/Size Quantity	84
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Steam Boiler	
Instance on 1st Floor	Does not exist
Fuel System	
Instance on 1st Floor	Does not exist
nclosed IDF Room	Does not exist
ATCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Not required
Gas System	1
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Does not exist
Hood Exhaust Ductwork	
Instance on 1st Floor	Does not exist
Hood Exhaust Fan	
Instance on 1st Floor	Does not exist
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
	The deficiencies recorded
Kitchon Sink	
Kitchen Sink	Inspected
Instance on 1st Floor	Inspected
Instance on 1st Floor Instance Condition	1- Good
Instance on 1st Floor Instance Condition Deficiency	1- Good No deficiencies recorded
Instance on 1st Floor Instance Condition	1- Good

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		IVI SU
uestion	Response	
MDF Room		
Dedicated A/C Equipment		
Instance on Room 116	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 100C	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	