Building Condition Assessment Survey 2023-2024

		AUXSVC-OLD 91) - MAN		CASTINGIAE			
Inspectio					Time In		Last Edited
	1661 ELECTRICAL				2023-12	2-13 08:53AN	M 2023-12-14 01:17PM
sset Data							
Question				Answer	*****	•.	
Have any	/ Systems/Major Building (Components been upgraded?		Systems:	Lighting - Secu	rity	
				Years:	2023	A 100 1 3	r tr: D
				Systems:	υ υ .	Auditorium, N	Multipurpose Room)
				Years:	2022	G	. G .: 1) E: 41
				Systems:	System (Printer 2020		ic Switch), Fire Alarm
				Years: Systems:	Auditorium (Lo	and Cound Cu	etam)
				·	•	cai Sound Sy	stem)
				Years:	2019	aiaatian Cresta	m) Multinum asa Daam
				Systems:	(Local Sound S (Except Science	ystem), Interi	m), Multipurpose Room or Fluorescent Lighting
				Years:	2017		
				Systems:	IPDVS/CCTV S	system	
				Years:	2013		
				Systems:			Breaker Panel Board
				Years:	2011, 2004, 200		#14 B
				Systems:	Amplifier Only		m 514, Room 310
				Years:	2008		
				Systems:	Science Rooms		
				Years:	2004	M	outual Card - E - 1
				Systems: Years:	Disconnect Swi 2000		ontrol Center, Fused el Board
				Systems:	Intrusion Alarm	System	
				Years:	1999	System	
Type of S	Service			Below Gro			
	eractive Whiteboard (IWB)	Exist?		Yes			
	netration In Electrical Room			No			
DEDIC	ATED INTERCOMS I	N FIRE RESCUE AREAS)				
Question					Response		
your b	uilding?	nce Areas, Fire Rescue Areas,	and/or Holding Room	ms in N	No		
<i>riority Co</i> Exist	Ondition Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
'es	Emergency Shut-Off Power - Not Operational	N/A	Emergency Shut-Off Power	Science Lab - Room 204	Ramgolam Rabindran uth	Fireman	No Photo Taken
No	Fire Alarm System -	Panel in Trouble	Fire Alarm	Exit 1		Fireman	No Photo Taken
.5	Defective		System	Vestibule	Rabindran uth		Amen
	Local Sound System -	N/A	Local Sound	Auditorium	_	Fireman	No Photo Taken
es	N C 1.		System		Rabindran uth		
	Not Connected to Public Address System						
	Public Address System						
	Public Address System			Response			
nspection	Public Address System 1			Response			
Question Electrica	Public Address System 1 1 1			Response Does not o			
Question Electrica	Public Address System 1 1 al ETIC FIELD			Does not e			
Electrica	Public Address System 1 1 1			-			

Building Condition Assessment Survey 2023-2024

uestion	Response
AUDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	-
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

Building Condition Assessment Survey 2023-2024

estion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System	Description of the second	
Instance on 1st Floor	Does not exist	
Theater Lighting System Instance on 1st Floor	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist Does not exist	

Building Condition Assessment Survey 2023-2024

1		
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	mspecced	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Surface Mounted	Does not exist	
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 407/408	Inspected	
Lighting		
Instance on Room 407/408	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 407/408	Inspected	
Pendant Mounted		
Instance on Room 407/408	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 407/408	Does not exist	
Recessed Mounted		
Instance on Room 407/408	Does not exist	
Lighting Fixture - HID		
Instance on Room 407/408	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 407/408	Does not exist	
Lighting Fixture - LED		
Instance on Room 407/408	Does not exist	
Raceway With Receptacles		
Instance on Room 407/408	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 407/408	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
MODIN UNI OSE KOOM		

Building Condition Assessment Survey 2023-2024

iricai Inspection	1413
Question	Response
MULTIPURPOSE ROOM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 204	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 404	Inspected
Power Panel?	No
Alternative Use	No
Lighting	110
Instance on Room 204	Inspected
Instance on Room 404	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 204	Inspected
Instance on Room 404	Inspected
Pendant Mounted	
Instance on Room 204	Inspected
···	ı

Building Condition Assessment Survey 2023-2024

Electrical Inspection		M510
Question	Response	_

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
Recessed Mounted	
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
Lighting Fixture - HID	
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
Lighting Fixture - Incandescent	200 100 51100
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
Lighting Fixture - LED	Does not exist
Instance on Room 204	Does not exist
Instance on Room 204	Does not exist
Emergency Gas Shut-Off Valve	DOCS HOT CAIST
Instance on Room 204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	No deficiencies recorded
Instance on Room 204	Inspected
Instance Condition	3- Fair
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 204	Inspected
Instance on Room 404	Inspected
Instructor Unit	•
Instance on Room 204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
2-11-1-11-1	

Building Condition Assessment Survey 2023-2024

Елесинсан Інѕресион	M1510

Question	Response
SCIENCE LAB	
Power Supply	
Meter Demonstration Unit	
Instance on Room 204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
Projection System	
Instance on Room 204	Does not exist
Instance on Room 404	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 404A	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 404A	Inspected
Lighting Fixture - Fluorescent	•
Instance on Room 404A	Inspected
Pendant Mounted	1
Instance on Room 404A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 404A	Does not exist
Recessed Mounted	
Instance on Room 404A	Does not exist
Lighting Fixture - HID	
Instance on Room 404A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 404A	Does not exist
Lighting Fixture - LED	
Instance on Room 404A	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 404A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 404A	Does not exist
Power Supply	
Instance on Room 404A	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	·
Condition	Inspected 2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

itell Inspection	14131
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

estion	Response	
IRE ALARM SYSTEM		
Bell/Horn		
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	PULL STATION COVER IS MISSING	
Deficiency Location/Instance	Corridor near Room 413	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL COVER	
Urgency of Action	PRIORITY 5	
Purpose of Action Violations	LEVEL 2 No violations recorded	
Fan Shutdown Control Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency	Inspected	
Duct Smoke Detector Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency		
CO Detector	Does not exist Inspected	
Heat Detector Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Magnetic Door Holder/Contactor Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Exit 1 Vestibule	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer Model	Edwards System Technology EST 2	
	ES1 2 Fire Alarm Control Panel	
EquipmentId	2000	
Installation Year Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	

Building Condition Assessment Survey 2023-2024

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST	
EquipmentId	Duct Detector Test Station	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Inspected	
Condition	5- Poor	
Deficiency	MONITOR NOT OPERATIONAL	
Deficiency Location/Instance	General Office - Room 514	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	

Building Condition Assessment Survey 2023-2024

uestion	Response
LAN	Кезропос
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
•	Does not exist
LIGHTNING PROTECTION	
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MCC-2
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Rooms 510, 404, 410, 210
	COLLIGOL HEAL KOOLIS 310: 404: 410: 210

Building Condition Assessment Survey 2023-2024

M510

Electrical Inspection

Question Response PANEL BOARD Molded Case Circuit Breaker Type Quantity Uom **EACH** Potential Action REPLACE PANEL BOARD PRIORITY 3 Urgency of Action Purpose of Action LEVEL 2 Violations No violations recorded Deficiency PANEL BOARD COVER IS MISSING Deficiency Location/Instance Boiler Room Deficiency Quantity Quantity Uom **EACH** Potential Action MAINTENANCE Urgency of Action PRIORITY 2 LEVEL 2 Purpose of Action Violations No violations recorded PUBLIC ADDRESS SYSTEM Inspected Instance Room 514 Instance Condition 3- Fair Instance Quantity 1

Building Condition Assessment Survey 2023-2024

ineai Inspection	141310
Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Lighting - Security Condition	Inspected 1- Good
	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Deficiency Location/Instance	By Exit 4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Electrical Room
Instance	3- Fair
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	American Switchboard Co.
EquipmentId	Main Service Switch
Capacity/Size Quantity	1600
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
	1965
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
i dipose of Action	
Violations	No violations recorded
Violations Instance	No violations recorded Electrical Room

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	3
	Inspected
Fused Disconnect Switch Type Instance	Boiler Room
	3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist