Building Condition Assessment Survey 2023-2024

Electrical Inspection M615

Asset: CHELSEA VOC HS - MANHATTAN, 131 AVE OF THE AMERICAS, MANHATTAN, NY, 10013			
Inspection Id	Inspection Type	Time In	Last Edited
3639	ELECTRICAL	2024-02-27 09:03AM	2024-06-17 11:34AM

1	ggat	Data	
ı	ssei	Data	

uestion	Answer	
ave any Systems/Major Building Components been upgraded?	Systems: Partial Raceway	with Receptacles in Computer Lab 103
	Years: 2022	
	Systems: Fire Alarm System	m
	Years: 2020	
	Systems: Local Sound Syst Entrance Lobby)	tem, LED Lighting (Auditorium, Main
	Years: 2019	
	Systems: Public Address S (Lighting)	ystem, Computer Lab - Room 405
	Years: 2017	
	Systems: Science Rooms (Emergency Shut	Emergency Gas Shut - Off Valve, - Off Power)
	Years: 2013	
	Systems: Surface HID Ligh	nting
	Years: 2011, 1997	
	Systems: IPDVS/CCTV Sy	vstem
	Years: 2010	
	Systems: Most Molded Cas	se Circuit Breaker Panel Board
	Years: 2008, 1999	
	Systems: Motor Control Co	enter
	Years: 1999, 1997	
	Systems: Emergency Light	/Exit Light Panel
	Years: 1999	
	Switchboard, Intr Fluorescent Light Lighting, Retrofit	ghting, Service Switch, Partial rusion Alarm System, Interior ting, Retrofitted Recessed Fluorescent ted Pendant Fluorescent Lighting cience Demo - Rooms (511, 514),

Years:

1995 Below Ground Type of Service

Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration In Electrical Room? Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Computer Lab - Rooms (205, 305, 310), Corridors, Classrooms, Administrative Spaces), Science Rooms

(Incandescent Lightning)

1997 Systems: Security Lighting

Years:

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Charlie Gomez	Fireman	

Inspection

Question	Response
----------	----------

Building Condition Assessment Survey 2023-2024

Electrical Inspection		M615
Question	Response	
Electrical		

incui Inspection	11013
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	1
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	D
Instance on 1st Floor	Does not exist
Theater Lighting System Instance on 1st Floor	Does not exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting Instance on 1st Floor	Turnopted
	Inspected
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

icui Inspection		17101
nestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		-
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	48	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System	<u> </u>	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	To deliciones recorded	
Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	3- Fair	
Condition		
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	520	
Quantity Uom Potential Action	EACH	
	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	120	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
	LEVEL 2	
Purpose of Action		
Violations	No violations recorded	
Violations Recessed Mounted	Does not exist	
Violations	Does not exist Inspected	
Violations Recessed Mounted	Does not exist Inspected Does not exist	
Violations Recessed Mounted Lighting Fixture - HID	Does not exist Inspected	

Building Condition Assessment Survey 2023-2024

incui inspection	14101
Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - HID	
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
COMPUTER LAB	Inspected
Instance on Room 103	Inspected
Power Panel?	Yes
Instance on Room 305	Inspected
Power Panel?	Yes
Instance on Room 405	Inspected
Power Panel?	No
Instance on Rooms 205, 310	Inspected
Power Panel?	No
Lighting	
Instance on Room 103	Inspected
Instance on Room 305	Inspected
Instance on Room 405	Inspected
Instance on Rooms 205, 310	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 103	Inspected
Instance on Room 305	Inspected
Instance on Room 405	Inspected
Instance on Rooms 205, 310	Inspected
	inspected
Pendant Mounted	Y 1
Instance on Room 103	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20 Execut
Quantity Uom Potential Action	EACH REPLACE UPCRADE
Urgency of Action	REPLACE-UPGRADE PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 305	
	Inspected 3- Fair
Instance Condition	
Deficiency Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33 Execut
Quantity Uom Potential Action	EACH DEDLAGE UDGDADE
	REPLACE-UPGRADE PRIORITY 1
Urgency of Action	PRIORITY I LEVEL 2
Purpose of Action	
Violations	No violations recorded
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection	1/1015

uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Rooms 205, 310	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	34	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action Violations	LEVEL 2 No violations recorded	
	No violations recorded	
Surface Mounted Instance on Room 103	Does not exist	
Instance on Room 305 Instance on Room 405	Does not exist Does not exist	
-		
Instance on Rooms 205, 310	Does not exist	
Recessed Mounted	Description of the second seco	
Instance on Room 103 Instance on Room 305	Does not exist	
	Does not exist	
Instance on Room 405	Does not exist	_
Instance on Rooms 205, 310	Does not exist	
Lighting Fixture - HID		
Instance on Room 103	Does not exist	
Instance on Room 305	Does not exist	
Instance on Room 405	Does not exist	
Instance on Rooms 205, 310	Does not exist	
Lighting Fixture - Incandescent	Down at wint	_
Instance on Room 103	Does not exist	
Instance on Room 305	Does not exist	
Instance on Room 405	Does not exist	
Instance on Rooms 205, 310	Does not exist	
Lighting Fixture - LED		
Instance on Room 103	Does not exist	
Instance on Room 305	Does not exist	
Instance on Room 405	Does not exist	
Instance on Rooms 205, 310	Does not exist	
Raceway With Receptacles		
Instance on Room 103	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 305	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 205, 310	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
YMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M615
Question	Response

Question	Response
KITCHEN	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	No violations recorded
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	DOCS HOT CAIST
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Does not exist
LIBRARY	Does not exist
	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	
SCIENCE DEMO ROOM	Inspected
Instance on Room 314	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 514	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 414	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 511	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 314	Inspected
Instance on Room 514	Inspected
Instance on Room 414	Inspected
Instance on Room 511	Inspected
Lighting Fixture - Fluorescent	Towards
Instance on Room 314 Instance on Room 514	Inspected
Instance on Room 514 Instance on Room 414	Inspected
Instance on Room 414 Instance on Room 511	Inspected
	Inspected
Pendant Mounted Instance on Room 314	Inspected
HISTORICE OF ROUTH 317	порессеи

Building Condition Assessment Survey 2023-2024

uestion	Response
SCIENCE DEMO ROOM	Тиоролос
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 514	Inspected
	3- Fair
Instance Condition	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	14
Quantity Uom Potential Action	EACH DEDLACE LIBERADE
	REPLACE-UPGRADE PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 414	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 314	Does not exist
Instance on Room 514	Does not exist
Instance on Room 414	Does not exist
Instance on Room 511	Does not exist

Does not exist

Instance on Room 314

Instance on Room 514

Instance on Room 414

Instance on Room 511

Instance on Room 314

Instance on Room 514
Instance on Room 414

Instance on Room 511

Lighting Fixture - Incandescent

Lighting Fixture - HID

Building Condition Assessment Survey 2023-2024

Duestion	Response	
SCIENCE DEMO ROOM	Response	
Lighting Lighting Fixture - Incandescent		
Instance on Room 314	Inspected	
Instance on Room 514	Does not exist	
Instance on Room 414	Inspected	
Instance on Room 511	Inspected	
Pendant Mounted		
Instance on Room 314	Does not exist	
Instance on Room 414	Does not exist	
Instance on Room 511	Does not exist	
Surface Mounted		
Instance on Room 314	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 414	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 511	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 314	Does not exist	
Instance on Room 414	Does not exist	
Instance on Room 511	Does not exist	
Lighting Fixture - LED		
Instance on Room 314	Does not exist	
Instance on Room 514	Does not exist	
Instance on Room 414	Does not exist	
Instance on Room 511	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 314	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 514	Does not exist	
Instance on Room 414	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 511	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 314	Does not exist	
Instance on Room 514	Does not exist	
Instance on Room 414	Does not exist	
Instance on Room 511	Does not exist	
Power Supply		
Instance on Room 314	Inspected	
Instance on Room 514	Does not exist	
Instance on Room 414	Inspected	
Instance on Room 511	Does not exist	
Instructor Unit		
Instance on Room 314	Inspected	

Building Condition Assessment Survey 2023-2024

cui inspection	1414
estion	Response
CIENCE DEMO ROOM	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Instance on Room 414	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 314	Does not exist
Instance on Room 414	Does not exist
Projection System	
Instance on Room 314	Does not exist
Instance on Room 514	Does not exist
Instance on Room 414	Does not exist
Instance on Room 511	Does not exist
CIENCE LAB	Inspected
Instance on Room 313	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Room 413	Inspected
Power Panel?	
	Yes
Alternative Use	No
Lighting	Turney d
Instance on Room 313	Inspected
Instance on Room 413	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 313	Inspected
Instance on Room 413	Inspected
Pendant Mounted	
Instance on Room 313	Inspected 3- Fair
Instance Condition	
Deficiency Overtity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	23 FACH
Quantity Uom	EACH PER A CE LIBERT A DE
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 413	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 313	Does not exist
Instance on Room 413	Does not exist
Recessed Mounted	
Instance on Room 313	Does not exist
Instance on Room 413	Does not exist
Lighting Fixture - HID	

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - HID Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist Does not exist	
Lighting Fixture - Incandescent	DOCS HOL CAISE	
Instance on Room 313	Inspected	
Instance on Room 413	Inspected	
Pendant Mounted	inspected	
Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist Does not exist	
	Does not exist	
Surface Mounted Instance on Room 313	Lungantad	
	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency		
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist	
Lighting Fixture - LED		
Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 313	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 313	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 313	Inspected	
Instance on Room 413	Inspected	
Instructor Unit		
Instance on Room 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist	

Inspected 3- Fair

Student Unit

Instance on Room 313

Instance Condition

Building Condition Assessment Survey 2023-2024

ciricai inspection	14101
Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Deficiency	No deficiencies recorded
Instance on Room 413	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 313	Does not exist
Instance on Room 413	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 411A	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 411A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 411A	Inspected
Pendant Mounted	
Instance on Room 411A	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 411A	Does not exist
Recessed Mounted	
Instance on Room 411A	Does not exist
Lighting Fixture - HID	
Instance on Room 411A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 411A	Does not exist
Lighting Fixture - LED	
Instance on Room 411A	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 411A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 411A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 411A	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

aricai inspection	WIOIS
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Recessed Mounted	
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
	Does not exist Does not exist
Lighting Fixture - Incandescent	Does not exist Does not exist
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

Building Condition Assessment Survey 2023-2024

icui inspection	WIGH
Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
	Inspected
Battery Pack Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	1 moughout the Bunding
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	5th Floor - Student Commons
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	
Deficiency Quantity	Basement by Staircase D, 1st Floor by Main Entrance Lobby
	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
· · · · · · · · · · · · · · · · · · ·	
Strobe	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good

Building Condition Assessment Survey 2023-2024

-		14101
uestion	Response	
FIRE ALARM SYSTEM		
Duct Smoke Detector		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	-
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Tamper Flow Switch/Chain Condition	1- Good	
	No deficiencies recorded	
Deficiency		
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	

Building Condition Assessment Survey 2023-2024

aricai inspection	191015
Question	Response
LAN	
Local Distribution Frame (I/LDF)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Basement - Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse - Tank Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MCC-RF
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 211
	2- Between Good and Fair
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Model	Bogen HTA250A

Building Condition Assessment Survey 2023-2024

estion	Pasnansa
	Response
UBLIC ADDRESS SYSTEM	2017
Installation Year Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	MDF Room 410
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 106
Instance Condition	3- Fair
Instance Quantity	1
- · · · · · · · · · · · · · · · · · · ·	EACH
Instance Quantity Uom Model	Vista - 128B
	1997
Installation Year	
Source of Installation Year Deficiency	Documented PANISIA NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	PANEL NOT CONNECTED TO DOE CENTRAL STATION 1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 106
Deficiency Quantity	l FACIL
Quantity Uom Potential Action	EACH DEDLACE
	REPLACE
Urgency of Action	PRIORITY 1 LEVEL 3
Purpose of Action Violations	No violations recorded
	Inspected
Infrared Sensor Condition	-
	3- Fair
Deficiency	No deficiencies recorded Does not exist
Panic Switch	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

ii icui 11	ispection	1/1/1
Question		Response
SERVIC	CE SWITCH	
	Instance	Electrical Room
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	All City Switchboard
	EquipmentId	DP-DCA
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1997
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	All City Switchboard
	EquipmentId	N/A
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1997
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
SWITC	HBOARD	Inspected
Numbe	er of Spares	0
Fused	Disconnect Switch Type	Inspected
	Instance	Electrical Room
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	All City Switchboard
	EquipmentId	DP-DCA Section 1 and Section 2
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	2
	Capacity/Size 2 Quantity	Section(s)
	Source of Capacity/Size	Service Switch Size
	Installation Year	1997
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Royal Switchboard Co.
	EquipmentId	N/A
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	2
	C 'A IC' A HOM	Section(s)
	Capacity/Size 2 UOM	(-)
	Source of Capacity/Size	Service Switch Size
	Source of Capacity/Size	Service Switch Size

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	