Building Condition Assessment Survey 2023-2024

Lieciricai Insp	cciion		111023
Asset:	HS OF GRAPHIC COMMUNICATION ARTS - 10019	MANHATTAN, 439 WEST 49 STREET, MANHATTAN	, NY,
Inspection Id	Inspection Type	Time In	Last Edited
1438	ELECTRICAL	2023-11-30 08:58AM	2024-06-19 09:25AM
Asset Data		·	
Overtion		Angreen	

Inspection Id Inspection Type	Time In Last Edited
1438 ELECTRICAL	2023-11-30 08:58AM 2024-06-19 09:25A
et Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency Lighting (Battery Pack)
	Years: 2022, 2018, 2016
	Systems: Fire Alarm System (CO Detector)
	Years: 2022, 2018
	Systems: Fire Alarm System (Partial Sub Panel)
	Years: 2022
	Systems: Gymnasium (LED Lighting)
	Years: 2021
	Systems: Most Service Switch, Most Switchboard
	Years: 2020, 2009, 2000
	Systems: Most Security Lighting
	Years: 2020, 1995
	Systems: IPDVS/CCTV System
	Years: 2020
	Systems: Most Molded Case Circuit Breaker Panel Board
	Years: 2018, 2016, 2009, 2007, 1990
	Systems: Toilet Rooms, Lightning Protection
	Years: 2018
	Systems: Recessed LED Lighting
	Years: 2017
	Systems: Cafeteria, Kitchen, Locker Rooms
	Years: 2016
	Systems: Surface Fluorescent Lighting, Surface LED Lighting, Pendant LED Lighting, Variable Frequency Drive
	Years: 2015
	Systems: Multipurpose Rooms, Gymnasium (Surface Mounted Lighting, Scoreboard), Raceway With Receptacles (Computer Lab - Rooms 707, 710, 721, 747)
	Years: 2014
	Systems: Library
	Years: 2013
	Systems: Intrusion Alarm System (Panic Switch)
	Years: 2012
	Systems: Exit Lights (Battery Pack), Telephone System
	Years: 2009
	Systems: Classrooms, Corridors and Administrative Offices (Pendant Fluorescent Lighting, Recessed Fluorescent Lighting)
	Years: 2007
	Systems: Public Address System, Local Sound System
	Years: 2005
	Systems: Intrusion Alarm System (Except Panic Switch), Fire Alarm System (Except Flow Switch/Chain, Sprinkler Flow/Air Pressure Switch), Emergency Light/Exit Light Panel
	Years: 2000
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

	ATED INTERCOMS IN	N FIRE RESCUE AREAS					
Question]	Response		
		nce Areas, Fire Rescue Areas, a	nd/or Holding Roon	ns in	Yes		
your bu		1 : 11 0.1	1 :				
		le in all of these spaces for use	during a fire?		No	422 522 (22	722
	ich spaces do not have dedi	cated intercoms?			Rooms 233, 333	, 433, 333, 633	9, 733
riority Co		~					
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo
				•			Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Area Smoke Detector	Bulkhead 2	Dennis Flores	Fireman	No Photo Taken
Yes	Emergency Gas Shut-Off Valve - Not Operational	The Master Valve is not operational.	Emergency Gas Shut-Off Valve	Science Lab - Room 601	Dennis Flores	Fireman	No Photo Taken
Yes	Water Leaks onto Electrical Equipment	Domestic Water Piping Leak affecting a Lighting Fixture	Lighting Fixture	Basement - Corridor by Room B32	Dennis Flores	Fireman	No Photo Taken
Inspection	1						
Question	l .			Response	2		
Electrica	ıl						
ATHL	ETIC FIELD			Does not	exist		
AUDIT	ORIUM			Inspected			
	Instance on 2nd Floor			Under con	nstruction		
CAFE	ΓΕΚΙΑ			Inspected			
	Instance on 1st Floor			Inspected			
Light	ting						
	Instance on 1st Floor			Inspected			
Lig	hting Fixture - Fluorescen	t					
_	Instance on 1st Floor			Inspected			
P	endant Mounted			D .	:-4		
_	Instance on 1st Floor			Does not	exist		
S	Instance on 1st Floor			Doggest	aviet		
_ n	Instance on 1st Floor			Does not	CAISI		
K	Instance on 1st Floor			Inspected			
	Instance Condition			*	en Good and Fa	ir	
	Deficiency				IG FIXTURE B		ECTIVE
	Deficiency Quantity			1	, J I IA I UKE D	LIDEAGI DEF	LUIITE
	Quantity Uom			EACH			
	Potential Action				E BALLAST		
	Urgency of Action			PRIORIT	Y 3		
	Purpose of Action			LEVEL 2			
	Violations			No violat	ions recorded		
Lig	hting Fixture - HID						
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - Incandesco	ent			• .		
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - LED			ъ .	• ,		
-	Instance on 1st Floor			Does not	exist		
Loca	I Sound System			Imamaat- 1			
	Instance on 1st Floor Instance Condition			Inspected	en Good and Fa	ir	
	Instance Condition Installation Year			2- Betwee 2016	an Good allu Fa		
		'ear		Documen			

Building Condition Assessment Survey 2023-2024

trical inspection	M625
Question	Response
CAFETERIA	
Local Sound System	
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 560	Inspected
Power Panel?	No
Instance on Room 707	Inspected
Power Panel?	No
Instance on Room 736	Inspected
Power Panel?	Yes
Instance on Room 532	Inspected
Power Panel?	Yes
Instance on Rooms 710, 721, 747	Inspected
Power Panel?	
	Yes
Instance on Room 559	Inspected
Power Panel?	No
Lighting	
Instance on Room 560	Inspected
Instance on Room 707	Inspected

Electrical Inspection		M625
0 4	D	_

estion	Response
OMPUTER LAB	
Lighting	
Instance on Room 736	Inspected
Instance on Room 532	Inspected
Instance on Rooms 710, 721, 747	Inspected
Instance on Room 559	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 560	Inspected
Instance on Room 707	Inspected
Instance on Room 736	Inspected
Instance on Room 532	Inspected
Instance on Rooms 710, 721, 747	Inspected
Instance on Room 559	Inspected
Pendant Mounted	
Instance on Room 560	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 736	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 532	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 710, 721, 747	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 559	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 560	Does not exist
Instance on Room 707	Does not exist
Instance on Room 736	Does not exist
Instance on Room 532	Does not exist
Instance on Rooms 710, 721, 747	Does not exist
Instance on Room 559	Does not exist
Recessed Mounted	
Instance on Room 560	Does not exist
Instance on Room 707	Does not exist
Instance on Room 736	Does not exist
Instance on Room 532	Does not exist
Instance on Rooms 710, 721, 747	Does not exist
Instance on Room 559	Does not exist
Lighting Fixture - HID	
Instance on Room 560	Does not exist
Instance on Room 707	Does not exist
	Does not exist
Instance on Room 736	Does not exist
Instance on Room 736 Instance on Room 532	Does not exist

	25
Question Response	

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 560	Does not exist
Instance on Room 707	Does not exist
Instance on Room 736	Does not exist
Instance on Room 532	Does not exist
Instance on Rooms 710, 721, 747	Does not exist
Instance on Room 559	Does not exist
Lighting Fixture - LED	
Instance on Room 560	Does not exist
Instance on Room 707	Does not exist
Instance on Room 736	Does not exist
Instance on Room 532	Does not exist
Instance on Rooms 710, 721, 747	Does not exist
Instance on Room 559	Does not exist
Raceway With Receptacles	
Instance on Room 560	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 707	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 736	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 532	Does not exist
Instance on Rooms 710, 721, 747	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 559	Does not exist
GYMNASIUM	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected

Electrical Inspection	M625
Question	Response

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Scoreboard	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	Y 1
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	D
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	D
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Daga met aviet
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 646	Inspected
Lighting	Tunmostod
Instance on Room 646	Inspected
Lighting Fixture - Fluorescent	Tunmostod
Instance on Room 646	Inspected
Pendant Mounted	Towns de d
Instance on Room 646	Inspected 2. Patroon Good and Fain
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

ctrical inspection		M1625
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on Room 646	Does not exist	
Recessed Mounted		
Instance on Room 646	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 646	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 646	Does not exist	
Lighting Fixture - LED		
Instance on Room 646	Does not exist	
Raceway With Receptacles		
Instance on Room 646	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 646	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative Use	Yes	
Lighting		
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Surface Mounted		
Instance on Basement - Boys, Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 201	Inspected	
Instance on Room 202	Inspected	
Lighting	This process	
Instance on Room 201	Inspected	
Instance on Room 202	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 201	Inspected	
Instance on Room 202	Inspected	
Pendant Mounted		
Instance on Room 201	Does not exist	
Instance on Room 202	Inspected	
Instance on Room 202	Inspected	

Building Condition Assessment Survey 2023-2024

icui inspection		IVIUZ
uestion	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
Recessed Mounted		
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 202	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	1.0 442.00.000	
Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
Lighting Fixture - LED	DOCS HOT CAIST	
Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
	Does not exist	
Local Sound System Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
	DOCS HOT CAIST	
Projection System Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
	DOCS HOT CAIST	
Theater Lighting System Instance on Room 201	Does not exist	
Instance on Room 202	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 606	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Rooms 643, 649, 659, 660	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 612	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 606	Inspected	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance on Room 612	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 606	Inspected	
Instance on Rooms 643, 649, 659, 660	Inspected	
	_	

Electrical Inspection	1/1025

4		
estion	Response	
CIENCE DEMO ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Room 606	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 612	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Recessed Mounted		
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Lighting Fixture - HID		
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Emergency Gas Shut-Off Valve	DOGS HOT CAIST	
Instance on Room 606	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 612	Inspected	
Instance on Room 612 Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Emergency Shut-Off Power	Does not exist	
Instance on Room 606		
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
Power Supply Instance on Room 606	Ingrested	
	Inspected	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance on Room 612	Inspected	
Instructor Unit	Y 1	
Instance on Room 606	Inspected	

Building Condition Assessment Survey 2023-2024

cui inspection		
estion	Response	
CIENCE DEMO ROOM		
Power Supply		
Instructor Unit		
Deficiency	No deficiencies recorded	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 612	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 606	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 643, 649, 659, 660	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 612	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 606	Does not exist	
Instance on Rooms 643, 649, 659, 660	Does not exist	
Instance on Room 612	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 601	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Rooms 602, 611	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 601	Inspected	
Instance on Rooms 602, 611	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 601	Inspected	
Instance on Rooms 602, 611	Inspected	
Pendant Mounted	1	
Instance on Room 601	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	The deficiences recorded	
Instance on Room 601	Does not exist	
Instance on Rooms 602, 611	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 601	Does not exist	
Instance on Rooms 602, 611	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room 601	Does not exist	
HISTARICE OII ROOHI OUT	Docs not caust	

Electrical Inspection	N1025
·	

estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 601	Does not exist	
Instance on Rooms 602, 611	Does not exist	
Lighting Fixture - LED		
Instance on Room 601	Does not exist	
Instance on Rooms 602, 611	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 601	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Y 1	
Instance on Room 601	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply	Y 1	
Instance on Room 601	Inspected	
Instance on Rooms 602, 611	Inspected	
Instructor Unit	Y 1	
Instance on Room 601	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 601	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 601	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 602, 611	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 601	Does not exist	

Building Condition Assessment Survey 2023-2024

ricai inspection		1/10/25
Question	Response	
SCIENCE LAB		
Projection System		
Instance on Rooms 602, 611	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 601A	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 601A	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 601A	Inspected	
Pendant Mounted	•	
Instance on Room 601A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 601A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 601A	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room 601A	Does not exist	
Lighting Fixture - Incandescent	DOG HOT CAIST	
Instance on Room 601A	Does not exist	
Lighting Fixture - LED	DOG HOT CAIST	
Instance on Room 601A	Does not exist	
Emergency Gas Shut-Off Valve	DOCS HOT CAIST	
Instance on Room 601A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	No deficiences recorded	
Instance on Room 601A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply	No deficiences recorded	
Instance on Room 601A	Inspected	
Instructor Unit	поресси	
Instance on Room 601A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	

Electrical Inspection	M625

Overtice	D	
Question	Response	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
ran Shutuvwii Cuntivi		

Building Condition Assessment Survey 2023-2024

icui Inspection		W1025
nestion	Response	
FIRE ALARM SYSTEM		
Fan Shutdown Control		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	-
Condition	3- Fair	
Deficiency	DETECTOR NOT OPERATIONAL	
Deficiency Location/Instance	Bulkhead 2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer Model	Notifier N/A	
EquipmentId	Fire Alarm Control Panel 2000	
Installation Year Source of Installation Year	Documented	
	No deficiencies recorded	
Deficiency	Does not exist	
Fire Alarm Control Panel (Standard)		
Sub-Panel Rell At Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	

Electrical Inspection	M625
-----------------------	------

•		
Question	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity Uom	EACH	
Manufacturer	Radionics	
Model	N/A	
EquipmentId	Fire Control Panel	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room B04	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	MPS-24A	
EquipmentId	Strobe Panel 2000	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room 04	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer Model	Cerberus Pyrotronics CP - 35	
EquipmentId	Fire Bell Panel	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room 04	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	NFS2-3030	
EquipmentId	Carbon Monoxide Control Panel	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	

Building Condition Assessment Survey 2023-2024

arical Inspection	N1023
Question	Response
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
	Inspected
Local Distribution Frame (I/LDF) Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Main Equipment Rack (MDF) Condition	3- Fair
	No deficiencies recorded
Deficiency	
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement (Pump Room, Mechanical Room B19, Room B34), Gymnasium - Mechanical Room, Fan Rooms (701, 759)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B09
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	21
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Closets (115, by Rooms (206, 240), 413, 551), by Room
Deficiency Quantity	745 9
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Computer Lab Room 747
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	By Electrical Room B09, Custodian's Office
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
PUBLIC ADDRESS SYSTEM	•
Instance	Sound Control Room 320 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
Installation Year	2005
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	MDF Room 533, Library, Science Demo Room 649, by Room 739
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2020
Source of Installation Year	Custodial Staff
Deficiency	CAMERA NOT OPERATIONAL
•	

Building Condition Assessment Survey 2023-2024

Question	Response
SECURITY	•
IPDVS/CCTV System	
Deficiency Location/Instance	Exterior Roof (E1-09, ER-06), Cafeteria (C1-22), Auditorium (C2-26), 3rd Floor - Escalator (C3-46), 6th Floor Stair 2 (C6-79), 7th Floor Stair 3 (C7-90)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 111
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	2000
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - Facing W50th Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B09
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard

Building Condition Assessment Survey 2023-2024

inspection	
on	Response
VICE SWITCH	
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
,	No deficiencies recorded
Deficiency	
Instance	Electrical Room B09
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	PP-BR1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
	2020
Installation Year	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
	Sub Switchboard Section A
EquipmentId	
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B09
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Electrical Room B09
Instance	``
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Sub Switchboard Section B
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B09
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

Electrical Inspection		

icui inspection	IV102.
uestion	Response
SERVICE SWITCH	
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	32
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B09
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	All City Switchboard
Manufacturer	Main Distribution Board
EquipmentId Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	Amps rotal
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Equipmenta Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Basement - Electrical Room On North Side
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation Year	Documented
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

cirical Inspection	1/1023
Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Electrical Room On North Side
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action Urgency of Action	REPLACE PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room B04
Instance Condition	1- Good
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	General Electric PP-BR1
EquipmentId Capacity/Size Quantity	800
Capacity/Size Quantity Capacity/Size UOM	
Capacity/Size 2 Quantity	Amps Total 2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Standard Co.
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B09
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2000

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B09
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B09
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist