Building Condition Assessment Survey 2023-2024

Asset:	CITTA	S SCHOOL (OLD 95) - MANI	TITINI, TO CEITIG	SON STREET,		
Inspectio	n Id Inspectio	on Type			Time In	Last Edited
	1171 ELECTR	ICAL			2023-11-17 08:58AM	2023-12-06 02:28PN
sset Data						
Question				Answer		
Have any	Systems/Major	Building Components been upgrade	?	Systems:	Retrofitted LED Surface Lighti Corridors at M721 Sped - Man	
					Retrofitted LED Pendant Light at City as School - Manhattan)	ing (Office - Room 506
				Years:	2022	
				Systems:		attery Pack)
				Years:	2019	
				Systems:	• •	
				Years:	2018	
				Systems:		eaker Panel Board
				Years:	2017, 2004, 1997	
				Systems:	Lighting - Non Battery Pack	Partial Emergency
				Years:	2017	
				Systems:		
				Years:	2016, 1997	iitala
				Systems:		Itcii
				Years:	2016	acres with December 100)
				Systems:	Library (Projection System, Ra 2015	ceway with Receptacies)
				Years: Systems:	Interior Fluorescent Lighting, I	
				Years:	Pack), Partial Security Lighting 2014	5
				Systems:	Fire Alarm System	
				Years:	2012	
				Systems:	Public Address System (Ampli	fier in Room 203)
				Years:	2006	
				Systems:	Intrusion Alarm System (Centra	al Control Panel)
				Years:	2005	
				Systems: Years:	Intrusion Alarm System (Exception 1998)	ot Central Control Panel)
				Systems:	Fused Disconnect Switch Type Control Center	Panel Board, Motor
				Years:	1997	
				Systems:		nel
				Years:	1992	
Type of S	ervice			Below G	round	
• •		ard (IWB) Exist?		Yes		
Water Per	netration In Elect	trical Room?		Yes		
DEDIC	ATED INTER	COMS IN FIRE RESCUE AR	AS			
Question					Response	
your bu	ilding?	ue Assistance Areas, Fire Rescue Ar		oms in	Yes	
		ms available in all of these spaces for	use during a fire?		Yes	
Are	all dedicated int	ercoms operational?			Yes	
Priority Co	ndition					
Exist	Priority	Condition	Component	Location	Person(s) Person(s)	Photo

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M641
-----------------------	------

No	Other	Potential risk of falling down (detachment from ceiling)	Lighting Fixture	Multipurpose Room - 1st Floor	Abdul Ammari	Fireman	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Abdul Ammari	Fireman	
No	Fire Alarm System - Not Connected to Central Station	"Dialer line dead" warning shown on the Panel's screen	Fire Alarm System - Main Panel	Main Entrance Lobby	Abdul Ammari	Fireman	FIRE ALARM CONTROL PANEL
Inspecti	ion						
Quest	tion			Response			
Electi	rical						
ATI	HLETIC FIELD			Does not e	xist		
AUI	DITORIUM			Inspected			
	Instance on Basement			Inspected			
He	ouse Lighting						
	Instance on Basement			Inspected			
-	Does a Chandelier Exis			No			
]	Lighting Fixture - Fluorescer	nt					
	Instance on Basement			Inspected			
	Pendant Mounted			T 1			
	Instance on Basement Instance Condition			Inspected 2 Patryon	n Good and Fa		
	Deficiency				ncies recorded		
	Surface Mounted			No deficie	ilcies recorded	1	
	Instance on Basement			Does not e	viet		
	Recessed Mounted			Does not e	Alst		
	Instance on Basement			Does not e	viet		
-	Lighting Fixture - HID			Does not e	Alst		
	Instance on Basement			Does not e	xist		
-	Lighting Fixture - Incandesc	ent		200011000			
•	Instance on Basement			Does not e	xist		
]	Lighting Fixture - LED						
	Instance on Basement			Does not e	xist		
Lo	ocal Sound System						_
	Instance on Basement			Inspected			
	Instance Condition			5- Poor			
	Installation Year			1998			
	Source of Installation Y	Year		Document	ed		
	Deficiency				ER NOT OPE	RATIONAL	
	Deficiency Quantity			1			
	Quantity Uom			EACH			
	Potential Action				SYSTEM		
	Urgency of Action			PRIORITY	(2		
	Purpose of Action			LEVEL 2			
	Violations			ino Violatio	ons recorded		

Building Condition Assessment Survey 2023-2024

ctrical Inspection	M641	
Question	Response	
AUDITORIUM		
Projection System		
Instance on Basement	Does not exist	

Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Does not exist
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
	nispected
Lighting Instance on 1st Floor	Inspected
	nispected
Lighting Fixture - Fluorescent Instance on 1st Floor	T
	Inspected
Pendant Mounted	T 1
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Does not exist
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
	Inspected
Lighting Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
	Inspected
Pendant Mounted	порески

Building Condition Assessment Survey 2023-2024

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR PRIORITY 2	
Urgency of Action	PRIORITY 3	
Purpose of Action Violations	LEVEL 2	
	No violations recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	DOOD HOT CAINT	
Instance on 1st Floor	Does not exist	
	DOGS HOL CAISE	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

rical Inspection		M
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 407/409	Inspected	
Lighting		
Instance on Room 407/409	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 407/409	Inspected	
Pendant Mounted		
Instance on Room 407/409	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 407/409	Does not exist	
Recessed Mounted		
Instance on Room 407/409	Does not exist	
Lighting Fixture - HID		
Instance on Room 407/409	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 407/409	Does not exist	
Lighting Fixture - LED		
Instance on Room 407/409	Does not exist	
Raceway With Receptacles		
Instance on Room 407/409	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 407/409	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not east	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
mstance Condition	2 Detween Good and I an	

No deficiencies recorded

Does not exist

Does not exist

Does not exist

Does not exist

Deficiency

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

Lighting Fixture - Incandescent
Instance on 1st Floor

Recessed Mounted

Lighting Fixture - HID

Lighting Fixture - LED

Local Sound System

Building Condition Assessment Survey 2023-2024

Question	Response		
MULTIPURPOSE ROOM			
Local Sound System			
Instance on 1st Floor	Inspected		
Instance Condition	5- Poor		
Installation Year	1980		
Source of Installation Year	Inspector Estimate		
Deficiency	AMPLIFIER NOT OPERATIONAL		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE SYSTEM		
Urgency of Action	PRIORITY 2		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Projection System			
Instance on 1st Floor	Does not exist		
Theater Lighting System			
Instance on 1st Floor	Does not exist		
SCIENCE DEMO ROOM	Does not exist		
SCIENCE LAB	Does not exist		
SCIENCE PREP ROOM	Does not exist		
SWIMMING POOL	Does not exist		
TOILET ROOM - STAFF	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Surface Mounted	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not exist		
	Does not exist		
Lighting Fixture - HID	Does not exist Does not exist		
Lighting Fixture - Incandescent	Does not exist Does not exist		
Lighting Fixture - LED			
TOILET ROOM - STUDENT	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Surface Mounted	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not exist		
Lighting Fixture - HID	Does not exist		
Lighting Fixture - Incandescent	Does not exist		
Lighting Fixture - LED	Does not exist		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected		
Condition	3- Fair		
Deficiency	INDICATOR PANEL NOT OPERATIONAL		
Deficiency Location/Instance	Boiler Room		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE PANEL		

Building Condition Assessment Survey 2023-2024

rical Inspection	M6	
Question	Response	
AUXILIARY SIGNAL/BELL SYSTEM		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL	
Deficiency Location/Instance	Electric Meter Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE CIRCUIT BREAKER	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EMERGENCY LIGHTING	Inspected	
	Inspected	
Battery Pack Condition	2- Between Good and Fair	
-		
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	17	
Quantity Uom	EACH PEN ACE DATTERY	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35643562Z	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	1st Floor by Stair G	
Deficiency Quantity	1	
Quantity Uom	EACH PERMACE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5 LEVEL 2	
Purpose of Action		
Violations	No violations recorded	
Non Battery Pack	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	5- Poor	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Basement (Outside Auditorium by Server Room 018, By Staircase	
	C, Boiler Room (Second Entrance, Rear Door))	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35643562Z	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	

Building Condition Assessment Survey 2023-2024

ent inspection	1/10
estion	Response
IRE ALARM SYSTEM	
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	FireFinder XLS
EquipmentId	Fire Alarm Control Panel
Installation Year	2012
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
	D
Fire Alarm Control Panel (Standard)	Does not exist

Building Condition Assessment Survey 2023-2024

iteui Inspection		1/10-11
Question	Response	
FIRE ALARM SYSTEM		
Remote Annunciator		
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office - Room 114	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	N/A	
EquipmentId	Fire Control Rack	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
	Inspector Estimate	
Source of Capacity/Size Installation Year	1997	

Building Condition Assessment Survey 2023-2024

•	
uestion	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Under construction
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Kitchen, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 402
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	4th Floor by Staircase B/Elevator Lobby, 2nd Floor by Men-Staff Toilet Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 210
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1968
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
PUBLIC ADDRESS SYSTEM		
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	By Rooms (210, 510)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Room 210	
Deficiency Quantity	109,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
	PRIORITY 1	
Urgency of Action Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	General Office - Room 203	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Dukane 125	
Installation Year	1980	
Source of Installation Year	Inspector Estimate	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	3rd Floor by Staircase B/Elevator Lobby	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	MASTER CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	General Office - Room 203	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	General Office - Room 203	
Deficiency Quantity	109,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
	PRIORITY 1	
Urgency of Action Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Room 100	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
· •		

Building Condition Assessment Survey 2023-2024

Duestion	Response
SECURITY	Response
Intrusion Alarm System Central Control Panel	
Model	Vista - 128B
Installation Year	2005
Source of Installation Year	Inspector Estimate
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - Facing Clarkson Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action Violations	LEVEL 3
	No violations recorded
Lighting - Security	Inspected 3- Fair
Condition	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Exterior Wall - By Exit 5
Quantity Uom	2 EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Boiler Room
Instance	2- Between Good and Fair
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	2000 A Main Switch
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size 2016
Installation Year Source of Installation Year	Documented

No deficiencies recorded

2- Between Good and Fair

Boiler Room

Deficiency

Instance Condition

Instance

Building Condition Assessment Survey 2023-2024

uestion		Response	
SERVICE SWITCH			
Instance Quanti	ty	1	
Instance Quanti	ty Uom	EACH	
Manufacturer		All City Switchboard	
EquipmentId		MDP	
Capacity/Size Q	Quantity	1600	
Capacity/Size U		Amps	
Source of Capa		Nameplate	
Installation Yea	r	2016	
Source of Instal	lation Year	Documented	
Deficiency		No deficiencies recorded	
SWITCHBOARD		Inspected	
Number of Spares		11	
Fused Disconnect Switc	h Туре	Inspected	
Instance		Boiler Room - By Electric Meter Room	
Instance Condit	ion	3- Fair	
Instance Quanti	tv	1	
Instance Quanti	-	EACH	
Manufacturer	ty com	Siemens	
EquipmentId		Main Distribution Panel MDP	
Capacity/Size Q	Duantity	1600	
Capacity/Size U			
		Amps Total 4	
Capacity/Size 2			
Capacity/Size 2		Section(s)	
Source of Capac		Nameplate 1997	
Installation Yea			
Source of Instal	lation Year	Documented	
Deficiency		No deficiencies recorded	
Instance		Boiler Room - By Oil Tank Room 001	
Instance Condit		2- Between Good and Fair	
Instance Quanti	ty	1	
Instance Quanti	ty Uom	EACH	
Manufacturer		American Switchboard Co.	
EquipmentId		MDP	
Capacity/Size C	Quantity	2000	
Capacity/Size U	JOM	Amps Total	
Capacity/Size 2	Quantity	1	
Capacity/Size 2	UOM	Section(s)	
Source of Capac	city/Size	Nameplate	
Installation Yea	r	2016	
Source of Instal	lation Year	Documented	
Deficiency		No deficiencies recorded	
Fused Knife Switch Typ	e	Does not exist	
Molded Case Circuit Br	reaker Type	Does not exist	
TELEPHONE SYSTEM		Inspected	
PBX/Intercom		Inspected	
Condition		1- Good	
Deficiency		No deficiencies recorded	
Standard		Inspected	
Condition		1- Good	
Deficiency		No deficiencies recorded	
		Inspected	
TRANSFORMER		-	
Instance		Roof - Elevator Machine Room	
Instance Condition Instance Quantity		2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Question	Response	
TRANSFORMER		
Instance Quantity Uom	EACH	
Manufacturer	Jefferson Electric	
EquipmentId	N/A	
Capacity/Size Quantity	40	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	