Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	OLD MANHATTAN VOC/TECH HS - MANHATTAN, 320 EAST 96 STREET, MANHATTAN, NY, 10128			28
Inspection Id	Inspection Type		Time In	Last Edited
2585	MECHANICAL		2024-01-22 07:10AM	2024-02-23 09:07AM
sset Data				
Question		Answer		

Have any Systems/Major Building Components been upgraded?	Systems: Gas Distribution Piping
	Years: 2023
	Systems: Terminal Unit Thermostatic Traps; Boiler Fresh Air
	Louver/Dampers (2 of 3); Drinking Fountains (~80%);
	Fixtures - Toilets, Urinals; Climate Control System -
	Pneumatic System: Air Compressors, Refrigerated Air
	Dryers, Pneumatic PRV Station
	Years: 2022
	Systems: Electric Domestic Water Heater (temporary, 1 of 2)
	Years: 2021
	Systems: Sump Pumps; Gas Fired Domestic Water Heater
	Years: 2019
	Systems: DX Split Systems for 1st Floor Corridors, Cafeteria and
	Multi-Purpose Room; MDF Room - Dedicated A/C
	Equipment (DX Split System); Enclosed IDF Room -
	Dedicated A/C Equipment (DX Split System)
	Years: 2014
	Systems: Sewage Ejector Pumps
	Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	12,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Boiler Room Mechanical Area
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement - Hydraulic/Pneumatic Booster Pump Room, Storage
	Room by Paint Room, Electrical Room (painted, 4)
Are there any Emergency Stop Switches with Missing Hammers?	Component: Boiler Room Entrances
	Location: Boiler Emergency Stop Switch

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Other	Missing (1)	Science Lab - Eye Wash	Room 400	Nelison Blasini	Fireman	
Yes	Defective Boiler Safety Auxiliary	(3)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2	Nelison Blasini	Fireman	

- Partie

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	an Inspection						
	Other	Missing shower head	Science Lab - Emergency Shower	Room 300	Nelison Blasini	Fireman	
	Defective Sprinkler/Standpipe System	Sprinkler Pipe is excessively corroded	Sprinkler Piping	Basement - Water Meter Room across Electrical Room; Boiler Room - Water Meter Room	Nelison Blasini	Fireman	
pectio	on						
Questic				Response			
Mechai							
	CONDITIONING			Inspected			
	illed Water System			Does not			
	v	n: Piping, Pumps and Auxiliarie	·s	Does not			
-	ling Coil in Ductwork	a. riping, rumps and ruxinark	.9	Does not			
	oling Tower			Does not	exist		
-	Split System			Inspected			
In	ndoor Unit			Inspected			
	Condition			2- Betwee	en Good and F	air	
	Deficiency			No defici	encies recorde	d	
0	utdoor Unit			Inspected			
	Condition			2- Betwee	en Good and F	air	
	Deficiency			No defici	encies recorde	d	
Dry	Cooler			Does not	exist		
	kaged / Rooftop Unit			Does not	exist		
-	kaged Terminal A/C			Does not	exist		
Ref	rigerant Leak Detection S	ystem		Does not	exist		
	rigerant Piping			Inspected			
C	ondition			2-Betwee	en Good and F	air	
	Deficiency			No defici	encies recorde	d	
Ret	urn Fan			Does not			
CEN	TRAL ACID WASTE NEU	JTRALIZING TANK		Inspected			
Con	ndition			3- Fair			
	Deficiency			No defici	encies recorde	d	
CLIN	ATE CONTROL SYSTE	Μ		Inspected			
BM	S			Does not			
Pne	eumatic System			Inspected			
	Instance			Througho	out		
	Instance Condition			3- Fair			
	Instance Quantity			1			
	Instance Quantity Uor			EACH			
		d by Operational System		81-100%			
	Deficiency				encies recorde	d	
	brid System			Does not			
	ctric System			Does not			
-	IPACTOR			Does not			
CON	VEYING			Does not	exist		
DOM	IESTIC WATER SYSTEM	1		Inspected			
Dor	nestic Cold Water System			Inspected			
C	ravity System			Does not	exist		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

tion	Response
DMESTIC WATER SYSTEM	
Domestic Cold Water System	Tecnootod
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Hydraulic/Pneumatic Booster Pump Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster Pump	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Hydraulic/Pneumatic Booster Pump Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Hydraulic/Pneumatic Booster Pump Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NOACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
Instance	Basement - Water Meter Room across Electrical Room, Boiler
Instance	Room - Water Meter Room
Instance Condition	3- Fair
Instance Condition	2
	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Water Meter Room across Electrical Room, Boiler Room - Water Meter Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	WATER MAIN: DEFECTIVE VALVE
Deficiency Location/Instance	Basement - Water Meter Room across Electrical Room
Deficiency Quantity	1
· · ·	
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Kitchen (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	215
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Documented
Deficiency	DEFECTIVE FLUE EXHAUST
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:CLOGGED
Deficiency Location/Instance	Girl's Locker Room
Deficiency Quantity	100
•	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected Inspected
1- Good
No deficiencies recorded
Inspected
3- Fair
CRACKED/PHYSICAL DAMAGE
1st Floor Boy's Toilet Room
1 EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected 1- Good
Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response
Does not exist
Does not exist
Inspected
Under construction
Does not exist
Inspected
3- Fair
AUXILIARY (VALVE, VENT):DEFECTIVE
Basement near Electrical Room, Staff Toilet Room
2
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Rooms 204, 311A 4
4 EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
RADIATOR/CONVECTOR:DAMAGED GUARD/SHIELD
Corridor near Room 308
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Under construction
Inspected
3- Fair
DEFECTIVE/LEAKS
Boiler Room
20
L.F.
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
3- Fair
DEFECTIVE/LEAKS
Corridor near Gym Entrance, Boy's Locker Room Main Lobby
and other locations 120

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
HEATING	
Steam Heating	
Steam Piping	
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen, Multipurpose Room; near Stairs - "EF/1", "CD/1" (5 of
	7)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	No
Burner Manufacturer	Preferred Utilities
Burner Model	BHE 55 3M4
Burner Type	Oil
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	MISSING HAMMER
Deficiency Location/Instance	Boiler Room Entrances
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FEEDWATER PUMP:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		IVIU
stion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Feedwater System		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Does not exist	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
oiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,783	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Titusville Iron Works Co	
EquipmentId	1467-01	
Capacity/Size Quantity	55	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
EATING PLANT	
Boiler System	
Steam Boiler	
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1958
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,783
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Titusville Iron Works Co
EquipmentId	1467-02
Capacity/Size Quantity	55
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1958
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	4,783
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Titusville Iron Works Co
EquipmentId	1467-03
Capacity/Size Quantity	55
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1958
Source of Installation Year	Documented
Deficiency	DEFECTIVE STRUCTURAL ELEMENTS(TUBE SHEETS, STAY BOLTS, ETC.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED REFRACTORY
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	S.r. REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations Fuel System	No violations recorded

Instance on Basement

Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
EATING PLANT	
Fuel System	
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	OIL BURNER:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room @ Boiler #3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BURNER CONTROL PANEL:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room @ Boiler #3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
nclosed IDF Room	Inspected
Instance on Room 206A	Inspected
Dedicated A/C Equipment	
Instance on Room 206A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	inspected
Instance on 1st Floor	Not required
	Totroquied
Gas System Instance on 1st Floor	Does not exist
Grease Trap Instance on 1st Floor	Inspected
	3- Fair
Instance Condition	No deficiencies recorded
Deficiency	no deficiencies recorded
Hood	Dage not and
Instance on 1st Floor	Does not exist
Hood Exhaust Ductwork	
Instance on 1st Floor	Does not exist
Hood Exhaust Fan	
Instance on 1st Floor	Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
Missing Air Gap
Kitchen
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
Yes
Inspected
No
Inspected
No
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Not required
Not required
Not required
Not required
Does not exist
Does not exist
Does not ovist
Does not exist Does not exist Does not exist Inspected 3- Fair No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

—		
uestion		Response
SCIENCE DEMO ROOM		
Eye Wash		
Instance on Room	1 404	Inspected
Instance Conditio	n	3- Fair
Deficiency		No deficiencies recorded
Hood Exhaust Ductwork		
Instance on Room	us 304, 401	Does not exist
Instance on Room	us 204	Does not exist
Instance on Room	404	Does not exist
Hood Exhaust Fan		
Instance on Room	us 304, 401	Does not exist
Instance on Room	us 204	Does not exist
Instance on Room	404	Does not exist
Fixed Laboratory Hood		
Instance on Room	us 304, 401	Does not exist
Instance on Room	us 204	Does not exist
Instance on Room	404	Does not exist
Laboratory Sink		
Instance on Room	us 304, 401	Inspected
Instance Condition		3- Fair
Deficiency		No deficiencies recorded
Instance on Room	as 204	Inspected
Instance Conditio		3- Fair
Deficiency		No deficiencies recorded
Instance on Room	404	Inspected
Instance Conditio		4- Between Fair and Poor
Deficiency		DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficiency Loc	ation/Instance	VALVE,ETC.) Room 404
Deficiency Qua		1
Quantity Uom	inty	EACH
Potential Action		MAINTENANCE
Urgency of Acti		PRIORITY 3
Purpose of Acti		LEVEL 2
Violations		No violations recorded
Make-up Air Unit		
Instance on Room	us 304, 401	Does not exist
Instance on Room		Does not exist
Instance on Room		Does not exist
CIENCE LAB		Inspected
Instance on Room	400	Inspected
Alternative Use	1400	No
Instance on Room	200	
	1300	Inspected
Alternative Use	200	No
Instance on Room	1 200	Inspected
Alternative Use		No
Acid Waste Neutralizing		
Instance on Room		Does not exist
Instance on Room		Does not exist
Instance on Room	1 200	Does not exist
CO Detector		
Instance on Room		Not required
Instance on Room		Not required
Instance on Room	ı 200	Not required

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

inicui Inspeciion	14104
iestion	Response
CIENCE LAB	
Emergency Shower	
Instance on Room 400	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 300	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE SHOWER
Deficiency Location/Instance	Room 300
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance on Room 200	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Eye Wash	
Instance on Room 400	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 400 (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance on Room 300	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 200	
	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 400	Does not exist
Instance on Room 300	Does not exist
Instance on Room 200	Does not exist
Hood Exhaust Fan	
Instance on Room 400	Does not exist
Instance on Room 300	Does not exist
Instance on Room 200	Does not exist
Fixed Laboratory Hood	
Instance on Room 400	Does not exist
Instance on Room 300	Does not exist
Instance on Room 200	Does not exist
Laboratory Sink	
Instance on Room 400	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Room 400
Deficiency Quantity	2
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
SCIENCE LAB	
Laboratory Sink	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 300	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 200	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Room 200
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Make-up Air Unit	
Instance on Room 400	Does not exist
Instance on Room 300	Does not exist
Instance on Room 200	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Rooms 200A, 300A, 400A	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Rooms 200A, 300A, 400A	Does not exist
CO Detector	
Instance on Rooms 200A, 300A, 400A	Not required
Emergency Shower	
Instance on Rooms 200A, 300A, 400A	Does not exist
Eye Wash	
Instance on Rooms 200A, 300A, 400A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Rooms 200A, 300A, 400A	Does not exist
Hood Exhaust Fan	
Instance on Rooms 200A, 300A, 400A	Does not exist
Fixed Laboratory Hood	
Instance on Rooms 200A, 300A, 400A	Does not exist
Laboratory Sink	
Instance on Rooms 200A, 300A, 400A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms 200A, 300A, 400A	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement - Hydraulic/Pneumatic Booster Pump Room, Storage
	Room by Paint Room, Electrical Room (painted, 4)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement - Water Meter Room across Electrical Room; Boiler
	Room - Water Meter Room
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	No
Exhaust Fan	Under construction
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Under construction
Unit Ventilator	Does not exist