ectrical Insp	ection						M60
Asset:	SCHL OF THE	FUTURE (OLD BACON)	- MANHATTAN,	127 EAST 22 S	TREET, MAN	NHATTAN, N	YY, 10010
<b>Inspection Id</b>	Inspection Type				Time	In	Last Edited
3021	ELECTRICAL				2024-	02-06 08:51A	M 2024-02-07 03:37PM
set Data							
Question				Answer			
Have any Syste	ems/Major Building (	Components been upgraded?		Systems:	Alarm System Remote Annu	n (Central Cont	Sattery Pack), Intrusion rol Panel, Infrared Sensor,
				Years:	2020		
				Systems:			Breaker Panel Board
				Years:	2014, 2006, 2		
				Systems:		Intercom System	m (Elevator)
				Years:	2014		
				Systems:	Auditorium (7 System)	Theater Lighting	g System, Projection
				Years:	2013		
				Systems:	Public Addres Sound System	, ,	olifier), Auditorium (Local
				Years:	2012		
				Systems:	Fire Alarm Sy	stem, Security	Lighting
				Years:	2007		
				Systems:	Science Lab F	Rooms 302, 803	
				Years:	2006		
				Systems:	Interior Fluore (401, 503)	escent Lighting	, Science Demo Rooms
				Years:	2004		
				Systems:	Intrusion Alar	m System (Exc	ept Central Control Panel)
				Years:	2000		
			Systems:	Emergency Light/Exit Light Panel, Partial Fused Disconnect Switch Type Panel Board			
				Years:	1995		
Type of Service	e			Below Gr	round		
Does Interactiv	e Whiteboard (IWB)	Exist?		Yes			
Water Penetrat	ion In Electrical Roo	m?		Yes			
	D INTERCOMS I	N FIRE RESCUE AREAS					
Question	TiC D A id	A F: D A	1/ II 11: D		Response		
your building	g?	ance Areas, Fire Rescue Areas, a			Yes		
		ble in all of these spaces for use	during a fire?		No	- (902 701 (0	1 501 401 201 202)
	aces do not have ded	neated intercoms?			Laieteria, Koom	is (802, 701, 60	1, 501, 401, 301, 203)
iority Condit		C Pr	<u> </u>	<u> </u>	<b>n</b> ()	<b>n</b> ()	DI 4
	ority tegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
	Alarm System -	There is a Supervisory	Fire Alarm	Fire Alarm	Romell	Fireman	
Def	èctive	warning on the panel's screen	System	Control Panel	Peters		
Shu	ergency Gas nt-Off Valve - Not erational	N/A	Emergency Gas Shut-Off Valve	Science Lab - Rooms (701, 702)	Romell Peters	Fireman	

#### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection M660

cirici	u Inspection						141000
es	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Romell Peters	Fireman	
0	Emergency Shut-Off Power - Not Operational	N/A	Emergency Shut-Off Power	Science Lab - Room 702	Romell Peters	Fireman	
spect	 ion						
Ques				Response			
Elect							
	HLETIC FIELD			Does not	exist		
-	DITORIUM			Inspected	- CAISt		
AU.	Instance on 2nd Floor			Inspected			
н	ouse Lighting			mspected			
- 11	Instance on 2nd Floor			Inspected			
	Does a Chandelier Exi	st?		No			
	Lighting Fixture - Fluoresce						
	Instance on 2nd Floor			Inspected			
	Pendant Mounted						
	Instance on 2nd Floor			Inspected			
	Instance Condition			3- Fair			
	Deficiency			LIGHTIN	G FIXTURE	BALLAST DE	FECTIVE
	Deficiency Quantity	7		1			
	Quantity Uom			EACH			
	Potential Action				E BALLAST		
	Urgency of Action Purpose of Action			PRIORIT LEVEL 2			
	Violations				ons recorded		
	Surface Mounted			NO VIOIAU	ons recorded		
	Instance on 2nd Floor			Inspected			
	Instance Condition			3- Fair			
	Deficiency				encies recorde	d	
	Recessed Mounted			140 deffet	c.cs recorde	•	
	Instance on 2nd Floor			Does not	exist		
	Lighting Fixture - HID			Does not			
	Instance on 2nd Floor			Does not	exist		
	Lighting Fixture - Incandeso	cent					
	Instance on 2nd Floor			Does not	exist		
	Lighting Fixture - LED						
	Instance on 2nd Floor			Does not	exist		
L	ocal Sound System						
	Instance on 2nd Floor			Inspected			
	Instance Condition			3- Fair			
	Installation Year			2012		<u> </u>	
	Source of Installation	Year		Documen			
_	Deficiency			No deficie	encies recorde	d	
Pi	rojection System						
	Instance on 2nd Floor			Inspected			
	Instance Condition			2- Betwee	n Good and F	aır	
	Is the projector on a co	ort or installed on the cailing?		Corling			

Ceiling

Is the projector on a cart or installed on the ceiling?

No deficiencies recorded  Inspected  Inspected  2- Between Good and Fair No deficiencies recorded  Inspected  2- Between Good and Fair
Inspected  Inspected 2- Between Good and Fair No deficiencies recorded  Inspected
Inspected  Inspected 2- Between Good and Fair No deficiencies recorded  Inspected
Inspected  Inspected 2- Between Good and Fair No deficiencies recorded  Inspected
Inspected 2- Between Good and Fair No deficiencies recorded Inspected
Inspected 2- Between Good and Fair No deficiencies recorded Inspected
2- Between Good and Fair No deficiencies recorded  Inspected
2- Between Good and Fair No deficiencies recorded  Inspected
No deficiencies recorded  Inspected
Inspected
2 Potrygon Good and Fair
No deficiencies recorded
Inspected
Inspected
Inspected
Inspected
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
No deficiences recorded
Description of the second of t
Does not exist
Does not exist
Does not exist
Inspected
5- Poor
1968
Inspector Estimate
AMPLIFIER NOT OPERATIONAL
EACH
REPLACE SYSTEM
PRIORITY 2
LEVEL 2
No violations recorded
140 VIOIALIOIIS ICCOIDCU
Does not exist
DOCS HOT CVIST
Does not exist
Inspected Inspected

#### **Building Condition Assessment Survey 2023-2024**

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
	Does not exist
Lighting Fixture - Incandescent	Does not exist  Does not exist
Lighting Fixture - LED	
COMPUTER LAB	Inspected
Instance on Room 402	Inspected
Power Panel?	No
Lighting	
Instance on Room 402	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 402	Inspected
Pendant Mounted	
Instance on Room 402	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 402	Does not exist
Recessed Mounted	
Instance on Room 402	Does not exist
Lighting Fixture - HID	Does not exist
Instance on Room 402	Does not exist
	DOCS HOLCAIST
Lighting Fixture - Incandescent	
Instance on Room 402	Does not exist
Lighting Fixture - LED	
Instance on Room 402	Does not exist
Raceway With Receptacles	
Instance on Room 402	Does not exist
GYMNASIUM	Inspected
Instance on 10th Floor	Inspected
Lighting	
Instance on 10th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 10th Floor	Inspected
Pendant Mounted	
Instance on 10th Floor	Does not exist
Surface Mounted	
Instance on 10th Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
organical organi	

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 10th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 10th Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 10th Floor	Does not exist	
Lighting Fixture - LED	DOCS NOT CAIST	
Instance on 10th Floor	Does not exist	
	Does not exist	
Local Sound System Instance on 10th Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1968	
Source of Installation Year	Inspector Estimate	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 10th Floor	Does not exist	
Scoreboard		
Instance on 10th Floor	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Theater Lighting System		
Instance on 10th Floor	Does not exist	
KITCHEN	Inspected	
Instance on 9th Floor	Inspected	
Lighting		
Instance on 9th Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 9th Floor	Inspected	
Pendant Mounted		
Instance on 9th Floor	Does not exist	
Surface Mounted		
Instance on 9th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 9th Floor	Inspected	
Instance Condition	3- Fair	

#### **Building Condition Assessment Survey 2023-2024**

rical Inspection	Dagmanga	M60
uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID  Instance on 9th Floor	Does not eviet	
	Does not exist	
Lighting Fixture - Incandescent Instance on 9th Floor	Does not exist	
-	Does not exist	
Lighting Fixture - LED  Instance on 9th Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
Instance on 10th Floor - Boys	Inspected	
Alternative Use	No	
Instance on 10th Floor Mezzanine - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on 10th Floor - Boys	Inspected	
Instance on 10th Floor Mezzanine - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on 10th Floor - Boys	Inspected	
Instance on 10th Floor Mezzanine - Girls	Inspected	
Pendant Mounted		
Instance on 10th Floor - Boys	Does not exist	
Instance on 10th Floor Mezzanine - Girls	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 10th Floor - Boys	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 10th Floor Mezzanine - Girls	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 10th Floor - Boys	Does not exist	
Instance on 10th Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 10th Floor - Boys	Does not exist	
Instance on 10th Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 10th Floor - Boys	Does not exist	
Instance on 10th Floor Mezzanine - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 10th Floor - Boys	Does not exist	
Instance on 10th Floor Mezzanine - Girls	Does not exist	

Does not exist

Inspected Inspected

No

No

MULTIPURPOSE ROOM

SCIENCE DEMO ROOM

Lighting

Power Panel?

Alternative Use

Instance on Rooms 401, 503

Question	Response	
SCIENCE DEMO ROOM		
Lighting		
Instance on Rooms 401, 503	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Rooms 401, 503	Inspected	
Pendant Mounted	<u> </u>	
Instance on Rooms 401, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 401, 503	Does not exist	
Recessed Mounted		
Instance on Rooms 401, 503	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 401, 503	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 401, 503	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 401, 503	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 401, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 401, 503	Does not exist	
Power Supply		
Instance on Rooms 401, 503	Inspected	
Instructor Unit		
Instance on Rooms 401, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 401, 503	Does not exist	
Projection System		
Instance on Rooms 401, 503	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 302	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 803	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 701	Inspected	
Power Panel?		
Alternative Use	No No	
	No Inspected	
Instance on Room 702	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	<b>Y Y</b>	
Instance on Room 302	Inspected	
Instance on Room 803	Inspected	
Instance on Room 701	Inspected	

uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 302	Inspected	
Instance on Room 803	Inspected	
Instance on Room 701	Inspected	
Instance on Room 702	Inspected	
Pendant Mounted		
Instance on Room 302	Does not exist	
Instance on Room 803	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 701	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 702	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 803	Does not exist	
Instance on Room 701	Does not exist	
Instance on Room 702	Does not exist	
Recessed Mounted	DOES HOT CAIST	
Instance on Room 302	Does not exist	
Instance on Room 803	Does not exist	
Instance on Room 701	Does not exist	
Instance on Room 702	Does not exist	
Lighting Fixture - HID	DOCS HOL CAISE	
Instance on Room 302	Does not exist	
Instance on Room 803	Does not exist	
Instance on Room 701	Does not exist	
Instance on Room 702	Does not exist  Does not exist	
Lighting Fixture - Incandescent	Does not exist	
	Does not exist	
Instance on Room 302 Instance on Room 803	Does not exist  Does not exist	
Instance on Room 701	Does not exist  Does not exist	
Instance on Room 701 Instance on Room 702	Does not exist  Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on Room 302	Door not aviat	
	Does not exist	
Instance on Room 803	Does not exist	
Instance on Room 701	Does not exist	
Instance on Room 702	Does not exist	
Emergency Gas Shut-Off Valve	Inonacted	
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 803	Does not exist	
Instance on Room 701	Inspected	
Instance Condition  Deficiency	4- Between Fair and Poor  NOT OPERATIONAL	

# **Building Condition Assessment Survey 2023-2024**

uestion	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Room 702	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Emergency Shut-Off Power		
Instance on Room 302	Does not exist	
Instance on Room 803	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 701	Inspected	
Instance Condition	3- Fair	
-	No deficiencies recorded	
Deficiency		
Instance on Room 702	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency Deficiency Quantity	NOT OPERATIONAL 1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Power Supply		
Instance on Room 302	Inspected	
Instance on Room 803	Inspected	
Instance on Room 701	Inspected	
Instance on Room 702	Inspected	
Instructor Unit		
Instance on Room 302	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 803	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 701	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 702		
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 302	Inspected	

No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
Inspected 3- Fair	
3- Fair	
-	
No deficiencies recorded	
<b>D</b>	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
Yes	
No	
Inspected	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
<del></del>	
Does not exist	
Does not exist	
Does not exist	
Inspected	
	Does not exist  Does not exist  Inspected  Inspected  Yes  No  Inspected  Inspected  Inspected  Inspected  Does not exist

## **Building Condition Assessment Survey 2023-2024**

*	-:
Question	Response
SCIENCE PREP ROOM	
Emergency Shut-Off Power	
Instance on Room 701A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 701A	Inspected
Instructor Unit	
Instance on Room 701A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Recessed Mounted	Does not exist  Does not exist
Lighting Fixture - HID	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	EACH INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	10	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE LENS MISSING	
Deficiency Location/Instance	By Room 603	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL LENS	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance		
Deficiency Quantity	Throughout the Building 7	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
<b>Duct Smoke Detector</b>	Does not exist	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

icai inspection		MIOO
uestion	Response	
FIRE ALARM SYSTEM		
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Tamper Flow Switch/Chain Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	2- Between Good and Fair	

## **Building Condition Assessment Survey 2023-2024**

icui inspection	141000
uestion	Response
INTERCOM SYSTEM	
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	
Potential Action	EACH
	EACH MAINTENANCE
	MAINTENANCE
Urgency of Action	MAINTENANCE PRIORITY 2
	MAINTENANCE
Urgency of Action Purpose of Action Violations	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded
Urgency of Action Purpose of Action Violations Deficiency	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded PANEL BOARD COVER IS MISSING
Urgency of Action Purpose of Action Violations  Deficiency Deficiency Location/Instance	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded PANEL BOARD COVER IS MISSING Penthouse - Elevator Machine Room
Urgency of Action Purpose of Action Violations  Deficiency Deficiency Location/Instance Deficiency Quantity	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded  PANEL BOARD COVER IS MISSING Penthouse - Elevator Machine Room 1
Urgency of Action Purpose of Action Violations  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded  PANEL BOARD COVER IS MISSING Penthouse - Elevator Machine Room 1 EACH
Urgency of Action Purpose of Action Violations  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded  PANEL BOARD COVER IS MISSING Penthouse - Elevator Machine Room 1 EACH MAINTENANCE
Urgency of Action Purpose of Action Violations  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	MAINTENANCE PRIORITY 2 LEVEL 2 No violations recorded  PANEL BOARD COVER IS MISSING Penthouse - Elevator Machine Room 1 EACH

## **Building Condition Assessment Survey 2023-2024**

estion	Response
UBLIC ADDRESS SYSTEM	Inspected
Instance	Room 205
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1968
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Kitchen, 7th Floor - Corridor, Dean's Office - Room 205
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Dean's Office - Room 205
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 205
Deficiency Quantity	75,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CCURITY	Inspected
IPDVS/CCTV System	Does not exist
ntrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Fan Room 356
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2020
Source of Installation Year	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Roma Switch	inspecied

Question	Response	
SECURITY	•	
Intrusion Alarm System		
Panic Switch		
Deficiency	SWITCH NOT OPERATIONAL	
Deficiency Location/Instance	Nurse's Office - Room 203	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Main Switch	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1962	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1962	
Source of Installation Year	Inspector Estimate	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	

## **Building Condition Assessment Survey 2023-2024**

- ·		
Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Penthouse - Elevator Machine Rooms	
Instance Condition	2- Between Good and Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Jefferson Electric	
EquipmentId	N/A	
Capacity/Size Quantity	51	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	