lectrical Insp	ection						M80
Asset:	HARVEY MILK	SCHOOL - MANHATTAN	N, 2-10 ASTOR	PLACE, MANH	ATTAN, NY,	10003	
Inspection Id	Inspection Type				Time	In	Last Edited
	ELECTRICAL				2023-	11-10 12:20PM	I 2023-11-11 10:25AM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Cafeteria (LED Lighting), Intercom System (Elevator), Exit/Emergency Lights, Telephone System, LAN		
				Years:	2019		
				Systems:	IPDVS/CCTV	System	
				Years:	2018		
				Systems:		ctrical Systems	and Components
				Years:	2003		
Type of Servic				Below Gr	ound		
	ve Whiteboard (IWB)			Yes			
	ion In Electrical Room			No			
	D INTERCOMS IN	N FIRE RESCUE AREAS					
Question	v I ife Recoue Accieta	nce Areas, Fire Rescue Areas, an	ud/or Holding Room		Response No		
your building		ice Areas, The Rescue Areas, an	id/of Holding Roof	ilis ili — 1	NO		
riority Condi							
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
	tegory	Description	Affected	Description	Notified	Title	Image
No condition r		F		F			
Inspection							
Question				Response			
Electrical				Kesponse			
	EIEL D			Does not	wist		
ATHLETIC							
AUDITORI				Does not	exist		
CAFETERI				Inspected			
	nstance on 3rd Floor			Inspected			
Lighting_	nstance on 3rd Floor			Inspected			
				mspected			
	Fixture - Fluorescen	<u> </u>		Does not	eviet		
-	Fixture - HID			Does not	ZAISt		
_	nstance on 3rd Floor			Does not	aviet		
	Fixture - Incandesco	ont		Does not	ZAISt		
_	nstance on 3rd Floor	-11t		Does not	eviet		
	Fixture - LED			Does not	ZAISt		
_	nstance on 3rd Floor			Inspected			
	nt Mounted			mspected			
_	nstance on 3rd Floor			Inspected			
_	nstance Condition				n Good and Fai	r	
_	Deficiency				encies recorded		
	e Mounted			110 deficit	incres recorded		
_	nstance on 3rd Floor			Does not	eviet		
	ed Mounted			Does not	ZAISt		
_	nstance on 3rd Floor			Does not	exist		
Local Sou				2363 1101			
_	nstance on 3rd Floor			Does not	exist		
Projection							
_	nstance on 3rd Floor			Does not	exist		
	ighting System						
	nstance on 3rd Floor			Inspected			

Building Condition Assessment Survey 2023-2024

rical Inspection	D	M
Question	Response	
CAFETERIA		
Theater Lighting System		
Dimming System		
Instance on 3rd Floor	Does not exist	
Theater Lighting		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
LOCKER ROOM	Does not exist	

Does not exist

Does not exist

Does not exist

MULTIPURPOSE ROOM

SCIENCE DEMO ROOM

SCIENCE LAB

Electrical Inspection	M807

	1,200,
Question	Response
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Health Scene	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	No deficiencies recorded Does not exist
Non Battery Pack	Does not exist
Non Battery Pack EXIT/EMERGENCY LIGHT	Does not exist Inspected
Non Battery Pack EXIT/EMERGENCY LIGHT Condition	Does not exist Inspected 1- Good
Non Battery Pack EXIT/EMERGENCY LIGHT Condition Deficiency	Does not exist Inspected 1- Good No deficiencies recorded
Non Battery Pack EXIT/EMERGENCY LIGHT Condition Deficiency FIRE ALARM SYSTEM	Does not exist Inspected 1- Good No deficiencies recorded Inspected
Non Battery Pack EXIT/EMERGENCY LIGHT Condition Deficiency FIRE ALARM SYSTEM Bell/Horn Condition	Does not exist Inspected 1- Good No deficiencies recorded Inspected Inspected
Non Battery Pack EXIT/EMERGENCY LIGHT Condition Deficiency FIRE ALARM SYSTEM Bell/Horn	Does not exist Inspected 1- Good No deficiencies recorded Inspected Inspected 3- Fair

Electrical Inspection	M807
Question	Response

Question	Response
FIRE ALARM SYSTEM	
Strobe	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	3rd Floor Elevator Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	N/A
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	1- Good

rical Inspection		M80
uestion	Response	
LAN		
Main Equipment Rack (MDF)		
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	By Room 329	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 314	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Cafeteria	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Does not exist	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	-
Panic Switch	Does not exist	
Remote Annunciator	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection M807

uestion		Response
SERVICE SWITCH		Inspected
Instance		3rd Floor - Closet Reception Area
Instance Co	ondition	3- Fair
Instance Q	uantity	1
Instance Q	uantity Uom	EACH
Manufactu	rer	General Electric
Equipment	Id	N/A
Capacity/S	ize Quantity	400
Capacity/S	ize UOM	Amps
Source of C	Capacity/Size	Nameplate
Installation	Year	2003
Source of I	nstallation Year	Documented
Deficiency		No deficiencies recorded
SWITCHBOARD		Inspected
Number of Spares		4
Fused Disconnect S	witch Type	Does not exist
Fused Knife Switch	Туре	Does not exist
Molded Case Circu	it Breaker Type	Inspected
Instance		3rd Floor - Cage Inside Cafeteria
Instance Co	ondition	3- Fair
Instance Q	uantity	1
Instance Q	uantity Uom	EACH
Manufactu	rer	Siemens
Equipment	Id	AC Unit Breakers
	ize Quantity	600
Capacity/S		Amps Total
	ize 2 Quantity	1
	ize 2 UOM	Section(s)
	Capacity/Size	Nameplate
Installation		2003
	nstallation Year	Documented
Deficiency		No deficiencies recorded
TELEPHONE SYST	EM	Inspected
PBX/Intercom		Inspected
Condition		1- Good
Deficiency		No deficiencies recorded
Standard		Inspected
Condition		1- Good
Deficiency		No deficiencies recorded
TRANSFORMER		Does not exist