Building Condition Assessment Survey 2023-2024

Asset:	C.S.E. 3 (R	EGION 10) - MANHATTAN, 13	3 MORNINGSII	DE AVENUE, M	ANHAT TAN	, NY, 10027	
Inspection	ı Id Inspection T	ype			Time	In	Last Edited
	2292 MECHANIC	AL			2024-	-01-09 11:29AM	1 2024-01-10 02:13PM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?			No Syster	n Upgraded			
Are there fuel tanks?			No				
Total # of water main service entries to the asset			0				
MERs/Fan Rooms Locations			6th Floor	MER, 7th Floor	MER, 8th Floor	MER	
Are there any spaces with Missing or Defective CO Detectors?			No				
		ted Sprinkler Heads?		No			
		Switches with Missing Hammers?		No compo	onents		
riority Co	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condit	ion recorded						
nspection							
Question				Response	;		
Mechanic	cal						
AIR CO	ONDITIONING			Inspected			
Chille	ed Water System			Does not	exist		
Cond	enser Water Distrik	oution: Piping, Pumps and Auxiliari	es	Inspected			
Con	dition			2- Betwee	en Good and Fai	ir	
	Deficiency			No deficie	encies recorded		
Coolin	ng Coil in Ductwor	k		Does not	exist		
Cooli	ng Tower			Does not			
	plit System			Does not			
Dry C				Does not	exist		
Раска	aged / Rooftop Unit Instance			Inspected 6th Floor	MED		
	Instance Conditi	on.		3- Fair	WILK		
	Instance Quantit			1			
	Instance Quantit	·		EACH			
	Manufacturer	y Com		FHP			
	EquipmentId			ACU-6-1			
	Capacity/Size Q	iantity		10			
	Capacity/Size U			Tons			
	Source of Capac	ity/Size		Inspector	Estimate		
	Installation Year			2006			
	Source of Install			Documen	ted		
	Source of Heatin			N/A			
	Refrigerant Type			R-22			
	Deficiency				encies recorded		
	Instance			7th Floor 3- Fair	MEK		
	Instance Conditi						
	Instance Quantit	<u> </u>		1 EACH			
	Instance Quantit	y ∪om					
	Manufacturer			FHP			
	EquipmentId Capacity/Size Q	iantity		ACU-7-1 10			
	Capacity/Size U			Tons			
	Source of Capac			Inspector	Estimate		
	Installation Year	•		2006			
	Source of Install	ation Year		Documen	ted		
	Source of Heatin	_		N/A			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	N1808

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	8th Floor MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	FHP
EquipmentId	ACU-8-1
Capacity/Size Quantity	10
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2006
Source of Installation Year	Documented
Source of Heating	N/A R-22
Refrigerant Type	
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Does not exist Does not exist
Return Fan	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	6th, 7th and 8th Floors
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2006
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	6th, 7th and 8th Floors
Deficiency Quantity	1 FACH
Quantity Uom	EACH DEDLAGE
Potential Action Urgency of Action	REPLACE PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
	Inspected
CONVEYING	<u> </u>
Dumbwaiter Elevator	Does not exist Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
	Does not exist
Escalator Non-auditorium Handicap Lift - Vertical	Does not exist Does not exist
Non-auditorium Handicap Lift - Verticai Non-auditorium Handicap Lift - Stair	Does not exist Does not exist
Ton additional Handicap Ditt - Stan	_ 000 100 0.1100

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	M808

Question	Response
CONVEYING	Коронос
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Does not exist
GAS FIRED FURNACE	Does not exist
	Does not exist
GAS SERVICE	
HEATING	Inspected
Heating Coil In Ductwork Condition	Inspected 2- Between Good and Fair
Deficiency	No deficiencies recorded
Hydronic Heating Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	Does not exist
Backflow Preventer	
Hot Water Heat Exchanger	Does not exist
Radiator/Convector/Fin Tube	Does not exist Does not exist
Steam Heating Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	Does not exist
	Inspected
Enclosed IDF Room	
Instance on Rooms 609, 709, 809	Inspected
Dedicated A/C Equipment	Increated
Instance on Rooms 609, 709, 809	Inspected 3- Fair
Instance Condition	J- 1 all

Building Condition Assessment Survey 2023-2024

Mechanical Inspection M808

anical Inspection		MISUS
eestion	Response	
Enclosed IDF Room		
Dedicated A/C Equipment		
Deficiency	No deficiencies recorded	
KITCHEN	Does not exist	
MDF Room	Inspected	
Instance on Room next to Room 711	Inspected	
Dedicated A/C Equipment	-	
Instance on Room next to Room 711	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist Does not exist	
Roof Tank Siamese Connection	Does not exist Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Sprinkler Piping Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Piping Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork Condition	Inspected 2- Between Good and Fair	
	2- Between Good and Fair Yes	
Are there any uninsulated ductwork by design in Mechanical rooms? Are there chain operated dampers?	res No	
Deficiency	No deficiencies recorded	
	Does not exist	
Supply Fan Unit Ventilator	Does not exist Does not exist	