Building Condition Assessment Survey 2023-2024

Electrical Inspection M844

Asset:	P.S. 138 ANNEX (OLD M047 AX) - MANHATTAN, 4	00 1ST AVENUE, MA	ANHATTAN, NY, 10010	
Inspection Id	Inspection Type		Time In	Last Edited
3027	ELECTRICAL		2024-02-06 11:45AM	2024-05-10 11:59AM
lsset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Exit/Emergency Light	
		Years:	2023	
		Systems:	Pendant and Surface LED Retrof (Recessed Retrofitted LED Light	0 0,
		Years:	2019	
		Systems:	Recessed LED Lighting	
		Years:	2016	
		Systems:	Fire Alarm System (Sprinkler Flo Switch, Tamper Flow Switch/Cha	
		Years:	2015	
		Systems:	Most Molded Case Circuit Break	er Type Panel Board
		Years:	2012, 1985	
		Systems:	Public Address System, Cafeteria System), Telephone System, Part	`
		Years:	2012	
		Systems:	Intercom System (Non Official H 330, 440, 550, 660)	Iolding Rooms 221,
		Years:	2011	
		Systems:	Intrusion Alarm System, Emerge Panel, Fire Alarm System (Electr Alarm Digital Communicator, St	onic Sub Panel, Fire

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS		
Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes	
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes	
Are all dedicated intercoms operational?	Yes	

2000

Years:

No

No

Below Ground

Priority Condition

Type of Service

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	Ground Fault causing different issues as per Custodian.	Fire Alarm System	Basement - Fire Alarm Panel Room	Nicholas Howley	Custodian	
No	Water Leaks onto Electrical Equipment	Toilet Leak (in Staff Toilet Room) affecting a Lighting Fixture.	Lighting Fixture	Basement - Hallway	Nicholas Howley	Custodian	

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist

Question	Response	
CAFETERIA	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 \$1100	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED	Boto not exist	
Instance on 3rd Floor	Inspected	
Pendant Mounted	inspected	
Instance on 3rd Floor	Lucusotod	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
COMPUTER LAB		
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	

Electrical Inspection	M844

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
	Does not exist
SCIENCE DEMO ROOM	
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
Deutrana Vansion 2.0 (P)	Page 2 of 10 Print Data: 9/9/2024

Building Condition Assessment Survey 2023-2024

tricai Inspection	M844
Question	Response
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
	Inspected
Battery Pack Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Non Battery Pack	
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Fire Alarm Digital Communicator	
Instance	Room 337A 3- Fair
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Manufacturer	Ademco
EquipmentId	Fire Alarm Control Communicator

Building Condition Assessment Survey 2023-2024

•		
estion	Response	
IRE ALARM SYSTEM		
Fire Alarm Digital Communicator		
Installation Year	2000	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Basement - Fire Alarm Panel Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm Control Board	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Deficiency Deficiency Location/Instance	BEYOND USEFUL LIFE Basement - Fire Alarm Panel Room	
Deficiency Quantity	57,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Basement - Fire Alarm Panel Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST	
EquipmentId	Strobe Control Panel 4	
Installation Year	2000	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Instance	Basement - Fire Alarm Panel Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	IRC-3	

duestion	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	
EquipmentId	Strobe Control Panel 3
Installation Year	2000
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Basement - Fire Alarm Panel Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	IRC-3
EquipmentId	Strobe Control Panel 2
Installation Year	2000
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Basement - Fire Alarm Panel Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer Model	Edwards System Technology EST 2
	Elevator Smoke Detection Panel/ Strobe Control Panel 1
EquipmentId Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Basement - Fire Alarm Panel Room 3- Fair
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm Annunciator
Installation Year	1974
Source of Installation Year	Documented DDV COVE VODE V AVEC
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Fire Alarm Panel Room
Deficiency Quantity	57,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Fire Alarm Panel Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Smoke Detection System
Installation Year	1974
Source of Installation Year	Documented
B & :	BEYOND USEFUL LIFE
Deficiency	DETOND CSELCE ELLE

Electrical Inspection	M844
Question	Response

Response
S.F.
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Basement - Fire Alarm Panel Room
3- Fair
1
EACH
ACME
Punch Register Panel
1974
Documented
BEYOND USEFUL LIFE
Basement - Fire Alarm Panel Room
57,000
S.F.
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Basement - Fire Alarm Panel Room
3- Fair
1
EACH
ACME
Fan Shutdown System
1974
Documented
BEYOND USEFUL LIFE
Basement - Fire Alarm Panel Room
57,000
S.F.
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
Does not exist
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected 2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
No deficiencies recorded Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

iricui Inspection	WIOTT
Question	Response
GROUNDING SYSTEM	
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected Does not exist
MOTOR CONTROL CENTER	Inspected
MOTOR STARTER/CONTACTOR Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Variable Frequency Drive PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Does not exist Inspected
Fused Knife Switch Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	9th Floor -Fan Room, Room 330B, Basement - Mechanical Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Corridor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 229

Building Condition Assessment Survey 2023-2024

uestion		Response
PUBLIC ADDRESS SYSTE		
Instance Condition		2- Between Good and Fair
Instance Quantity		1
Instance Quantity V	Jom	EACH
Model		Dukane 250
Installation Year		2012
Source of Installati	on Year	Documented
Deficiency	er m	CLOCK NOT OPERATIONAL
Deficiency Loca Deficiency Quan		By Room 449
	uity	1 EACH
Quantity Uom Potential Action		REPLACE
Urgency of Action	an an	PRIORITY 3
Purpose of Actio		LEVEL 2
Violations	II.	No violations recorded
ECURITY		Inspected
IPDVS/CCTV System		Does not exist
Intrusion Alarm System		Inspected
Central Control Panel		Inspected
Instance		Room 115
Instance Condition		3- Fair
Instance Quantity		1
Instance Quantity I	Jom	EACH
Model		N/A
Installation Year		2000
Source of Installati	on Year	Custodial Staff
Deficiency		PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quan	ıtity	1
Quantity Uom		EACH
Potential Action		INSTALL CONNECTION
Urgency of Action		PRIORITY 4
Purpose of Actio	n	LEVEL 3
Violations		No violations recorded
Infrared Sensor		Inspected
Condition		3- Fair
Deficiency		No deficiencies recorded
Panic Switch		Does not exist
Remote Annunciator		Inspected
Condition		3- Fair
Deficiency		No deficiencies recorded
Siren/Strobe		Inspected
Condition		3- Fair
Deficiency		No deficiencies recorded
Lighting - Security		Inspected
Condition		5- Poor
Deficiency	. ~	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Loca		Exterior Walls - Building Perimeter
Deficiency Quan	шу	7 EACH
Quantity Uom		EACH PERMAGE
Potential Action		REPLACE
Urgency of Action		PRIORITY 3
Purpose of Actio	n	LEVEL 3
Violations		No violations recorded
SERVICE SWITCH		Inspected
Instance		Basement - Electrical Room

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pringle
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Instance	Basement - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Cole
Manufacturer	N/A
EquipmentId Capacity/Size Quantity	1N/A 2500
Capacity/Size Quantity Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	Amps rotal
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Standard Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist