

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Asset: ELEANOR ROOSEVELT HS - MANHATTAN, 411 EAST 76 STREET, MANHATTAN, NY, 10021

Inspection Id	Inspection Type	Time In	Last Edited
3144	ARCHITECTURAL - ASSOCIATE	2024-02-12 09:15AM	2024-03-17 09:30PM
3206	ARCHITECTURAL - SENIOR	2024-02-12 10:04AM	2024-03-06 01:13PM

Asset Data

Question	Answer
Was the Building Fully Accessible for Inspection?	Yes
Principal(s) Information	
Principal Name	Dimitri Saliani
Principal Organization	Eleanor Roosevelt H.S. - Manhattan
Meeting with Principal?	No
Principal Feedback	The Principal returned the questionnaire with the following comment: The roof top air conditioning units are in need of maintenance.
Custodian	Jared Giandolfo
Was the Custodian Present?	Yes
Fireman	Israel Santiago
Was the Fireman Present?	Yes
Building Square Footage	66,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	5+B
Comments on the Year Built	1950
Student Population	520
Staff Population	50
Comments on the Number of Classrooms	22
Weather	Fair
Facade Photo	



East 76th Street - East View

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Main Entrance Photo



Facade A - East 76th Street

Roof Photo



Roof 1 - North View

Do Stormwater Management/Green Infrastructure systems exist?

No

Type

No Storm Water Management Type Selected

Have any Systems/Major Building Components been upgraded?

Systems: Sidewalk repairs and Flooring replacement on 4th and 5th Floors. Science Rooms 414, 415, 417 new epoxy floor. Cafeteria new Floor.

Years: 2022

Systems: Exterior Wall and Parapet repointing, selective Roof repairs, Sidewalk repairs and Flooring replacement on 4th and 5th Floors.

Years: 2022

Systems: Tiles on 1st, 2nd and 3rd floors (partial)

Years: 2021

Systems: Library upgrades, 2nd Floor Corridor Flooring upgrades

Years: 2019

Systems: Partial Roof repairs, Bulkhead repairs, Library upgrades, 2nd Floor Corridor Flooring upgrades

Years: 2019

Systems: Window repairs (partial)

Years: 2012

Systems: Coping, Flashing, Parapet, Roofing repairs (partial)
Coping, Parapet, Exterior Masonry repairs

Years: 2010

Systems: Coping, Parapet, Exterior Masonry repairs

Years: 2007

Systems: Complete Interior renovation (conversion to school use)

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Have there been any New Building Additions?
 Tandem
 Leased Space?
 Year Leased
 Inspection Type

Years: 2003
 Systems: Complete Interior renovation (conversion to school use); Windows/Guards, Roofing replacement (full)
 Years: 2003
 No New Construction
 No Tandem
 Yes
 2003
 Full Inspection

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the Primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are All floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Exterior Entrances & Exits		Yes				
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	No		No			

Interior Routes

Corridor and Lobby H/C Lifts	Yes	Yes				
Interior Corridor Doors And Hardware	Yes	Yes				
Interior Corridors & Lobbies		Yes				
Interior Elevators	Yes	Yes				
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	Yes	Yes				

Rooms & Spaces

Art Rooms						
Room 212	Yes	Yes				
Auditorium						
1st Floor	Yes	Yes			FM System	Yes
Cafeteria						
2nd Floor	Yes	Yes			FM System	Yes
Classrooms						
2nd-5th Floors	Yes	Yes				
Computer Rooms						
Room 518	Yes	Yes				


**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
Gymnasium	No					
Library						
Room 511	Yes	Yes				
Main Office						
Room 108	Yes	Yes				
Multi-purpose Room						
Room 218/219	Yes	Yes			FM System	Yes
Nurse's Office						
Room 304	Yes	Yes				
Pool	No					
Science Lab						
Rooms 414 and 417	Yes	Yes				
Toilet Rooms (boys)						
1st-5th Floors	Yes	Yes				
Toilet Rooms (girls)						
1st-5th Floors	Yes	Yes				
Toilet Rooms (staff)						
1st-5th Floors	Yes	Yes				

Building Template



Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Does not exist
CHIMNEY	Inspected
Material Type(s)	Metal
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COPING	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855


Question	Response
----------	----------

EXTERIOR

COPING

Deficiency
Deficiency Location/Instance

TERRA COTTA:CRACKED/BROKEN PIECES



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo 1

25
L.F.
REPLACE-IN-KIND
PRIORITY 3
LEVEL 2




Roof 1 - Facade B

Deficiency Photo 2
Violations

No photo recorded
No violations recorded

Deficiency
Deficiency Location/Instance

TERRA COTTA:DETERIORATED TRANSVERSE JOINTS



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo 1

15
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2



Roof 1 - Facade B

Deficiency Photo 2
Violations

No photo recorded
No violations recorded

CORNICE

Does not exist

DOORS

Inspected

DOORS AND FRAMES

Inspected

Condition

3- Fair

Deficiency

METAL:DETERIORATED DOOR AND FRAME - MINOR
DETERIORATION

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855


Question	Response
----------	----------

EXTERIOR

DOORS

DOORS AND FRAMES

Deficiency Location/Instance



Deficiency Quantity

4

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo 1



Deficiency Photo 2

Exit 2

Violations

No photo recorded

No violations recorded

DOOR HARDWARE

Inspected

Condition

3- Fair

Deficiency

No deficiencies recorded

LINTELS

Inspected

Condition

2- Between Good and Fair

Deficiency

No deficiencies recorded

TRANSOM/SIDE LIGHT

Inspected

Condition

2- Between Good and Fair

Deficiency

No deficiencies recorded

EXTERIOR WALLS

Inspected

Material Type(s)

Masonry

Replacement Quantity

20,000

Replacement Uom

S.F.

Instance on All Facades

Inspected

Instance Condition

3- Fair

Instance Quantity

20,000


Instance Quantity Uom

S.F.

Deficiency

BRICK:DETERIORATED MASONRY SILLS - MAJOR

Roof Plan Reference



**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855


Question

Response

EXTERIOR

EXTERIOR WALLS

Elevation



Facade A

Elevation Reference

15

Deficiency Quantity

L.F.

Quantity Uom

REMOVE AND REPLACE

Potential Action

PRIORITY 4

Urgency of Action

LEVEL 2

Purpose of Action

Deficiency Photo 1



Facade A

Deficiency Photo 2

No photo recorded


Violations

No violations recorded


Deficiency

BRICK:MAJOR / THRU CRACKS

Roof Plan Reference



Elevation



Facade A

Elevation Reference

5

Deficiency Quantity

S.F.

Quantity Uom

REMOVE AND REBUILD

Potential Action

PRIORITY 4

Urgency of Action

LEVEL 2

Purpose of Action

Deficiency Photo 1



Facade A

Deficiency Photo 2

No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
----------	----------

EXTERIOR

EXTERIOR WALLS

Violations

No violations recorded

EXTERIOR SOFFITS

Condition

Inspected

Deficiency

2- Between Good and Fair

LOADING DOCK

Does not exist

LOUVER

Does not exist

PARAPETS

Inspected

Material Type(s)

Masonry

Replacement Quantity

6,000

Replacement Uom

C.F.

Instance on All Facades

Inspected

Instance Condition

3- Fair

Instance Quantity

6,000


Instance Quantity Uom

CF

Deficiency

BRICK:DETERIORATED JOINTS

Deficiency Location/Instance



Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo 1



Roof 1 - Facade C

Deficiency Photo 2

No photo recorded


Violations

No violations recorded

Deficiency

BRICK:MINOR CRACKS, SPALLING

Deficiency Location/Instance



Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3




Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
EXTERIOR	
PARAPETS	
Deficiency Photo 1	
Deficiency Photo 2	Roof 1 - Facade C
Violations	No photo recorded No violations recorded
PLAZA DECK	Does not exist
ROOF	Inspected
ROOFING	Inspected
ROOF HATCH/SMOKE HATCH	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ROOF BARRIER/FENCE	Does not exist
ROOF CAGE	Does not exist
ROOFING	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.
Instance on Modified Bitumen:All Roofs	Inspected
Instance Roof Photo	
	Roof 1
Instance Condition	3- Fair
Instance Quantity	15,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this Roof Instance have a Sustainable Roof System?	No
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	No
Installation Year	2003
Source of Installation Year	Documented
Deficiency	MODIFIED BITUMEN:ROOFING:DELAMINATION
Deficiency Location/Instance	
Deficiency Quantity	100

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection




M855

Question	Response
EXTERIOR	
ROOF	
ROOFING	
ROOFING	
Quantity Uom	S.F.
Potential Action	REPLACE ROOFING WITHOUT MAJOR EQUIPMENT REMOVAL
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Roof 1
Violations	No photo recorded
Deficiency	No violations recorded
Deficiency Location/Instance	MODIFIED BITUMEN:ROOFING:BEYOND USEFUL LIFE
Deficiency Quantity	Modified Bitumen:All Roofs
Quantity Uom	15,000
Potential Action	S.F.
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 1
Deficiency Photo 2	LEVEL 2
Violations	No photo recorded
ROOFING DRAINS	No violations recorded
Condition	Inspected
Deficiency	2- Between Good and Fair
SPECIALTIES	No deficiencies recorded
BULKHEAD/PENTHOUSE	Inspected
Condition	Inspected
Deficiency	2- Between Good and Fair
CUPOLA/ SPIRES/ TOWERS	No deficiencies recorded
DORMER	Does not exist
DUNNAGE STEEL	Does not exist
Condition	Inspected
Deficiency	2- Between Good and Fair
SKYLIGHT/ROOF VENT	No deficiencies recorded
ROOF/GRAVITY TANK	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist
WINDOWS	Does not exist
Replacement Quantity	Inspected
Replacement Uom	6,000
EXTERIOR GUARDS	S.F.
Condition	Inspected
Deficiency	2- Between Good and Fair
LINTELS	No deficiencies recorded
Condition	Inspected
Deficiency	2- Between Good and Fair
WINDOWS	No deficiencies recorded
Material Type(s)	Inspected
	Aluminum

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M855

Question	Response
EXTERIOR	
WINDOWS	
WINDOWS	
Instance on Aluminum - Double Hung:All Facades	Inspected
Instance Condition	3- Fair
Instance Quantity	6,000
Instance Quantity Uom	S.F.
Installation Year	2003
Source of Installation Year	Documented
Are these windows insulated?	No
Deficiency	ALUMINUM - DOUBLE HUNG:INOPERABLE BALANCE
Roof Plan Reference	
Elevation	
Elevation Reference	Facade A
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALANCES
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Room 218/219 shown, also Room 312
Violations	No photo recorded No violations recorded
INTERIOR	Inspected
POOLS	Does not exist
STRUCTURAL	Inspected
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	3- Fair
Deficiency	STEEL COLUMNS/BEAMS:DETERIORATED/MISSING SPRAY-ON FIREPROOFING
Deficiency Location/Instance	Basement
Deficiency Quantity	15
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M855

Question	Response
INTERIOR	
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	
Deficiency Photo 1	
Deficiency Photo 2	Electrical Panel Room
Violations	No photo recorded
Deficiency	No violations recorded
Deficiency Location/Instance	MASONRY BEARING WALL:CRACKED/SPALLED
Deficiency Quantity	Basement
Quantity Uom	50
Potential Action	S.F.
Urgency of Action	RESTITCH
Purpose of Action	PRIORITY 3
Deficiency Photo 1	LEVEL 5
	
Deficiency Photo 2	Electrical Panel Room
Violations	No photo recorded
	No violations recorded
FLOOR STRUCTURE	Inspected
Condition	3- Fair
Deficiency	METAL DECK AND CONCRETE:DETERIORATED
Deficiency Location/Instance	Basement
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo 1	
Deficiency Photo 2	Electrical Panel Room
Violations	No photo recorded
Deficiency	No violations recorded
Deficiency Location/Instance	CONCRETE:CRACKS/SPALLED/REINFORCEMENT EXPOSED
Deficiency Quantity	Basement
	15

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
STRUCTURAL	
FLOOR STRUCTURE	
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo 1	
Deficiency Photo 2	Electrical Panel Room
Violations	No photo recorded No violations recorded
FOUNDATION WALLS	
Material Type(s)	Inspected Concrete, Masonry
Condition	3- Fair
Deficiency	CONCRETE:CRACKED/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Basement
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo 1	
Deficiency Photo 2	Electrical Panel Room
Violations	No photo recorded No violations recorded
ROOF STRUCTURE	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
VAULTS-BUNKERS	
Condition	Does not exist
AUDITORIUM	
Instance on 1st Floor (240 Seats)	Inspected
Ceiling	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fixed H/C Lift	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
AUDITORIUM	
Fixed H/C Lift	
Instance on 1st Floor (240 Seats)	Does not exist
Fixed Seating	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	DAMAGED/BROKEN/INOPERABLE
Deficiency Location/Instance	Seats A/107,111, B/105, D/107,
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Floor Finish	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 1st Floor (240 Seats)	Does not exist
Stage	
Instance on 1st Floor (240 Seats)	Inspected
Stage	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stage Curtain Rigging	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stage Curtains	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on 1st Floor (240 Seats)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Window Curtains/Shades/Blinds	
Instance on 1st Floor (240 Seats)	Does not exist
CAFETERIA	
Instance on 2nd Floor	Inspected
Ceiling	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
INTERIOR	
CAFETERIA	
Ceiling	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on 2nd Floor	Does not exist
Floor Finish	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 2nd Floor	Does not exist
Stage	
Instance on 2nd Floor	Does not exist
Walls	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Near Kitchen
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Kitchen
Violations	No photo recorded
	No violations recorded
Window Curtains/Shades/Blinds	
Instance on 2nd Floor	Does not exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	
	Inspected
Ceiling	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Rooms 212, 321, 417
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M855

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Deficiency Photo 1	
Deficiency Photo 2	Room 417
Violations	No photo recorded
	No violations recorded
Deficiency	TECTUM:DAMAGED/MISSING
Deficiency Location/Instance	Corridor near Room 318
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Corridor near Room 318
Violations	No photo recorded
	No violations recorded
Deficiency	GYPSUM BOARD:DAMAGED/DETERIORATED
Deficiency Location/Instance	Main Entrance Lobby
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Main Entrance Lobby
Violations	No photo recorded
	No violations recorded
Door(s)	Inspected
Condition	4- Between Fair and Poor
Deficiency	WOOD:DETERIORATED DOOR
Deficiency Location/Instance	Rooms 501, 518
Deficiency Quantity	2
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Door(s)	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Room 518
Violations	No photo recorded No violations recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	CERAMIC TILE:BROKEN/MISSING TILES
Deficiency Location/Instance	Main Entrance Lobby
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Main Entrance Lobby
Violations	No photo recorded No violations recorded
Deficiency	QUARRY TILE:TRIPPING HAZARD - ELECTRICAL OUTLET
Deficiency Location/Instance	Room 212
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REMOVE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo 1	
Deficiency Photo 2	Room 212
Violations	No photo recorded No violations recorded
Walls	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Architectural Inspection


M855

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Walls	
Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Corridor near Rooms 212, 308, 310, 316, 407, and others
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Corridor near Room 316
Violations	No photo recorded No violations recorded
Specialties	Inspected
Classroom Locker(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Seating	Does not exist
GYMNASIUM	Does not exist
INTERIOR DOOR HARDWARE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on 2nd Floor	Inspected
Ceiling	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 511	Inspected
Built-in Furnishing	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
INTERIOR	
LIBRARY	
Built-in Furnishing	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ceiling	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Near Office
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Office
Violations	No photo recorded No violations recorded
Door(s)	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	
Instance on 2nd Floor - Boys (78 Lockers)	Inspected
Alternative Use	No
Instance on 2nd Floor - Girls (54 Lockers)	Inspected
Alternative Use	No
Ceiling	
Instance on 2nd Floor - Boys (78 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Center
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
-----------------	-----------------

INTERIOR

LOCKER ROOM

Ceiling

Deficiency Photo 1



Center

Deficiency Photo 2

No photo recorded

Violations

No violations recorded

Instance on 2nd Floor - Girls (54 Lockers)

Inspected

Instance Condition

2- Between Good and Fair

Deficiency

ACOUSTIC TILES:DAMAGED/MISSING

Deficiency Location/Instance

Center

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo 1



Center

Deficiency Photo 2

No photo recorded

Violations

No violations recorded

Door(s)

Instance on 2nd Floor - Boys (78 Lockers)

Inspected

Instance Condition

3- Fair

Deficiency

METAL:DAMAGED LOUVER

Deficiency Location/Instance

Entrance

Deficiency Quantity

1

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo 1



Entrance

Deficiency Photo 2

No photo recorded

Violations

No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
----------	----------


INTERIOR

LOCKER ROOM

Door(s)

Instance on 2nd Floor - Girls (54 Lockers)	Inspected
Instance Condition	3- Fair
Deficiency	METAL:DAMAGED LOUVER
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded

Floor Finish

Instance on 2nd Floor - Boys (78 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls (54 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	CERAMIC TILE:BROKEN/MISSING TILES
Deficiency Location/Instance	Center
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded

Locker Room Lockers



Instance on 2nd Floor - Boys (78 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls (54 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Walls

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
INTERIOR	
LOCKER ROOM	
Walls	
Instance on 2nd Floor - Boys (78 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Windows
Violations	No photo recorded
	No violations recorded
Instance on 2nd Floor - Girls (54 Lockers)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Windows
Violations	No photo recorded
	No violations recorded
MULTI-PURPOSE ROOM	
Instance on Room 218/219	Inspected
Instance on Room 218/219	Inspected
Ceiling	
Instance on Room 218/219	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	TECTUM:DAMAGED/MISSING
Deficiency Location/Instance	Near Windows, center
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M855

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Ceiling	
Deficiency Photo 1	
	Near Windows
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Door(s)	
Instance on Room 218/219	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on Room 218/219	Does not exist
Floor Finish	
Instance on Room 218/219	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on Room 218/219	Does not exist
Stage	
Instance on Room 218/219	Does not exist
Walls	
Instance on Room 218/219	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Near Windows, near Entrance
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Near Windows
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Window Curtains/Shades/Blinds	
Instance on Room 218/219	Does not exist
SCIENCE DEMO ROOM	
Instance on Rooms 402, 403, 409	Inspected
Alternative Use	No
Fixed Equipment	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M855

Question	Response
INTERIOR	
SCIENCE DEMO ROOM	
Fixed Equipment	
Instance on Rooms 402, 403, 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Fixed Equipment	
Instance on Rooms 414, 417	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	CABINETRY:MISSING/DAMAGED
Deficiency Location/Instance	Room 417
Deficiency Quantity	2
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SCIENCE PREP ROOM	
Fixed Equipment	
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	CABINETRY:MISSING/DAMAGED
Deficiency Location/Instance	Room 415
Deficiency Quantity	2
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SHOWER ROOM	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	Inspected
Do Letter Stair Signs Exist?	Yes
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Stair B/1
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Stair B/1 No photo recorded
Violations	No violations recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Partition	Does not exist
Railings	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stairs and Landings	Inspected
Condition	2- Between Good and Fair
Deficiency	VINYL TILES:DETERIORATED SUBSTRATE
Deficiency Location/Instance	Stair B/1
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Stair B/1 No photo recorded
Violations	No violations recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	GYPSUM BOARD:DETERIORATED
Deficiency Location/Instance	Stairs A/2, B/1,2
Deficiency Quantity	30

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection




M855

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Walls	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Stair B/2
Violations	No photo recorded
	No violations recorded
TOILET ROOMS - STAFF	
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Room 331
Deficiency Quantity	5
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOMS - STUDENTS	
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	ACOUSTIC TILES:DAMAGED/MISSING
Deficiency Location/Instance	Room 405
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Ceiling	
Deficiency Photo 1	
Deficiency Photo 2	Room 405
Violations	No photo recorded No violations recorded
Door(s)	Inspected
Condition	5- Poor
Deficiency	WOOD:DAMAGED LOUVER
Deficiency Location/Instance	Room 508
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Room 508
Violations	No photo recorded No violations recorded
Deficiency	WOOD:DETERIORATED DOOR
Deficiency Location/Instance	Room 204
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Room 204
Violations	No photo recorded No violations recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M855

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Stalls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not exist
STEEL STAIRS	Does not exist
SITE	Inspected
CONTAINERIZATION	Does not exist
DRAINAGE SYSTEM FOR ASPHALT	Does not exist
DRAINAGE SYSTEM FOR CONCRETE	Does not exist
DRAINAGE SYSTEM FOR SOIL	Does not exist
DRINKING FOUNTAINS	Does not exist
FENCES	Does not exist
IRRIGATION SYSTEM	Does not exist
PAVING	Inspected
Student Non-Use	Does not exist
Student Use	Does not exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Along West 76th Street
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Along West 76th Street
Violations	No photo recorded
Violations	No violations recorded
Deficiency	HEAVING
Deficiency Location/Instance	Along West 76th Street
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M855

Question	Response
SITE	
PAVING	
DOT Sidewalk	
Concrete	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Along West 76th Street
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Does not exist
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Architectural Inspection

M855

Does the SCA expect asset to have artwork?

No