Building Condition Assessment Survey 2023-2024

Electrical Inspection M875

Asset:	P.S. 226 (FIRST PRESB CHURCH) - MANHATTAN,	12 WEST 12 STREET	Γ, MANHATTAN, NY, 10011	
Inspection Id	Inspection Type		Time In	Last Edited
1967	ELECTRICAL		2023-12-28 11:52AM	2023-12-28 03:37PM
sset Data				
Question		Answer		
Have any Syste	ems/Major Building Components been upgraded?	Systems:	Interior LED Lighting (Retrofitte	ed)
		Years:	2022	
		Systems:	Exit/Emergency Light, Telephon	e System
		Years:	2018	
		Systems:	Security Lighting, Fire Alarm Sy	stem, Service Switch,
			Switchboard, Grounding System	
			Switch Type Panel Board, Most	
			Breaker Panel Board, Exit Light	` '
		V	IPDVS/CCTV System, Variable	Frequency Drive
		Years:	2014	~
		Systems:	Motor Starter, Staff Toilet Room	s (LED Lighting)
		Years:	2012	

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

QuestionResponseAre there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?No

Below Ground

Yes

No

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Lightning Protection - Defective	Lightning Protection Conductor Clamps Not Properly Attached	Lightning Protection	Roof	Joe Diaz	Fireman	

Inspection

Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

rical Inspection		M8
Question	Response	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
TOILET ROOM - STAFF	Inspected	
Lighting Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - Fitorescent Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
a tu	1 C1	

Condition

Bell/Horn

Condition

Deficiency
FIRE ALARM SYSTEM

1- Good

Inspected

Inspected

No deficiencies recorded

2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection M875

	1110
Response	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
-	
EACH	
Gamewell	
E3 Series	
Fire Alarm Control Panel	
No deficiencies recorded	
Does not exist Does not exist	
	No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected Basement - Staff Room 2- Between Good and Fair 1 EACH N/A Central Office Transmitter 2014 Custodial Staff No deficiencies recorded Inspected Does not exist Inspected Basement - Staff Room 2- Between Good and Fair 1 EACH Castodial Staff No deficiencies recorded Inspected Does not exist Inspected Basement - Staff Room 2- Between Good and Fair 1 EACH Gamewell E3 Series Fire Alarm Control Panel 2014 Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection M875

unostion.	Dagmanga
uestion	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Does not exist
LIGHTNING PROTECTION	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTNING PROTECTION CONDUCTOR CLAMPS NOT
Deficiency	PROPERLY ATTACHED
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition Case Circuit Breaker Type	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	5th Floor and 3rd Floor Electrical Closet
Deficiency Quantity	2
z erreterely & amusely	<u> </u>

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	тегропос
Molded Case Circuit Breaker Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
PUBLIC ADDRESS SYSTEM	2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
SECURITY INDIVIGICATIVE A	Inspected Inspected
IPDVS/CCTV System Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Does not exist
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Basement Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
Manufacturer EquipmentId	Sprinkler Booster Pump SS4 Fire Pump
Equipmentid Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	SW#1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Basement Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	SW#2
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection M875

Question	Response		
SWITCHBOARD			
Number of Spares	4		
Fused Disconnect Switch Type	Inspected		
Instance	Basement Corridor By Electrical Room		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	All City Switchboard		
EquipmentId	N/A		
Capacity/Size Quantity	1200		
Capacity/Size UOM	Amps Total		
Capacity/Size 2 Quantity	1		
Capacity/Size 2 UOM	Section(s)		
Source of Capacity/Size	Service Switch Size		
Installation Year	2014		
Source of Installation Year	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not exist		
Molded Case Circuit Breaker Type	Does not exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		