Electrical Inspection	M876
-----------------------	------

Asset:	GREGORIO LUI	PERON PREP. SCHOOL	- MANHATTAN	, 501 WEST 16:	5 STREET, M	ANHATTAN	N, NY, 10032
Inspectio	n Id Inspection Type				Time 1	[n	Last Edited
	84 ELECTRICAL				2023-	10-10 07:56A	M 2023-11-06 06:11PM
Asset Data							
Question				Answer			
Have any	Systems/Major Building Co	omponents been upgraded?		Systems:	LAN, Gymnas	sium (Scoreboa	nrd)
				Years:	2023		
				Systems:			213), Partial Emergency
				<b>V</b>		ery Pack), Part	ial Exit/Emergency Lights
				Years: Systems:	2022 Partial Lightin	o Security	
				Years:	2019	ig - Security	
				Systems:		trical Systems	and Components
				Years:	2008	aricar bysteins	and components
Type of S	ervice			Below Gr			
	ractive Whiteboard (IWB) I	Exist?		Yes			
	netration In Electrical Room			No			
DEDIC	ATED INTERCOMS IN	FIRE RESCUE AREAS					
Question					Response		
		ce Areas, Fire Rescue Areas, a	nd/or Holding Roon	ns in	Yes		
your bu		e in all of these spaces for use	during a fire?		Yes		
	all dedicated intercoms ope		during a fire:		No		
		on-operational dedicated interc	coms?		Gymnasium		
Priority Co							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Leaks onto	N/A	Electrical Unit	Staircase	Jose Perez	Fireman	No Photo Taken
1.0	Electrical Equipment		Heater	A/Bulkhead	00001000	1 11 0 1 1 1 1 1	
Yes	Intercom - Not	N/A	Intercom	Elevators -	Jose Perez	Fireman	No Photo Taken
	Connected to Remote		System -	Devices ID:			
	Monitoring Station		Elevator	1P45193,			
				1P45194			
Inspection	1						
Question	1			Response	•		
Electrica	l						
ATHL	ETIC FIELD			Does not	exist		
AUDIT	TORIUM			Does not	exist		
CAFE	ΓERIA			Inspected			
	Instance on Basement			Inspected			
Light	ting						
	Instance on Basement			Inspected			
Lig	hting Fixture - Fluorescent	t					
_	Instance on Basement			Inspected			
P	endant Mounted				• .		
_	Instance on Basement			Does not	exist		
S	urface Mounted			-	• .		
_	Instance on Basement			Does not	exist		
R	ecessed Mounted						
	Instance on Basement			Inspected			
	Instance Condition			3- Fair			
	Deficiency Deficiency Quantity				IG FIXTURE BA	ALLAST DEF	ECTIVE
				8 EACH			
	Quantity Uom Potential Action				E BALLAST		
	i otentiai Action			KEFLAC	T DUPPUSI		
CAS Danta	Version 2.0 (P)		Page 1	-£12			Print Date: 8/8/202

## **Building Condition Assessment Survey 2023-2024**

Electrical InspectionM876QuestionResponse

action	Dagnanga	
estion	Response	
AFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	15	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE 10	
	10 EACH	
Quantity Uom		
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2  No violations recorded	
Violations		

## **Building Condition Assessment Survey 2023-2024**

N10/0
Response
Does not exist
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
nispected
Inspected
3- Fair
No deficiencies recorded
No deficiencies recorded
Does not exist
Does not exist
Y 1
Inspected 3- Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Y 1
Inspected
3- Fair
2008
Documented  No deficiencies recorded
No deficiencies recorded
Door not exist
Does not exist
Insuranted
Inspected 1- Good
No deficiencies recorded
D
Does not exist
Inspected
Inspected
Inspected

Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	•	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 315	Inspected	
Lighting		
Instance on Room 315	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 315	Inspected	
Pendant Mounted	1	
Instance on Room 315	Does not exist	
Surface Mounted		
Instance on Room 315	Does not exist	
Recessed Mounted		
Instance on Room 315	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on Room 315	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 315	Does not exist	
Lighting Fixture - LED		
Instance on Room 315	Does not exist	
Raceway With Receptacles		
Instance on Room 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 315	Does not exist	
LOCKER ROOM	Inspected	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected	
J /	1	

Duestion	Response	
`	кезронзе	
LOCKER ROOM		_
Lighting Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected	_
Pendant Mounted	nispected	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not exist	
Surface Mounted	DOCS HOT CAIST	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not exist	
Recessed Mounted	DOES NOT CAIST	_
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	_
Lighting Fixture - HID	140 deficiencies recorded	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not exist	
Lighting Fixture - Incandescent	DOES NOT CAIST	_
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not exist	
Lighting Fixture - LED	DOES NOT CAIST	_
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not exist	_
MULTIPURPOSE ROOM	Inspected	
		_
Instance on 1st Floor	Inspected	
Lighting Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on 1st Floor	Inspected	
Pendant Mounted	inspected	_
Instance on 1st Floor	Does not exist	_
Surface Mounted	DOGS HOT CAIST	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	_
Instance on 1st Floor	Inspected	_
Instance Condition	3- Fair	
	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		_
Instance on 1st Floor	Does not exist	_
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	_
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	_
Installation Year	2008	_
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	

Electrical Inspection		W18 / 0
Question	Dognongo	

Question	Response
MULTIPURPOSE ROOM	
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Rooms 302, 310, 312	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Rooms 302, 310, 312	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 302, 310, 312	Inspected
Pendant Mounted	
Instance on Rooms 302, 310, 312	Does not exist
Surface Mounted	
Instance on Rooms 302, 310, 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 302, 310, 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 302, 310, 312	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 302, 310, 312	Does not exist
Lighting Fixture - LED	
Instance on Rooms 302, 310, 312	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 302, 310, 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 302, 310, 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 302, 310, 312	Inspected
Instructor Unit	
Instance on Rooms 302, 310, 312	Inspected
Instance Condition	3- Fair

### **Building Condition Assessment Survey 2023-2024**

Duestion	Response	
	Response	
SCIENCE LAB		
Power Supply Instructor Unit		
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Meter Demonstration Unit	To an and all	
Instance on Rooms 302, 310, 312	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 302, 310, 312	Does not exist	
Projection System		
Instance on Rooms 302, 310, 312	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Inspected	
Instance on Room 308	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 308	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 308	Inspected	
Pendant Mounted		
Instance on Room 308	Does not exist	
Surface Mounted		
Instance on Room 308	Does not exist	
Recessed Mounted		
Instance on Room 308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 308	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 308	Does not exist	
Lighting Fixture - LED		
Instance on Room 308	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	1.0 40110101010100	

Instance on Room 308

Instance on Room 308

**Lighting Fixture - Fluorescent** 

Instance Condition Deficiency

**Power Supply** 

Lighting

**SWIMMING POOL** 

TOILET ROOM - STAFF

**Pendant Mounted** 

Inspected

Does not exist

Does not exist

Inspected Inspected

Inspected Does not exist

Inspected

No deficiencies recorded

3- Fair

## **Building Condition Assessment Survey 2023-2024**

<b>F</b>		
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	·
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition		
Deficiency	2- Between Good and Fair No deficiencies recorded	

Electrical Inspection	N18/6

estion	Response	
TRE ALARM SYSTEM		
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Room 114	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Silent Knight	
EquipmentId	Central Station Fire Alarm	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	

## **Building Condition Assessment Survey 2023-2024**

incui inspection	141070
Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevators - Devices ID: 1P45193, 1P45194
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5 LEVEL 6
Purpose of Action Violations	No violations recorded
	Does not exist
Holding Area	Inspected
LAN Level Distribution France (III DE)	Inspected
Local Distribution Frame (I/LDF)  Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER  MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
ruseu roggie Switch Type	Does not exist  Does not exist
Molded Case Circuit Breaker Type	
	Does not exist
Molded Case Circuit Breaker Type	Does not exist Inspected

## **Building Condition Assessment Survey 2023-2024**

neui Inspection	14107
Question	Response
PUBLIC ADDRESS SYSTEM	
Instance	Room 114
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room C20D
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Near Main Entrance
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Electrical Meter Room C04B
Instance Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	DP-AHU

## **Building Condition Assessment Survey 2023-2024**

Question		Response
SERVICE	E SWITCH	
	Capacity/Size Quantity	2500
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Meter Room C04B
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	DP-EM
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Meter Room C04B
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	Fire Pump Switch
	Capacity/Size Quantity	600
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Meter Room C04B
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
		EACH
	Instance Quantity Uom	
	Manufacturer	Square D
	EquipmentId	MDP
	Capacity/Size Quantity	2500
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate 2008
	Installation Year Source of Installation Year	
		Documented
	Deficiency	No deficiencies recorded
SWITCH		Inspected
Number	of Spares	13
Fused D	Disconnect Switch Type	Inspected
	Instance	Closet Next to Electrical Meter Room C04B
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	DP-EM
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	1
	Capacity/Size 2 Qualitity	

## **Building Condition Assessment Survey 2023-2024**

estion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room C04B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	DP-AHU
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room C04B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MDP
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist